

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2017 and 05/07/2017, and defects raised outside of inspections on the same Section(s) during this period.

(Section Code is 10821/05) Or

(Section Code is 10827/39)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
10821/05 : WITH: BR.OVER A812-BRIDGE OVER CARDROSS RD									
Safety Inspection of A82 Inspection on 05 January 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 12 January 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 19 January 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 26 January 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 02 February 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 09 February 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 16 February 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 23 February 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 02 March 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 09 March 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 16 March 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 23 March 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 30 March 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 06 April 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 06 April 2017	415m	415m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	04/05/2017	Completed Defects	01/05/2017	A82 NB 200M PRIOR TO CARDROSS O/BRDGE @ CROSSING POINT
SW77258967-235075865									
Safety Inspection of A82 Inspection on 13 April 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 20 April 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 27 April 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 04 May 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 11 May 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 18 May 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 25 May 2017	89m	90m	SAFETY_FENCE	Other (OTHR)	CAT 1	26/05/2017	Completed Defects	25/05/2017	A82 NB APPROX 200YRDS AFTER RENTON ROAD, RENTON
SW77217087-235163146									
Safety Inspection of A82 Inspection on 01 June 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 08 June 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 15 June 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 22 June 2017									
No defects recorded									
Safety Inspection of A82 Inspection on 29 June 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded									
1082739 : LOCH SLOY POWER STATION TO ARDLUI STATION									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 04 January 2017 No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 11 January 2017 No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 18 January 2017 VWG5234566-235032253	5,970m	0m	CARRIAGEWAY	Pothole VIA/FIX (POTV)	CAT 1	19/01/2017	Completed Defects	18/01/2017	JUST SOUTH OF ARDLUI, S/B C/WAY
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 25 January 2017 VWG5237485-235040965	982m	0m	CARRIAGEWAY	Pothole VIA/FIX (POTV)	CAT 1	26/01/2017	Completed Defects	25/01/2017	SEVEN SISTERS LOCH LOMOND, (CENTRE OF C/WAY)
VWG5237485-235040964	1,308m	0m	CARRIAGEWAY	Pothole VIA/FIX (POTV)	CAT 1	26/01/2017	Completed Defects	25/01/2017	NORTH SIDE OF SEVEN SISTERS, N/B C/WAY
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 01 February 2017 No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 08 February 2017 VWG5242680-235052994	1,304m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/03/2017	Completed Defects	22/02/2017	NORTH SIDE OF SEVEN SISTERS, S/B C/WAY
VWG5242680-235052995	660m	0m	CARRIAGEWAY	Pothole VIA/FIX (POTV)	CAT 1	09/02/2017	Completed Defects	08/02/2017	NORTH SIDE OF SEVEN SISTERS, N/B C/WAY
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 15 February 2017 No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 22 February 2017 VWG11244797-235056563	3,527m	0m	CARRIAGEWAY	Flooding (FLOD)	CAT 1	23/02/2017	Completed Defects	22/02/2017	NORTH OF ARDVORLICH HOUSE, N/B C/WAY
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 01 March 2017 VWG21246622-235061774	1,758m	0m	CARRIAGEWAY	Flooding (FLOD)	CAT 1	29/03/2017	Completed Defects	28/03/2017	1KM SOUTH OF ARDVORLICH HOUSE, LOCH LOMOND, (N/B VERGE)
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 08 March 2017 No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 15 March 2017 No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 22 March 2017 VWG21252929-235071956	894m	0m	GULLY	Rocking under load (IRLD)	CAT 1	19/04/2017	Completed Defects	28/03/2017	SOUTH SIDE OF SEVEN SISTERS, LOCH LOMOND, (N/B C/WAY)
VWG21252929-235071960	3,588m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2017	Completed Defects	04/04/2017	HOUSE, S/B C/WAY
VWG21252929-235071957	863m	0m	CARRIAGEWAY	Pothole VIA/FIX (POTV)	CAT 1	23/03/2017	Completed Defects	22/03/2017	SOUTH SIDE OF SEVEN SISTERS, LOCH LOMOND, (N/B C/WAY)
VWG21252929-235071959	3,279m	0m	CARRIAGEWAY	Pothole VIA/FIX (POTV)	CAT 1	23/03/2017	Completed Defects	22/03/2017	NORTH OF ARDVORLICH HOUSE, N/B C/WAY
VWG21252929-235071961	3,588m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2017	Completed Defects	04/04/2017	NORTH OF ARDVORLICH HOUSE, S/B C/WAY
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 29 March 2017 VWG21254940-235074285	5,934m	0m	CARRIAGEWAY	Patch - loss of material (fredding) (PLMT)	CAT 1	26/04/2017	Completed Defects	25/04/2017	SOUTH OF ARDLUI, N/B C/WAY
VWG21254940-235074286	4,067m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	26/04/2017	Completed Defects	25/04/2017	JUST SOUTH OF FULPIT ROCK, N/B C/WAY

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG1254940-235074287	984m	0m	CARRIAGEWAY	Bituminous surfacing	CAT 1	26/04/2017	Completed Defects	24/04/2017	A82 NORTH SIDE OF SEVEN SISTERS, LOCH LOMOND. (N/B C/WAY)
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 05 April 2017 NWG21263623-235075631	4,945m	0m	CARRIAGEWAY	freting (BFRT) Patch - material cracking (PMCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	NTH OF PULPIT ROCK SB C/WAY
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 12 April 2017 NWG21259617-235078641	1,924m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/05/2017	Completed Defects	09/05/2017	700M SOUTH OF ARDVORLICH HOUSE, S/B C/WAY
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 19 April 2017 No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 26 April 2017 NWG21263620-235110474	2,838m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	27/04/2017	Completed Defects	26/04/2017	JUST NORTH OF ARDVORLICH HOUSE ACCESS, S/B VERGE BETWEEN PULPIT ROCK & ARDVORICH HOUSE, N/B C/WAY.
NWG21263620-235110476	3,546m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/05/2017	Completed Defects	24/05/2017	ARDVORICH HOUSE, N/B C/WAY.
NWG21263620-235110479	3,545m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/05/2017	Completed Defects	24/05/2017	BETWEEN PULPIT ROCK & ARDVORICH HOUSE, N/B C/WAY.
NWG21263620-235110480	3,542m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/05/2017	Completed Defects	24/05/2017	BETWEEN PULPIT ROCK & ARDVORICH HOUSE, N/B C/WAY.
NWG21263620-235110475	2,917m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	27/04/2017	Completed Defects	26/04/2017	JUST NORTH OF ARDVORLICH HOUSE ACCESS, S/B VERGE BETWEEN PULPIT ROCK & ARDVORICH HOUSE, N/B C/WAY.
NWG21263620-235110477	3,534m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/05/2017	Completed Defects	24/05/2017	ARDVORICH HOUSE, N/B C/WAY.
NWG21263620-235110473	2,865m	0m	BOLLARDS	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	OUTSIDE ARDVORLICH HOUSE ACCESS, N/B VERGE
NWG21263620-235110481	3,549m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/05/2017	Completed Defects	24/05/2017	BETWEEN PULPIT ROCK & ARDVORICH HOUSE, S/B C/WAY.
NWG21263620-235110478	3,543m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/05/2017	Completed Defects	24/05/2017	BETWEEN PULPIT ROCK & ARDVORICH HOUSE, S/B C/WAY.
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 03 May 2017 No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 10 May 2017 No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 17 May 2017 No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 24 May 2017 No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 31 May 2017 No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 07 June 2017 No defects recorded									
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 14 June 2017 NW31279270-235193526	6,577m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	12/07/2017	Awaiting CCMS Permanent Date	01/01/9999	GARRISTUCK JUST STH OF ARDLUINB
NW31279270-235193528	402m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/07/2017	Awaiting CCMS Permanent Date	01/01/9999	NTH OF LOCH SLOY POWER STATION NB
NW31279270-235193530	2,650m	0m	CARRIAGEWAY	Debris / Refuse (DETR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST STH OF ARDVORLICH BOTH C/WAYS
NW31279270-235193532	1,321m	0m	CARRIAGEWAY	Bituminous surfacing freting (BFRT)	CAT 1	12/07/2017	Awaiting CCMS Permanent Date	01/01/9999	1.3KM NTH OF LOCH SLOY POWER STATION NB

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW31279270-235193533	1,336m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/07/2017	Awaiting CCMS Permanent Date	01/01/9999	1.3KM NTH OF LOCH SLOY POWER STATION NB
NW31279270-235193529	2,237m	0m	CARRIAGEWAY	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	2.2KM NTH OF LOCH SLOY POWER STATION SB
NW31279270-235193531	1,881m	0m	CULVERT	Free flow impeded (FRFL)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	1.9KM NTH OF LOCH SLOY POWER STATION NB VERGE
<p>Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 21 June 2017 No defects recorded</p> <p>Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 28 June 2017 NW31281579-235235511 2,096m 0m CULVERT Free flow impeded (FRFL)</p> <p>NW31281579-235235512 2,305m 0m CARRIAGEWAY Patch - loss of material (freting) (PLMT)</p> <p>Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 05 July 2017 NWG30-281798-235253424 532m 0m CARRIAGEWAY Pothole (POTH)</p>									
					CAT 1	26/07/2017	Awaiting CCMS Permanent Date	01/01/9999	600M SOUTH OF ARDYORLICH HOUSE, N/B VERGE.
					CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST SOUTH OF ARDYORLICH HOUSE, S/B C/WAY.
					CAT 1	02/08/2017	Awaiting CCMS Permanent Date	01/01/9999	500M NORTH OF SLOY POWER STATION, N/B C/WAY.