
## **Inspection Defect Summary Report**



(Section Code is 11920/05)



Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description		
11920/05 : A819 JUNCTION T	O SCHOO	LLOCH	IAWF								
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 11 January 2017											
No defects recorded Safety Inspection of A82 A85 A83 NWG5234566-235032243	3 Safety Ballo 146m		nnel Inv - Tarbet on 18 J CARRIAGEWAY	January 2017 Pothole VIAFIX (POTV)	CAT 1	19/01/2017	Completed Defects	18/01/2017	JUST WEST OF INVERARY A819 JCT, E/B C/WAY		
NWG5234566-235032244	88m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/02/2017	Completed Defects	09/02/2017	JUST WEST OF INVERARY A819 JCT, E/B C/WAY		
NWG5234566-235032241	286m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/01/2017	Completed Defects	18/01/2017	JUST WEST OF INVERARY A819 JCT, E/B C/WAY		
NWG5234566-235032242	202m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/01/2017	Completed Defects	18/01/2017	JUST WEST OF INVERARY A819 JCT, E/B C/WAY		
Safety Inspection of A82 A85 A83	Safety Ballo	och - Con	nnel Inv - Tarbet on 25 J	January 2017							
Safety Inspection of A82 A85 A83	No defects recorded Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 01 February 2017										
No defects recorded Safety Inspection of A82 A85 A83	Safety Ballo	och - Con	inel Inv - Tarbet on 08 F	ebruary 2017							
No defects recorded Safety Inspection of A82 A85 A83											
NWG5243222-235057164	2,337m	0m	GULLY	Rocking under load (IRLD)	CAT 1	15/03/2017	Completed Defects	09/03/2017	EAST SIDE OF LOCHAWE VILLAGE, E/B C/WAY		
NWG5243222-235057165	2,266m	0m	GULLY	Rocking under load (IRLD)	CAT 1	15/03/2017	Completed Defects	09/03/2017	EAST SIDE OF LOCHAWE VILLAGE, E/B C/WAY		
NWG5243222-235057166	2,187m	0m	GULLY	Rocking under load (IRLD)	CAT 1	15/03/2017	Completed Defects	09/03/2017	EAST SIDE OF LOCHAWE VILLAGE, E/B C/WAY		
Safety Inspection of A82 A85 A83 No defects recorded Safety Inspection of A82 A85 A83	-			-							
No defects recorded Safety Inspection of A82 A85 A83	Safety Ballo	och - Con	nnel Inv - Tarbet on 08 N	March 2017							
NWG21248951-235066603	3,180m		Culvert	Flooding (FLOD)	CAT 1	05/04/2017	Completed Defects	15/03/2017	BETWEEN VILLAGE SHOP & OLD SCHOOL HOUSE, LOCHAWE VILLAGE. (E/B VERGE)		
NWG21248951-235066601	3,182m	0m	GULLY	Blockage (BLOK)	CAT 1	05/04/2017	Completed Defects	15/03/2017	BETWEEN VILLAGE SHOP & OLD SCHOOL HOUSE, LOCHAWE VILLAGE. (E/B C/WAY)		
NWG21248951-235066593	1,200m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2017	Completed Defects	05/04/2017	STRONMILCHAN B8077 JCT, WEST OF LOCHAWE VILLAGE. (W/B C/WAY)		
NWG21248951-235066595	1,182m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2017	Completed Defects	05/04/2017	STRONMILCHAN B8077 JCT, WEST OF LOCHAWE VILLAGE. (W/B C/WAY)		
NWG21248951-235066604	3,080m	0m	GULLY	Blockage (BLOK)	CAT 1	05/04/2017	Completed Defects	15/03/2017	BETWEEN VILLAGE SHOP & OLD SCHOOL HOUSE, LOCHAWE VILLAGE. (E/B C/WAY)		
NWG21248951-235066605	2,963m	0m	GULLY	Blockage (BLOK)	CAT 1	05/04/2017	Completed Defects	15/03/2017	BETWEEN VILLAGE SHOP & OLD SCHOOL HOUSE, LOCHAWE VILLAGE. (E/B C/WAY)		

05/04/2018

Page 1 of 6

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
	111	111			Category	Completion Date		Date	
NWG21248951-235066607	2,823m	0m	GULLY	Blockage (BLOK)	CAT 1	05/04/2017	Completed Defects	15/03/2017	BETWEEN VILLAGE SHOP & OLD SCHOOL HOUSE, LOCHAWE VILLAGE. (E/B C/WAY)
NWG21248951-235066594	1,192m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	05/04/2017	Completed Defects	05/04/2017	OPPOSITE STRONMILCHAN B8077 JCT, WEST OF LOCHAWE VILLAGE. (W/B C/WAY)
NWG21248951-235066602	3,160m	0m	GULLY	Blockage (BLOK)	CAT 1	05/04/2017	Completed Defects	15/03/2017	BETWEEN VILLAGE SHOP & OLD SCHOOL HOUSE, LOCHAWE VILLAGE. (E/B C/WAY)
NWG21248951-235066606	2,881m	0m	GULLY	Blockage (BLOK)	CAT 1	05/04/2017	Completed Defects	15/03/2017	BETWEEN VILLAGE SHOP & OLD SCHOOL HOUSE, LOCHAWE VILLAGE. (E/B C/WAY)
Safety Inspection of A82 A85 A83 NWG21250945-235068231	3 Safety Ballo 106m		nnel Inv - Tarbet on 15 I CARRIAGEWAY	March 2017 Pothole VIAFIX (POTV)	CAT 1	16/03/2017	Completed Defects	15/03/2017	A85, JUST WEST OF INVERARAY A819 JCT, E/B C/WAY
Safety Inspection of A82 A85 A83	Safety Ballo	och - Co	nnel Inv - Tarbet on 22 I	March 2017					
No defects recorded  Safety Inspection of A82 A85 A83	S Safoty Ball	och - Co	nnol Inv - Tarbot on 20 I	March 2017					
NWG21254940-235074276	253m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	26/04/2017	Completed Defects	26/04/2017	A85, JUST WEST OF INVERARAY A819 JUNCTION, E/B C/WAY
Safety Inspection of A82 A85 A83 NWG21256923-235075524	3,030m		nnel Inv - Tarbet on 05 i CARRIAGEWAY	April 2017 Bituminous	CAT 1	03/05/2017	Completed	27/04/2017	WEST OF LOCHAWE HOTEL
14WG21230923-233013324	3,030111	OIII	CARRIAGEWAT	surfacing fretting (BFRT)	CATT	03/03/2017	Defects	27/04/2017	WB CWAY
Safety Inspection of A82 A85 A83	•								
NWG21259617-235078632	278m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/04/2017	Completed Defects	12/04/2017	JUST WEST OF INVERARAY A819 JCT, E/B C/WAY
NWG21259617-235078633	73m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/04/2017	Completed Defects	12/04/2017	JUST WEST OF INVERARAY A819 JCT, W/B C/WAY
NWG21259617-235078631	329m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/04/2017	Completed Defects	12/04/2017	JUST WEST OF INVERARAY A819 JCT, E/B C/WAY
NWG21259617-235078634	105m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/04/2017	Completed Defects	12/04/2017	JUST WEST OF INVERARAY A819 JCT, W/B C/WAY
Safety Inspection of A82 A85 A83 No defects recorded									
Safety Inspection of A82 A85 A83 No defects recorded	Safety Ball	och - Co	nnel Inv - Tarbet on 26	April 2017					
Safety Inspection of A82 A85 A83	Safety Rall	och - Co	nnel Inv - Tarbet on 03 l	May 2017					
NWG21265986-235133438	187m		CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/05/2017	Completed Defects	03/05/2017	A85, JUST WEST OF INVERARAY A819 JUNCTION, E/B C/WAY
NWG21265986-235133439	188m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/05/2017	Completed Defects	03/05/2017	A85, JUST WEST OF INVERARAY A819 JUNCTION, E/B C/WAY
Safety Inspection of A82 A85 A83 No defects recorded	Safety Ballo	och - Co	nnel Inv - Tarbet on 10 l	May 2017					<u> </u>
Safety Inspection of A82 A85 A83	Safety Ball	och - Co	nnel Inv - Tarbet on 17	May 2017					

Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 17 May 2017 No defects recorded

Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 24 May 2017 No defects recorded

Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 31 May 2017 No defects recorded

Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 07 June 2017 No defects recorded

Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 14 June 2017

No defects recorded

Page 2 of 6

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description			
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 21 June 2017 No defects recorded												
Safety Inspection of A82 A85 A83 NW31281579-235235518	3 Safety Ball 2,996m		nel Inv - Tarbet on 28 Jo GULLY	une 2017 Rocking under load (IRLD)	CAT 1	26/07/2017	Completed Defects	25/07/2017	JUST WEST OF LOCHAWE VILLAGE SHOP, E/B C/WAY.			
NW31281579-235235519	2,961m	0m	MANHOLE	Rocking under load (IRLD)	3RD PTY	26/07/2017	Awaiting CCMS Temp Date	01/01/9999	JUST WEST OF LOCHAWE VILLAGE SHOP, W/B C/WAY.			
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 05 July 2017  No defects recorded												
Safety Inspection of A82 A85 A83 No defects recorded	-			-								
Safety Inspection of A82 A85 A83 NWG11282452-235268513	3 Safety Ball 1,201m		inel Inv - Tarbet on 19 Ji CARRIAGEWAY	uly 2017  Localised edge  deterioration  (LODT)	CAT 1	16/08/2017	Completed Defects	10/08/2017	OPP THE STRONMILCHAN / B8077 JCT			
Safety Inspection of A82 A85 A83 No defects recorded Safety Inspection of A82 A85 A83	•			uly 2017								
No defects recorded Safety Inspection of A82 A85 A83	3 Safety Ball	och - Con	nel Inv - Tarbet on 09 A	ugust 2017								
NW31283113-235299534	2,479m		CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/08/2017	Completed Defects	09/08/2017	JUST EAST OF LOCH AWE HOTEL WB			
NW31283113-235299533	2,442m	0m	GULLY	Blockage (BLOK)	CAT 1	06/09/2017	Completed Defects	06/09/2017	JUST EAST OF LOCH AWE HOTEL WB			
No defects recorded Safety Inspection of A82 A85 A83	Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 16 August 2017  No defects recorded  Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 23 August 2017											
No defects recorded Safety Inspection of A82 A85 A83	3 Safety Ball	och - Con	inel Inv - Tarbet on 30 A	ugust 2017								
No defects recorded Safety Inspection of A82 A85 A83 No defects recorded	_			_								
Safety Inspection of A82 A85 A83					0.47.4	44/40/0047	0 11 1	04/00/0047	0.05.4/// 50.54.07.05.07			
NWG8295173-235372303	3,048m		Culvert	Free flow impeded (FRFL)	CAT 1	11/10/2017	Completed Defects	21/09/2017	0.25 MILES EAST OF ST CONANS KIRK LOCHAWE EB VERGE			
NWG8295173-235372301	2,485m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	11/10/2017	Completed Defects	11/10/2017	JUST EAST OF LOCHAWE HOTEL EB			
NWG8295173-235372308	3,153m	0m	GULLY	Seized (SIEZ)	CAT 1	11/10/2017	Completed Defects	21/09/2017	0.25 MILES EAST OF ST CONANS KIRK LOCHAWE EB			
NWG8295173-235372302	2,480m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	11/10/2017	Completed Defects	11/10/2017	JUST EAST OF LOCHAWE HOTEL WB			
Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 20 September 2017												
No defects recorded Safety Inspection of A82 A85 A83												
NWG11314880-235387477	2,265m	0m	GULLY	Difference in level with road (IDLV)	CAT 1	25/10/2017	Completed Defects	19/10/2017	JUST WEST OF CARRAIG THURA ACCESS, LOCHAWE VILLAGE. (E/B C/WAY)			
NWG11314880-235387476	1,507m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	28/09/2017	Completed Defects	27/09/2017	OPPOSITE LOCHAWE VILLAGE HALL, E/B C/WAY.			
NWG11314880-235387478	2,012m	0m	CARRIAGEWAY	Flooding (FLOD)	CAT 1	25/10/2017	Completed Defects	19/10/2017	EITHER SIDE OF CARRIAG THURA HOUSE ACCESS, LOCHAWE VILLAGE. (E/B VERGE)			
Safety Inspection of A82 A85 A83 No defects recorded	3 Safety Ball	och - Con	nel Inv - Tarbet on 04 C	ctober 2017								
Safety Inspection of A82 A85 A83 No defects recorded	3 Safety Ball	och - Con	nel Inv - Tarbet on 11 O	ctober 2017								

Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 18 October 2017

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11315440-235431029	3,055m	0m	Culvert	Free flow impeded (FRFL)	CAT 1	15/11/2017	Completed Defects	10/11/2017	350M EAST OF OLD SCHOOL HOUSE, LOCHAWE VILLAGE. (E/B VERGE)
NWG11315440-235431032	2,478m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/10/2017	Completed Defects	18/10/2017	JUST EAST OF LOCHAWE HOTEL, LOCHAWE VILLAGE. (E/B C/WAY)
NWG11315440-235431033	1,991m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/10/2017	Completed Defects	18/10/2017	JUST EAST OF LOCHAWE VILLAGE, W/B C/WAY.
NWG11315440-235431030	3,008m	0m	GULLY	Blockage (BLOK)	CAT 1	15/11/2017	Completed Defects	10/11/2017	400M EAST OF OLD SCHOOL HOUSE, LOCHAWE VILLAGE. (E/B C/WAY)
NWG11315440-235431031	2,484m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/10/2017	Completed Defects	18/10/2017	JUST EAST OF LOCHAWE HOTEL, LOCHAWE VILLAGE. (W/B C/WAY)
Safety Inspection of A82 A85 A8 No defects recorded	83 Safety Ball	och - Co	onnel Inv - Tarbet on 25	October 2017					
Safety Inspection of A82 A85 A8									
NWG11315730-235451353	2,491m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/11/2017	Completed Defects	01/11/2017	EAST SIDE OF LOCHAWE HOTEL, LOCHAWE VILLAGE. (E/B C/WAY)
NWG11315730-235451354	2,491m	0m	MANHOLE	Blockage (BLOK)	CAT 1	29/11/2017	Completed Defects	10/11/2017	EAST SIDE OF LOCHAWE HOTEL, LOCHAWE VILLAGE. (E/B FOOTWAY)
NWG11315730-235451352	2,491m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/11/2017	Completed Defects	01/11/2017	EAST SIDE OF LOCHAWE HOTEL, LOCHAWE VILLAGE. (E/B C/WAY)
NWG11315730-235451355	1,478m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/11/2017	Completed Defects	01/11/2017	OUTSIDE LOCHAWE VILLAGE HALL, E/B C/WAY.
Safety Inspection of A82 A85 A8 No defects recorded	_								
Safety Inspection of A82 A85 A8 NWG8316165-235470593	83 Safety Ball 419m		onnel Inv - Tarbet on 15 CARRIAGEWAY	November 2017 Pothole VIAFIX	CAT 1	16/11/2017	Completed	15/11/2017	A85, JUST WEST OF
		OIII		(POTV)		16/11/2017	Completed Defects		INVERARAY A819 JCT, E/B C/WAY.
NWG8316165-235470592	452m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/11/2017	Completed Defects	15/11/2017	A85, JUST WEST OF INVERARAY A819 JCT, E/B C/WAY.
NWG8316165-235470594	400m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/11/2017	Completed Defects	15/11/2017	A85, JUST WEST OF INVERARAY A819 JCT, E/B C/WAY.
NWG8316165-235470596	387m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/11/2017	Completed Defects	15/11/2017	A85, JUST WEST OF INVERARAY A8219 JCT, E/B C/WAY.
NWG8316165-235470595	389m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/11/2017	Completed Defects	15/11/2017	A85, JUST WEST OF INVERARAY A819 JCT, E/B C/WAY.
NWG8316165-235470597	248m		CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/11/2017	Completed Defects	15/11/2017	A85, JUST WEST OF INVERARAY A819 JCT, E/B C/WAY.
Safety Inspection of A82 A85 A8 NWG11316327-235473981	3,059m		Culvert	Free flow impeded	CAT 1	01/01/9999	Completed Defects	19/12/2017	JUST WEST OF LOCHAWE VILLAGE SHOP, E/B VERGE.
NWG11316327-235473982	3,028m	0m	GULLY	(FRFL) Blockage (BLOK)	CAT 1	01/01/9999	Completed Defects	19/12/2017	JUST WEST OF LOCHAWE VILLAGE SHOP, E/B C/WAY.
Safety Inspection of A82 A85 A8 No defects recorded	83 Safety Ball	och - Co	onnel Inv - Tarbet on 29	November 2017					
Safety Inspection of A82 A85 A8	-				O4T 4	00/04/0040	Comprehensel	00/04/0040	WEST SIDE OF CARRAIC
NWG11316622-235487356	2,197m	0m	CARRIAGEWAY	Flooding (FLOD)	CAT 1	03/01/2018	Completed Defects	03/01/2018	WEST SIDE OF CARRAIG THURA ACCESS, LOCHAWE VILLAGE. (BOTH SIDES OF C/WAY)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A82 A85 A8	83 Safety Ballo	och - Co	nnel Inv - Tarbet on 15	3 December 2017					
NW122316783-235496087	2,264m	0m	GULLY	Difference in level with road (IDLV)	CAT 1	10/01/2018	Completed Defects	10/01/2018	JUST WEST OF CARRAIG THURA ACCESS, LOCHAWE VILLAGE. (E/B C/WAY)
Safety Inspection of A82 A85 A8 NWG11316950-235498004	83 Safety Ballo 6m		onnel Inv - Tarbet on 20 TRAFFIC_SIGNS	O December 2017 Missing (MISS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	(A85) OPPOSITE INVERARAY A819 JUCTION. (E/B VERGE)
NWG11316950-235498003	7m	0m	TRAFFIC_SIGNS	Physical condition of fittings (COFT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST INSIDE INVERARAY A819 JUCTION. (W/B VERGE)
Safety Inspection of A82 A85 A8	-				0.4= -	00/40/22/17	Onesel I I	07/10/05 :=	WOT FACT OF LOOMAN/F
NWG11317070-235512895	1,483m		CARRIAGEWAY	Pothole VIAFIX (POTV)		28/12/2017	Completed Defects	27/12/2017	JUST EAST OF LOCHAWE VILLAGE, E/B C/WAY.
NWG11317070-235512894	3,010m	0m	GULLY	Rocking under load (IRLD)	CAT 1	24/01/2018	Completed Defects	24/01/2018	JUST WEST OF LOCHAWE VILLAGE SHOP, E/B C/WAY.
Safety Inspection of A82 A85 A8	-								
NWG11317218-235513560	305m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	31/01/2018	Completed Defects	31/01/2018	(A85) EAST SIDE OF KILCHURN CASTLE ACCESS, E/B C/WAY.
NWG11317218-235513558	74m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/01/2018	Completed Defects	03/01/2018	(A85) JUST EAST OF KILCHURN CASTLE ACCESS, W/B C/WAY.
NWG11317218-235513559	82m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/01/2018	Completed Defects	03/01/2018	(A85) JUST EAST OF KILCHURN CASTLE ACCESS, W/B C/WAY.
Safety Inspection of A82 A85 A8									
NWG11317395-235514067	283m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/01/2018	Completed Defects	10/01/2018	JUST EAST OF ORCHY BRIDGE, E/B C/WAY.
NWG11317395-235514073	120m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	07/02/2018	Completed Defects	07/02/2018	(A85) JUST WEST OF INVERARAY A819 JUNCTION, E/B C/WAY.
NWG11317395-235514070	122m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	07/02/2018	Completed Defects	07/02/2018	(A85) JUST WEST OF INVERARAY A819 JUNCTION, W/B C/WAY.
NWG11317395-235514071	136m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	07/02/2018	Completed Defects	07/02/2018	(A85) JUST WEST OF INVERARAY A819 JUNCTION, W/B C/WAY.
NWG11317395-235514063	2,186m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/01/2018	Completed Defects	10/01/2018	OUTSIDE CARRAIG THURA, LOCHAWE VILLAGE. (E/B C/WAY)
NWG11317395-235514065	465m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/01/2018	Completed Defects	10/01/2018	JUST EAST OF ORCHY BRIDGE, E/B C/WAY.
NWG11317395-235514069	117m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	07/02/2018	Completed Defects	07/02/2018	(A85) JUST WEST OF INVERARAY A819 JUNCTION, E/B C/WAY.
NWG11317395-235514072	129m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	07/02/2018	Completed Defects	07/02/2018	(A85) JUST WEST OF INVERARAY A819 JUNCTION.
NWG11317395-235514066	281m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/01/2018	Completed Defects	10/01/2018	JUST EAST OF ORCHY BRIDGE, E/B C/WAY.
NWG11317395-235514068	110m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	07/02/2018	Completed Defects	07/02/2018	(A85) JUST WEST OF INVERARAY A819 JUNCTION, E/B C/WAY.
NWG11317395-235514064	1,947m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	07/02/2018	Completed Defects	07/02/2018	100YDS EAST OF LOCHAWE  VILLAGE, W/B C/WAY.

Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 17 January 2018
No defects recorded

Safety Inspection of A82 A85 A83 Safety Balloch - Connel Inv - Tarbet on 24 January 2018
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A82 A85 A8	83 Safety Ball	och - Con	nel Inv - Tarbet on 31	January 2018					
NWG11318016-235530421	2,483m	0m	CARRIAGEWAY	Pothole VIAFIX	CAT 1	01/02/2018	Completed	31/01/2018	LOCHAWE VILLAGE, E/B
				(POTV)			Defects		C/WAY.
				, ,					
Safety Inspection of A82 A85 A8	83 Safety Ball	och - Con	nel Inv - Tarbet on 07 /	February 2018					
NWG11318672-235534309	1,481m	0m	CARRIAGEWAY	Pothole VIAFIX	CAT 1	08/02/2018	Completed	07/02/2018	OPPOSITE LOCHAWE
				(POTV)			Defects		VILLAGE HALL, E/B C/WAY.
				, ,					
NWG11318672-235534310	1,484m	0m	CARRIAGEWAY	Pothole VIAFIX	CAT 1	08/02/2018	Completed	07/02/2018	OPPOSITE LOCHAWE
				(POTV)			Defects		VILLAGE HALL, E/B C/WAY.
Safety Inspection of A82 A85 A8	83 Safety Ball	och - Con	nel Inv - Tarbet on 09	February 2018					
No defects recorded									
Safety Inspection of A82 Safety	Tyndrum, A8	28 & A85	Oban - Dalmally on 13	February 2018					
No defects recorded									
Safety Inspection of A82 Safety	Tyndrum, A8	28 & A85	Oban - Dalmally on 20	February 2018					
No defects recorded									
Safety Inspection of A82 Safety	Tyndrum, A8	28 & A85	Oban - Dalmally on 27	February 2018					
NWG23-322548-235549656	2,189m		CARRIAGEWAY	Pothole	CAT 1	28/02/2018	Completed	09/03/2018	LOCHAWE, TOWER OF GLEN
				(POTH)			Defects		STRAE
				, - /					
Safety Inspection of A82 Safety	Tyndrum, A8	28 & A85	Oban - Dalmally on 06	March 2018					
NWG23-324660-235552265	2,993m		MANHOLE	Other (OTHR)	3RD PTY	03/04/2018	Awaiting CCMS	01/01/9999	LOCH AWE
				, ,			Temp Date		
							•		