

Date	Details	Road	Comments
07/04/2017 23:09	<p>Location: EDENBANK BRIDGE & Tullis Rusell Roundabout</p> <p>Description: Anti skid surface in the bend here at the bridge is an utter disgrace. This surface is worn out cracked and fretting. Very fast bend here so this needs urgent works done. IF SAFETY IS TOP PRIORITY MAYBE YOU WOULD NOTICE THE SURFACE IS WRECKED. Surface southbound at roundabout is a complete joke. Covered in potholes all worn out and cracked. You will cause accident as this surface is dangerous. SAFETY TOP PRIORITY JOKE JOKE JOKE.</p>	A92	Anonymous complaint
18/02/2017 15:38	<p>Location: Preston Roundabout to Tullis Russell Roundabout</p> <p>Description: Damaged road gullies and very poor sections of carriageway both north/south. Re-surface is required to make this road safe again. 60mph then a 40mph section need upgrading.</p>	A92	Anonymous complaint
07/01/2017 07:30	<p>Location: Tullis Russell Roundabout to Balfarg Junction</p> <p>Description: NEW SPEED LIMIT OF 40MPH IN FORCE. Why have you not informed public of new speed limit. There is a severe lack of 40MPH marker signs and no road markings to advise of new limit. DRIVERS ARE IGNRING LIMIT DUE TO LACK OF SIGNS. You need more 40mph signs and you need to paint 40mph road markings on road. This road was 50mph for years yet now reduced and you fail to make road users aware that there is a new limit in place. Shocking is what it is your sign markings are an utter disgrace and you should be ashamed of yourself.</p>	A92	Anonymous complaint
09/12/2016 20:29	<p>Location: Tullis Russell Roundabout</p> <p>Description: Heading north at this roundabout both lanes show ahead only. This used to be right lane for Markinch and left to Tullis Russells and ahead north bound. Twice recently I've had drivers in the right lane trying to overtake the left hand lane narrowly avoiding collision. 2 lanes into 1 does not go!....also the road number shown on the lanes is wrong. This needs corrected urgently.</p>	A92	Anonymous complaint
16/09/2016 14:53	<p>Location: Various location</p> <p>Description: On the tullis Russell roundabout, newinn roundabout and Kirkcaldy west roundabout have arrows painted on the ground for going straight on but the road name is for the road to the left or the right. Why has this been done as a lot of people are in the wrong lanes and I am being cut up on a frequent basis because of this.</p>	A92	
01/07/2016 08:52	<p>Location: Tullis Russell round about</p> <p>Description: The surface of the road is far too slippy when wet and caused my car to spin off this morning and hit a lamppost.</p>	A92	
01/07/2016 08:44	<p>Location: Tullis Russel Roundabout</p> <p>Description: This is a very dangerous roundabout. I recently watched two cars spin out heading southwards, at relatively low speed, just as they come level with the turnoff to Markinch. There s something badly wrong with the cohesive nature of that road surface. I have heard of at least 4 cars spinning out in the last few weeks and now there has been an accident this morning at exactly the same point. Please advise how many reports you need before you take action because I can soon start a wee social media campaign that will inundate you with reports.</p>	A92	
27/06/2016 20:43	<p>Location: Tullis Russell roundabout, Glenrothes</p> <p>Description: The road surface of this roundabout is very slippy especially when damp or wet. I have had a skid/spin on this roundabout at very slow speed ending up on the grass facing the wrong way and with a dented wheel. The car behind me also skidded. There have been numerous incidents of cars sliding on the roundabout and have seen two 3 vehicles off the road due to the dangerous surface. Placing a couple of road signs warning of possible slippy conditions is not a satisfactory solution. Even locals who know about this problem have been caught out. If nothing is done about this it is only a matter of time before there is a major incident.</p>	A92	
14/06/2016 23:03	<p>Location: Tullis Russell roundabout southbound</p> <p>Description: Lost control in wet conditions doing approx 17 mph exiting the roundabout. Road surface not correct for wet. Tyres in good condition. Going slightly slower than the three cars in front, luckily nothing behind me as it was late evening 2215 approx.</p>	A92	
10/05/2016 20:00	<p>Location: Tullis Rusell R/About S/Bound Exit</p> <p>Description: Road markings on roundabout southbound are worn away and need refreshed urgently. Anti skid surface as you exit roundabout southbound onto A92 is an utter disgrace. It has potholes. It is all broken up with numerous ruts/cracks and defects and you still just ignore it all the time. Why do you keep ignoring this section of road. This surface is supposed to be a safety measure but it is an utter disgrace and needs replaced and repaired urgently. Your road maint on the A92 Fife between Glenrothes and Dundee needs a serious re-think going by the state of the road surfaces in places.</p>	A92	Anonymous complaint