

Document: Form 163

Issue: 1

Related to: All Contracts

Page No. 1 of 1

Safety and Patrol Inspections



Date: 29-4-16 Inspectors: [Redacted]

Vehicle Reg: [Redacted]

Cat 1/2: 1 Weather: RAIN

Route	Link / Section	Chainage	XSP	Single Dual Illway	CW Width (m)	Speed MPH	Defect Type	Measurement	Location	Photo No.
A90	12361/05	71	L01	S	7.2	40	ACCID	PED CROSSING X 2 NEED REPAIRED	LEFT ADDITIONAL LANE AT BRIDGE'S DEE ROTS/S	
A90	12357/86	3308	LPI	D	7.2	70	POTV	PATCH 0.75M X 0.5M	APPROACHING BUS STOP ASDA FORTLEITHEN S/B	
A90	12357/86	3283	LPI	D	7.2	70	POTV	PATCH 0.5M X 0.25M	APPROACHING BUS STOP ASDA FORTLEITHEN S/B	
A90	12245/06	2500	LPI	D	7.2	70	POTH	PATCH 1.25M X 1.25M	AFTER COOKSTON BREACHIN BY PASS S/B	
A90	12245/06	2300	LPI	D	7.2	70	POTH	PATCH 1.25M X 0.5M	AFTER COOKSTON BREACHIN BY PASS S/B	

Issue:	1
Related to:	All Contracts
Page No.	1 of 1

Safety and Patrol Inspections



Date: 29-4-16 Inspectors: [Redacted] Vehicle Reg: [Redacted]
 Cat 1/2: 1 Weather: WET

Route	Link / Section	Chainage	XSP	Single Dual	CW	Speed	Defect Type	Measurement	Location	Photo No.
				Drain	Width (m)	MPH				
A90	12240/96	446	LP1	D	7.2	70	POTH	PATCH 0.5M X 0.25M	START OF STORM DRAIN NIB CONCRETE SECTION	
A90	12240/95	656	LP1	D	7.2	70	POTH	PATCH 1M X 0.5M	600M BEFORE ST ANNES JCT NIB	
A90	12245/85	73	LP1	D	7.2	70	POTH	PATCH 1.25M X 1.25M	JUST AFTER ST ANNES JCT NIB	
A90	12245/05	1696	LP1	D	7.2	70	POTH	PATCH 1M X 0.5M	APPROACHING COOKSTON NIB	
A90	12245/06	2180	LO2	D	7.2	70	ACCD	1 X PARKING 1/2 MILE SIGN 2 X GOMM POLES DAMAGED	JUST AFTER COOKSTON NIB	
A90	12245/05	2311	LP1	D	7.2	70	POTH	PATCH 1M X 0.5M	APPROACHING GOLF COURSE NIB	
A90	12368/20	132	LO3	S	7.2	40	ACCD	1 X LIGHTING COLUMN WX3201 DAMAGED	@ BRIDGE OF DON NIB	