

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/08/2017 and 28/08/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST:DRUMMORE RBT TO END OF DUAL CWAY SECTION',) Or

(Section is 'DRUMMORE RBT TO SHAWHEAD ROADEND JUNCTION',) Or

(Section is 'DRUMMORE ROUNDABOUT',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
11526/58 : AGAINST:DRUMMORE RBT TO END OF DUAL CWAY SECTION									
Detailed Inspection TEMPLATE of A75 M Detail on 16 August 2017									
SW86-282923-107	950m	980m	WOODLAND	Injurious weeds (IWED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-282923-110	1,914m	1,924m	WOODLAND	Injurious weeds (IWED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-282923-105	47m	67m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-282923-108	1,222m	1,232m	WOODLAND	Injurious weeds (IWED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-282923-109	1,445m	1,465m	WOODLAND	Injurious weeds (IWED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86-282923-106	457m	507m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
Detailed Inspection TEMPLATE of A75 M Detail on 28 May 2018									
SW81-332075-223	454m	481m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-230	956m	970m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-219	119m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-233	1,372m	1,395m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-220	162m	215m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-222	356m	406m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-224	468m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-226	548m	578m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-221	287m	345m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-228	657m	697m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	

SW81-332075-232	1,305m	1,362m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-229	848m	928m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-231	1,186m	1,210m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-225	477m	486m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-227	627m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999

Annual Detailed Inspection - Carriageways of A75 M Detail

No defects recorded

CR Detailed Inspection - Carriageways of A75 M Detail

No defects recorded

11528/11 : DRUMMORE RBT TO SHAWHEAD ROADEND JUNCTION

Detailed Inspection TEMPLATE of A75 M Detail on 16 August 2017

SW86-282923-100	3,106m	2,306m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-282923-102	1,826m	1,626m	WOODLAND	Injurious weeds (IWED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-282923-17	243m	253m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-282923-19	988m	1,288m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-282923-21	1,584m	1,684m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-282923-104	886m	876m	WOODLAND	Injurious weeds (IWED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-282923-23	2,106m	2,606m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-282923-24	2,655m	2,705m	WOODLAND	Injurious weeds (IWED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-282923-20	1,201m	1,401m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-282923-101	2,161m	2,151m	WOODLAND	Injurious weeds (IWED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-282923-103	1,439m	1,339m	WOODLAND	Injurious weeds (IWED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-282923-16	50m	60m	WOODLAND	Invasive species (INVS)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-282923-22	1,920m	1,960m	WOODLAND	Injurious weeds (IWED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW86-282923-18	591m	601m	WOODLAND	Injurious weeds (IWED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999

Detailed Inspection TEMPLATE of A75 M Detail on 28 May 2018

SW81-332075-59	1,291m	1,340m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-61	1,369m	1,369m	CARRIAGEWAY	Localised cracking	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999

				(LOCK)					
SW81-332075-75	2,675m	2,706m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-78	2,812m	2,853m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-72	2,450m	2,459m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-49	279m	286m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-55	972m	980m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-57	1,249m	1,279m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-80	2,917m	2,923m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-70	2,239m	2,315m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-51	785m	787m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-52	824m	850m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-45	159m	162m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-46	214m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-56	1,249m	1,279m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-63	1,541m	1,591m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-67	1,755m	1,790m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-73	2,590m	2,621m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-81	2,915m	2,923m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-48	248m	253m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-60	1,370m	1,470m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-62	1,542m	1,592m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-76	2,734m	2,769m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW81-332075-79	2,893m	0m	TRAFFIC_SIGNS	Physical condition of	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	

SW81-332075-71	2,272m	2,296m	CARRIAGEWAY	post (COPT) Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-77	2,780m	2,845m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-64	1,641m	1,667m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-66	1,756m	1,766m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-53	826m	845m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-74	2,639m	2,645m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-50	731m	768m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-54	955m	975m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-68	2,020m	2,041m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-44	135m	165m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-58	1,290m	1,340m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-65	1,721m	1,743m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-47	223m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW81-332075-69	2,086m	2,101m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999

Annual Detailed Inspection - Carriageways of A75 M Detail

No defects recorded

CR Detailed Inspection - Carriageways of A75 M Detail

No defects recorded

11528/04 : DRUMMORE ROUNDABOUT

Detailed Inspection TEMPLATE of A75 M Detail on 16 August 2017

No defects recorded

Detailed Inspection TEMPLATE of A75 M Detail on 28 May 2018

SW81-332075-43	43m	115m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
----------------	-----	------	-------------	---------------------------	-------	------------	-----------------------	------------

Annual Detailed Inspection - Carriageways of A75 M Detail

No defects recorded

CR Detailed Inspection - Carriageways of A75 M Detail

No defects recorded