Contract	Inventory numb	Strin nlan	Route	Species
SE	-	A1 Sheet 2 W3	A1	Deer
SE		A1 Sheet 2 W3 A1 Sheet 4 W1	A1 A1	N/A
SE		A1 Sheet 4 W2	A1 A1	Rabbit
SE		A1 Sheet 5 W3	A1	N/A Dabbit
SE	-	A1 Sheet 6 W1	A1	Rabbit
SE		A1 Sheet 6 W2	A1	Rabbit
SE		A1 Sheet 7 W3	A1	Rabbit
SE		A1 Sheet 16 W1	A1	General
SE		A7 Sheet 2 W1	A7	N/A
SE		A7 Sheet 3 W3	A7	Deer
SE		A7 Sheet 26 W2	A7	Deer
SE	12	A7 Sheet 27 W2	A7	Deer
SE			A7	Bat
SE			A7	Bat
SE	13	A702 Sheet 13 W3	A702	N/A
SE			A876	Otter
SE			A876	Otter
SE	-	-	A876	Otter
SE			A876	N/A
SE			A876	N/A
SE			A876	Mammal
SE	14	A6091 Sheet 1 W2	A6091	Badger
SE	15	A6091 Sheet 3 W2	A6091	Badger
SE	16	A6091 Sheet 4 W1	A6091	Badger
SE	17	M8 Sheet 16 W1	M8	Badger
SE	18	M8 Sheet 16 W2	M8	Badger
SE	19	M8 Sheet 16 W2	M8	Badger
SE	20	M8 Sheet 16 W2	M8	Badger
SE	21	M8 Sheet 16 W2	M8	Newt
SE	22	M8 Sheet 16 W3	M8	Badger
SE	23	M8 Sheet 16 W3	M8	Badger
SE	24	M8 Sheet 17 W3	M8	Badger
SE			A985	Bird
FB			A90	Bird
				Mammal
				fencing
				(deer,
				otter,
	25	CO21000101/0300/060-062	M8	badger)
			M8	Badger
			M8	Otter
		CO21000101-3500-060 Rev A	M8	Bat
			M8	Mammal

Wildlife Mitigation	Date	Co-ordinates	Licence? Y/N
3 fences: A. Post/wire B. Deer fen	c: Unknown	NT 371714 - ???	n
Chain link fence around wet wood	la Unknown	NT 398736 - NT 402737n	
Rabbit fence	Unknown	NT 404474 - NT 40773	88 n
Recently planted saplings in fence	d Unknown	NT 441730 - NT 44273	8C n
Same woodland behind rabbit fend	ciı Unknown	NT 447732	n
Rabbit fence	Unknown	NT 456734	n
Rabbit fence	Unknown	NT 486738	n
Wildlife tunnel	Unknown	NT 677773	n
New saplings in tubes	Unknown	NY 390756	n
Wildlife mitigation deer warning signal	gı Unknown	NY 375795	n
Wildlife mitigation deer warning signal	gı Unknown	NT 470252	n
Wildlife mitigation deer warning signal	gı Unknown	NT 476274	n
Bat boxes (1)		2016 NY 37076 83382	у
Bat boxes (6)		2016 NT 48831 32204	у
Balancing pond with surrounding p	oc Unknown	NT 108474	n
Otter ledge	circa 2008	NS 92195 89401	
Otter ledge	circa 2008	NS 92118 89087	
Otter ledge	circa 2008	NS 92038 89065	
SUDs	circa 2008	NS 92288 89485	
SUDs	circa 2008	NS 92166 89373	
Mammal fencing	circa 2008	various around A876	
Badger tunnel	Unknown	NT 518342	n
Badger tunnel	Unknown	NT 562340	n
Badger tunnel	Unknown	NT 576338	n
Badger tunnel	Unknown	NT 125712 - NT 12571	.1n
Badger fencing	Unknown	NT 131712	n
Badger tunnel	Unknown	NT 131712	n
Badger tunnel	Unknown	NT 134713	n
Newt conservation area	Unknown	NT 130711	n
Badger fencing	Unknown	NT 138716	n
Badger fencing	Unknown	NT 138715	n
Badger tunnel	Unknown	NT 155713	n
Marine Licence		2016 NS 92230 86993	У
Marine Licence		2015 NT 12550 80099	У

Mammal fencing	2016-2017	N
Badger tunnel	2015-2017	N
otter ledge	2015-2017	N
boxes	2015-2017	Y
Green overpass	2015-2017	N

Comments

"investigate wet woodland ownership"

Bat box erected for temporary closure of roost entrance. Main entrance was left open. 100+ daubentons b Bat boxes erected as compensation measures for confirmed roosts in trees that required removal. 1 hibern

Mitigation installed for the construction of Clackmannanshire Bridge Mitigation installed for the construction of Clackmannanshire Bridge

Marine licence for works on Kincardine Bridge. Stipulates conditions for works on the bridge during winterin Marine licence for works on Forth Road Bridge (within 400m of Long Craig Island). Stipulates conditions fo

mitiigation for the design and construction of M8 M73 M74 project mitiigation for the design and construction of M8 M73 M74 project mitiigation for the design and construction of M8 M73 M74 project mitiigation for the design and construction of M8 M73 M74 project mitiigation for the design and construction of M8 M73 M74 project at, maternity roost (and likely hibernation) ating bat identified. Mitigtaion has been highly successful from subsequent monitoring

ng bird season (Firth of Forth SPA) regarding noise levels. r works on the bridge during breeding terns regarding noise levels (Forth Islands SPA).