

# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 31/01/2015 and 07/01/2017, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'JUNCTION NETHER YETT TO DANCINGKNOWE ROUNDABOUT',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>11519/70 : JUNCTION NETHER YETT TO DANCINGKNOWE ROUNDABOUT</b>									
<b>Detailed Inspection TEMPLATE of A75 E Detail on 24 August 2015</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection TEMPLATE of A75 E Detail on 22 August 2016</b>									
SW86177250-3	242m	442m	WOODLAND	<i>Invasive species (INVS)</i>	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86177250-73	26m	36m	WOODLAND	<i>Invasive species (INVS)</i>	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	



# Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 31/01/2015 and 31/01/2017, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'END OF HATCHING TO JUNCTION NETHER YETT',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<b>11519/39 : END OF HATCHING TO JUNCTION NETHER YETT</b>									
<b>Detailed Inspection TEMPLATE of A75 E Detail on 24 August 2015</b>									
SW86121442-65	753m	763m	WOODLAND	Injurious weeds (IWED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86121442-51	221m	226m	WOODLAND	Injurious weeds (IWED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
<b>Annual Detailed Inspection - Carriageways of A75 E Detail ( Partially Completed )</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection - All other Footways of A75 E Detail ( Partially Completed )</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection - All signs of A75 E Detail ( Partially Completed )</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection - Gully, Catchpit, Manhole etc of A75 E Detail ( Partially Completed )</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection - Kerbs, Channels, Edgings of A75 E Detail ( Partially Completed )</b>									
<i>No defects recorded</i>									
<b>Detailed Inspection TEMPLATE of A75 E Detail ( Awaiting Return )</b>									
SW6085829-412	20m	55m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A75 End hatching - Nether Yett JCT
SW6085829-414	83m	120m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A75 End hatching - Nether Yett JCT
SW6085829-416	144m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A75 End hatching - Nether Yett JCT
SW6085829-415	117m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A75 End hatching - Nether Yett JCT
SW6085829-418	410m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A75 End hatching - Nether Yett JCT
SW6085829-413	66m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A75 End hatching - Nether Yett JCT
SW6085829-417	300m	0m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A75 End hatching - Nether Yett JCT
<b>Detailed Inspection TEMPLATE of A75 E Detail on 22 August 2016</b>									
SW86177250-74	159m	179m	WOODLAND	Injurious weeds (IWED)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	

