

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/06/2016 and 19/07/2017, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'LENDALFOOT BRIDGE TO ARDMILLAN CASTLE',) Or

(Section is 'ARDMILLAN CASTLE TO A714 SHALLOCHPARK ROUNDABOUT',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
11617/05 : LENDALFOOT BRIDGE TO ARDMILLAN CASTLE									
Safety Inspection of A77 Ayr South V1 on 02 June 2016									
SW82159540-1965601	1,932m	1,938m	CARRIAGEWAY	Failed repair (RFAL)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A77 N/B C/W 200M AFTER START OF STRAID PASS NORTH OF LENDALFOOT
Safety Inspection of A77 Ayr South V1 on 09 June 2016									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 16 June 2016									
SW82165394-2018586	383m	385m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	17/06/2016	Completed Defects	16/06/2016	A77 N/B C/W 600M NORTH OF LENDALFOOT
Safety Inspection of A77 Ayr South V1 on 23 June 2016									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 30 June 2016									
SW82170640-2041265	700m	701m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/07/2016	Completed Defects	30/06/2016	A77 BOTH C/W 700M NORTH OF LENDALFOOT
Safety Inspection of A77 Ayr South V1 on 07 July 2016									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 14 July 2016									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 21 July 2016									
SW82175251-2086652	2,609m	2,610m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/07/2016	Completed Defects	21/07/2016	A 77 S/B C/W AT START OF STRAID PASS
Safety Inspection of A77 Ayr South V1 on 28 July 2016									
SW82176377-2089998	1,590m	1,591m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/07/2016	Completed Defects	28/07/2016	A77 S/B C/W AT END OF STRAID PASS NORTH OF LENDALFOOT
Safety Inspection of A77 Ayr South V1 on 04 August 2016									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 11 August 2016									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 18 August 2016									
SW101-180342-2112849	3,042m	3,043m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	19/08/2016	Completed Defects	18/08/2016	A77 S/B BETWEEN KENNEDYS PASS AND STRAID PASS
Safety Inspection of A77 Ayr South V1 on 25 August 2016									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 02 September 2016									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 08 September 2016									
SW82183624-2197782	4,727m	4,728m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/10/2016	Completed Defects	03/10/2016	A77 S/B C/W 600M SOUTH OF ARDWELL FARM SOUTH OF GIRVAN
SW82183624-2197784	3,314m	3,314m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 1	06/10/2016	Completed Defects	26/09/2016	A77 N/B VERGE 300M SOUTH OF KENNEDYS PASS
Safety Inspection of A77 Ayr South V1 on 15 September 2016									
SW82186195-2204204	1,841m	1,843m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/10/2016	Completed Defects	24/10/2016	A77 N/B C/W 200M NORTH OF START STRAID PASS NORTH OF LENDALFOOT
Safety Inspection of A77 Ayr South V1 on 22 September 2016									

No defects recorded

Safety Inspection of A77 Ayr South V1 on 29 September 2016

No defects recorded

Safety Inspection of A77 Ayr South V1 on 06 October 2016

SW82194048-2246769	1,074m	1,074m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A77 N/B AT LAYBY SOUTH OF STRAID PASS
--------------------	--------	--------	---------------	----------------	-------	------------	-----------------------	------------	---------------------------------------

Safety Inspection of A77 Ayr South V1 on 13 October 2016

No defects recorded

Safety Inspection of A77 Ayr South V1 on 20 October 2016

No defects recorded

Safety Inspection of A77 Ayr South V1 on 27 October 2016

No defects recorded

Safety Inspection of A77 Ayr South V1 on 03 November 2016

No defects recorded

Safety Inspection of A77 Ayr South V1 on 10 November 2016

No defects recorded

Safety Inspection of A77 Ayr South V1 on 17 November 2016

SW82210827-2346897	3,944m	3,946m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/11/2016	Completed Defects	17/11/2016	A77 S/B AT START OF KENNEDYS PASS S/B CW
--------------------	--------	--------	-------------	-----------------------	-------	------------	-------------------	------------	--

Safety Inspection of A77 Ayr South V1 on 24 November 2016

No defects recorded

Safety Inspection of A77 Ayr South V1 on 01 December 2016

No defects recorded

Safety Inspection of A77 Ayr South V1 on 08 December 2016

No defects recorded

Safety Inspection of A77 Ayr South V1 on 15 December 2016

SW82222009-2375545	1,588m	1,589m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/12/2016	Completed Defects	15/12/2016	A77 S/B CW AT THE SOUTNSIDE OF STRAID PASS JUST BEFORE GATEWAY TO OLD QUARRY COA H ROAD
--------------------	--------	--------	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 22 December 2016

SW82224893-2389942	1,664m	1,666m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/12/2016	Completed Defects	22/12/2016	A77 VARIOUSE POTHOLES STRAID PASS
--------------------	--------	--------	-------------	-----------------------	-------	------------	-------------------	------------	-----------------------------------

Safety Inspection of A77 Ayr South V1 on 29 December 2016

No defects recorded

Safety Inspection of A77 Ayr South V1 on 05 January 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 12 January 2017

SW82233666-235030707	3,401m	3,402m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/01/2017	Completed Defects	12/01/2017	southbound carriageway at southside of kennedys pass opposite average speed camera sign
----------------------	--------	--------	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 19 January 2017

SW82236609-235030704	2,943m	2,944m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/01/2017	Completed Defects	19/01/2017	A77 S/B CW 150M NORTH OF STRAID PASS
----------------------	--------	--------	-------------	-----------------------	-------	------------	-------------------	------------	--------------------------------------

Safety Inspection of A77 Ayr South V1 on 26 January 2017

SW82239492-235030701	2,634m	2,635m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	27/01/2017	Completed Defects	26/01/2017	between kennedys pass and straid pass nb cw
----------------------	--------	--------	-------------	-----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 02 February 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 09 February 2017

SW82243019-235053110	1,604m	1,605m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2017	Completed Defects	04/03/2017	A77 S/B CW 20N NORTH OF OLD QUARRY AT START OF STRAID PASS
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

SW82243019-235053111	1,969m	1,970m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2017	Completed Defects	04/03/2017	A77 N/B CW 150M AFTER START OF STRAID PASS
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	--

SW82243019-235053112	2,946m	2,947m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2017	Completed Defects	04/03/2017	A77 S/B CW BETWEEN STAID PASS AND KENNEDYS PASS
----------------------	--------	--------	-------------	----------------	-------	------------	-------------------	------------	---

Safety Inspection of A77 Ayr South V1 on 16 February 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 23 February 2017

SW82246218-235058648	1,967m	0m	CARRIAGEWAY	Pothole	CAT 1	23/03/2017	Completed	13/03/2017	A77 SYRAID PASS BETWEEN
----------------------	--------	----	-------------	---------	-------	------------	-----------	------------	-------------------------

				(POTH)			Defects		GIRVAN AND LENDALFOOT SIB CW 3 X POTHLES
Safety Inspection of A77 Ayr South V1 on 02 March 2017									
SW82248242-235062032	346m	346m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 1	30/03/2017	Completed Defects	12/04/2017	A77 S/B VERGE 300M NORTH OF LENDELFOOT
Safety Inspection of A77 Ayr South V1 on 09 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 16 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 23 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 30 March 2017									
SW82256306-235075167	5,165m	5,167m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/04/2017	Completed Defects	21/04/2017	A77 N/B C/W OPPOSITE ARDWELL FARM SOUTH OF GIRVAN
Safety Inspection of A77 Ayr South V1 on 06 April 2017									
SW82258945-235075799	593m	600m	CARRIAGEWAY	Surfacing joints (SRJT)	CAT 1	04/05/2017	Completed Defects	03/05/2017	A77 ON CENTRE LINE 500M NORTH OF LENDELFOOT
Safety Inspection of A77 Ayr South V1 on 13 April 2017									
SW82261042-235087337	2,963m	2,854m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/05/2017	Completed Defects	28/04/2017	A77 S/B C/W ON STRAIGHT BETWEEN STRAID PASS AND KENNEDYS PASS . . SOUTH OF GIRVAN . (300M PRIOR TO CLOSURE FOR LAND SLIP)
Safety Inspection of A77 Ayr South V1 on 20 April 2017									
SW82262993-235096952	2,895m	2,897m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/05/2017	Completed Defects	07/06/2017	A77 NORTHBOUND 400M SOUTH OF KENNEDYS PASS NEAR LAND SLIP
SW82262993-235096951	2,848m	2,850m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/05/2017	Completed Defects	07/06/2017	A77 NORTHBOUND 500M SOUTH OF KENNEDYS PASS NEAR LAND SLIP
Safety Inspection of A77 Ayr South V1 on 27 April 2017									
SW82265290-235124675	4,170m	4,171m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/05/2017	Completed Defects	23/05/2017	A77 STH BD CW JUST AFTER AVG SPEED CAMERA SIGN BEFORE KENNEDYS PASS
SW82265290-235124676	239m	240m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/05/2017	Completed Defects	19/05/2017	A77 CENTER LINE 170M NTH OF LENDALFOOT
Safety Inspection of A77 Ayr South V1 on 04 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 11 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 18 May 2017									
SW82273879-235161148	2,638m	2,639m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/06/2017	Completed Defects	14/06/2017	A77 NB CW AT TRAFFIC LIGHTS, STRAID PASS STH OF KENNEDYS PASS
SW82273879-235161150	2,597m	2,598m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/06/2017	Completed Defects	14/06/2017	A77 NB CW AT STH START OF TRAFFIC LIGHTS AT STRAID PASS STH OF KENNEDYS PASS
SW82273879-235161149	2,614m	2,615m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/06/2017	Completed Defects	14/06/2017	A77 NB CW AT TRAFFIC LIGHT JCT STRAID PASS STH OF KENNEDYS PASS
Safety Inspection of A77 Ayr South V1 on 25 May 2017									
SW82277052-235163152	1,523m	1,524m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/06/2017	Completed Defects	20/06/2017	A77 ON CENTRE LINE AT START OF STRAID PASS NORTH OF LENDELFOOT
SW82277052-235163153	3,096m	3,098m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/06/2017	Completed Defects	13/06/2017	A77 N/B C/W AT END OF STRAIGHT BETWEEN STRAID PASS AND KENNEDYS PASS NORTH OF LENDELFOOT
Safety Inspection of A77 Ayr South V1 on 01 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A77 Ayr South V1 on 08 June 2017									
<i>No defects recorded</i>									

Safety Inspection of A77 Ayr South V1 on 15 June 2017*No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 June 2017***No defects recorded***Safety Inspection of A77 Ayr South V1 on 29 June 2017**

SW82281701-235240864	2,245m	2,248m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/07/2017	Awaiting CCMS Permanent	01/01/9999	A77 NB CW 20M NTH OF LAYBY, STH OF TRAFFIC LIGHTS STRAIDS PASS
SW82281701-235240866	2,969m	2,972m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/07/2017	Awaiting CCMS Permanent	01/01/9999	A77 NB CW 350M NTH OF STRAIDS PASS TRAFFIC LIGHTS
SW82281701-235240867	2,987m	2,988m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/07/2017	Awaiting CCMS Permanent	01/01/9999	A77 NB CW 360M NTH OF STRAIDS PASS TRAFFIC LIGHTS
SW82281701-235240865	3,041m	3,042m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/07/2017	Awaiting CCMS Permanent	01/01/9999	A7 NB CW 400M NTH OF TRAFFIC LIGHTS AT STRAIDS PASS, AT SIGN POLE
SW82281701-235240863	2,220m	2,223m	CARRIAGEWAY	Pothole (POTH)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A77 NB CW 10M NTH OF LAYBY, STH OF TRAFFIC LIGHTS AT STRAIDS PASS

Safety Inspection of A77 Ayr South V1 on 06 July 2017*No defects recorded***Safety Inspection of A77 Ayr South V1 on 13 July 2017***No defects recorded***11617/73 : ARDMILLAN CASTLE TO A714 SHALLOCHPARK ROUNDABOUT****Safety Inspection of A77 Ayr South V1 on 02 June 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 09 June 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 16 June 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 23 June 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 30 June 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 07 July 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 14 July 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 21 July 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 28 July 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 04 August 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 11 August 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 18 August 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 25 August 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 02 September 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 08 September 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 15 September 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 22 September 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 29 September 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 06 October 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 13 October 2016***No defects recorded***Safety Inspection of A77 Ayr South V1 on 20 October 2016**

No defects recorded
Safety Inspection of A77 Ayr South V1 on 27 October 2016
No defects recorded
Safety Inspection of A77 Ayr South V1 on 03 November 2016
No defects recorded
Safety Inspection of A77 Ayr South V1 on 10 November 2016
No defects recorded
Safety Inspection of A77 Ayr South V1 on 17 November 2016
No defects recorded
Safety Inspection of A77 Ayr South V1 on 24 November 2016
No defects recorded
Safety Inspection of A77 Ayr South V1 on 01 December 2016
No defects recorded
Safety Inspection of A77 Ayr South V1 on 08 December 2016
No defects recorded
Safety Inspection of A77 Ayr South V1 on 15 December 2016
No defects recorded
Safety Inspection of A77 Ayr South V1 on 22 December 2016
No defects recorded
Safety Inspection of A77 Ayr South V1 on 29 December 2016
No defects recorded
Safety Inspection of A77 Ayr South V1 on 05 January 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 12 January 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 19 January 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 26 January 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 02 February 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 09 February 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 16 February 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 23 February 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 02 March 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 09 March 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 16 March 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 23 March 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 30 March 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 06 April 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 13 April 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 20 April 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 27 April 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 04 May 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 11 May 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 18 May 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 25 May 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 01 June 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 08 June 2017
No defects recorded
Safety Inspection of A77 Ayr South V1 on 15 June 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 22 June 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 29 June 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 06 July 2017

No defects recorded

Safety Inspection of A77 Ayr South V1 on 13 July 2017

No defects recorded