

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 15/11/2015 and 22/08/2017, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'SPEED DERESTRICTION TO JCT B777 WARDROP STREET',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
14355/27 : SPEED DERESTRICTION TO JCT B777 WARDROP STREET									
Safety Inspection of A737 & A738 Westway V1 on 16 November 2015									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 23 November 2015									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 30 November 2015									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 07 December 2015									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 14 December 2015									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 21 December 2015									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 28 December 2015									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 04 January 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 11 January 2016									
SW85132835-1663735	124m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	08/02/2016	Completed Defects	21/01/2016	A737 BEITH BETWEEN 100 AND 200 YARD COUNTDOWN MARKERS
Safety Inspection of A737 & A738 Westway V1 on 18 January 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 25 January 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 01 February 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 08 February 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 15 February 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 22 February 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 29 February 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 07 March 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 14 March 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 21 March 2016									
<i>No defects recorded</i>									
Safety Inspection of Westway - A737 & A738 on 24 March 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 26 March 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 28 March 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 04 April 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 11 April 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 18 April 2016									
<i>No defects recorded</i>									
Safety Inspection of A737 & A738 Westway V1 on 25 April 2016									
<i>No defects recorded</i>									

Safety Inspection of A737 & A738 Westway V1 on 02 May 2016*No defects recorded***Safety Inspection of A737 & A738 Westway V1 on 09 May 2016***No defects recorded***Safety Inspection of A737 & A738 Westway V1 on 16 May 2016***No defects recorded***Safety Inspection of A737 & A738 Westway V1 on 23 May 2016**

SW85156054-1950823	798m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/05/2016	Completed Defects	23/05/2016	A737 W/B AT JCT B777
SW85156054-1950819	577m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/05/2016	Completed Defects	23/05/2016	A737 E/B 60M AFTER BP GARAGE BEITH
SW85156054-1950822	758m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	24/05/2016	Completed Defects	23/05/2016	A737 W/B AT JCT B777 BEITH

Safety Inspection of A737 & A738 Westway V1 on 30 May 2016*No defects recorded***Detailed Inspection TEMPLATE of A737 Detail on 01 June 2016**

SW86159635-78	116m	118m	WOODLAND	Obscured sign (OBSG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW86159635-56	26m	28m	WOODLAND	Obscured sign (OBSG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	

Safety Inspection of A737 & A738 Westway V1 on 06 June 2016*No defects recorded***Safety Inspection of A737 & A738 Westway V1 on 13 June 2016***No defects recorded***Safety Inspection of A737 & A738 Westway V1 on 20 June 2016***No defects recorded***Detailed Inspection TEMPLATE of A737 Detail on 06 May 2016**

SW80143087-266	82m	108m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW80143087-269	677m	713m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW80143087-270	718m	740m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW80143087-265	78m	100m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW80143087-268	288m	310m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW80143087-264	57m	75m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	
SW80143087-267	124m	139m	CARRIAGEWAY	Localised cracking (LOCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	

Detailed Inspection - All other Footways of A737 Detail*No defects recorded***Detailed Inspection - All signs of A737 Detail***No defects recorded***Detailed Inspection - Gully, Catchpit, Manhole etc of A737 Detail***No defects recorded***Detailed Inspection - Kerbs, Channels, Edgings of A737 Detail***No defects recorded***CR Detailed Inspection - Carriageways of A737 Detail***No defects recorded***Safety Inspection of A737 & A738 Westway V1 on 27 June 2016***No defects recorded***Safety Inspection of A737 & A738 Westway V1 on 04 July 2016***No defects recorded***Safety Inspection of A737 & A738 Westway V1 on 11 July 2016**

No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 18 July 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 25 July 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 01 August 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 08 August 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 15 August 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 22 August 2016
 SW85180947-2134471 633m 0m TRAFFIC_SIGNS Obscured sign (OBSG) CAT 1 23/08/2016 Completed Defects 22/08/2016

Safety Inspection of A737 & A738 Westway V1 on 29 August 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 05 September 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 12 September 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 19 September 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 26 September 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 03 October 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 10 October 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 17 October 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 24 October 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 31 October 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 07 November 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 14 November 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 21 November 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 28 November 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 05 December 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 12 December 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 19 December 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 23 December 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 29 December 2016
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 05 January 2017
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 09 January 2017
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 16 January 2017
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 23 January 2017
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 30 January 2017
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 06 February 2017
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 13 February 2017
 No defects recorded
Safety Inspection of A737 & A738 Westway V1 on 20 February 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 27 February 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 06 March 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 13 March 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 20 March 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 27 March 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 03 April 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 10 April 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 17 April 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 24 April 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 28 April 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 05 May 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 08 May 2017

SW77269798-235150411	244m	244m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	09/05/2017	Completed Defects	08/05/2017	A737 WB BEITH GATEWAY
----------------------	------	------	---------------	----------------------	-------	------------	-------------------	------------	-----------------------

Detailed Inspection - All other Footways of A737 Detail

No defects recorded

Detailed Inspection - All signs of A737 Detail

No defects recorded

Detailed Inspection - Gully, Catchpit, Manhole etc of A737 Detail

No defects recorded

Detailed Inspection - Kerbs, Channels, Edgings of A737 Detail

No defects recorded

Detailed Inspection TEMPLATE of A737 Detail on 08 May 2017

SW77257612-110	743m	743m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW77257612-55	281m	281m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW77257612-56	395m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999
SW77257612-111	101m	101m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999

Safety Inspection of A737 & A738 Westway V1 on 15 May 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 22 May 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 29 May 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 05 June 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 12 June 2017

SW77279772-235193451	78m	78m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	10/07/2017	Completed Defects	28/06/2017	A737 EB SPEED RESTRICTION SIGNS @ BEITH
----------------------	-----	-----	---------------	----------------------	-------	------------	-------------------	------------	---

Safety Inspection of A737 & A738 Westway V1 on 19 June 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 26 June 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 03 July 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 10 July 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 17 July 2017

No defects recorded

Detailed Inspection TEMPLATE of A737 Detail on 07 July 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 24 July 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 31 July 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 07 August 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 14 August 2017

No defects recorded

Safety Inspection of A737 & A738 Westway V1 on 21 August 2017

No defects recorded

Maintenance Unit: SW
Item number: SW161018

Week Commencing: 06/06/16
Version: 2

Primary Route: A737
Start Link: 70 2 2 - LIN A737 B777 Beith - B707 Dalry (N)
End Link: 70 2 2 - LIN A737 B777 Beith - B707 Dalry (N)
Exact Location: Beith
Direction: EAST AND WEST

Start Date: 07/06/16 **End Date:** 08/06/16
Start Time: 22:00 **End Time:** 06:00

M	T	W	T	F	S	S	M	When
X								Each Night

Description:

2 Way Lights for Railbridge safety inspection
 LA Reference: 2072034

Traffic Management: Coneworx **Estimated Delay:** 1/3
Main Contractor: Amey Consulting **Closure Type:** B (N/A)
Second Users: **STLO Name:**
Diversion: no **STLO Phone:**

[Back]

Maintenance Unit: SW
Item number: SW161539

Week Commencing: 13/06/16
Version: 2

Primary Route: A737
Start Link: 70 2 1 - LIN A737 Lochwinnoch - B777 Beith
End Link: 70 2 1 - LIN A737 Lochwinnoch - B777 Beith
Exact Location: Beith
Direction: WESTBOUND

Start Date: 14/06/16 **End Date:** 15/06/16
Start Time: 09:30 **End Time:** 15:30

M	T	W	T	F	S	S	M	When
X								Each Day

Description:

Temporary Traffic Control on the A737 Beith between Bigholm Road and B777 Jct

For carriageway repairs

Traffic Management: Scotland
TranServ

Estimated Delay: 1/3

Main Contractor: Scotland
TranServ

Closure Type: B (N/A)

Second Users:

STLO Name:

Diversion: no

STLO Phone:

[Back]

Maintenance Unit: SW
Item number: SW161753

Week Commencing: 18/07/16
Version: 2

Primary Route: A737

Start Link: 70 2 2 - LIN A737 B777 Beith - B707 Dalry (N)

End Link: 70 2 2 - LIN A737 B777 Beith - B707 Dalry (N)

Exact Location: Beith

Direction: EAST AND WEST

Start Date: 20/07/16

End Date: 23/07/16

Start Time: 20:00

End Time: 06:00

M	T	W	T	F	S	S	M	When
		X	X	X				Each Night

Description:

Total road closure between Roebank Rd and Manrahead Rbt.
 No access to / from B706
 Local access WB maintained to Wardrop St / Head St
 Local access EB maintained Geilsland Rd – Roebank Rd

Diversion:

A737 WB traffic leave A737 at Roebank Rd and follow Wilson St – B7049 – rejoin A737 at Manrahead Rbt

A737 EB traffic leave at Manrahead Rbt and follow reverse of above.

Works:

Carriageway resurfacing

Traffic Management: Scotland
TranServ

Estimated Delay: 2/3

Main Contractor: Aggregate
Industries

Closure Type: B (N/A)

Second Users:

STLO Name:

Diversion: yes

STLO Phone:

[Back]

Maintenance Unit: SW
Item number: SW161835

Week Commencing: 25/07/16
Version: 1

Primary Route: A737
Start Link: 70 2 1 - LIN A737 Lochwinnoch - B777 Beith
End Link: 70 2 1 - LIN A737 Lochwinnoch - B777 Beith
Exact Location: Beith By-pass
Direction: EAST AND WEST

Start Date: 26/07/16 **End Date:** 26/07/16
Start Time: 09:30 **End Time:** 15:30

M	T	W	T	F	S	S	M	When
X								Each Day

Description:

Four way Traffic Control on the A737 at Gateside Avenue, Beith Bypass

For kerbing repairs
 LA2122345

Traffic Management: Scotland
 TranServ

Estimated Delay: 1/3

Main Contractor: Scotland
 TranServ

Closure Type: B (N/A)

Second Users:

STLO Name:

Diversion: no

STLO Phone:

[Back]

Maintenance Unit: SW
Item number: SW162027

Week Commencing: 08/08/16
Version: 1

Primary Route: A737

Start Link: 70 2 2 - LIN A737 B777 Beith - B707 Dalry (N)

End Link: 70 2 2 - LIN A737 B777 Beith - B707 Dalry (N)

Exact Location: Beith

Direction: EAST AND WEST

Start Date: 10/08/16

End Date: 11/08/16

Start Time: 20:00

End Time: 06:00

M	T	W	T	F	S	S	M	When
		X						Each Night

Description:

Total road closure between Roebank Rd and Manrahead Rbt.
 Local access SB maintained to B706
 Local access NB maintained B706 – Roebank Rd

Diversion:

A737 SB traffic leave A737 at Roebank Rd and follow Wilson St – B7049 – rejoin A737 at Manrahead Rbt

A737 NB traffic leave at Manrahead Rbt and follow reverse of above.

Works:

Carriageway resurfacing
 LA2134483

Traffic Management: Scotland
 TranServ

Estimated Delay: 2/3

Main Contractor: Aggregate
 Industries

Closure Type: B (N/A)

Second Users:

STLO Name:

Diversion: yes

STLO Phone:

[Back]

Maintenance Unit: SW
Item number: SW162337

Week Commencing: 03/10/16
Version: 1

Primary Route: A737
Start Link: 70 2 1 - LIN A737 Lochwinnoch - B777 Beith
End Link: 70 2 1 - LIN A737 Lochwinnoch - B777 Beith
Exact Location: B777 Jct
Direction: WESTBOUND

Start Date: 03/10/16 **End Date:** 06/10/16
Start Time: 09:30 **End Time:** 15:30

M	T	W	T	F	S	S	M	When
X	X	X	X					Each Day

Description:

3 way set of lights to accommodate the resurfacing of B777
A737 @ Junction with B777 Wardrop St by North Ayrshire Council

Traffic Management: Central Traffic Management **Estimated Delay:** 1/3
Main Contractor: North Ayrshire Council **Closure Type:** B (N/A)
Second Users: **STLO Name:**
Diversion: no **STLO Phone:**

[Back]

Maintenance Unit: SW
Item number: SW162545

Week Commencing: 17/10/16
Version: 2

Primary Route: A737
Start Link: 70 2 1 - LIN A737 Lochwinnoch - B777 Beith
End Link: 70 2 2 - LIN A737 B777 Beith - B707 Dalry (N)
Exact Location: Beith
Direction: EAST AND WEST

Start Date: 14/10/16 **End Date:** 18/10/16
Start Time: 07:00 **End Time:** 19:00

M	T	W	T	F	S	S	M	When
X	X							Continuously

Description:

4 way TTL for emergency Scottish Power works on Wardrop St Beith Jct
 Will be manually controlled at peak times

Traffic Management: Class 1 **Estimated Delay:** 2/3
Main Contractor: Morrison Utilities **Closure Type:** A (N/A)
Second Users: **STLO Name:**
Diversion: no **STLO Phone:**

[Back]

Maintenance Unit: SW
Item number: SW162545

Week Commencing: 10/10/16
Version: 1

Primary Route: A737
Start Link: 70 2 1 - LIN A737 Lochwinnoch - B777 Beith
End Link: 70 2 2 - LIN A737 B777 Beith - B707 Dalry (N)
Exact Location: Beith
Direction: EAST AND WEST

Start Date: 14/10/16 **End Date:** 21/10/16
Start Time: 07:00 **End Time:** 19:00

M	T	W	T	F	S	S	M	When
				X	X	X	X	Continuously

Description:

4 way TTL for emergency Scottish Power works on Wardrop St Beith Jct
 Will be manually controlled at peak times

Traffic Management: Class 1 **Estimated Delay:** 2/3
Main Contractor: Morrison Utilities **Closure Type:** A (N/A)
Second Users: **STLO Name:**
Diversion: no **STLO Phone:**

[Back]

Maintenance Unit: SW
Item number: SW16490

Week Commencing: 07/03/16
Version: 1

Primary Route: A737
Start Link: 70 1 5 - LIN A737 B787 Howwood - Lochwinnoch
End Link: 70 2 2 - LIN A737 B777 Beith - B707 Dalry (N)
Exact Location: Beith
Direction: EAST AND WEST

Start Date: 09/03/16 **End Date:** 11/03/16
Start Time: 20:00 **End Time:** 06:00

M	T	W	T	F	S	S	M	When
		X	X					Each Night

Description:

1. Total closure of the A737 E/B and W/B from Manrahead Rbt to the B777 Jct

Div a: Wilson St – B7079 – Manrahead Rbt
 Div b: B7079 - Wilson St – rejoin A737

For patching works

Traffic Management: Scotland
 TranServ

Estimated Delay: 1/3

Main Contractor: Scotland
 TranServ

Closure Type: B (N/A)

Second Users:

STLO Name:

Diversion: yes

STLO Phone:

[Back]

Maintenance Unit: SW
Item number: SW16490

Week Commencing: 07/03/16
Version: 1

Primary Route: A737

Start Link: 70 1 5 - LIN A737 B787 Howwood - Lochwinnoch

End Link: 70 2 2 - LIN A737 B777 Beith - B707 Dalry (N)

Exact Location: Beith

Direction: EAST AND WEST

Start Date: 09/03/16

End Date: 11/03/16

Start Time: 20:00

End Time: 06:00

M	T	W	T	F	S	S	M	When
		X	X					Each Night

Description:

1. Total closure of the A737 E/B and W/B from Manrahead Rbt to the B777 Jct

Div a: Wilson St – B7079 – Manrahead Rbt

Div b: B7079 - Wilson St – rejoin A737

For patching works

Traffic Management: Scotland
TranServ

Estimated Delay: 1/3

Main Contractor: Scotland
TranServ

Closure Type: B (N/A)

Second Users:

STLO Name:

Diversion: yes

STLO Phone:

[Back]

Maintenance Unit: SW
Item number: SW16736

Week Commencing: 04/04/16
Version: 2

Primary Route: A737
Start Link: 70 2 2 - LIN A737 B777 Beith - B707 Dalry (N)
End Link: 70 2 2 - LIN A737 B777 Beith - B707 Dalry (N)
Exact Location: Beith
Direction: WESTBOUND

Start Date: 07/04/16 **End Date:** 08/04/16
Start Time: 09:30 **End Time:** 15:00

M	T	W	T	F	S	S	M	When
			X	X				Each Day

Description:

Temporary traffic control on the A737 Beith Just south of the B777 Jct
 For sign and fence repairs

Traffic Management: Scotland
 TranServ

Estimated Delay: 1/3

Main Contractor: Scotland
 TranServ

Closure Type: B (N/A)

Second Users:

STLO Name:

Diversion: no

STLO Phone:

[Back]

Maintenance Unit: SW
Item number: SW16898

Week Commencing: 18/04/16
Version: 1

Primary Route: A737
Start Link: 70 2 1 - LIN A737 Lochwinnoch - B777 Beith
End Link: 70 2 2 - LIN A737 B777 Beith - B707 Dalry (N)
Exact Location: Beith
Direction: EAST AND WEST

Start Date: 19/04/16 **End Date:** 19/04/16
Start Time: 09:30 **End Time:** 15:30

M	T	W	T	F	S	S	M	When
X								Each Day

Description:

Temporary Traffic Light Control on the A737 within Beith North and South Gateways

For Carriageway Patching works

Traffic Management: Scotland
TranServ

Estimated Delay: 1/3

Main Contractor: Scotland
TranServ

Closure Type: B (N/A)

Second Users:

STLO Name:

Diversion: no

STLO Phone:

[Back]

Maintenance Unit: SW
Item number: SW17522

Week Commencing: 13/03/17
Version: 1

Primary Route: A737

Start Link: 70 2 1 - LIN A737 Lochwinnoch - B777 Beith

End Link: 70 2 1 - LIN A737 Lochwinnoch - B777 Beith

Exact Location: Beith Bypass

Direction: EAST AND WEST

Start Date: 13/03/17

End Date: 14/03/17

Start Time: 09:30

End Time: 16:00

M	T	W	T	F	S	S	M	When
X	X							Each Day

Description:

2-way progressive traffic control

Works:

Carriageway re-texturing works
 LA2237722

Traffic Management: Scotland
 TranServ

Estimated Delay: 1/3

Main Contractor: Scotland
 TranServ

Closure Type: B (N/A)

Second Users:

STLO Name:

Diversion: no

STLO Phone:

[Back]

Maintenance Unit: SW
Item number: SW17986

Week Commencing: 24/04/17
Version: 1

Primary Route: A737
Start Link: 70 2 2 - LIN A737 B777 Beith - B707 Dalry (N)
End Link: 70 2 2 - LIN A737 B777 Beith - B707 Dalry (N)
Exact Location: Beith
Direction: EAST AND WEST

Start Date: 24/04/17 **End Date:** 25/04/17
Start Time: 20:00 **End Time:** 06:00

M	T	W	T	F	S	S	M	When
X								Each Night

Description:

2 way traffic lights at Beith layby 300 yards south of Beith
 For sign and column replacement

Traffic Management: Scotland
 TranServ

Estimated Delay: 1/3

Main Contractor: Scotland
 TranServ

Closure Type: B (N/A)

Second Users:

STLO Name:

Diversion: no

STLO Phone:

[Back]

Roadworks: SW/2017/745, SW/2017/782, SW/2017/783, SW/2017/784 ... SW/2017/785


Operating Company Contract:


South West Unit - Transerv

A737 Beith to Howwood

Roadwork Identifier: SW/2017/745

Route:

 **Start:** A737 - Speed Derestriction Sign to B777 Jct (55.75482°, -4.62591°)

 **End:** A737 - End Dual Carriageway to Elliston Jct (55.80946°, -4.56412°)

Direction:

Northbound

SRWR Reference Number:

Not Specified

Diversion:

No Diversion

Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours

Works Periods:

Work Start	Work End	Traffic Management
21/08/2017 09:30	22/08/2017 15:30	Stop/Go Boards Traffic Control

Works Activities:

Works Activity Type	Contractors	Statuses
Utility Works	Renfrewshire Council (Primary) 	2 of 2 Not Completed.

Communication Logs:

Log Type	Details
Log Type: Note	Description: progressive stop & go works on single carriageway for litter picking and channel sweeping

Draft Media Release (optional):

A737 St James Int to Linwood w/b

Roadwork Identifier: SW/2017/782

Route:

 **Start:** M8 (55.85639°, -4.45123°)

 **End:** A737 (55.85313°, -4.46895°)

Direction:

Westbound

SRWR Reference Number:

Not Specified

Diversion:

No Diversion

Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours

Emergency Reason:

3rd Party/Utility defect

Works Periods:

Work Start	Work End	Traffic Management
15/08/2017 09:30	15/08/2017 15:30	Mobile Lane Closures

Works Activities:

Works Activity Type	Contractors	Statuses
Cyclic Maintenance	Renfrewshire Council (Primary) 	1 of 1 Completed.

Communication Logs:

Log Type	Details
----------	---------

There are no communications logs to display.

Draft Media Release (optional):

A737 St James Int to Linwood e/b

Roadwork Identifier: SW/2017/783

Route:

-  **Start:** A737 (55.85246°, -4.47181°)
-  **End:** A737 (55.85328°, -4.46902°)

Direction:

Eastbound

SRWR Reference Number:

Not Specified

Diversion:

No Diversion

Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours


Emergency Reason:

3rd Party/Utility defect

Works Periods:

Work Start	Work End	Traffic Management
18/08/2017 09:30	18/08/2017 15:30	Mobile Lane Closures

Works Activities:

Works Activity Type	Contractors	Statuses
Cyclic Maintenance	Renfrewshire Council (Primary) 	1 of 1 Completed.

Communication Logs:



Log Type	Details
There are no communications logs to display.	

Draft Media Release (optional):

A737 Linwood to Kilbarchan w/b

Roadwork Identifier: SW/2017/784

Route:

-  **Start:** A737 (55.84606°, -4.48224°)
-  **End:** A737 (55.83112°, -4.53580°)

Direction:
Westbound

SRWR Reference Number:
Not Specified

Diversion:
No Diversion


Estimated Delay:
1 - Little or No Delay, 3 - Off Peak Hours

Emergency Reason:
3rd Party/Utility defect

Works Periods:

Work Start	Work End	Traffic Management
16/08/2017 09:30	16/08/2017 15:30	Mobile Lane Closures

Works Activities:

Works Activity Type	Contractors	Statuses
Cyclic Maintenance	Renfrewshire Council (Primary) 	1 of 1 Completed.

Communication Logs:

Log Type	Details
There are no communications logs to display.	


Draft Media Release (optional):

A737 Linwood to Kilbarchan e/b

Roadwork Identifier: SW/2017/785

Route:

 **Start: A737** (55.83030°, -4.53614°)

 **End: A737** (55.84445°, -4.48635°)

Direction:

Eastbound

SRWR Reference Number:

Not Specified

Diversion:

No Diversion

Estimated Delay:

1 - Little or No Delay, 3 - Off Peak Hours

Emergency Reason:

3rd Party/Utility defect

Works Periods:

Work Start	Work End	Traffic Management
17/08/2017 09:30	17/08/2017 15:30	Mobile Lane Closures

Works Activities:

Works Activity Type	Contractors	Statuses
Cyclic Maintenance	Renfrewshire Council (Primary) 	1 of 1 Completed.

Communication Logs:

Log Type	Details
----------	---------

There are no communications logs to display.

Draft Media Release (optional):