Accident, Vehicle and Casualty Details

Accident Reference: 0000429

Date/Time: 07 January 2012

Severity: SLIGHT

Road/Link/Section/Chainage: A90 12225/08 (414m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
1	CAR (FOUR	NS	ON MAIN	NOT AT, OR WITHIN 20	GOING AHEAD	NO	NONE	NONE
	WHEELED)		CARRIAGEWAY	METRES OF, JUNCTION	OTHER	SKIDDING/JACK-KNIFIN		
						G		

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	DRIVER			SLIGHT

Contributory Factors

PASSING TOO CLOSE TO CYCLIST, HORSE RIDER, OR PEDESTRIAN (VERY LIKELY)

FATIGUE (VERY LIKELY)

Road/Link/Section/Chainage: A90 12240/95 (623m)

Date/Time: 29 January 2012

Junction Road Code: ?

Severity: SERIOUS

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned SKIDDED AND OVERTURNED	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class DRIVER	Sex	Age	Severity SLIGHT
1	VEHICLE OR PILLION PASSENGER			SERIOUS

Contributory Factors

TYRES ILLEGAL, DEFECTIVE OR UNDER INFLATED (VERY LIKELY)

Date/Time: 05 March 2012

Road/Link/Section/Chainage: A90 12276/70 (2,844m)

Junction Road Code: U

Severity: SLIGHT

Junction Location: CLEARED JUNCTION OR WAITING/PARKED AT JUNCTI

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Dark

Vehicle Details

Veh. No	Vehicle Type AGRICULTURAL VEHICLES	Direction W E	Location ON MAIN CARRIAGEWAY	Junction Location CLEARED JUNCTION OR WAITING/PARKED AT JUNCTION EXIT	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction SW NE	Location ON MAIN CARRIAGEWAY	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
2	DRIVER			SLIGHT

Contributory Factors

OTHER (VERY LIKELY)

Date/Time: 28 March 2012

Junction Road Code: ?

Severity: SERIOUS

Skidded/overturned

Lighting Conditions:

Road/Link/Section/Chainage: A90 12276/51 (593m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Light

Vehicle Details

Veh. No Vehicle Type CAR (FOUR WHEELED)

Direction Location NSON MAIN **CARRIAGEWAY**

Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Manoeuvres **OVERTAKING** MOVING

OFFSIDE

SKIDDED VEHICLE ON ITS

Hit Object in Cway **KERB**

Hit Object off Cway CENTRAL CRASH

BARRIER

Casualty Details

Veh. No. 1

Casualty Class DRIVER

Sex

Age

Severity **SERIOUS**

Contributory Factors

SWERVED (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

Date/Time: 02 February 2012

_

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12220/25 (5,913m)

Junction Road Code: A928

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Weather Conditions: Fine

Road Surface Conditions: Dry

Dark

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres CHANGING LANE TO RIGHT	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SLIGHT
2	DRIVER			SLIGHT

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

ROAD LAYOUT (EG. BEND, WINDING ROAD, HILL CREST) (POSSIBLE)

Vehicle Type

CAR (FOUR

WHEELED)

Weather Conditions: Snow

Date/Time: 04 February 2012

Road/Link/Section/Chainage: A90 12225/07 (1,238m)

Junction Road Code: U309

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

NONE

Road Surface Conditions: Ice

Lighting Conditions: Dark

Vehicle Details Veh. No

Junction Location Skidded/overturned Hit Object in Cway Hit Object off Cway Manoeuvres

G

G

Severity: SLIGHT

ON MAIN APPROACHING JUNCTION **CARRIAGEWAY** OR WAITING/PARKED AT

MOVING VEHICLE ON ITS

OVERTAKING

SKIDDING/JACK-KNIFIN

NONE

Veh. No Vehicle Type **PSV**

Direction Location SN ON MAIN

Direction

SN

Junction Location

JUNCTION APPROACH

APPROACHING JUNCTION

OR WAITING/PARKED AT

JUNCTION APPROACH

OFFSIDE Manoeuvres **GOING AHEAD**

OTHER

Skidded/overturned

SKIDDING/JACK-KNIFIN

Hit Object in Cway

Hit Object off Cway

NONE

NONE

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity VEHICLE OR PILLION PASSENGER 1 **SLIGHT**

CARRIAGEWAY

Location

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)

ROAD LAYOUT (EG. BEND, HILL, NARROW CARRIAGEWAY) (VERY LIKELY)

SUDDEN BRAKING (POSSIBLE)

LOSS OF CONTROL (VERY LIKELY)

SUDDEN BRAKING (POSSIBLE)

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)

Date/Time: 17 February 2012

Innation Bood Code: A022

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12228/06 (2,012m)

Junction Road Code: A932

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Fine

Road Surface Conditions: Wet

Light

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction N S	Location ON MAIN CARRIAGEWAY	Junction Location ENTERING MAIN ROAD	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction N S	Location ON MAIN CARRIAGEWAY	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
2	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

POOR TURN OR MANOEUVRE (VERY LIKELY)
FAILED TO LOOK PROPERLY (VERY LIKELY)

Weather Conditions: Fine

Date/Time: 04 February 2012

Road Surface Conditions: Ice

Road/Link/Section/Chainage: A90 12250/70 (1,120m)

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Lighting Conditions: Dark

Vehicle Details

Veh. No Vehicle Type Location Direction

NS

ON MAIN **CARRIAGEWAY**

Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION Manoeuvres **GOING AHEAD** OTHER

Skidded/overturned

G

SKIDDING/JACK-KNIFIN

Hit Object in Cway NONE

Hit Object off Cway

NONE

Casualty Details

Veh. No. **Casualty Class** DRIVER 1

CAR (FOUR

WHEELED)

Sex

Age

Severity **SLIGHT**

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY) TRAVELLING TOO FAST FOR CONDITIONS (POSSIBLE)

LOSS OF CONTROL (VERY LIKELY)

Date/Time: 11 February 2012

Severity: SLIGHT

Junction Road Code: A94

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Weather Conditions: Fine

500CC

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No Vehicle Type MOTORCYCLE OVER

Road/Link/Section/Chainage: A90 12228/06 (74m)

Direction Location ON MAIN **CARRIAGEWAY**

E S

Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT

JUNCTION APPROACH

Manoeuvres TURNING LEFT Skidded/overturned

Hit Object in Cway NONE

Hit Object off Cway NONE

SKIDDING/JACK-KNIFIN

G

Casualty Details

Veh. No. **Casualty Class** 1 **DRIVER**

Sex

Age

Severity **SLIGHT**

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

Road/Link/Section/Chainage: A90 12250/07 (635m)

Date/Time: 28 March 2012

Junction Road Code: ?

Severity: SLIGHT

Lighting Conditions:

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Light

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction N S	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction N S	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres SLOWING OR STOPPING	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

FOLLOWING TOO CLOSE (POSSIBLE)

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

FATIGUE (POSSIBLE)

Weather Conditions: Snow

Road/Link/Section/Chainage: A90 12240/70 (2,212m)

Date/Time: 03 April 2012

Road Surface Conditions: Snow

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
1	CAR (FOUR	SN	ON MAIN	NOT AT, OR WITHIN 20	GOING AHEAD	SKIDDED	NONE	NONE
	WHEELED)		CARRIAGEWAY	METRES OF, JUNCTION	OTHER			

Casualty Details

Veh. No.	Casualty Class DRIVER	Sex	Age	Severity SLIGHT
1	VEHICLE OR PILLION PASSENGER			SLIGHT
1	VEHICLE OR PILLION PASSENGER			SLIGHT
1	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)
TRAVELLING TOO FAST FOR CONDITIONS (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

Road/Link/Section/Chainage: A90 12220/26 (2,225m)

Date/Time: 12 April 2012

Junction Road Code: C6

Severity: SLIGHT

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction E W	Location ON MAIN CARRIAGEWAY	Junction Location ENTERING MAIN ROAD	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway OTHER PERMANENT OBJECT
Veh. No 2	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction N S	Location ON MAIN CARRIAGEWAY	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Casualty Class	Sex	Age	Severity
DRIVER			SLIG

Contributory Factors

ILLNESS OR DISABILITY, MENTAL OR PHYSICAL (VERY LIKELY)

FAILED TO LOOK PROPERLY (POSSIBLE)

Date/Time: 20 April 2012

Severity: SLIGHT

G

Road/Link/Section/Chainage: A90 12233/05 (962m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No Vehicle Type Direction Location Hit Object in Cway **Hit Object off Cway Junction Location** Manoeuvres Skidded/overturned CAR (FOUR **KERB** NONE SN NOT AT, OR WITHIN 20 **GOING AHEAD** ON MAIN WHEELED) OTHER SKIDDING/JACK-KNIFIN **CARRIAGEWAY** METRES OF, JUNCTION

Casualty Details

Veh. No.	Casualty Class
	DRIVER

Contributory Factors

LOSS OF CONTROL (POSSIBLE) DISTRACTION IN VEHICLE (POSSIBLE) DISTRACTION OUTSIDE VEHICLE (POSSIBLE)

Date/Time: 25 April 2012

Junction Road Code: ?

Severity: SLIGHT

Road/Link/Section/Chainage: A90 12240/95 (35m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction N S	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned OVERTURNED	Hit Object in Cway NONE	Hit Object off Cway CENTRAL CRASH BARRIER
Veh. No 2	Vehicle Type GOODS VEHICLE 3.5 TONNES MGW AND UNDER	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway ENTERED DITCH

Casualty Details

o. Casualty Class Sex Age Severity
DRIVER SLIG

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

Date/Time: 20 April 2012

Junction Road Code: ?

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12225/23 (1,763m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

Road Surface Conditions: Wet

Light

Vehicle Details

Veh. No Vehicle Type Direction Location **Junction Location** Manoeuvres Skidded/overturned Hit Object in Cway Hit Object off Cway NONE CAR (FOUR NS**GOING AHEAD** ON MAIN NOT AT, OR WITHIN 20 NO NEARSIDE OR WHEELED) OTHER SKIDDING/JACK-KNIFIN **CARRIAGEWAY** METRES OF, JUNCTION OFFSIDE CRASH G **BARRIER**

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 **DRIVER SLIGHT**

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (POSSIBLE)

TYRES ILLEGAL, DEFECTIVE OR UNDER INFLATED (POSSIBLE)

IMPAIRED BY ALCOHOL (POSSIBLE)

Road/Link/Section/Chainage: A90 12245/05 (3,659m)

Date/Time: 14 May 2012

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Other

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle	Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres WAITING TO GO AHEAD BUT HELD UP	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	asualty Class Sex Age	Severity
	RIVER	

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)

TRAVELLING TOO FAST FOR CONDITIONS (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

FAILED TO LOOK PROPERLY (POSSIBLE)

IMPAIRED BY ALCOHOL (POSSIBLE)

Weather Conditions: Fine

Date/Time: 28 May 2012

Road/Link/Section/Chainage: A90 12240/08 (2,223m)

Junction Road Code: ?

Road Surface Conditions: Dry

Severity: SERIOUS

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
1	GOODS VEHICLE 7.5	NS	ON MAIN	NOT AT, OR WITHIN 20	GOING AHEAD	NO	NONE	NONE
	TONNES MGW AND		CARRIAGEWAY	METRES OF, JUNCTION	OTHER	SKIDDING/JACK-KNIFIN		
	OVER					G		
Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
Veh. No 2	Vehicle Type AGRICULTURAL	Direction N S	Location ON MAIN	Junction Location NOT AT, OR WITHIN 20	Manoeuvres GOING AHEAD	Skidded/overturned NO	Hit Object in Cway NONE	Hit Object off Cway
Veh. No 2	•••						, ,	,

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
2	DRIVER			SERIOUS

Contributory Factors

FATIGUE (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

Date/Time: 06 June 2012

Junction Road Code: ?

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12276/50 (429m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Other

Road Surface Conditions: Wet

Light

Vehicle Details

Veh. No Vehicle Type Direction Location **Junction Location** Hit Object in Cway **Hit Object off Cway** Manoeuvres Skidded/overturned CAR (FOUR SN NONE NONE NOT AT, OR WITHIN 20 **GOING AHEAD** SKIDDED AND ON MAIN **OVERTURNED** OTHER WHEELED) **CARRIAGEWAY** METRES OF, JUNCTION

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 DRIVER SLIGHT

Contributory Factors

RAIN, SLEET, SNOW, OR FOG (VERY LIKELY) SPRAY FROM OTHER VEHICLES (POSSIBLE)

Date/Time: 16 June 2012

Junction Road Code: ?

lunation

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

Veh. No Vehicle Type

Road Surface Conditions: Wet

Lighting Conditions:

Severity: SLIGHT

NO

G

Light

NONE

Vehicle Details

2

Veh. No Vehicle Type
1 CAR (FOUR
WHEELED)

CAR (FOUR

WHEELED)

Direction N S

Direction

NS

Road/Link/Section/Chainage: A90 12270/92 (3,099m)

Location
ON MAIN
CARRIAGEWAY
Location
ON MAIN

CARRIAGEWAY

Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION Junction Location

NOT AT. OR WITHIN 20

METRES OF, JUNCTION

GOING AHEAD OTHER Manoeuvres GOING AHEAD OTHER

Manoeuvres

Skidded/overturned SKIDDED AND OVERTURNED Skidded/overturned

SKIDDING/JACK-KNIFIN

Hit Object in Cway

Hit Object in Cway

Hit Object off Cway

Hit Object off Cway

NONE

NONE

Casualty Details

Veh. No. Casualty Class
1 DRIVER

Sex

Age

Severity SLIGHT

Contributory Factors

SWERVED (VERY LIKELY)

LOSS OF CONTROL (POSSIBLE)

POOR TURN OR MANOEUVRE (POSSIBLE)

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)

Road/Link/Section/Chainage: A90 12270/04 (2,166m)

Date/Time: 21 August 2012

Junction Road Code: U

Severity: SLIGHT

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Fine

OVER

CAR (FOUR

WHEELED)

Road Surface Conditions: Dry

ROUNDABOUT OR ON

MAIN ROAD

Lighting Conditions:

Light

Vehicle Details

Veh. No Hit Object off Cway Vehicle Type Direction Location **Junction Location** Manoeuvres Skidded/overturned Hit Object in Cway TURNING RIGHT NONE NONE N W **ENTERING MAIN ROAD GOODS VEHICLE 7.5** ON MAIN NO TONNES MGW AND **CARRIAGEWAY**

SKIDDING/JACK-KNIFIN

G

Veh. No Vehicle Type Direction Skidded/overturned Hit Object in Cway Hit Object off Cway Location **Junction Location** Manoeuvres NONE 2 NONE

GOING AHEAD NO MID JUNCTION - ON

OTHER SKIDDING/JACK-KNIFIN

G

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity VEHICLE OR PILLION PASSENGER **SLIGHT**

Contributory Factors

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

SN

ON MAIN

CARRIAGEWAY

POOR TURN OR MANOEUVRE (VERY LIKELY)

Date/Time: 09 July 2012

Junction Road Code: ?

Severity: SLIGHT

Lighting Conditions:

G

Road/Link/Section/Chainage: A90 12270/04 (2,340m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Light

Vehicle Details

Veh. No Vehicle Type Location Direction

NE SW

Junction Location NOT AT, OR WITHIN 20 Skidded/overturned

Hit Object in Cway

Hit Object off Cway OTHER

CAR (FOUR WHEELED)

ON MAIN **CARRIAGEWAY**

METRES OF, JUNCTION

Manoeuvres **GOING AHEAD** OTHER

SKIDDING/JACK-KNIFIN

NONE

PERMANENT OBJECT

Casualty Details

Veh. No. **Casualty Class** 1 **DRIVER**

Sex

Age

Severity SLIGHT

Contributory Factors

LOSS OF CONTROL (VERY LIKELY) SUDDEN BRAKING (VERY LIKELY)

Date/Time: 17 June 2012 1850

Severity: SLIGHT

Road/Link/Section/Chainage: A90 12272/50 (2,248m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
1	CAR (FOUR	SN	ON MAIN	NOT AT, OR WITHIN 20	GOING AHEAD	SKIDDED	NONE	CENTRAL CRASH
	WHEELED)		CARRIAGEWAY	METRES OF JUNCTION	OTHER			BARRIFR

Casualty Details

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)

Date/Time: 30 June 2012

Date/Time. 30 June 20

Severity: SLIGHT

Road/Link/Section/Chainage: A90 12220/26 (4,618m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction N S	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	DRIVER			SLIGHT

Contributory Factors

ILLEGAL TURN OR DIRECTION OF TRAVEL (VERY LIKELY)

AGGRESSIVE DRIVING (VERY LIKELY)

ILLNESS OR DISABILITY, MENTAL OR PHYSICAL (VERY LIKELY)

Road/Link/Section/Chainage: A90 12250/63 (2,481m)

Date/Time: 21 September 2012

Junction Road Code: ?

Severity: SERIOUS

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Dark

Vehicle Details

Veh. No Vehicle Type Skidded/overturned Location Hit Object in Cway Hit Object off Cway Direction **Junction Location** Manoeuvres SW NE SKIDDED NONE CENTRAL CRASH CAR (FOUR ON MAIN NOT AT, OR WITHIN 20 **GOING AHEAD**

WHEELED) CARRIAGEWAY METRES OF, JUNCTION OTHER BARRIER

Casualty Details

 Veh. No.
 Casualty Class
 Sex
 Age
 Severity

 1
 VEHICLE OR PILLION PASSENGER
 SERIOUS

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

Date/Time: 11 September 2012

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No Vehicle Type
1 GOODS VEHICLE 3.5
TONNES MGW AND

Road/Link/Section/Chainage: A90 12276/70 (2,844m)

Direction Location
SW NE ON MAIN
CARRIAGEWAY

Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION Manoeuvres OVERTAKING MOVING VEHICLE ON ITS

OFFSIDE

Skidded/overturned OVERTURNED

Hit Object in Cway KERB Hit Object off Cway CENTRAL CRASH

BARRIER

Casualty Details

Veh. No. Casualty Class 1 DRIVER

UNDER

Sex

Age

Severity SLIGHT

Contributory Factors

CARELESS/RECKLESS/IN A HURRY (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

Road/Link/Section/Chainage: A90 12347/36 (598m)

Date/Time: 04 April 2012

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway OTHER OBJECT	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
2	DRIVER			SLIGHT
2	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

FOLLOWING TOO CLOSE (POSSIBLE)

EXCEEDING SPEED LIMIT (POSSIBLE)

FAILED TO LOOK PROPERLY (POSSIBLE)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

SUDDEN BRAKING (POSSIBLE)

ANIMAL OR OBJECT IN CARRIAGEWAY (VERY LIKELY)

Road/Link/Section/Chainage: A90 12220/26 (4,449m)

Date/Time: 21 July 2012

Junction Road Code: ?

Severity: SERIOUS

Lighting Conditions:

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Dark

Vehicle Details

Veh. No Vehicle Type Direction Location **Junction Location** Skidded/overturned Hit Object in Cway Hit Object off Cway Manoeuvres CAR (FOUR **OVERTURNED** NONE CENTRAL CRASH NSON MAIN NOT AT, OR WITHIN 20 **GOING AHEAD** OTHER WHEELED) **CARRIAGEWAY** METRES OF, JUNCTION **BARRIER**

Casualty Details

 Veh. No.
 Casualty Class
 Sex
 Age
 Severity

 1
 DRIVER
 SERIOUS

Contributory Factors

FATIGUE (POSSIBLE)

Road/Link/Section/Chainage: A90 12240/34 (3,233m)

Date/Time: 03 August 2012

Junction Road Code: B957

Severity: SLIGHT

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Dark & Lit

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction N S	Location ON MAIN CARRIAGEWAY	Junction Location ENTERING MAIN ROAD	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction SW NE	Location ON MAIN CARRIAGEWAY	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class DRIVER	Sex	Age	Severity SLIGHT
1	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY) CARELESS/RECKLESS/IN A HURRY (POSSIBLE) JUNCTION OVERSHOOT (POSSIBLE)

Date/Time: 05 June 201

Junction Road Code: B957

Severity: SLIGHT

Road/Link/Section/Chainage: A90 12240/34 (3,246m)

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction NW S	Location ON MAIN CARRIAGEWAY	Junction Location ENTERING MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SLIGHT

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY) DISOBEYED GIVE WAY OR STOP SIGN OR MARKINGS (VERY LIKELY)

Weather Conditions: Rain

Date/Time: 07 July 2012

Road Surface Conditions: Wet

Junction Road Code: ?

Road/Link/Section/Chainage: A90 12237/06 (2,137m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Lighting Conditions:

Severity: SLIGHT

Light

Vehicle Details

Veh. No Vehicle Type Location Skidded/overturned Hit Object in Cway **Hit Object off Cway** Direction **Junction Location** Manoeuvres **OVERTURNED** NONE CAR (FOUR NS**GOING AHEAD** ON MAIN NOT AT, OR WITHIN 20 OTHER WHEELED) **CARRIAGEWAY** METRES OF, JUNCTION

OTHER

PERMANENT

OBJECT

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 **DRIVER** SLIGHT

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)

LOSS OF CONTROL (POSSIBLE)

Date/Time: 09 July 2012

Junction Road Code: ?

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12240/19 (2,016m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Light

Vehicle Details

Veh. No Vehicle Type Direction Location **Junction Location** Skidded/overturned Hit Object in Cway **Hit Object off Cway** Manoeuvres **OVERTURNED** NONE NONE CAR (FOUR NSNOT AT, OR WITHIN 20 **GOING AHEAD** ON MAIN OTHER WHEELED) **CARRIAGEWAY** METRES OF, JUNCTION

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 VEHICLE OR PILLION PASSENGER SLIGHT

Contributory Factors

LOSS OF CONTROL (VERY LIKELY) EXCEEDING SPEED LIMIT (POSSIBLE)

Date/Time: 12 November 2012

Severity: SERIOUS

Road/Link/Section/Chainage: A90 12276/05 (1,007m)

Junction Road Code: U

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction W S	Location ON MAIN CARRIAGEWAY	Junction Location ENTERING MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SERIOUS
2	DRIVER			SLIGHT

Contributory Factors

DISOBEYED GIVE WAY OR STOP SIGN OR MARKINGS (VERY LIKELY)

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

CARELESS/RECKLESS/IN A HURRY (VERY LIKELY)

Date/Time: 22 October 2012

Road/Link/Section/Chainage: A90 12272/05 (1,098m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fog

Road Surface Conditions: Wet

Lighting Conditions: Light

Severity: SLIGHT

Vehicle Details

Veh. No 1	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 3	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
3	DRIVER			SLIGHT

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (POSSIBLE)

SLIPPERY ROAD (DUE TO WEATHER) (POSSIBLE)

FOLLOWING TOO CLOSE (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

FOLLOWING TOO CLOSE (VERY LIKELY)

SLIPPERY ROAD (DUE TO WEATHER) (POSSIBLE)

Date/Time: 18 October 2012

Junction Road Code: ?

Severity: SLIGHT

Road/Link/Section/Chainage: A90 12250/11 (973m)

Junction Road Gode.

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction N S	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres CHANGING LANE TO RIGHT	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction N S	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres OVERTAKING MOVING VEHICLE ON ITS OFFSIDE	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	DRIVER			SLIG

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

DAZZLING SUN (VERY LIKELY)

VEHICLE BLIND SPOT (VERY LIKELY)

CAR (FOUR

WHEELED)

Road/Link/Section/Chainage: A90 12225/23 (3,999m)

NS

ON MAIN

CARRIAGEWAY

Date/Time: 20 October 2012

Junction Road Code: U

Severity: SLIGHT

NO

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Hit Object in Cway

NONE

Hit Object off Cway

NONE

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No Vehicle Type Location Direction **Junction Location** Manoeuvres Skidded/overturned

> OTHER SKIDDING/JACK-KNIFIN OR WAITING/PARKED AT G

GOING AHEAD

JUNCTION APPROACH

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 **DRIVER SLIGHT**

APPROACHING JUNCTION

Contributory Factors

SWERVED (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

FATIGUE (POSSIBLE)

Date/Time: 10 October 2012

Severity: SLIGHT

Road/Link/Section/Chainage: A90 12240/08 (70m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Ice

Lighting Conditions: Dark

Vehicle Details

Veh. No Vehicle Type Location Skidded/overturned Hit Object in Cway **Hit Object off Cway** Direction **Junction Location** Manoeuvres **GOODS VEHICLE 7.5 OVERTURNED** NONE NSNOT AT, OR WITHIN 20 **GOING AHEAD** ON MAIN ROAD SIGN / OTHER **TONNES MGW AND CARRIAGEWAY** METRES OF, JUNCTION TRAFFIC SIGNAL

OVER

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	DRIVER			SLIGHT

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

FATIGUE (VERY LIKELY)

Date/Time: 10 December 2012

Road/Link/Section/Chainage: A90 12276/71 (2,963m)

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Ice

Lighting Conditions: Light

Vehicle Details

Veh. No Vehicle Type Direction Location

NS

LocationJunction LocationON MAINNOT AT, OR WITHIN 20CARRIAGEWAYMETRES OF, JUNCTION

Manoeuvres GOING AHEAD OTHER **Skidded/overturned** SKIDDED

Hit Object in Cway

Hit Object off Cway

NONE TREE

Casualty Details

Veh. No. Casualty Class 1 DRIVER

CAR (FOUR

WHEELED)

Sex

Age

Severity SLIGHT

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)

CAR (FOUR

WHEELED)

Weather Conditions: Fine

Veh. No Vehicle Type

Date/Time: 10 December 2012

Junction Road Code: ?

Severity: SLIGHT Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Road/Link/Section/Chainage: A90 12276/51 (2,699m)

Direction

NS

Location

ON MAIN

CARRIAGEWAY

Light

KERB

Vehicle Details

Road Surface Conditions: Ice

Junction Location

NOT AT, OR WITHIN 20

METRES OF, JUNCTION

Lighting Conditions:

SKIDDED AND

OVERTURNED

Skidded/overturned

Hit Object in Cway Hit Object off Cway

OTHER

PERMANENT OBJECT

Casualty Details Veh. No.

1

Casualty Class DRIVER

Sex

Age

Severity SLIGHT

Manoeuvres

OTHER

GOING AHEAD

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)

Road/Link/Section/Chainage: A90 12272/51 (1,765m)

Date/Time: 27 November 2012

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Light

Severity: SLIGHT

Vehicle Details

Veh. No Vehicle Type Direction Location **Junction Location** Skidded/overturned Hit Object in Cway Hit Object off Cway Manoeuvres CAR (FOUR **OVERTURNED** NONE NONE NSON MAIN NOT AT, OR WITHIN 20 **GOING AHEAD**

WHEELED) CARRIAGEWAY METRES OF, JUNCTION OTHER

Casualty Details

Veh. No.Casualty ClassSexAgeSeverity1DRIVERSLIGHT

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

Date/Time: 11 November 2012

Severity: SERIOUS

Road/Link/Section/Chainage: A90 12276/70 (3,469m)

Junction Road Code: U

Junction Location: MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROA

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction E N	Location ON MAIN CARRIAGEWAY	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway KERB	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway KERB	Hit Object off Cway TREE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	VEHICLE OR PILLION PASSENGER			SERIOUS

Contributory Factors

POOR TURN OR MANOEUVRE (VERY LIKELY) FAILED TO LOOK PROPERLY (VERY LIKELY)

Date/Time: 21 December 2012

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12220/26 (2,210m)

Junction Road Code: C6

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Rain

Road Surface Conditions: Wet

Dark & Lit

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction E N	Location ON MAIN CARRIAGEWAY	Junction Location ENTERING MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction N S	Location ON MAIN CARRIAGEWAY	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
2	DRIVER			SLIGHT

Contributory Factors

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY) INEXPERIENCED OR LEARNER DRIVER/RIDER (VERY LIKELY)

Road/Link/Section/Chainage: A90 12240/53 (542m)

Date/Time: 25 December 201

Junction Road Code: U

Severity: SERIOUS

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Road Surface Conditions: Wet

Weather Conditions: Fine

Lighting Conditions: Dark

Hit Object off Cway

CENTRAL CRASH

BARRIER

Vehicle Details

Veh. No Vehicle Type CAR (FOUR WHEELED)

Direction SW NE

Location ON MAIN **CARRIAGEWAY**

Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT

JUNCTION APPROACH

Manoeuvres **GOING AHEAD** OTHER

Skidded/overturned **OVERTURNED**

Hit Object in Cway NONE

Casualty Details

Veh. No. **Casualty Class** 1 **DRIVER**

Sex

Age

Severity **SERIOUS**

Contributory Factors

POOR TURN OR MANOEUVRE (POSSIBLE)

FATIGUE (POSSIBLE)

Date/Time: 18 December 2012

Junction Road Code: ?

Severity: SERIOUS

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

: Dark

Vehicle Details

Veh. No Vehi

Road Surface Conditions: Wet

Lighting Conditions:

Jaik

0	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
	MOTORCYCLE OVER	SN	ON MAIN	NOT AT, OR WITHIN 20	GOING AHEAD	NO	NONE	CENTRAL CRASH

500CC CARRIAGEWAY METRES OF, JUNCTION OTHER SKIDDING/JACK-KNIFIN BARRIER

G

Casualty Details

Veh. No.	Casualty Class	Sex Age	Severity
	DRIVER		SERIOUS

Contributory Factors

DEFECTIVE LIGHTS OR INDICATORS (VERY LIKELY)

Road/Link/Section/Chainage: A90 12240/07 (1,128m)

Road/Link/Section/Chainage: A90 12233/06 (276m)

Date/Time: 30 November 2012

Junction Road Code: ?

Severity: SLIGHT

Weather Conditions: Fine

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR	Direction N S	Location ON MAIN	Junction Location NOT AT, OR WITHIN 20	Manoeuvres GOING AHEAD	Skidded/overturned NO	Hit Object in Cway NONE	Hit Object off Cway OTHER
	WHEELED)		CARRIAGEWAY	METRES OF, JUNCTION	OTHER	SKIDDING/JACK-KNIFIN G		PERMANENT OBJECT

Casualty Details

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

SWERVED (VERY LIKELY) OTHER (VERY LIKELY)

Date/Time: 24 November 2012

Junction Road Code: ?

Severity: SLIGHT

Road/Link/Section/Chainage: A90 12233/06 (14m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Ice

Lighting Conditions: Light

Vehicle Details

Veh. N	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
	CAR (FOUR	N S	ON MAIN	NOT AT, OR WITHIN 20	GOING AHEAD	NO	NONE	OTHER
	WHEELED)		CARRIAGEWAY	METRES OF, JUNCTION	OTHER	SKIDDING/JACK-KNIFIN G		PERMANENT OBJECT

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)

SWERVED (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

Date/Time: 13 November 2012

Severity: SLIGHT

Road/Link/Section/Chainage: A90 12240/33 (1,675m) Junction Road Code: ? Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction S S	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres U TURN	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	DRIVER			SLIGHT

Contributory Factors

POOR TURN OR MANOEUVRE (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY) FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (POSSIBLE)

Date/Time: 19 November 2012

Junction Road Code: ?

Severity: SLIGHT

Road/Link/Section/Chainage: A90 12240/70 (2,026m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Dark

Vehicle Details

Veh. No Vehicle Type Location Hit Object in Cway Hit Object off Cway Direction **Junction Location** Manoeuvres Skidded/overturned NONE ENTERED DITCH CAR (FOUR SN NOT AT, OR WITHIN 20 **GOING AHEAD** ON MAIN NO

WHEELED) **CARRIAGEWAY** METRES OF, JUNCTION OTHER SKIDDING/JACK-KNIFIN G

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity DRIVER 1 **SLIGHT**

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (POSSIBLE)

DEFECTIVE STEERING OR SUSPENSION (POSSIBLE)

Date/Time: 26 November 2012

Severity: SLIGHT

Road/Link/Section/Chainage: A90 12240/33 (1,211m)

Junction Road Code: B957

Junction Location: LEAVING MAIN ROAD

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Dark

Vehicle Details

Veh. No	Vehicle Type GOODS VEHICLE 3.5 TONNES MGW AND UNDER	Direction N W	Location ON MAIN CARRIAGEWAY	Junction Location LEAVING MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction S N	Location ON MAIN CARRIAGEWAY	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
2	DRIVER			SLIGHT
2	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

FAILED TO LOOK PROPERLY (POSSIBLE)

FAILED TO SIGNAL/MISLEADING SIGNAL (POSSIBLE)

Date/Time: 24 November 2012

Severity: SERIOUS

Lighting Conditions:

Road/Link/Section/Chainage: A90 12240/07 (2,799m)

Junction Road Code: C32

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Fine

Road Surface Conditions: Wet

Dark

Vehicle Details

Veh. No	Vehicle Type CAR (FOUR WHEELED)	Direction N W	Location ON MAIN CARRIAGEWAY	Junction Location ENTERING MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR (FOUR WHEELED)	Direction W E	Location ON MAIN CARRIAGEWAY	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING/JACK-KNIFIN G	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SERIOUS
1	VEHICLE OR PILLION PASSENGER			SERIOUS

Contributory Factors

POOR TURN OR MANOEUVRE (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

Date/Time: 21 September 2012

Junction Road Code: ?

Severity: SERIOUS

Lighting Conditions:

Road/Link/Section/Chainage: A90 12250/70 (22m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

Dark

Vehicle Details

Veh. No	Vehicle Type CAR	Direction N S	Location ON MAIN	Junction Location NOT AT. OR WITHIN 20	Manoeuvres GOING AHEAD	Skidded/overturned NO SKIDDING.	Hit Object in Cway NONE	Hit Object off Cway NEARSIDE OR
'	5/ tr	110	CARRIAGEWAY - NOT	METRES OF, JUNCTION	OTHER	JACK-KNIFING OR		OFFSIDE CRASH
			IN RESTRICTED LANE			OVERTURNING		BARRIER

Casualty Details

Veh. No. Casu	Sex	Age	Severity
VEHIC			SERIOU

Contributory Factors

LOSS OF CONTROL (VERY LIKELY) FOLLOWING TOO CLOSE (VERY LIKELY)

Road/Link/Section/Chainage: A90 12220/25 (3,870m)

Date/Time: 03 January 2013

Junction Road Code: C6

Severity: SLIGHT

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction E N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location ENTERING MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
D	RIVER		Ĭ	SLI

Contributory Factors

ILLEGAL TURN OR DIRECTION OF TRAVEL (VERY LIKELY)

DISOBEYED GIVE WAY OR STOP SIGN OR MARKINGS (VERY LIKELY)

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (POSSIBLE)

FOLLOWING TOO CLOSE (POSSIBLE)

Road/Link/Section/Chainage: A90 12240/18 (1m)

Date/Time: 14 January 2013

Junction Road Code: C32

Severity: FATAL

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Weather Conditions: Fine Road Surface Conditions: Ice

Lighting Conditions: Dark

Vehicle Details

Veh. No	Vehicle Type CAR	Direction SW NE	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction SW NE	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			FATAL

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

POOR TURN OR MANOEUVRE (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

Date/Time: 16 January 2013

Junction Road Code: U310

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12225/22 (1,526m)

Junction Location: ENTERING FROM SLIP ROAD

Weather Conditions: Fine

Road Surface Conditions: Wet

Dark & Lit

Vehicle Details

Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
1	CAR	SN	ON MAIN	ENTERING FROM SLIP	CHANGING	NO SKIDDING,	NONE	NONE
			CARRIAGEWAY - NOT	ROAD	LANE TO RIGHT	JACK-KNIFING OR		
			IN RESTRICTED LANE			OVERTURNING		
Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
Veh. No 2	Vehicle Type CAR	Direction S N	Location ON MAIN	Junction Location APPROACHING JUNCTION	Manoeuvres GOING AHEAD	Skidded/overturned NO SKIDDING,	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	7 1						,	

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	DRIVER			SLIGHT

Contributory Factors

POOR TURN OR MANOEUVRE (VERY LIKELY)

Date/Time: 05 February 2013

Road/Link/Section/Chainage: A90 12240/08 (2,133m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Light

Severity: SLIGHT

Vehicle Details

Veh. No	Vehicle Type VAN/GOODS VEHICLE 3.5 TONNES MAXIMUM GROSS WEIGHT (MGW) AND UNDER	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres SLOWING OR STOPPING	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 3	Vehicle Type GOODS VEHICLE OVER 3.5 TONNES AND UNDER 7.5 TONNES MGW	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

FOLLOWING TOO CLOSE (POSSIBLE)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY) DANGEROUS ACTION IN CARRIAGEWAY (EG. PLAYING) (VERY LIKELY)

Date/Time: 22 February 2013

Severity: SERIOUS

Lighting Conditions:

Road/Link/Section/Chainage: A90 12240/34 (3,642m)

Junction Road Code: B957

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Weather Conditions: Fine

Road Surface Conditions: Dry

Light

Vehicle Details

Veh. NoVehicle TypeDirectionLocationJunction Location1MINIBUS (8 - 16 PASSENGER SEATS)N S ON MAIN APPROACHING JUNCTION OR WAITING/PARKED AT IN RESTRICTED LANEOR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned SKIDDED	Hit Object in Cway NONE	Hit Object off Cway CENTRAL CRASH BARRIER
--	------------------------------------	--------------------------------------	-----------------------------------	---

Casualty Details

Veh. No.	Casualty Class VEHICLE OR PILLION PASSENGER	Sex	Age	Severity SERIOUS
1	VEHICLE OR PILLION PASSENGER			SLIGHT
1	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

DISTRACTION IN VEHICLE (VERY LIKELY)
FAILED TO LOOK PROPERLY (VERY LIKELY)

Date/Time: 13 February 2013

Date, Time: 10 1 oblidary 2

Severity: SLIGHT

Road/Link/Section/Chainage: A90 12225/07 (1,739m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Snow

Road Surface Conditions: Snow

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
---------	----------------------------	-------------------------	--	--	------------------------------------	--	----------------------------	-----------------------------

Casualty Details

Veh. No. Casualty Class Sex Age Severity
DRIVER SLIGHT

Contributory Factors

TRAVELLING TOO FAST FOR CONDITIONS (POSSIBLE)

FAILED TO LOOK PROPERLY (VERY LIKELY)
FAILED TO LOOK PROPERLY (POSSIBLE)

Date/Time: 10 March 2013

Road/Link/Section/Chainage: A90 12225/22 (3,687m)

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Snow

Road Surface Conditions: Ice

Lighting Conditions: Dark

Vehicle Details

Veh. No	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction PARKED	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres PARKED	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

SUDDEN BRAKING (POSSIBLE) LOSS OF CONTROL (POSSIBLE)

Road/Link/Section/Chainage: A90 12240/95 (16m)

Date/Time: 10 May 2013

Junction Road Code: ?

IN RESTRICTED LANE

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

OVER

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
1	GOODS VEHICLE 7.5	SW NE	ON MAIN	NOT AT, OR WITHIN 20	GOING AHEAD	OVERTURNED	NONE	NONE
	TONNES MGW AND		CARRIAGEWAY - NOT	METRES OF, JUNCTION	OTHER			

Casualty Details

Contributory Factors

ROAD LAYOUT (EG. BEND, HILL, NARROW CARRIAGEWAY) (POSSIBLE)

FAILED TO LOOK PROPERLY (VERY LIKELY)
POOR TURN OR MANOEUVRE (POSSIBLE)

SWERVED (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

FATIGUE (POSSIBLE)

Road/Link/Section/Chainage: A90 12220/26 (2,220m)

Date/Time: 17 May 2013

Severity: SERIOUS

Junction Road Code: U317

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No 1	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres CHANGING LANE TO RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

. No. Casualty Class Sex Age Severity
CLE OR PILLION PASSENGER SE

Contributory Factors

ANIMAL OR OBJECT IN CARRIAGEWAY (VERY LIKELY)

FAILED TO LOOK PROPERLY (POSSIBLE)

Road/Link/Section/Chainage: A90 12272/50 (2,946m)

Date/Time: 08 March 2013

Date/Time: 00 March

Severity: FATAL

Junction Location: ENTERING MAIN ROAD

Light

Weather Conditions: Rain

Junction Road Code: U

Road Surface Conditions: Wet

Lighting Conditions:

Vehicle Details

Veh. No	Vehicle Type CAR	Direction SW NE	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location ENTERING MAIN ROAD	Manoeuvres MOVING OFF	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction NE SW	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned SKIDDED	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 3	Vehicle Type CAR	Direction SW NE	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class DRIVER	Sex	Age	Severity SERIOUS
3	DRIVER			SERIOUS
3	VEHICLE OR PILLION PASSENGER			FATAL
3	VEHICLE OR PILLION PASSENGER			FATAL

Contributory Factors

JUNCTION RESTART (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

Road/Link/Section/Chainage: A90 12272/50 (2,362m)

Date/Time: 20 October 2012

Junction Road Code: ?

Severity: FATAL

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fog

Road Surface Conditions: Wet

Lighting Conditions: Dark

Vehicle Details

Veh. No Vehicle Type Hit Object in Cway **Hit Object off Cway** Direction Location **Junction Location** Manoeuvres Skidded/overturned NONE NONE SW NE **GOING AHEAD** NO SKIDDING, **GOODS VEHICLE 7.5** ON MAIN NOT AT, OR WITHIN 20 **TONNES MGW AND CARRIAGEWAY - NOT** METRES OF, JUNCTION

OVER

IN RESTRICTED LANE

OTHER

JACK-KNIFING OR **OVERTURNING**

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity **PEDESTRIAN** 1 **FATAL**

Contributory Factors

RAIN, SLEET, SNOW, OR FOG (VERY LIKELY)

IMPAIRED BY ALCOHOL (VERY LIKELY)

FAILED TO JUDGE VEHICLE'S PATH OR SPEED (VERY LIKELY)

FAILED TO LOOK PROPERLY (POSSIBLE)

Date/Time: 08 November 2012

ater fille: 00 November 20

Severity: SERIOUS

Lighting Conditions:

Road/Link/Section/Chainage: A90 12276/90 (4,070m)

Junction Road Code: U

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Weather Conditions: Fine

Road Surface Conditions: Dry

Dark

Vehicle Details

Veh. No	Vehicle Type CAR	Direction SW NE	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD LEFT HAND BEND	Skidded/overturned SKIDDED	Hit Object in Cway NONE	Hit Object off Cway CENTRAL CRASH BARRIER
Veh. No 2	Vehicle Type AGRICULTURAL VEHICLE (INCLUDES DIGGERS ETC.)	Direction SW NE	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD LEFT HAND BEND	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SERIOUS

Contributory Factors

FAILED TO LOOK PROPERLY (POSSIBLE)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (POSSIBLE)

FOLLOWING TOO CLOSE (POSSIBLE)

DRIVING TOO SLOW FOR CONDITIONS OR SLOW VEH (EG. TRACTOR) (POSSIBLE)

Road/Link/Section/Chainage: A90 12237/06 (976m)

Date/Time: 12 July 2013

Junction Road Code: ?

Severity: SERIOUS

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type AGRICULTURAL VEHICLE (INCLUDES DIGGERS ETC.)	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway ENTERED DITCH

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SLIGHT
2	DRIVER			SLIGHT
2	VEHICLE OR PILLION PASSENGER			SERIOUS

Contributory Factors

Road/Link/Section/Chainage: A90 12276/51 (3,044m)

Date/Time: 18 July 2013

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

METRES OF, JUNCTION

Lighting Conditions: Light

Vehicle Details

Veh. No Vehicle Type Direction Location Skidded/overturned Hit Object in Cway Hit Object off Cway **Junction Location** Manoeuvres CAR **OVERTURNED KERB TREE** NSON MAIN NOT AT, OR WITHIN 20 **GOING AHEAD**

> **CARRIAGEWAY - NOT** IN RESTRICTED LANE

OTHER

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 DRIVER SLIGHT

Contributory Factors

Vehicle Type

Vehicle Type

AGRICULTURAL

Road/Link/Section/Chainage: A90 12272/25 (474m)

Direction

Direction

NE SW

NE SW

Date/Time: 20 August 2013

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

NONE

Road Surface Conditions: Wet

Weather Conditions: Rain **Vehicle Details**

CAR

Junction Location

NOT AT, OR WITHIN 20

METRES OF, JUNCTION

Lighting Conditions: Light

NO SKIDDING,

Hit Object in Cway Hit Object off Cway Manoeuvres Skidded/overturned

NONE

OTHER JACK-KNIFING OR **VEHICLE (INCLUDES CARRIAGEWAY - NOT** METRES OF, JUNCTION **OVERTURNING** DIGGERS ETC.)

IN RESTRICTED LANE

Skidded/overturned **Junction Location** Manoeuvres NOT AT, OR WITHIN 20

OTHER

GOING AHEAD

SKIDDED GOING AHEAD

Hit Object in Cway Hit Object off Cway

NONE

NONE

Casualty Details

Veh. No

Veh. No

2

Veh. No. **Casualty Class** Sex Age Severity DRIVER **SLIGHT**

Location

ON MAIN

Location

ON MAIN

CARRIAGEWAY - NOT

IN RESTRICTED LANE

Contributory Factors

Road/Link/Section/Chainage: A90 12250/63 (574m)

Date/Time: 20 August 2013

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres CHANGING LANE TO RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No	Vehicle Type GOODS VEHICLE OVER 3.5 TONNES AND UNDER 7.5 TONNES MGW	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres SLOWING OR STOPPING	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Contributory Factors

Road/Link/Section/Chainage: A90 12245/06 (1,236m)

Date/Time: 04 June 2013

Junction Road Code: ?

Severity: FATAL

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway PARKED VEHICLE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction PARKED	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres PARKED	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Contributory Factors

0

Road/Link/Section/Chainage: A90 12220/26 (5,377m)

Date/Time: 05 July 2013

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Road Surface Conditions: Dry

Lighting Conditions:

Light

Vehicle Details

Weather Conditions: Fine

Veh. No 1	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres SLOWING OR STOPPING	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NEARSIDE OR OFFSIDE CRASH BARRIER
Veh. No 2	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres WAITING TO GO AHEAD BUT HELD UP	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 3	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres WAITING TO GO AHEAD BUT HELD UP	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 4	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres WAITING TO GO AHEAD BUT HELD UP	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

Date/Time: 30 July 2013

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Severity: SLIGHT

Weather Conditions: Fine

Road/Link/Section/Chainage: A90 12250/11 (900m)

Road Surface Conditions: Dry

Lighting Conditions: Dark & Lit

Vehicle Details

Veh. No Vehicle Type Direction Location **Junction Location** Skidded/overturned Hit Object in Cway Hit Object off Cway Manoeuvres CAR **OVERTURNED** NONE CENTRAL CRASH NS**GOING AHEAD** ON MAIN NOT AT, OR WITHIN 20 METRES OF, JUNCTION

CARRIAGEWAY - NOT IN RESTRICTED LANE OTHER

BARRIER

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 DRIVER SLIGHT

Contributory Factors

Date/Time: 31 July 2013

Junction Road Code: ?

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12250/63 (2,014m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Light

Vehicle Details

Veh. No Vehicle Type Direction Location **Junction Location** Skidded/overturned Hit Object in Cway Hit Object off Cway Manoeuvres CAR SW NE **OVERTURNED KERB** ON MAIN **GOING AHEAD** NOT AT, OR WITHIN 20 CENTRAL CRASH

CARRIAGEWAY - NOT IN RESTRICTED LANE

OTHER METRES OF, JUNCTION

BARRIER

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 DRIVER SLIGHT

Contributory Factors

Road/Link/Section/Chainage: A90 12250/10 (1,497m)

Date/Time: 13 July 2013

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Junction Road Code: ? Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

	/ehicle Type CAR	Direction SW NE	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned OVERTURNED	Hit Object in Cway NONE	Hit Object off Cway NONE
--	----------------------------	---------------------------	---	---	---	----------------------------------	----------------------------	-----------------------------

Casualty Details

Veh. No.	Casualty Class DRIVER	Sex	Age	Severity SLIGHT
1	VEHICLE OR PILLION PASSENGER			SLIGHT
1	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

Date/Time: 28 September 2013

Junction Road Code: ?

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12276/71 (925m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Light

Vehicle Details

Veh. No Vehicle Type 1 CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned OVERTURNED	Hit Object in Cway KERB	Hit Object off Cway NONE
-------------------------------	-------------------------	---	--	------------------------------------	----------------------------------	----------------------------	------------------------------------

Casualty Details

Veh. No.	Casualty Class DRIVER	Sex	Age	Severity SLIGHT
1	VEHICLE OR PILLION PASSENGER			SLIGHT
1	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

LOSS OF CONTROL (POSSIBLE) DAZZLING SUN (POSSIBLE)

Date/Time: 23 January 2013

Road/Link/Section/Chainage: A90 12347/06 (1,301m)

Junction Road Code: U

Junction Location: MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROA

Weather Conditions: Snow

Road Surface Conditions: Snow

Lighting Conditions: Dark

Severity: SERIOUS

Vehicle Details

Veh. No	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres GOING AHEAD OTHER	Skidded/overturned SKIDDED AND OVERTURNED	Hit Object in Cway NONE	Hit Object off Cway ROAD SIGN / TRAFFIC SIGNAL
Veh. No 2	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SERIOUS
2	DRIVER			SERIOUS

Contributory Factors

TRAVELLING TOO FAST FOR CONDITIONS (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)

Date/Time: 13 October 2013

Junction Road Code: ?

Severity: SLIGHT

Road/Link/Section/Chainage: A90 12270/92 (3,590m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No Vehicle Type Direction Location Skidded/overturned Hit Object in Cway Hit Object off Cway **Junction Location** Manoeuvres CAR **OVERTURNED** NONE NS**GOING AHEAD** ON MAIN NOT AT, OR WITHIN 20 **CENTRAL CRASH**

CARRIAGEWAY - NOT IN RESTRICTED LANE

OTHER METRES OF, JUNCTION

BARRIER

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 DRIVER SLIGHT

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

Road/Link/Section/Chainage: A90 12276/51 (976m)

Date/Time: 04 July 2013

Junction Road Code: U

Severity: SERIOUS

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction NW S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location ENTERING MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction SW NE	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SERIOUS
2	DRIVER			SERIOUS

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)
POOR TURN OR MANOEUVRE (VERY LIKELY)

Date/Time: 25 November 2013

Junction Road Code: U

Severity: SERIOUS

Junction Location: CLEARED JUNCTION OR WAITING/PARKED AT JUNCTI

Road/Link/Section/Chainage: A90 12276/51 (3m)

Road Surface Conditions: Wet

Lighting Conditions: Dark

Vehicle Details

Weather Conditions: Fine

Veh. No	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction W S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location CLEARED JUNCTION OR WAITING/PARKED AT JUNCTION EXIT	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
2	CAR	SN	ON MAIN	APPROACHING JUNCTION	OVERTAKING	NO SKIDDING,	NONE	NONE
			CARRIAGEWAY - NOT	OR WAITING/PARKED AT	MOVING	JACK-KNIFING OR		
			IN RESTRICTED LANE	JUNCTION APPROACH	VEHICLE ON ITS	OVERTURNING		

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	DRIVER			SERIOUS

OFFSIDE

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

CARELESS/RECKLESS/IN A HURRY (VERY LIKELY)

Date/Time: 11 February 2013

Road/Link/Section/Chainage: A90 12270/91 (4,188m)

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Dark

Vehicle Details

Veh. No	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres CHANGING LANE TO RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres OVERTAKING MOVING VEHICLE ON ITS OFFSIDE	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway CENTRAL CRASH BARRIER

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	VEHICLE OR PILLION PASSENGER		Ĭ	SLIGH

Contributory Factors

POOR TURN OR MANOEUVRE (VERY LIKELY)

FAILED TO SIGNAL/MISLEADING SIGNAL (VERY LIKELY)

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

Date/Time: 01 October 2013

Junction Road Code: ?

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12240/96 (112m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Light

Vehicle Details

Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
1	CAR	EW	ON MAIN	NOT AT, OR WITHIN 20	GOING AHEAD	NO SKIDDING,	NONE	OTHER
			CARRIAGEWAY - NOT	METRES OF, JUNCTION	OTHER	JACK-KNIFING OR		PERMANENT
			IN RESTRICTED LANE			OVERTURNING		OBJECT

Casualty Details

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

Road/Link/Section/Chainage: A90 12240/08 (2,638m)

Date/Time: 25 October 2013

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Dark

Vehicle Details

Veh. No Vehicle Type Skidded/overturned Hit Object in Cway Hit Object off Cway Direction Location **Junction Location** Manoeuvres **OVERTURNED** NONE NS**GOING AHEAD GOODS VEHICLE 7.5** ON MAIN NOT AT, OR WITHIN 20 **CENTRAL CRASH** METRES OF, JUNCTION

TONNES MGW AND CARRIAGEWAY - NOT OVER IN RESTRICTED LANE OTHER

BARRIER

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 **DRIVER SLIGHT**

Contributory Factors

FATIGUE (POSSIBLE) SWERVED (POSSIBLE)

Date/Time: 14 November 2013 Accident Reference: 0001794

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine Road Surface Conditions: Wet

Vehicle Details

Road/Link/Section/Chainage: A90 12240/08 (302m)

Lighting Conditions: Dark

Severity: SLIGHT

Veh. No	Vehicle Type CAR	Direction E W	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres OVERTAKING MOVING VEHICLE ON ITS OFFSIDE	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction E W	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No	Vehicle Type CAR	Direction E W	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway CENTRAL CRASH BARRIER

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SLIGHT

Contributory Factors

LOSS OF CONTROL (POSSIBLE)

Weather Conditions: Fine

Road/Link/Section/Chainage: A90 12220/26 (7m)

Date/Time: 08 August 2013

Junction Road Code: B928

Severity: SLIGHT

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction W S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres WAITING TO TURN LEFT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (POSSIBLE)

INEXPERIENCE OF DRIVING ON THE LEFT (POSSIBLE)

Road/Link/Section/Chainage: A90 12220/26 (181m)

Date/Time: 10 January 2014

Junction Road Code: U522

Severity: FATAL

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Rain

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction E W	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location ENTERING MAIN ROAD	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No	o. Casualty Class	Sex	Age	Severity
1	DRIVER			FATAL
2	DRIVER			SLIGHT

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

Road/Link/Section/Chainage: A90 12225/86 (11m)

Date/Time: 19 January 2014

Severity: SLIGHT

Lighting Conditions:

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

Road Surface Conditions: Wet

Dark & Lit

Vehicle Details

Veh. No	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned OVERTURNED	Hit Object in Cway NONE	Hit Object off Cway NONE
			IN RESTRICTED LANE					

Casualty Details

Veh. No. Casualty Class	ss Sex Age	Age Severity
DRIVER		SLIGHT

Contributory Factors

IMPAIRED BY ALCOHOL (VERY LIKELY)

FATIGUE (POSSIBLE)

LOSS OF CONTROL (VERY LIKELY)

Road/Link/Section/Chainage: A90 12250/63 (2,468m)

Date/Time: 03 February 2014

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions:

Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type AGRICULTURAL VEHICLE (INCLUDES DIGGERS ETC.)	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
2	DRIVER			SLIGHT

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

FATIGUE (POSSIBLE)

Road/Link/Section/Chainage: A90 12270/91 (4,439m)

Date/Time: 08 January 2014

Junction Road Code: U

Severity: SLIGHT

Junction Location: MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROA

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction E N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway TREE
Veh. No 2	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	DRIVER			SLIGHT

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

Road/Link/Section/Chainage: A90 12272/25 (1,417m)

Date/Time: 30 January 2014

Junction Road Code: B9120

Severity: SERIOUS

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions:

Dark & Lit

Vehicle Details

Veh. No	Vehicle Type CAR	Direction E W	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location ENTERING MAIN ROAD	Manoeuvres MOVING OFF	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type GOODS VEHICLE OVER 3.5 TONNES AND UNDER 7.5 TONNES MGW	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres OVERTAKING MOVING VEHICLE ON ITS OFFSIDE	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 3	Vehicle Type CAR	Direction S E	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres WAITING TO TURN RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

CARELESS/RECKLESS/IN A HURRY (POSSIBLE)

Road/Link/Section/Chainage: A90 12272/05 (1,410m)

Date/Time: 28 December 2013

Date/Time: 20 Decemb

Severity: SERIOUS

Junction Road Code: B9120

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Dark

Vehicle Details

Veh. No	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction E N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location ENTERING MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
2	VEHICLE OR PILLION PASSENGER			SERIOUS

Contributory Factors

POOR TURN OR MANOEUVRE (VERY LIKELY)
FAILED TO LOOK PROPERLY (VERY LIKELY)

Road/Link/Section/Chainage: A90 12240/19 (914m)

Date/Time: 01 March 2014

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Road Surface Conditions: Dry

Weather Conditions: Fine

Lighting Conditions: Light

<u>Vehicle</u>	<u>Details</u>

Veh. No	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres CHANGING LANE TO LEFT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Casualty Class Sex Age Severity
DRIVER SLIG

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

Date/Time: 06 March 2014

Junction Road Code: C6

Severity: FATAL

Lighting Conditions:

Road/Link/Section/Chainage: A90 12220/26 (2,019m)

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Weather Conditions: Rain

Road Surface Conditions: Wet

Dark & Lit

Vehicle Details

Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
1	CAR	NS	ON MAIN	APPROACHING JUNCTION	GOING AHEAD	NO SKIDDING,	NONE	NONE
			CARRIAGEWAY - NOT	OR WAITING/PARKED AT	OTHER	JACK-KNIFING OR		
			IN RESTRICTED LANE	JUNCTION APPROACH		OVERTURNING		

Casualty Details

Veh. No. Casualty Class Sex Age Severity
PEDESTRIAN FATAL

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY) IMPAIRED BY ALCOHOL (VERY LIKELY)

PEDESTRIAN WEARING DARK CLOTHING AT NIGHT (VERY LIKELY)

Date/Time: 07 March 2014

Junction Road Code: U

Severity: SLIGHT

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions:

Dark & Lit

NONE

Hit Object in Cway

Vehicle Details

Veh. No Vehicle Type CAR

Road/Link/Section/Chainage: A90 12220/26 (2,188m)

Direction Location ON MAIN

NS

Junction Location APPROACHING JUNCTION **CARRIAGEWAY - NOT** OR WAITING/PARKED AT IN RESTRICTED LANE JUNCTION APPROACH

Manoeuvres **GOING AHEAD** OTHER

Skidded/overturned NO SKIDDING, JACK-KNIFING OR

OVERTURNING

Hit Object off Cway TREE

Casualty Details

1

Veh. No. **Casualty Class**

VEHICLE OR PILLION PASSENGER

Sex

Age

Severity **SLIGHT**

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

SWERVED (POSSIBLE)

Date/Time: 07 April 2013

Junction Road Code: ?

Severity: SERIOUS

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction S N	Location ON MAIN	Junction Location NOT AT. OR WITHIN 20	Manoeuvres GOING AHEAD	Skidded/overturned OVERTURNED	Hit Object in Cway NONE	Hit Object off Cway CENTRAL CRASH
			CARRIAGEWAY - NOT IN RESTRICTED LANE	METRES OF, JUNCTION	OTHER			BARRIER

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity	
1	DRIVER			SERIOUS	
1	VEHICLE OR PILLION PASSENGER			SERIOUS	

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

INEXPERIENCE WITH TYPE OF VEHICLE (VERY LIKELY)

Road/Link/Section/Chainage: A90 12240/18 (1,318m)

SUDDEN BRAKING (POSSIBLE)

Road/Link/Section/Chainage: A90 12240/71 (631m)

Date/Time: 08 April 2013

Junction Road Code: ?

Severity: SERIOUS

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned JACK-KNIFED	Hit Object in Cway KERB	Hit Object off Cway CENTRAL CRASH BARRIER
Veh. No 2	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SERIOUS

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

SWERVED (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

Date/Time: 01 May 2014

. . .

Severity: SERIOUS

Road/Link/Section/Chainage: A90 12240/07 (385m)

Junction Road Code: ?

Junction Location: MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROA

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction S E	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Contributory Factors

POOR OR DEFECTIVE ROAD SURFACE (VERY LIKELY)

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (POSSIBLE)

Road/Link/Section/Chainage: A90 12245/05 (1,776m)

Date/Time: 31 May 2014

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No 1	Vehicle Type GOODS VEHICLE OVER 3.5 TONNES AND UNDER 7.5 TONNES MGW	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres CHANGING LANE TO RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres OVERTAKING MOVING VEHICLE ON ITS OFFSIDE	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
2	DRIVER			SLIGHT

Contributory Factors

POOR TURN OR MANOEUVRE (VERY LIKELY)

Road/Link/Section/Chainage: A90 12220/25 (3,369m)

Date/Time: 09 June 2014

Severity: SLIGHT

Junction Road Code: U317

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Rain

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction E N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location ENTERING MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SLIGHT
1	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (POSSIBLE)

Date/Time: 20 June 2014

Junction Road Code: U

Severity: SERIOUS

Lighting Conditions:

Road/Link/Section/Chainage: A90 12220/26 (2,913m)

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Weather Conditions: Fine

Road Surface Conditions: Dry

Light

Vehicle Details

Veh. No	Vehicle Type GOODS VEHICLE OVER 3.5 TONNES AND UNDER 7.5 TONNES MGW	Direction S S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres U TURN	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway ROAD SIGN / TRAFFIC SIGNAL
Veh. No 2	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	DRIVER			SERIOUS

Contributory Factors

POOR TURN OR MANOEUVRE (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

Date/Time: 27 August 2014

ate/fille. 27 /tagast 20

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12276/70 (1,238m)

Junction Road Code: U

Junction Location: MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROA

Weather Conditions: Fine

Road Surface Conditions: Dry

Light

Vehicle Details

Veh. No	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction E N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type AGRICULTURAL VEHICLE (INCLUDES DIGGERS ETC.)	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	VEHICLE OR PILLION PASSENGER			SLIGHT
2	DRIVER			SLIGHT

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

JUNCTION RESTART (VERY LIKELY)

Date/Time: 28 August 2014

Junction Road Code: ?

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12347/05 (483m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

Road Surface Conditions: Wet

Light

Vehicle Details

Veh. No Vehicle Type Hit Object in Cway **Hit Object off Cway** Direction Location **Junction Location** Manoeuvres Skidded/overturned NONE SN **GOING AHEAD** NO SKIDDING, VAN/GOODS VEHICLE ON MAIN NOT AT, OR WITHIN 20 ROAD SIGN / OTHER JACK-KNIFING OR 3.5 TONNES MAXIMUM **CARRIAGEWAY - NOT** METRES OF, JUNCTION TRAFFIC SIGNAL **OVERTURNING GROSS WEIGHT** IN RESTRICTED LANE

Casualty Details

1

Casualty Class Veh. No. Sex Age Severity **DRIVER SLIGHT**

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

(MGW) AND UNDER

Weather Conditions: Fog

Date/Time: 20 July 2014

Road/Link/Section/Chainage: A90 12240/96 (322m)

Junction Road Code: ?

Severity: SERIOUS

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No Vehicle Type

1 MOTORCYCLE OVER
500CC

Direction N S Location
ON MAIN
CARRIAGEWAY - NOT
IN RESTRICTED LANE

Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION **Manoeuvres** GOING AHEAD OTHER **Skidded/overturned** NO SKIDDING, JACK-KNIFING OR

OVERTURNING

Hit Object in Cway NONE

Hit Object off Cway

Casualty Details

Veh. No. Casualty Class
1 DRIVER

Sex

Age

Severity SERIOUS

Contributory Factors

OVERLOADED OR POORLY LOADED VEHICLE OR TRAILER (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

Road/Link/Section/Chainage: A90 12225/08 (640m)

Date/Time: 01 July 2014

Junction Road Code: ?

. . .

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type VAN/GOODS VEHICLE 3.5 TONNES MAXIMUM GROSS WEIGHT (MGW) AND UNDER	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type VAN/GOODS VEHICLE 3.5 TONNES MAXIMUM GROSS WEIGHT (MGW) AND UNDER	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres WAITING TO GO AHEAD BUT HELD UP	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres OVERTAKING STATIONARY VEHICLE ON ITS OFFSIDE	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SLIGHT

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)
DISTRACTION IN VEHICLE (POSSIBLE)
DISTRACTION OUTSIDE VEHICLE (POSSIBLE)

Road/Link/Section/Chainage: A90 12225/07 (1,249m)

Date/Time: 20 July 2014

Junction Road Code: U309

Severity: SLIGHT

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No 1	Vehicle Type VAN/GOODS VEHICLE 3.5 TONNES MAXIMUM GROSS WEIGHT (MGW) AND UNDER	Direction E N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location ENTERING MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Casualty Class
R

Contributory Factors

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

FAILED TO LOOK PROPERLY (VERY LIKELY)

Date/Time: 09 August 2014

Junction Road Code: ?

Severity: SERIOUS

Lighting Conditions:

Road/Link/Section/Chainage: A90 12240/53 (1,008m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Light

Vehicle Details

Veh. No Vehicle Type Hit Object in Cway Hit Object off Cway Direction Location **Junction Location** Manoeuvres Skidded/overturned MOTORCYCLE OVER NONE SN **GOING AHEAD** NO SKIDDING, ON MAIN NOT AT, OR WITHIN 20 **CENTRAL CRASH** LEFT HAND 500CC **CARRIAGEWAY - NOT**

BEND

IN RESTRICTED LANE

METRES OF, JUNCTION

JACK-KNIFING OR **OVERTURNING**

BARRIER

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 **DRIVER SERIOUS**

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

Date/Time: 20 September 2014

Severity: SERIOUS

Lighting Conditions:

Road/Link/Section/Chainage: A90 12276/50 (6m) Junction Road Code: B966

Junction Location: MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROA

Weather Conditions: Fine

Road Surface Conditions: Dry

Dark

Vehicle Details

Veh. No	Vehicle Type CAR	Direction NE NW	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction SW NE	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class DRIVER	Sex	Age	Severity SLIGHT
2	VEHICLE OR PILLION PASSENGER			SERIOUS
2	VEHICLE OR PILLION PASSENGER			SERIOUS

Contributory Factors

INEXPERIENCE WITH TYPE OF VEHICLE (VERY LIKELY)

OTHER (VERY LIKELY)

Road/Link/Section/Chainage: A90 12272/51 (2,663m)

Date/Time: 24 September 2014

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Junction Road Code: ?

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
2	DRIVER			SLIGHT

Contributory Factors

SUDDEN BRAKING (VERY LIKELY)

INEXPERIENCE WITH TYPE OF VEHICLE (VERY LIKELY)

Date/Time: 07 October 2014

Junction Road Code: ?

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12347/05 (1,134m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

Road Surface Conditions: Wet

Light

Vehicle Details

Veh. No Vehicle Type Direction Hit Object in Cway Location **Junction Location** Manoeuvres Skidded/overturned Hit Object off Cway CAR NONE SN **GOING AHEAD** NO SKIDDING, ON MAIN NOT AT, OR WITHIN 20 **CENTRAL CRASH** OTHER **CARRIAGEWAY - NOT**

IN RESTRICTED LANE

METRES OF, JUNCTION

JACK-KNIFING OR **OVERTURNING**

BARRIER

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity VEHICLE OR PILLION PASSENGER 1 **SLIGHT**

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY) TRAVELLING TOO FAST FOR CONDITIONS (VERY LIKELY)

Date/Time: 22 September 2014

Severity: SERIOUS

Road/Link/Section/Chainage: A90 12220/25 (5,407m)

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Weather Conditions: Fine

Road Surface Conditions: Dry

Junction Road Code: U

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type GOODS VEHICLE OVER 3.5 TONNES AND UNDER 7.5 TONNES MGW	Direction S W	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location LEAVING MAIN ROAD	Manoeuvres TURNING LEFT	Skidded/overturned OVERTURNED	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class DRIVER	Sex	Age	Severity SLIGHT
2	VEHICLE OR PILLION PASSENGER			SERIOUS
2	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

FOLLOWING TOO CLOSE (POSSIBLE)

FAILED TO LOOK PROPERLY (VERY LIKELY)

DISTRACTION IN VEHICLE (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (POSSIBLE)

Date/Time: 01 August 2014

Innetion Bood Code:

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12240/96 (87m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Light

Vehicle Details

Veh. No Vehicle Type
1 GOODS VEHICLE
OVER 3.5 TONNES

Direction Location
NE SW ON MAIN

LocationJunction LocationON MAINNOT AT, OR WITHIN 20CARRIAGEWAY - NOTMETRES OF, JUNCTIONIN RESTRICTED LANE

Manoeuvres GOING AHEAD OTHER

Skidded/overturned NO SKIDDING, JACK-KNIFING OR

OVERTURNING

Hit Object in Cway
NONE
Hit Object off Cway
ENTERED DITCH

Casualty Details

1

Veh. No. Casualty Class

AND UNDER 7.5

TONNES MGW

VEHICLE OR PILLION PASSENGER

Sex

Age

Severity SLIGHT

Contributory Factors

FATIGUE (VERY LIKELY)

TYRES ILLEGAL, DEFECTIVE OR UNDER INFLATED (POSSIBLE)

Road/Link/Section/Chainage: A90 12240/34 (696m)

Date/Time: 10 July 2014

Junction Road Code: ?

Severity: SLIGHT

Junction Location: CLEARED JUNCTION OR WAITING/PARKED AT JUNCTI

Weather Conditions: Fine

Veh. No Vehicle Type

Road Surface Conditions: Dry

Junction Location

WAITING/PARKED AT

JUNCTION EXIT

CLEARED JUNCTION OR

Lighting Conditions: Light

Vehicle Details

OTHER

Manoeuvres

GOING AHEAD

Skidded/overturned NO SKIDDING, JACK-KNIFING OR

OVERTURNING

Hit Object in Cway NONE

Hit Object off Cway
CENTRAL CRASH

BARRIER

Casualty Details

Veh. No. Casualty Class
1 DRIVER

OTHER MOTOR

VEHICLE

Sex

Age

Severity SLIGHT

Contributory Factors

ILLNESS OR DISABILITY, MENTAL OR PHYSICAL (VERY LIKELY)

Direction

NS

Location

ON MAIN

CARRIAGEWAY - NOT

IN RESTRICTED LANE

Date/Time: 18 July 2014

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12240/96 (1,043m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Light

Vehicle Details

Veh. No Vehicle Type Direction Hit Object in Cway Hit Object off Cway Location **Junction Location** Manoeuvres Skidded/overturned CAR SN NONE **GOING AHEAD** NO SKIDDING, ON MAIN NOT AT, OR WITHIN 20 CENTRAL CRASH OTHER

CARRIAGEWAY - NOT METRES OF, JUNCTION IN RESTRICTED LANE

JACK-KNIFING OR **OVERTURNING**

BARRIER

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 **DRIVER SLIGHT**

Contributory Factors

ILLNESS OR DISABILITY, MENTAL OR PHYSICAL (VERY LIKELY)

Road/Link/Section/Chainage: A90 12240/95 (840m)

Date/Time: 28 October 2014

Severity: SLIGHT

Lighting Conditions:

Junction Road Code: A935

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

Road Surface Conditions: Wet

Light

Vehicle Details

Veh. N	o Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
1	GOODS VEHICLE 7.5	SN	ON MAIN	NOT AT, OR WITHIN 20	CHANGING	NO SKIDDING,	NONE	NONE
	TONNES MGW AND		CARRIAGEWAY - NOT	METRES OF, JUNCTION	LANE TO RIGHT	JACK-KNIFING OR		
	OVER		IN RESTRICTED LANE			OVERTURNING		
Veh. N	o Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
2	CAR	SN	ON MAIN	NOT AT, OR WITHIN 20	OVERTAKING	NO SKIDDING,	NONE	CENTRAL CRASH
			CARRIAGEWAY - NOT	METRES OF, JUNCTION	MOVING	JACK-KNIFING OR		BARRIER
			IN RESTRICTED LANE		VEHICLE ON ITS	OVERTURNING		
					OFFSIDE			

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	DRIVER			SLIGHT

Contributory Factors

TRAVELLING TOO FAST FOR CONDITIONS (POSSIBLE)

POOR TURN OR MANOEUVRE (POSSIBLE)

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

CARELESS/RECKLESS/IN A HURRY (POSSIBLE)

Date/Time: 13 January 2015

Severity: SERIOUS

Lighting Conditions:

Road/Link/Section/Chainage: A90 12225/23 (404m)

Junction Road Code: B9127

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Snow

Road Surface Conditions: Snow

Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type VAN/GOODS VEHICLE 3.5 TONNES MAXIMUM GROSS WEIGHT (MGW) AND UNDER	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 3	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 4	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
3	DRIVER			SERIOUS

Contributory Factors

TRAVELLING TOO FAST FOR CONDITIONS (VERY LIKELY)

CARELESS/RECKLESS/IN A HURRY (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

Date/Time: 29 December 2014

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12276/06 (859m)

Junction Road Code: U

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Weather Conditions: Fine

Road Surface Conditions: Wet

Light

Vehicle Details

Veh. No 1	Vehicle Type VAN/GOODS VEHICLE 3.5 TONNES MAXIMUM GROSS WEIGHT (MGW) AND UNDER	Direction NW SW	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres WAITING TO TURN RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction NE SW	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 3	Vehicle Type CAR	Direction NE SW	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location MID JUNCTION - ON ROUNDABOUT OR ON MAIN ROAD	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Casualty Class VEHICLE OR PILLION PASSENGER	Veh. No. 2
,	DRIVER

Contributory Factors

JUNCTION OVERSHOOT (VERY LIKELY)

DAZZLING SUN (POSSIBLE)

Road/Link/Section/Chainage: A90 12276/51 (2,614m)

Date/Time: 01 April 2015

Junction Road Code: U

JUNCTION EXIT

Severity: SLIGHT

OVERTURNING

Junction Location: CLEARED JUNCTION OR WAITING/PARKED AT JUNCTI

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No Vehicle Type Hit Object in Cway Direction Location **Junction Location** Manoeuvres Skidded/overturned Hit Object off Cway CAR NONE NE SW **GOING AHEAD** NO SKIDDING, ON LAY-BY OR HARD **CLEARED JUNCTION OR** ROAD SIGN / OTHER JACK-KNIFING OR SHOULDER WAITING/PARKED AT TRAFFIC SIGNAL

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 **DRIVER SLIGHT**

Contributory Factors

NOT DISPLAYING LIGHTS AT NIGHT OR IN POOR VISIBILITY (VERY LIKELY)

Road/Link/Section/Chainage: A90 12240/08 (901m)

Date/Time: 04 February 2015

Junction Road Code: ?

Severity: FATAL

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Dark

Vehicle Details

1

Veh. No Vehicle Type Direction Location

NE SW

Junction Location ON MAIN NOT AT, OR WITHIN 20 **CARRIAGEWAY - NOT** METRES OF, JUNCTION Manoeuvres **GOING AHEAD** OTHER

Skidded/overturned **OVERTURNED**

Hit Object in Cway NONE

Hit Object off Cway OTHER **PERMANENT**

OBJECT

OVER

Casualty Details Veh. No.

Casualty Class DRIVER

GOODS VEHICLE 7.5

TONNES MGW AND

Sex

IN RESTRICTED LANE

Age

Severity **FATAL**

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

FATIGUE (POSSIBLE)

Date/Time: 08 February 2015

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12240/71 (490m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

Dark

Vehicle Details

Veh. No Vehicle Type Direction Skidded/overturned Hit Object in Cway Hit Object off Cway Location **Junction Location** Manoeuvres CAR **OVERTURNED** NONE NONE $\mathsf{E}\,\mathsf{W}$ **GOING AHEAD** ON MAIN NOT AT, OR WITHIN 20

CARRIAGEWAY - NOT IN RESTRICTED LANE

METRES OF, JUNCTION OT

OTHER

Casualty Details

Veh. No.Casualty ClassSexAgeSeverity1DRIVERSLIGHT

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

Date/Time: 21 February 2015

Junction Road Code: A920

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12233/06 (77m) Junction Ro

Junction Location: CLEARED JUNCTION OR WAITING/PARKED AT JUNCTI

Weather Conditions: Fine

Road Surface Conditions: Dry

Dark & Lit

Vehicle Details

Veh. No	Vehicle Type CAR	Direction E W	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location CLEARED JUNCTION OR WAITING/PARKED AT JUNCTION EXIT	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	DRIVER			SLIG

Contributory Factors

POOR TURN OR MANOEUVRE (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

Road/Link/Section/Chainage: A90 12225/85 (18m)

Date/Time: 20 March 2015

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No Vehicle Type Direction Location **Junction Location** Skidded/overturned Hit Object in Cway Hit Object off Cway Manoeuvres CAR SE **OVERTURNED** NONE NONE NOT AT, OR WITHIN 20 **GOING AHEAD** ON MAIN **CARRIAGEWAY - NOT** METRES OF, JUNCTION

IN RESTRICTED LANE

OTHER

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 DRIVER SLIGHT

Contributory Factors

FATIGUE (VERY LIKELY)

Road/Link/Section/Chainage: A90 12276/91 (4,005m)

Date/Time: 17 May 2015

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction E W	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD RIGHT HAND BEND	Skidded/overturned OVERTURNED	Hit Object in Cway KERB	Hit Object off Cway CENTRAL CRASH BARRIER
---------	----------------------------	-------------------------	---	--	---	----------------------------------	-----------------------------------	---

Casualty Details

Veh. No. 1	Casualty Class DRIVER	Sex	Age	Severity SLIGHT
1	VEHICLE OR PILLION PASSENGER		Ē	SLIGHT

Contributory Factors

DISTRACTION IN VEHICLE (POSSIBLE)

Date/Time: 29 June 2015

Severity: SERIOUS

Road/Link/Section/Chainage: A90 12276/12 (1,705m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction N S	Location ON LAY-BY OR HARD SHOULDER	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction PARKED	Location ON LAY-BY OR HARD SHOULDER	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres PARKED	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SERIOUS

Contributory Factors

ILLNESS OR DISABILITY, MENTAL OR PHYSICAL (POSSIBLE)

Vehicle Type

CAR

Road/Link/Section/Chainage: A90 12220/25 (3,871m)

Direction

IN RESTRICTED LANE

SN

Date/Time: 04 May 2015

Junction Road Code: U

Severity: SLIGHT

Weather Conditions: Fine

Road Surface Conditions: Dry

JUNCTION EXIT

Lighting Conditions:

Light

Junction Location: CLEARED JUNCTION OR WAITING/PARKED AT JUNCTI

Hit Object off Cway

NONE

Vehicle Details

Veh. No

2

Veh. No Vehicle Type Direction Location **Junction Location** Manoeuvres Skidded/overturned Hit Object in Cway Hit Object off Cway CAR TURNING RIGHT NONE ENNO SKIDDING, NONE ON MAIN CLEARED JUNCTION OR JACK-KNIFING OR **CARRIAGEWAY - NOT**

WAITING/PARKED AT **OVERTURNING** JUNCTION EXIT

IN RESTRICTED LANE Skidded/overturned Hit Object in Cway Location **Junction Location** Manoeuvres

OVERTURNED NONE **GOING AHEAD** ON MAIN **CLEARED JUNCTION OR CARRIAGEWAY - NOT** WAITING/PARKED AT OTHER

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity **DRIVER SLIGHT**

Contributory Factors

POOR TURN OR MANOEUVRE (VERY LIKELY)

FAILED TO LOOK PROPERLY (VERY LIKELY)

Road/Link/Section/Chainage: A90 12225/08 (1,916m)

Date/Time: 22 June 2015

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
1	CAR	NS	ON MAIN	NOT AT, OR WITHIN 20	GOING AHEAD	NO SKIDDING,	NONE	NONE
			CARRIAGEWAY - NOT	METRES OF, JUNCTION	OTHER	JACK-KNIFING OR		
			IN RESTRICTED LANE			OVERTURNING		

Casualty Details

Contributory Factors

EXCEEDING SPEED LIMIT (POSSIBLE)
SUDDEN BRAKING (VERY LIKELY)
SWERVED (VERY LIKELY)
DAZZLING SUN (POSSIBLE)

Road/Link/Section/Chainage: A90 12225/23 (1,344m)

Date/Time: 17 June 2015

Severity: SLIGHT

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
V	ELUOLE OD DULLON DAGOENOED		Ĭ	SLIG

Contributory Factors

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

FOLLOWING TOO CLOSE (VERY LIKELY)

SUDDEN BRAKING (POSSIBLE)

Road/Link/Section/Chainage: A90 12250/10 (810m)

Date/Time: 21 August 2015

Junction Road Code: ?

Severity: FATAL

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

Road Surface Conditions: Wet

Lighting Conditions: Dark

Vehicle Details

Veh. No	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres OVERTAKING MOVING VEHICLE ON ITS OFFSIDE	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	PEDESTRIAN			FATAL

Contributory Factors

FAILED TO LOOK PROPERLY (POSSIBLE)

DANGEROUS ACTION IN CARRIAGEWAY (EG. PLAYING) (POSSIBLE)

IMPAIRED BY ALCOHOL (POSSIBLE)

IMPAIRED BY DRUGS (ILLICIT OR MEDICINAL) (POSSIBLE)

Date/Time: 01 September 2015

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Light

Severity: SLIGHT

Vehicle Details

Veh. No Vehicle Type Hit Object in Cway **Hit Object off Cway** Direction Location **Junction Location** Manoeuvres Skidded/overturned OTHER OBJECT NONE N SW **GOING AHEAD** NO SKIDDING, VAN/GOODS VEHICLE ON MAIN NOT AT, OR WITHIN 20

GROSS WEIGHT

3.5 TONNES MAXIMUM

(MGW) AND UNDER

CARRIAGEWAY - NOT METRES OF, JUNCTION IN RESTRICTED LANE

RIGHT HAND BEND

JACK-KNIFING OR **OVERTURNING**

Casualty Details

1

Veh. No. **Casualty Class** Sex Age Severity **DRIVER SLIGHT**

Contributory Factors

ANIMAL OR OBJECT IN CARRIAGEWAY (VERY LIKELY)

Road/Link/Section/Chainage: A90 12276/91 (703m)

Date/Time: 03 November 2015

Junction Road Code: ?

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12220/25 (3,019m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fog

Road Surface Conditions: Wet

Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres OVERTAKING MOVING VEHICLE ON ITS OFFSIDE	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
---------	----------------------------	-------------------------	--	--	---	--	----------------------------	-----------------------------

Casualty Details

Ve	eh. No.	Casualty Class	Sex	Age	Severity
1		PEDESTRIAN			SLIGHT
1		PEDESTRIAN			SLIGHT

Contributory Factors

RAIN, SLEET, SNOW, OR FOG (VERY LIKELY)

RAIN, SLEET, SNOW, OR FOG (VERY LIKELY)

CARELESS/RECKLESS/IN A HURRY (POSSIBLE)

FAILED TO JUDGE VEHICLE'S PATH OR SPEED (POSSIBLE)

CARELESS/RECKLESS/IN A HURRY (POSSIBLE) RAIN, SLEET, SNOW, OR FOG (VERY LIKELY)

Date/Time: 02 January 2015

antina Dand Cada: A04

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12228/05 (1,913m)

Junction Road Code: A94

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Weather Conditions: Fine

Road Surface Conditions: Wet

Dark & Lit

Vehicle Details

Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
1	CAR	SN	ON MAIN	APPROACHING JUNCTION	GOING AHEAD	NO SKIDDING,	NONE	OTHER
			CARRIAGEWAY - NOT	OR WAITING/PARKED AT	OTHER	JACK-KNIFING OR		PERMANENT
			IN RESTRICTED LANE	JUNCTION APPROACH		OVERTURNING		OBJECT

Casualty Details

Veh. No. Casualty Class Sex Age Severity
DRIVER SLIGHT

Contributory Factors

JUNCTION OVERSHOOT (POSSIBLE)
SUDDEN BRAKING (POSSIBLE)
SWERVED (POSSIBLE)
FATIGUE (POSSIBLE)
OTHER (VERY LIKELY)

Date/Time: 26 January 2015

Junction Road Code: U

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12220/25 (3,875m)

IN RESTRICTED LANE

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Weather Conditions: Fine

Road Surface Conditions: Dry

JUNCTION APPROACH

Dark & Unlit

Vehicle Details

Veh. No Vehicle Type Direction Hit Object in Cway **Hit Object off Cway** Location **Junction Location** Manoeuvres Skidded/overturned CAR NONE NONE SN **GOING AHEAD** SKIDDED AND ON MAIN APPROACHING JUNCTION OTHER **OVERTURNED CARRIAGEWAY - NOT** OR WAITING/PARKED AT

Casualty Details

Contributory Factors

EXCEEDING SPEED LIMIT (VERY LIKELY)

SUDDEN BRAKING (VERY LIKELY)

FAILED TO LOOK PROPERLY (VERY LIKELY)

Accident Reference: 0000551 Date/Til

Date/Time: 24 November 2015

Junction Road Code: U

Junction Location: CLEARED JUNCTION OR WAITING/PARKED AT JUNCTI

Weather Conditions: Fine

Road/Link/Section/Chainage: A90 12240/71 (175m)

Road Surface Conditions: Wet

Lighting Conditions: Light

Severity: SLIGHT

Vehicle Details

1	eh. No	Vehicle Type CAR	Direction E W	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location CLEARED JUNCTION OR WAITING/PARKED AT JUNCTION EXIT	Manoeuvres MOVING OFF	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
2	eh. No	Vehicle Type GOODS VEHICLE OVER 3.5 TONNES AND UNDER 7.5 TONNES MGW	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	DRIVER			SLIGH

Contributory Factors

CARELESS/RECKLESS/IN A HURRY (VERY LIKELY)

POOR TURN OR MANOEUVRE (VERY LIKELY)

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

VEHICLE BLIND SPOT (POSSIBLE)

ROAD LAYOUT (EG. BEND, HILL, NARROW CARRIAGEWAY) (POSSIBLE)

Date/Time: 25 November 2015

Severity: FATAL

Road/Link/Section/Chainage: A90 12240/71 (1,828m) Junction Road Code: U Junction Location: CLEARED JUNCTION OR WAITING/PARKED AT JUNCTI

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND	Direction E S	Location ON MAIN CARRIAGEWAY - NOT	Junction Location CLEARED JUNCTION OR WAITING/PARKED AT	Manoeuvres WAITING TO GO AHEAD BUT HELD UP	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No	OVER Vehicle Type	Direction	IN RESTRICTED LANE Location	JUNCTION EXIT Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
2	CAR	S N	ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	GOING AHEAD OTHER	NO SKIDDING, JACK-KNIFING OR OVERTURNING	PARKED VEHICLE	NONE

Casualty Details

/eh. No.		Age	Severity
	DRIVER	Ĭ	FATAI

Contributory Factors

POOR TURN OR MANOEUVRE (VERY LIKELY) FAILED TO LOOK PROPERLY (VERY LIKELY)

Road/Link/Section/Chainage: A90 12272/50 (616m)

Direction

SN

Location

ON MAIN

IN RESTRICTED LANE

Date/Time: 20 June 2013

Junction Road Code: U

Severity: SERIOUS

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Lighting Conditions: Light

Vehicle Details

Weather Conditions: Fine

Veh. No Vehicle Type

CAR

Road Surface Conditions: Dry

JUNCTION APPROACH

Hit Object in Cway **Junction Location** Manoeuvres Skidded/overturned Hit Object off Cway **KERB GOING AHEAD** SKIDDED AND APPROACHING JUNCTION ROAD SIGN / OTHER **OVERTURNED CARRIAGEWAY - NOT** OR WAITING/PARKED AT TRAFFIC SIGNAL

Casualty Details

Veh. No.	Casualty Class DRIVER	Sex	Age	Severity SLIGHT
1	VEHICLE OR PILLION PASSENGER			SERIOUS
1	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

FATIGUE (VERY LIKELY)

CARELESS/RECKLESS/IN A HURRY (VERY LIKELY)

Date/Time: 27 January 2016

•

Severity: SERIOUS

Lighting Conditions:

OVERTURNING

Road/Link/Section/Chainage: A90 12240/70 (240m)

Junction Road Code: ?

IN RESTRICTED LANE

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

Road Surface Conditions: Wet

Dark

Vehicle Details

Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
1	CAR	SN	ON MAIN	NOT AT, OR WITHIN 20	GOING AHEAD	NO SKIDDING,	NONE	TREE
			CARRIAGEWAY - NOT	METRES OF, JUNCTION	OTHER	JACK-KNIFING OR		

Casualty Details

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)
SUDDEN BRAKING (VERY LIKELY)

Date/Time: 30 January 2016

Junction Road Code: ?

Severity: SERIOUS

Lighting Conditions:

Road/Link/Section/Chainage: A90 12233/05 (1,903m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

Road Surface Conditions: Wet

Dark & Lit

Vehicle Details

Veh. No Vehicle Type Direction Hit Object in Cway Hit Object off Cway Location **Junction Location** Manoeuvres Skidded/overturned CAR SN NONE LAMP POST **GOING AHEAD** NO SKIDDING, ON MAIN NOT AT, OR WITHIN 20 **CARRIAGEWAY - NOT** METRES OF, JUNCTION

IN RESTRICTED LANE

OTHER

JACK-KNIFING OR

OVERTURNING

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 **DRIVER SERIOUS**

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

Date/Time: 30 January 2016

Junction Road Code: ?

Severity: SLIGHT

Road/Link/Section/Chainage: A90 12250/70 (908m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Ice

Lighting Conditions: Dark

Vehicle Details

Veh. No	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres OVERTAKING STATIONARY VEHICLE ON ITS OFFSIDE	Skidded/overturned SKIDDED	Hit Object in Cway NONE	Hit Object off Cway CENTRAL CRASH BARRIER
Veh. No 2	Vehicle Type BUS OR COACH (17 OR MORE PASSENGER SEATS)	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	DRIVER			SLIGHT

Contributory Factors

SLIPPERY ROAD (DUE TO WEATHER) (VERY LIKELY) TRAVELLING TOO FAST FOR CONDITIONS (POSSIBLE)

LOSS OF CONTROL (VERY LIKELY)

DISTRACTION OUTSIDE VEHICLE (POSSIBLE)

Date/Time: 16 February 2016

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12245/05 (4,276m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Dark

Vehicle Details

Veh. No Vehicle Type Direction Hit Object in Cway **Hit Object off Cway** Location **Junction Location** Manoeuvres Skidded/overturned CAR SN NONE **TREE GOING AHEAD** SKIDDED AND ON MAIN NOT AT, OR WITHIN 20

CARRIAGEWAY - NOT

OTHER METRES OF, JUNCTION

IN RESTRICTED LANE

OVERTURNED

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 DRIVER SLIGHT

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

SWERVED (POSSIBLE)

Road/Link/Section/Chainage: A90 12250/10 (1,944m)

Date/Time: 07 February 2016

Junction Road Code: ?

Severity: SERIOUS

Lighting Conditions:

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

Road Surface Conditions: Wet

Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR	Hit Object in Cway NONE	Hit Object off Cway ROAD SIGN / TRAFFIC SIGNAL
			IN RESTRICTED LANE	, , , , , , , , ,		OVERTURNING		

Casualty Details

Veh. No.	Casualty Class DRIVER	Sex	Age	Severity SLIGHT
1	VEHICLE OR PILLION PASSENGER			SERIOUS

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

SWERVED (POSSIBLE)

RAIN, SLEET, SNOW, OR FOG (VERY LIKELY)

Weather Conditions: Fine

Road/Link/Section/Chainage: A90 12240/96 (1,011m)

Date/Time: 11 May 2016

Road Surface Conditions: Dry

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Light

Lighting Conditions:

Vehicle Details

Veh. No Vehicle Type Direction Location Skidded/overturned Hit Object in Cway Hit Object off Cway **Junction Location** Manoeuvres CAR **OVERTURNED** NONE NS**GOING AHEAD** ON MAIN NOT AT, OR WITHIN 20 CENTRAL CRASH

CARRIAGEWAY - NOT IN RESTRICTED LANE

OTHER METRES OF, JUNCTION

BARRIER

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 DRIVER SLIGHT

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

Date/Time: 17 June 2016

Severity: SERIOUS

Road/Link/Section/Chainage: A90 12220/26 (2,216m)

Junction Road Code: C6

Junction Location: CLEARED JUNCTION OR WAITING/PARKED AT JUNCTI

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction E W	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location CLEARED JUNCTION OR WAITING/PARKED AT JUNCTION EXIT	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 3	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location CLEARED JUNCTION OR WAITING/PARKED AT JUNCTION EXIT	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway CENTRAL CRASH BARRIER

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SERIOUS
2	DRIVER			SERIOUS

Contributory Factors

POOR TURN OR MANOEUVRE (VERY LIKELY) FAILED TO LOOK PROPERLY (VERY LIKELY)

Road/Link/Section/Chainage: A90 12276/91 (3,605m)

Date/Time: 19 August 2016

Junction Road Code: U

Severity: SLIGHT

Junction Location: ENTERING MAIN ROAD

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type VAN/GOODS VEHICLE 3.5 TONNES MAXIMUM GROSS WEIGHT (MGW) AND UNDER	Direction W S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location ENTERING MAIN ROAD	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction S N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned SKIDDED AND OVERTURNED	Hit Object in Cway KERB	Hit Object off Cway NONE

Casualty Details

Casualty Class Sex Age Severit
DRIVER

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

Date/Time: 10 August 2016

Severity: SERIOUS

Lighting Conditions:

Road/Link/Section/Chainage: A90 12220/25 (3,872m)

Junction Road Code: C6

Junction Location: CLEARED JUNCTION OR WAITING/PARKED AT JUNCTI

Weather Conditions: Rain Road Surface Conditions: Wet

Light

Vehicle Details

Veh. No 1	Vehicle Type CAR	Direction E N	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location CLEARED JUNCTION OR WAITING/PARKED AT JUNCTION EXIT	Manoeuvres TURNING RIGHT	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location APPROACHING JUNCTION OR WAITING/PARKED AT JUNCTION APPROACH	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

ſ	Veh. No.	Casualty Class	Sex	Age	Severity
	1	DRIVER			SLIGHT
	2	DRIVER			SERIOUS

Contributory Factors

FAILED TO LOOK PROPERLY (VERY LIKELY)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

Date/Time: 13 October 2016

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Veh. No Vehicle Type

CAR

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Hit Object in Cway Direction Location **Junction Location** Manoeuvres Skidded/overturned

> **CARRIAGEWAY - NOT** IN RESTRICTED LANE

NOT AT, OR WITHIN 20 METRES OF, JUNCTION **GOING AHEAD** OTHER

NO SKIDDING, JACK-KNIFING OR

OVERTURNING

NONE

Hit Object off Cway NONE

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 **DRIVER SLIGHT**

ON MAIN

Contributory Factors

DEPOSIT ON ROAD (EG. OIL, MUD, CHIPPINGS) (POSSIBLE)

Road/Link/Section/Chainage: A90 12276/91 (4,191m)

NE SW

LOSS OF CONTROL (VERY LIKELY)

Accident Reference: 0000549

Date/Time: 27 September 2016

Severity: FATAL

Road/Link/Section/Chainage: A90 12240/08 (2,442m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Rain

Road Surface Conditions: Wet

Lighting Conditions: Dark

Vehicle Details

IN RESTRICTED LANE	Veh. No 1	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned OVERTURNED	Hit Object in Cway NONE	Hit Object off Cway WALL OR FENCE
--------------------	--------------	----------------------------	-------------------------	---	--	------------------------------------	----------------------------------	-----------------------------------	--------------------------------------

Casualty Details

Veh. No.	Casualty Class Sex Age Se
	DRIVER FA

Contributory Factors

SUDDEN BRAKING (POSSIBLE) LOSS OF CONTROL (POSSIBLE) SWERVED (POSSIBLE)

Date/Time: 27 October 2016

Junction Road Code: ?

Severity: SERIOUS

Lighting Conditions:

Road/Link/Section/Chainage: A90 12220/25 (1,039m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

500CC

Road Surface Conditions: Dry

METRES OF, JUNCTION

Dark

Vehicle Details

Veh. No Vehicle Type Skidded/overturned Hit Object in Cway **Hit Object off Cway** Direction Location **Junction Location** Manoeuvres MOTORCYCLE OVER **OVERTURNED** NONE **TREE** SN **GOING AHEAD** ON MAIN NOT AT, OR WITHIN 20

> **CARRIAGEWAY - NOT** IN RESTRICTED LANE

OTHER

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 **DRIVER SERIOUS**

Contributory Factors

ANIMAL OR OBJECT IN CARRIAGEWAY (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

Date/Time: 18 November 2016

Severity: SERIOUS

Lighting Conditions:

Road/Link/Section/Chainage: A90 12220/26 (4,168m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Dark

Vehicle Details

Veh. No	Vehicle Type CAR	Direction SS	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres U TURN	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway CENTRAL CRASH BARRIER

Casualty Details

Veh. No.	Casualty Class DRIVER	Sex	Age	Severity SERIOUS
1	VEHICLE OR PILLION PASSENGER			SLIGHT
2	DRIVER			SERIOUS
2	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

POOR TURN OR MANOEUVRE (VERY LIKELY)

FAILED TO LOOK PROPERLY (VERY LIKELY)

Date/Time: 19 November 2016 2

Severity: SERIOUS

Road/Link/Section/Chainage: A90 12225/86 (112m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

Lighting Conditions: Dark & Lit

Vehicle Details

Veh. No 1	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE		Manoeuvres OVERTAKING MOVING VEHICLE ON ITS OFFSIDE	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway LAMP POST

Casualty Details

Veh. No.	Casualty Class DRIVER	Sex	Age	Severity SERIOUS
2	DRIVER			SERIOUS
2	VEHICLE OR PILLION PASSENGER			SERIOUS

Contributory Factors

FAILED TO LOOK PROPERLY (POSSIBLE)

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (POSSIBLE)

FATIGUE (POSSIBLE)

Road/Link/Section/Chainage: A90 12276/51 (2,552m)

Date/Time: 14 October 2015

Junction Road Code: ?

Severity: SERIOUS

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type VAN/GOODS VEHICLE 3.5 TONNES MAXIMUM GROSS WEIGHT (MGW) AND UNDER	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres MOVING OFF	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	DRIVER			SERIOUS

Contributory Factors

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

ILLNESS OR DISABILITY, MENTAL OR PHYSICAL (POSSIBLE)

DISTRACTION IN VEHICLE (POSSIBLE)

FATIGUE (POSSIBLE)

Date/Time: 06 June 2016

Severity: SERIOUS

Lighting Conditions:

Road/Link/Section/Chainage: A90 12220/26 (5,599m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction PARKED	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres PARKED	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SERIOUS
1	VEHICLE OR PILLION PASSENGER			SLIGHT

Contributory Factors

FATIGUE (VERY LIKELY)

POOR TURN OR MANOEUVRE (VERY LIKELY)

Date/Time: 02 February 2017

Junction Road Code: ?

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12272/51 (693m)

Junction Road Gode.

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Wet

Dark

Vehicle Details

Veh. No	Vehicle Type CAR	Direction N SW	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres SLOWING OR STOPPING	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction N SW	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway OTHER OBJECT	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SLIGHT
2	DRIVER			SLIGHT

Contributory Factors

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

Date/Time: 19 January 2017

Severity: SLIGHT

Road/Link/Section/Chainage: A90 12250/11 (1,426m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned OVERTURNED	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction PARKED	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres PARKED	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SLIGHT

Contributory Factors

DAZZLING SUN (VERY LIKELY)

Date/Time: 21 January 2017

Junction Road Code: ?

Severity: SLIGHT

Lighting Conditions:

Road/Link/Section/Chainage: A90 12250/11 (651m)

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fog

Road Surface Conditions: Wet

Dark

Vehicle Details

Veh. No Vehicle Type Direction Hit Object in Cway Hit Object off Cway Location **Junction Location** Manoeuvres Skidded/overturned CAR NONE NS **GOING AHEAD** NO SKIDDING, ON MAIN NOT AT, OR WITHIN 20 CENTRAL CRASH **CARRIAGEWAY - NOT** METRES OF, JUNCTION

IN RESTRICTED LANE

OTHER

JACK-KNIFING OR

OVERTURNING

BARRIER

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 **DRIVER SLIGHT**

Contributory Factors

RAIN, SLEET, SNOW, OR FOG (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

Road/Link/Section/Chainage: A90 12240/53 (847m)

Date/Time: 10 March 2017

Junction Road Code: ?

Severity: SLIGHT

Lighting Conditions:

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Dark

Vehicle Details

Veh. No Vehicle Type Direction Location **Junction Location** Manoeuvres Skidded/overturned Hit Object in Cway Hit Object off Cway CAR NONE SW NE **GOING AHEAD** NO SKIDDING, ON MAIN NOT AT, OR WITHIN 20 ROAD SIGN / **CARRIAGEWAY - NOT** METRES OF, JUNCTION TRAFFIC SIGNAL

IN RESTRICTED LANE

OTHER **OVERTURNING**

JACK-KNIFING OR

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity VEHICLE OR PILLION PASSENGER 1 **SLIGHT**

Contributory Factors

FATIGUE (POSSIBLE)

LOSS OF CONTROL (POSSIBLE)

PASSING TOO CLOSE TO CYCLIST, HORSE RIDER, OR PEDESTRIAN (VERY LIKELY)

POOR TURN OR MANOEUVRE (POSSIBLE)

Road/Link/Section/Chainage: A90 12220/26 (2,224m)

Date/Time: 23 May 2017

Junction Road Code: C6

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type CAR	Direction W E	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres OVERTAKING STATIONARY VEHICLE ON ITS OFFSIDE	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction PARKED	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres PARKED	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SLIGHT
2	DRIVER			SLIGHT

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

ILLNESS OR DISABILITY, MENTAL OR PHYSICAL (POSSIBLE)

Date/Time: 29 May 2017

Junction Road Code: A928

Severity: SERIOUS

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No Vehicle Type Hit Object in Cway **Hit Object off Cway** Direction Location **Junction Location** Manoeuvres Skidded/overturned CAR NONE LAMP POST NS **GOING AHEAD** NO SKIDDING, ON MAIN NOT AT, OR WITHIN 20 **CARRIAGEWAY - NOT** METRES OF, JUNCTION

IN RESTRICTED LANE

OTHER

JACK-KNIFING OR **OVERTURNING**

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 **PEDESTRIAN FATAL**

Contributory Factors

IMPAIRED BY ALCOHOL (VERY LIKELY)

IMPAIRED BY DRUGS (ILLICIT OR MEDICINAL) (POSSIBLE)

Road/Link/Section/Chainage: A90 12225/08 (1,945m)

FAILED TO LOOK PROPERLY (POSSIBLE)

SWERVED (POSSIBLE)

Road/Link/Section/Chainage: A90 12240/08 (2,414m)

Date/Time: 22 April 2017

Junction Road Code: U370

Severity: SLIGHT

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Light

Road Surface Conditions: Dry

Weather Conditions: Fine

Lighting Conditions:

Veh. No	Vehicle Type	Direction	Location	Junction Location	Manoeuvres	Skidded/overturned	Hit Object in Cway	Hit Object off Cway
1	CAR	SW SW	ON MAIN	APPROACHING JUNCTION	U TURN	NO SKIDDING,	NONE	NONE
			CARRIAGEWAY - NOT	OR WAITING/PARKED AT		JACK-KNIFING OR		

OVERTURNING IN RESTRICTED LANE JUNCTION APPROACH

Veh. No Vehicle Type Direction Hit Object in Cway Hit Object off Cway Location **Junction Location** Manoeuvres Skidded/overturned NONE 2 CAR NONE SW NE **GOING AHEAD** NO SKIDDING, ON MAIN APPROACHING JUNCTION

> OTHER JACK-KNIFING OR **CARRIAGEWAY - NOT** OR WAITING/PARKED AT **OVERTURNING** JUNCTION APPROACH IN RESTRICTED LANE

Casualty Details

Vehicle Details

Veh. No.	Casualty Class	Sex	Age	Severity
1	DRIVER			SLIGHT

Contributory Factors

CARELESS/RECKLESS/IN A HURRY (VERY LIKELY)

POOR TURN OR MANOEUVRE (VERY LIKELY)

FAILED TO LOOK PROPERLY (VERY LIKELY)

Date/Time: 21 April 2016

Severity: SERIOUS

Road/Link/Section/Chainage: A90 12276/06 (579m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction N S	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No 2	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction PARKED	Location ON LAY-BY OR HARD SHOULDER	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres PARKED	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
Veh. No	Vehicle Type GOODS VEHICLE 7.5 TONNES MGW AND OVER	Direction PARKED	Location ON LAY-BY OR HARD SHOULDER	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres PARKED	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh.	. No.	Casualty Class	Sex	Age	Severity
2		DRIVER			SLIGHT
2		VEHICLE OR PILLION PASSENGER			SERIOUS

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

Date/Time: 25 February 2016

Road/Link/Section/Chainage: A90 12276/90 (3,916m) Junction Road Code: ?

Severity: SERIOUS

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No	Vehicle Type MOTORCYCLE OVER 500CC	Direction SW NE	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres OVERTAKING MOVING VEHICLE ON ITS OFFSIDE	Skidded/overturned SKIDDED AND OVERTURNED	Hit Object in Cway KERB	Hit Object off Cway NONE
Veh. No 2	Vehicle Type CAR	Direction SW NE	Location ON MAIN CARRIAGEWAY - NOT IN RESTRICTED LANE	Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION	Manoeuvres GOING AHEAD OTHER	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE

Casualty Details

Veh. No.	Casualty Class	Sex	Age	Severity
	DRIVER			SERIOU

Contributory Factors

FAILED TO JUDGE OTHER PERSON'S PATH OR SPEED (VERY LIKELY)

SWERVED (VERY LIKELY)

LOSS OF CONTROL (VERY LIKELY)

FAILED TO LOOK PROPERLY (VERY LIKELY)

SWERVED (POSSIBLE)

Road/Link/Section/Chainage: A90 12240/08 (1,640m)

Date/Time: 26 June 2017

Junction Road Code: ?

Severity: SERIOUS

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Light

Vehicle Details

Veh. No Vehicle Type Direction Hit Object in Cway Hit Object off Cway Location **Junction Location** Manoeuvres Skidded/overturned CAR NONE ENTERED DITCH NS**GOING AHEAD** NO SKIDDING, ON MAIN NOT AT, OR WITHIN 20 **CARRIAGEWAY - NOT**

IN RESTRICTED LANE

METRES OF, JUNCTION

OTHER

JACK-KNIFING OR **OVERTURNING**

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 **DRIVER SERIOUS**

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

FATIGUE (VERY LIKELY)

Date/Time: 12 June 2017

Junction Road Code: A935

Severity: SLIGHT

Lighting Conditions:

OVERTURNING

Road/Link/Section/Chainage: A90 12240/95 (1,283m)

Junction Location: APPROACHING JUNCTION OR WAITING/PARKED AT JU

Weather Conditions: Fine

Road Surface Conditions: Dry

JUNCTION APPROACH

IN RESTRICTED LANE

Light

Vehicle Details

Veh. No Vehicle Type Direction Location **Junction Location** Manoeuvres Skidded/overturned Hit Object in Cway Hit Object off Cway CAR NONE SN **GOING AHEAD** NO SKIDDING, ON MAIN APPROACHING JUNCTION ROAD SIGN / OTHER JACK-KNIFING OR **CARRIAGEWAY - NOT** OR WAITING/PARKED AT TRAFFIC SIGNAL

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity VEHICLE OR PILLION PASSENGER 1 **SLIGHT**

Contributory Factors

POOR TURN OR MANOEUVRE (VERY LIKELY) JUNCTION OVERSHOOT (VERY LIKELY)

Road/Link/Section/Chainage: A90 12220/25 (454m)

Date/Time: 16 July 2017

Junction Road Code: ?

Severity: SLIGHT

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Lighting Conditions: Dark

Vehicle Details

Veh. No Vehicle Type Hit Object in Cway **Hit Object off Cway** Direction Location **Junction Location** Manoeuvres Skidded/overturned NONE NONE SN **GOING AHEAD** NO SKIDDING, **GOODS VEHICLE 7.5** ON MAIN NOT AT, OR WITHIN 20

OTHER JACK-KNIFING OR **TONNES MGW AND CARRIAGEWAY - NOT** METRES OF, JUNCTION **OVER** IN RESTRICTED LANE

OVERTURNING

Casualty Details

Veh. No. **Casualty Class** Sex Age Severity 1 **PEDESTRIAN SLIGHT**

Contributory Factors

IMPAIRED BY ALCOHOL (VERY LIKELY)

PEDESTRIAN WEARING DARK CLOTHING AT NIGHT (VERY LIKELY)

Date/Time: 28 July 2017

Severity: SERIOUS

Road/Link/Section/Chainage: A90 12237/05 (2,113m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

CAR

Road Surface Conditions: Dry

Lighting Conditions: Dark

Vehicle Details

Veh. No Vehicle Type Direction Location SN

ON MAIN **CARRIAGEWAY - NOT**

IN RESTRICTED LANE

Junction Location NOT AT, OR WITHIN 20 METRES OF, JUNCTION Manoeuvres **GOING AHEAD** OTHER

Skidded/overturned **OVERTURNED**

Hit Object in Cway NONE

Hit Object off Cway LAMP POST

Casualty Details

1

Veh. No. **Casualty Class**

VEHICLE OR PILLION PASSENGER

Sex

Age

Severity **SERIOUS**

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

FATIGUE (VERY LIKELY)

Date/Time: 27 August 2017

Severity: SERIOUS

Lighting Conditions:

Road/Link/Section/Chainage: A90 12240/33 (1,726m)

Junction Road Code: ?

Junction Location: NOT AT, OR WITHIN 20 METRES OF, JUNCTION

Weather Conditions: Fine

Road Surface Conditions: Dry

Light

Vehicle Details

Veh. No Vehicle Type Direction Location Junction Location 1 CAR W E ON MAIN NOT AT, OR WITHIN 20 CARRIAGEWAY - NOT METRES OF, JUNCTION IN RESTRICTED LANE	GOING AHEAD NOTHER J	Skidded/overturned NO SKIDDING, JACK-KNIFING OR OVERTURNING	Hit Object in Cway NONE	Hit Object off Cway NONE
---	----------------------	--	----------------------------	-----------------------------

Casualty Details

Veh. No.	Casualty Class DRIVER	Sex	Age	Severity SERIOUS
1	VEHICLE OR PILLION PASSENGER			SERIOUS

Contributory Factors

LOSS OF CONTROL (VERY LIKELY)

ILLNESS OR DISABILITY, MENTAL OR PHYSICAL (POSSIBLE)