## Flooding Reports - M8 Junction 10 to 20

Date	Location	Comments
2015		
23-Feb	Jct 15 Eastbound	Flood cleared
30-Mar	Jct 12 Eastbound	No trace
05-May	Jct 17 Westbound	No trace
18-May	Jct 12 Eastbound	Flooding due to water cascading from surface street - gullies cleared and running freely.
05-Jul	Jct 15 Westbounf On Slip	Flooding due to water cascading from surface street - gullies cleared and running freely.
17-Jul	Jct 19 On Slip	Flood cleared
28-Aug	Jct 15	Surface Water - No Action Required
28-Nov	Jct 13	Surface Water - No Action Required
01-Dec	Jct 12 Eastbound	Gullies cleared - water running freely
05-Dec	Jct 19 Eastbound Off Slip	Gullies cleared - water running freely
06-Dec	Jct 18-19 Westbound	No trace
30-Dec	Jct 12 Eastbound	Gullies cleared - water running freely
30-Dec	Jct 17 Westbound	Surface Water - No Action Required
30-Dec	Jct 14-13 Eastbound	5 Gullies cleared - water running freely
30-Dec	Jct 12 Westbound	8 Gullies cleared - water running freely
30-Dec	Jct 11 Westbound	4 Gullies cleared - water running freely
30-Dec	Jct 12 Eastbound On Slip	4 Gullies cleared - water running freely
30-Dec	Jct 19-18 Eastbound	No trace
30-Dec	Jct 18-17 Eastbound	5 Gullies cleared - water running freely
2016		
00 5-1-	lat 10 10 \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	Heavy rainfall. Sweeper and vactor unit attended and water cleared. Gullies cleaned and carrier pipes
09-Feb	Jct 18-19 Westbound	jetted.
16-Feb	Jct 15-14 Eastbound	Surface water due to heavy rain. Gantry speed restrictions implemented.

30-Sep	Jct 18 Eastbound	2 gullies cleaned, water flowing freely.
18-Nov	Jct 19 Westbound	Gully cleaned and water dispersed.
25-Dec	Jct 19-18 Eastbound	Flood cleared
25-Dec	Jct 16-17 Westbound	2 gullies cleaned, water flowing freely.
25-Dec	Jct 19 Eastbound	2 gullies cleaned, water flowing freely.
26-Dec	Jct 14-15 Westbound	7 gullies cleaned, water flowing freely.
26-Dec	Jct 15 Eastbound On slip	3 gullies cleaned and leaves removed from area.
26-Dec	Jct 14-13 Eastbound	6 gullies cleaned, water flowing freely
26-Dec	Jct 19 On slip	3 gullies cleaned, water flowing freely
27-Dec	Jct 19 Westbound	1 gully cleaned, water flowing freely
31-Dec	Jct 12 Westbound	4 gullies cleaned, water flowing freely
31-Dec	<b>Charing Cross Tunnel</b>	1 gully cleaned, water flowing freely
31-Dec	Jct 12 Eastbound	Heavy rainfall, 2 gullies cleaned.
2047		
2017		
09-Jan	Jct 19 Eastbound	Heavy rainfall - surface water - no action
10-Jan	Jct 18-19 Westbound	5 gullies cleaned - water flowing freely
11-Jan	Jct 11 Westbound On slip	6 gullies cleaned - water flowing freely
31-Jan	Jct 15 Eastbound On slip	2 gullies cleaned - water flowing freely
16-Mar	Jct 12 Eastbound	2 gullies cleaned - water flowing freely
14-Apr	Jct 15 Eastbound On slip	1 gully cleaned - water flowing freely
06-Jun	Jct 16-17 Westbound	Vactor Unit cleared carrier pipes and water flowing freely
06-Jun	Jct 19 Eastbound On slip	1 gully cleaned - water flowing freely
04-Jul	Jct 11 Eastbound On slip	2 gullies cleaned - water flowing freely
04-Jul	Jct 15 Westbound	No trace
26-Jul	Jct 19 Off slip	Vactor Unit cleared carrier pipes and water flowing freely
04-Sep	Jct 14-15 Westbound	Surface water due to heavy rain. Gantry speed restrictions implemented
07-Sep	Jct 18-19 Werstbound	Heavy rainfall - gullies operating correctly - volume of water - gantry speed restrictions
16-Oct	Jct 12-11 Eastbound	2 gullies cleaned - water flowing freely
22-Nov	Jct 19	1 gully cleared of leaves and thereafter working correctly