

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 20/02/2016 and 20/02/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section Code is 16585/50)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
16585/50 : Tangy Lodge to Airport Junc									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 February 2016									
NWG21136515-1698975	5,816m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	26/02/2016	Completed Defects	25/02/2016	200M NORTH OF THE CRAIGS JCT (3 MILES NORTH OF CAMPBELTOWN)
Safety Inspection of A83 Safety Inverary - Campbeltown (Awaiting Return)									
NWG21138462-1703610	5,916m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/03/2016	Completed Defects	03/03/2016	OPPOSITE MACHRIHANISH JCT, S/B C/WAY
NWG21138462-1703611	5,796m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	04/03/2016	Completed Defects	03/03/2016	JUST NORTH OF MACHRIHANISH JCT, S/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 10 March 2016									
NWG11140427-1728610	5,695m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	11/03/2016	Completed Defects	10/03/2016	JUST NORTH OF MACRAHANISH JCT
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 March 2016									
NWG11142202-1738919	5,812m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/03/2016	Completed Defects	17/03/2016	JUST NORTH OF MACRAHANISH JCT
NWG11142202-1738923	4,783m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/03/2016	Completed Defects	17/03/2016	JUST SOUTH OF KILCHENZIE
NWG11142202-1738922	4,785m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/03/2016	Completed Defects	17/03/2016	JUST SOUTH OF KILCHENZIE
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 March 2016									
NWG11142357-1741366	1,815m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/04/2016	Completed Defects	18/04/2016	SOUTH SIDE OF WESTPORT BEACH ACCESS
NWG11142357-1741365	1,815m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/03/2016	Completed Defects	24/03/2016	SOUTH SIDE OF WESTPORT BEACH ACCESS
Safety Inspection of A83 Safety Inverary - Campbeltown on 31 March 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 April 2016									
NWG21143015-1811668	5,706m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/04/2016	Completed Defects	07/04/2016	JUST NORTH OF MACRAHANISH JCT
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 April 2016									
NWG21143551-1842611	5,922m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	15/04/2016	Completed Defects	14/04/2016	JUST NORTH OF MACRAHANISH JCT
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 April 2016									
NWG11143660-1853682	5,925m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/04/2016	Completed Defects	21/04/2016	NORTH SIDE OF MACHRIHANISH JCT, S/B C/WAY
NWG11143660-1853683	5,817m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/04/2016	Completed Defects	21/04/2016	NORTH SIDE OF MACHRIHANISH JCT, S/B C/WAY
NWG11143660-1853681	5,932m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/04/2016	Completed Defects	21/04/2016	NORTH SIDE OF MACHRIHANISH JCT, S/B C/WAY
NWG11143660-1853684	5,839m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/04/2016	Completed Defects	21/04/2016	NORTH SIDE OF MACHRIHANISH JCT, S/B C/WAY
NWG11143660-1853680	5,931m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/05/2016	Completed Defects	04/05/2016	NORTH SIDE OF MACHRIHANISH JCT, S/B C/WAY

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 April 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 May 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 May 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 May 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 26 May 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 June 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 June 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 June 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 June 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 June 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 July 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 July 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 July 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 July 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 August 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 August 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 August 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 August 2016									
NWG21180668-2141686	4,636m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	26/08/2016	Completed Defects	25/08/2016	SOUTH OF KILCHENZIE N/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 September 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 September 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 15 September 2016									
NWG11184384-2198622	1,931m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/09/2016	Completed Defects	15/09/2016	JUST SOUTH OF WEST SANDS CAR PARK ACCESS, N/B C/WAY
NWG11184384-2198621	1,841m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	16/09/2016	Completed Defects	15/09/2016	JUST SOUTH OF WEST SANDS CAR PARK ACCESS, S/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 22 September 2016									
NWG11186966-2212301	5,213m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	NORTH OF CAMPBELTOWN, N/B VERGE
Safety Inspection of A83 Safety Inverary - Campbeltown on 29 September 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 October 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 03 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 10 November 2016									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 November 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 November 2016									
NWG5211643-2353506	4,174m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/11/2016	Completed Defects	24/11/2016	KILCHENZIE E/B C/WAY
NWG5211643-2353507	4,173m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	25/11/2016	Completed Defects	24/11/2016	KILCHENZIE W/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 December 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 December 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 15 December 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 22 December 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 29 December 2016									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 January 2017									
NWG5234567-235031402	4,043m	0m	TRAFFIC_SIGNS	Pointing wrong way (RWAY)	CAT 1	16/02/2017	Completed Defects	15/02/2017	KILCHENZIE, W/B VERGE
Safety Inspection of A83 Safety Inverary - Campbeltown on 26 January 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 February 2017									
NWG5242681-235053139	4,181m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	KILCHENZIE BUS STOP, W/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 February 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 March 2017									
NWG21246823-235058782	4,433m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	30/03/2017	Completed Defects	29/03/2017	JUST WEST OF KILCHENZIE, W/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 March 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 March 2017									
NWG21254941-235072816	1,835m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	31/03/2017	Completed Defects	30/03/2017	JUST WEST OF WESTPORT SANDS, W/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 April 2017									
NWG21261629-235096400	1,872m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/04/2017	Completed Defects	20/04/2017	100YDS WEST OF WESTPORT BEACH CAR PARK, W/B C/WAY
NWG21261629-235096401	1,843m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/04/2017	Completed Defects	20/04/2017	100YDS WEST OF WESTPORT BEACH CAR PARK, W/B C/WAY
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 April 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 May 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 May 2017									
NWG7268971-235150170	1,783m	0m	BOLLARDS	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	WESTPORT BEACH CARPARK ACCESS N/B VERGE
NWG7268971-235150169	1,554m	0m	TRAFFIC_SIGNS	Damaged (DAMG)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	JUST NORTH OF WESTPORT BEACH CARPARK S/B VERGE
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 May 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 June 2017									
NWG7278728-235189876	2,093m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	09/08/2017	JUST WEST OF WESTPORT SANDS ACCESS, W/B C/WAY.
NWG7278728-235189877	2,107m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	09/08/2017	JUST WEST OF WESTPORT SANDS ACCESS, W/B C/WAY.
NWG7278728-235189879	2,129m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	09/08/2017	JUST WEST OF WESTPORT SANDS ACCESS, W/B C/WAY.
NWG7278728-235189878	2,120m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 2	01/01/9999	Completed Defects	09/08/2017	JUST WEST OF WESTPORT SANDS ACCESS, W/B C/WAY.
NWG7278728-235189875	1,964m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	09/06/2017	Completed Defects	08/06/2017	JUST WEST OF WESTPORT SANDS ACCESS, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 15 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 22 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 29 June 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 06 July 2017									
NWG30-281800-235255908	4,653m	0m	CARRIAGEWAY	Localised edge deterioration (LODT)	CAT 1	03/08/2017	Completed Defects	02/08/2017	JUST WEST OF KILCHENZIE, W/B C/AY.
NWG30-281800-235255909	4,878m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/07/2017	Completed Defects	06/07/2017	JUST WEST OF KILCHENZIE, E/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 13 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 20 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 27 July 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 03 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown (Awaiting Return)									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 17 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 24 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 31 August 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 September 2017									
<i>No defects recorded</i>									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 September 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NWG11314882-235380151	1,844m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	29/09/2017	Completed Defects	28/09/2017	WESTPORT BEACH CAR PARK, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 05 October 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 12 October 2017									
NWG8315308-235427467	4,176m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	13/10/2017	Completed Defects	12/10/2017	KILCHENZIE SB
Safety Inspection of A83 Safety Inverary - Campbeltown on 19 October 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 26 October 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 02 November 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 09 November 2017									
NWG11316037-235465649	4,049m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 1	07/12/2017	Completed Defects	20/11/2017	KILCHENZIE, W/B VERGE.
NWG11316037-235465650	5,169m	0m	TRAFFIC_SIGNS	Physical condition of post (COPT)	CAT 1	07/12/2017	Completed Defects	20/11/2017	KILMAHO, EAST OF KILCHENZIE. (E/B C/WAY)
Safety Inspection of A83 Safety Inverary - Campbeltown on 16 November 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 23 November 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 30 November 2017									
NWG11316430-235483575	1,834m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/12/2017	Completed Defects	30/11/2017	JUST WEST OF WESTPORT SANDS ACCESS, W/B C/WAY.
NWG11316430-235483577	4,790m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/12/2017	Completed Defects	30/11/2017	JUST WEST OF KILCHENZIE, E/B C/WAY.
NWG11316430-235483576	1,832m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/12/2017	Completed Defects	30/11/2017	JUST WEST OF WESTPORT SANDS ACCESS, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 07 December 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 December 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 21 December 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 28 December 2017									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 04 January 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 11 January 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 18 January 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 25 January 2018									
NW122317734-235520728	1,924m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Awaiting CCMS Permanent Date	01/01/9999	JUST WEST OF WESTPORT BEACH CAR PARK ACCESS, W/B C/WAY.
NW122317734-235520724	1,815m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	22/02/2018	Awaiting CCMS Permanent Date	01/01/9999	JUST WEST OF WESTPORT BEACH CAR PARK ACCESS, W/B C/WAY.
NW122317734-235520725	1,819m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	22/02/2018	Awaiting CCMS Permanent Date	01/01/9999	JUST WEST OF WESTPORT BEACH CAR PARK ACCESS, W/B C/WAY.
NW122317734-235520723	1,843m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	22/02/2018	Awaiting CCMS Permanent Date	01/01/9999	JUST WEST OF WESTPORT BEACH CAR PARK ACCESS, W/B C/WAY.
NW122317734-235520726	1,825m	0m	CARRIAGEWAY	Bituminous surfacing fretting (BFRT)	CAT 1	22/02/2018	Awaiting CCMS Permanent Date	01/01/9999	JUST WEST OF WESTPORT BEACH CAR PARK ACCESS, W/B C/WAY.

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NW122317734-235520727	1,923m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Awaiting CCMS Permanent Date	01/01/9999	JUST WEST OF WESTPORT BEACH CAR PARK ACCESS, W/B C/WAY.
NW122317734-235520729	1,954m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/02/2018	Awaiting CCMS Permanent Date	01/01/9999	JUST WEST OF WESTPORT BEACH CAR PARK ACCESS, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 01 February 2018									
NWG11318017-235531638	1,940m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	01/03/2018	Awaiting CCMS Permanent Date	01/01/9999	200M WEST OF WEST PORT BEACH CAR PARK, W/B C/WAY.
Safety Inspection of A83 Safety Inverary - Campbeltown on 08 February 2018									
No defects recorded									
Safety Inspection of A83 Safety Inverary - Campbeltown on 14 February 2018									
No defects recorded									