Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 19/02/2018 and 26/02/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: SLIP TO M8 WB',) Or

(Section is 'WITH: JCT 18 TO JCT 19',) Or

(Section is 'WITH: OFF SLIP TO STOBCROSS ST',) Or

(Section is 'WITH: JCT 19 WB OFF SLIP TO ON SLIP',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
4.40.45/40 MUTH OLID TO	. 140 M/D								
14245/10 : WITH: SLIP TO) M8 MB								
Safety Inspection of M8 Tannochside V1 on 20 February 2018									
No defects recorded									
Safety Patrol of M8 Tannoche No defects recorded	side V1 on 2	24 Februar	y 2018						
14245/30 : WITH: JCT 18	TO JCT 1	9							
Safety Inspection of M8 Tann No defects recorded	ochside V1	on 20 Feb	oruary 2018						
Safety Patrol of M8 Tannoche No defects recorded	side V1 on 2	24 Februar	y 2018						
14250/05 : WITH: JCT 19	WB OFF	SLIP TO	ON SLIP						
Safety Inspection of M8 Tann No defects recorded	ochside V1	on 20 Feb	oruary 2018						
Safety Patrol of M8 Tannoche No defects recorded	side V1 on 2	24 Februar	y 2018						
14250/50 : WITH: OFF SL	IP TO STO	OBCROS	S ST						
Safety Inspection of M8 Tanr	ochside V1	on 20 Feb	ruary 2018						

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 February 2018

No defects recorded

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 19/02/2018 and 26/02/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST: WOODLANDS RD OBR TO ON SLIP EB M8',) Or

(Section is 'AGAINST: EB JCT 19 TO JCT 18',) Or

(Section is 'AGAINST: JCT 19 EB OFF SLIP TO ON SLIP',) Or

(Section is 'AGAINST: SLIP OFF M8 EB TO BOTHWELL ST',) Or

(Section is 'AGAINST: SLIP OFF M8 EB TO A814',)

Defect Reference	Start	End	Item Type	Item Detail	Defect	Required	Current Status	Completion	Location Description
	m	m			Category	Completion Date		Date	

14245/26: AGAINST: WOODLANDS RD OBR TO ON SLIP EB M8

Safety Inspection of M8 Tannochside V1 on 20 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 February 2018

No defects recorded

14245/61 : AGAINST: EB JCT 19 TO JCT 18

Safety Inspection of M8 Tannochside V1 on 20 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 February 2018

No defects recorded

14250/06: AGAINST: JCT 19 EB OFF SLIP TO ON SLIP

Safety Inspection of M8 Tannochside V1 on 20 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 February 2018

No defects recorded

14250/53: AGAINST: SLIP OFF M8 EB TO BOTHWELL ST

Safety Inspection of M8 Tannochside V1 on 20 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 February 2018

No defects recorded

14250/90 : AGAINST: SLIP OFF M8 EB TO A814

Safety Inspection of M8 Tannochside V1 on 20 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 February 2018

No defects recorded



22/03/2018 Page 1 of 1