

Done Date/Time	Location	Section Reference	Activity Type Description	Section Description	Road Part	Activity	Observations?	Start	End	L.A.Codes?	Link Id	Done Date	Date Due	Frequency	Late?	Composite Act.	Parameter 1 Value	Parameter 2 Value	Survey
30/01/2018 20:00	11445/07	11445/07	Minor Carriageway Repairs	11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	M77	MC	Y	0	1190	Y	11445	30/01/2018	30/01/2018		N				9305
18/01/2018 15:16	11445/07	11445/07	Safety Patrol	11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	M77	PAT	N	0	1190	N	11445	18/01/2018	18/01/2018	1 Week	N	Rain	Wet		9287
25/01/2018 11:47	11445/07	11445/07	Safety Patrol	11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	M77	PAT	N	0	1190	N	11445	25/01/2018	25/01/2018	1 Week	N	Fine	Dry		9296
01/02/2018 07:44	11445/07	11445/07	Safety Patrol	11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	M77	PAT	N	0	1190	N	11445	01/02/2018	01/02/2018	1 Week	N	Fine	Dry		9299
08/02/2018 09:42	11445/07	11445/07	Safety Patrol	11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	M77	PAT	N	0	1190	N	11445	08/02/2018	08/02/2018	1 Week	N	Fine	Dry		9304
15/02/2018 11:59	11445/07	11445/07	Safety Patrol	11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	M77	PAT	Y	0	1190	Y	11445	15/02/2018	15/02/2018	1 Week	N	Fine	Dry		9312
15/01/2018 12:29	11445/07	11445/07	Safety Inspection	11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	M77	SAF	N	0	1190	N	11445	15/01/2018	15/01/2018	1 Week	N	Rain	Wet		9283
22/01/2018 12:30	11445/07	11445/07	Safety Inspection	11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	M77	SAF	N	0	1190	N	11445	22/01/2018	22/01/2018	1 Week	N	Rain	Wet		9288
29/01/2018 19:21	11445/07	11445/07	Safety Inspection	11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	M77	SAF	Y	0	1190	Y	11445	29/01/2018	29/01/2018	1 Week	N	Fine	Dry		9297
05/02/2018 10:56	11445/07	11445/07	Safety Inspection	11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	M77	SAF	N	0	1190	N	11445	05/02/2018	05/02/2018	1 Week	N	Fine	Dry		9300
13/02/2018 09:40	11445/07	11445/07	Safety Inspection	11445/07 M77 N/B: MAIDENHILL INT OVERBRIDGE TO A77 OVERBRIDGE A	M77	SAF	N	0	1190	N	11445	13/02/2018	12/02/2018	1 Week	Y	Fine	Wet		9307

