

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 15/01/2018 and 16/02/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: A77 OVERBRIDGE TO CROOKFUR INT',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
11450/07 : WITH: A77 OVERBRIDGE TO CROOKFUR INT									
Safety Inspection of M77 Inspection on 18 January 2018									
<i>No defects recorded</i>									
Safety Patrol of M77 Inspection on 21 January 2018									
<i>No defects recorded</i>									
Safety Patrol of M77 Inspection on 21 January 2018									
<i>No defects recorded</i>									
Safety Inspection of M77 Inspection on 25 January 2018									
<i>No defects recorded</i>									
Safety Patrol of M77 Inspection on 28 January 2018									
<i>No defects recorded</i>									
Safety Inspection of M77 Inspection on 01 February 2018									
<i>No defects recorded</i>									
Safety Patrol of M77 Inspection on 04 February 2018									
<i>No defects recorded</i>									
Safety Inspection of M77 Inspection on 08 February 2018									
<i>No defects recorded</i>									
Safety Patrol of M77 Inspection on 11 February 2018									
<i>No defects recorded</i>									
Safety Inspection of M77 Inspection on 15 February 2018									
<i>No defects recorded</i>									

