

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/01/2017 and 01/06/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A702',)
 (Section Code is 13533/79) Or
 (Section Code is 13534/05)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
13534/05 : 30 MPHS WEST LINTON TO JCT. SOUTH MAINS									
Safety Inspection of Amey A702 Safety Inspection on 04 January 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 11 January 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 18 January 2017									
SE67235818-235032143	2,976m	0m	TRAFFIC_SIGNS	Corrosion of columns (CCOR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	nb just prior to Carlops
Safety Inspection of Amey A702 Safety Inspection on 25 January 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 01 February 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 08 February 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 15 February 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 22 February 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 01 March 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 08 March 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 15 March 2017									
SE67251813-235068185	32m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/04/2017	Completed Defects	06/04/2017	sb just prior to west linton gateway
Safety Inspection of Amey A702 Safety Inspection on 22 March 2017									
SE67253795-235071900	741m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/04/2017	Completed Defects	13/04/2017	sb app 1/2 mile prior to west linton
Safety Inspection of Amey A702 Safety Inspection on 29 March 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 05 April 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 12 April 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 19 April 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 26 April 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 03 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 10 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 17 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 24 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 31 May 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 07 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 June 2017									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 21 June 2017									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 June 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 05 July 2017									
SE65282146-235253428	1,432m	0m	Drainage Ancillary Items	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	nb prior to rutherford junction in layby
Safety Inspection of Amey A702 Safety Inspection on 12 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 19 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 26 July 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
SE65316823-235495412	138m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/01/2018	Completed Defects	10/01/2018	A702 SB 150M PRIOR TO WEST LINTON
SE65316823-235495413	122m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	10/01/2018	Completed Defects	10/01/2018	A702 N/B 125M NORTH OF WEST LINTON
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
SE65317775-235528440	2,249m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2018	Completed Defects	10/02/2018	A702 N/B 100M NORTH OF RUTHERFORD CASTLE JCT PRIOR TO CARLOPS
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
SE57318919-235534062	455m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/03/2018	Completed Defects	10/02/2018	A702 S/B 400M PRIOR TO WEST LINTON
SE57318919-235534061	1m	1m	CARRIAGEWAY	Pothole (POTH)	CAT 1	07/03/2018	Completed Defects	17/02/2018	A702 S/B 100M PRIOR TO ROBINLAND RBT, WEST LINTON
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
SE55321401-235545066	2,280m	0m	CARRIAGEWAY	Cracking around ironwork (CKIR)	CAT 1	21/03/2018	Completed Defects	15/03/2018	A702 SB Slip after Carlops, Prior to Rutherford jct.
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
SE55327537-235554823	2,547m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/04/2018	Completed Defects	30/03/2018	A702 NB opp. Rutherford castle jct
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
SE65331518-235607677	143m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	25/04/2018	Completed Defects	11/05/2018	A702 S/B 150M PRIOR TO WEST LINTON
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
SE55336331-235619232	598m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/05/2018	Completed Defects	09/05/2018	A702 NB 1km north West Linton
SE55336331-235619233	2,746m	0m	TRAFFIC_SIGNS	Surface corrosion (SFCO)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	A702 NB 160m south Macbiehill jct
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
SE65340434-235660867	1,434m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/05/2018	Completed Defects	11/05/2018	A702 S/B 500M PRIOR TO ROBINSLAND R/B
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 09 May 2018									
SE57346108-235731407	1,037m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/06/2018	Completed Defects	16/05/2018	A702 N/B NORTH OF ROBINSWOOD RBT 60M AFTER 2 SMALL JCTS ON THE LEFT
SE57346108-235731408	867m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/06/2018	Completed Defects	22/05/2018	A702 S/B PRIOR TO WEST LINTON, 40M B4 TOURIST HISTORIC SIGN
Safety Inspection of Amey A702 Safety Inspection on 16 May 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 23 May 2018									
No defects recorded									
Safety Inspection of Amey A702 Safety Inspection on 30 May 2018									
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

13533/79 : ROBINS LAND RBT TO 30MPH NORTH OF WEST LINTON

Safety Inspection of Amey A702 Safety Inspection on 04 January 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 11 January 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 18 January 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 25 January 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 01 February 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 08 February 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 15 February 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 22 February 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 01 March 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 08 March 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 15 March 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 22 March 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 29 March 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 05 April 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 12 April 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 19 April 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 26 April 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 03 May 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 10 May 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 17 May 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 24 May 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 31 May 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 07 June 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 14 June 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 21 June 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 28 June 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 05 July 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 12 July 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 19 July 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 26 July 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 02 August 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 09 August 2017
No defects recorded

Safety Inspection of Amey A702 Safety Inspection on 16 August 2017
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of Amey A702 Safety Inspection on 23 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 August 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 September 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 October 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 01 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 08 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 15 November 2017 SE65316231-235470535	12m	0m	BOLLARDS	Accident damage (ACCD)	CAT 1	13/12/2017	Completed Defects	12/02/2018	A702 SB ON THE SPLITTER ISLAND AT ROBIN LAND RBT, WEST LINTON
Safety Inspection of Amey A702 Safety Inspection on 22 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 29 November 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 06 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 13 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 20 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 27 December 2017									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 03 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 10 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 17 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 24 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 31 January 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 February 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 07 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 14 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 21 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 28 March 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 04 April 2018									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	------------	----------	-----------	-------------	--------------------	-----------------------------	----------------	--------------------	----------------------

<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 11 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 18 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 25 April 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 02 May 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 09 May 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 16 May 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 23 May 2018									
<i>No defects recorded</i>									
Safety Inspection of Amey A702 Safety Inspection on 30 May 2018									
<i>No defects recorded</i>									