

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/12/2017 and 28/02/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'AGAINST: EB JCT 15 OFF SLIP TO ENTRY SLIP',) Or

(Section is 'AGAINST: JCT 16 ON SLIP TO JCT 15 OFF SLIP',) Or

(Section is 'AGAINST: JCT 16 CRAIGHALL RD TO ENTRY M8 EB',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
------------------	---------	-------	-----------	-------------	-----------------	--------------------------	----------------	-----------------	----------------------

14235/06 : AGAINST: EB JCT 15 OFF SLIP TO ENTRY SLIP

Safety Patrol of M8 Tannochside V1 on 02 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 February 2018

No defects recorded

14235/82 : AGAINST: JCT 16 ON SLIP TO JCT 15 OFF SLIP

Safety Patrol of M8 Tannochside V1 on 02 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 December 2017

SW85-316987-235510265	225m	225m	STRUCTURE	Graffiti - Offensive (OFFS)	CAT 1	16/01/2018	Completed Defects	20/12/2017	M8 W/B J16 OFFSLIP @ THE START
-----------------------	------	------	-----------	-----------------------------------	-------	------------	----------------------	------------	-----------------------------------

Safety Patrol of M8 Tannochside V1 on 23 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 February 2018

No defects recorded

14240/06 : AGAINST: JCT 16 CRAIGHALL RD TO ENTRY M8 EB

Safety Patrol of M8 Tannochside V1 on 02 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 January 2018

SW85-317765-235529054	13m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/02/2018	Completed Defects	15/02/2018	M8 EB JCT 17 LANE 4 TO CASTLE ST AT DOBBIES LOAN
-----------------------	-----	----	-------------	-------------------	-------	------------	----------------------	------------	---

Safety Patrol of M8 Tannochside V1 on 27 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 February 2018

No defects recorded

Inspection Defect Summary Report



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 01/12/2017 and 28/02/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Section is 'WITH: JCT 16 OFF SLIP TO CRAIGHALL RD',) Or

(Section is 'WITH: ENTRY M8 WB TO JCT 16 OFF SLIP',) Or

(Section is 'WITH: M8 OBRIDGE TO SLIP ON TO M8 WB',)

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
14235/39 : WITH: M8 OBRIDGE TO SLIP ON TO M8 WB									
Safety Patrol of M8 Tannochside V1 on 02 December 2017									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 05 December 2017									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 09 December 2017									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 12 December 2017									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 16 December 2017									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 19 December 2017									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 23 December 2017									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 27 December 2017									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 30 December 2017									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 03 January 2018									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 06 January 2018									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 09 January 2018									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 13 January 2018									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 16 January 2018									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 20 January 2018									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 23 January 2018									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 27 January 2018									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 30 January 2018									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 03 February 2018									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 06 February 2018									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 10 February 2018									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 13 February 2018									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 17 February 2018									
<i>No defects recorded</i>									
Safety Inspection of M8 Tannochside V1 on 20 February 2018									
<i>No defects recorded</i>									
Safety Patrol of M8 Tannochside V1 on 24 February 2018									
<i>No defects recorded</i>									

Safety Inspection of M8 Tannochside V1 on 27 February 2018

No defects recorded

14235/81 : WITH: ENTRY M8 WB TO JCT 16 OFF SLIP

Safety Patrol of M8 Tannochside V1 on 02 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 20 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 24 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 February 2018

No defects recorded

14240/05 : WITH: JCT 16 OFF SLIP TO CRAIGHALL RD

Safety Patrol of M8 Tannochside V1 on 02 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 05 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 09 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 12 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 16 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 19 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 23 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 December 2017

No defects recorded

Safety Patrol of M8 Tannochside V1 on 30 December 2017

No defects recorded

Safety Inspection of M8 Tannochside V1 on 03 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 06 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 09 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 13 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 16 January 2018

SW85-317630-235518833	361m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	13/02/2018	Completed Defects	09/02/2018	M8 WB JCT 16-17 LANE 2 MAIN C/WAY OS WT
-----------------------	------	----	-------------	-------------------	-------	------------	----------------------	------------	--

Safety Patrol of M8 Tannochside V1 on 20 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 23 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 27 January 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 30 January 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 03 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 06 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 10 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 13 February 2018

No defects recorded

Safety Patrol of M8 Tannochside V1 on 17 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 20 February 2018

SW85-321388-235545865	257m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	20/03/2018	Completed Defects	08/03/2018	M8 WB JCT 16 MAIN C/WAY 150M PRIOR TO SOS BOX 725W OS WT
-----------------------	------	----	-------------	-------------------	-------	------------	----------------------	------------	--

Safety Patrol of M8 Tannochside V1 on 24 February 2018

No defects recorded

Safety Inspection of M8 Tannochside V1 on 27 February 2018

No defects recorded

