## **Inspection Defect Summary Report**



This report is produced from the WDM Limited RMS System and shows defects identified from inspections during the period between 06/08/2016 and 06/08/2018, and defects raised outside of inspections on the same Section(s) during this period.

(Road is 'A90',)

(Section Code is 12250/10) Or

(Section Code is 12250/06) Or

(Section Code is 12245/05) Or

(Section Code is 12240/95) Or

(Section Code is 12240/70) Or

(Section Code is 12240/53) Or

(Section Code is 12240/33) Or

(Section Code is 12240/18) Or

(Section Code is 12240/07)

		m			Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
12240/07: WITH: B9128 JUNCT	ION TO	PARKF(	ORD						
Safety Inspection of A90 & A972 Sou									
No defects recorded									
Safety Patrol of A90 Swallow to SCC	ວ on 12 Aບ	gust 201f	6						
No defects recorded	11 40		***						
Safety Inspection of A90 & A972 Sou No defects recorded	1th on 16 F	August 20	J16						
Safety Patrol of A90 Swallow to SCC	3 on 19 Aı	uaust 201	16						
No defects recorded	•	<b>3</b>							
Safety Inspection of A90 & A972 Sou	ath on 23 /	August 20	.016						
No defects recorded	2 00 4	4.004							
Safety Patrol of A90 Swallow to SCC No defects recorded	∍ on 26 Au⁄	gust 2016	i						
Safety Inspection of A90 & A972 Sou	uth on 30	August 2'	<b>∠016</b>						
No defects recorded	4								
Safety Patrol of A90 Swallow to SCC	on 02 Se	ptember ?	2016						
No defects recorded	11 00	• • • • • • • • • • • • • • • • • • •	2240						
Safety Inspection of A90 & A972 Sou No defects recorded	ith on us a	Septembe	∌r 2016						
Safety Patrol of A90 Swallow to SCC	3 on 09 S€	aptember '	2016						
No defects recorded									
Safety Inspection of A90 & A972 Sou	uth on 13 f	Septembe	er 2016						
No defects recorded	2 40 0:	- 4 - mala a m	2240						
Safety Patrol of A90 Swallow to SCC No defects recorded									
Safety Inspection of A90 & A972 Sou				Dathala MACIV	CAT 1	04/00/2046	Commisted	20/00/2016	A DDDO A OLUMO
NE8-186981-2206275	225m	um (	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/09/2016	Completed Defects	20/09/2016	APPROACHING BATTLEDYKES N/B
NE8-186981-2206285 2	2,711m	0m /	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/09/2016	Completed Defects	20/09/2016	APPROACHING BOGIDOLLO JCT N/B
Safety Patrol of A90 Swallow to SCC No defects recorded	on 23 Se	ptember 7	2016						
Safety Inspection of A90 & A972 Sou No defects recorded		-							
Safety Patrol of A90 Swallow to SCC No defects recorded	on 30 Ser	ptember 2	2016						
Safety Inspection of A90 & A972 Sou No defects recorded	uth on 04 (	October 2	<b>2016</b>						
Safety Patrol of A90 Swallow to SCC	on 07 Oc	tober 201	16						



20/09/2018 Page 1 of 64

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded									
Safety Inspection of A90 & A!  No defects recorded	972 South on 1	1 October 2	2016						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 14	October 201	6						
Safety Inspection of A90 & A	72 South on 1	8 October 2	2016						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 21 (	October 201	6						
No defects recorded Safety Inspection of A90 & A	972 South on 2	5 October 2	2016						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 28 (	October 201	6						
No defects recorded Safety Inspection of A90 & A	972 South on 0	1 Novembe	r 2016						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 04 I	November 2	2016						
No defects recorded Safety Inspection of A90 & A	972 South on 0	8 Novembe	r 2016						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 11 I	November 2	016						
No defects recorded Safety Inspection of A90 & A90	972 South on 1	5 Novembe	r 2016						
No defects recorded Safety Patrol of A90 Swallow									
No defects recorded Safety Inspection of A90 & A90									
No defects recorded Safety Patrol of A90 Swallow									
No defects recorded Safety Inspection of A90 & A	972 South on 2	9 Novembe	r 2016						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 02 I	December 2	016						
No defects recorded  Safety Inspection of A90 & A90  No defects recorded	972 South on 0	6 Decembe	r 2016						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 09 I	December 2	016						
Safety Inspection of A90 & As No defects recorded Safety Patrol of A90 Swallow									
No defects recorded Safety Inspection of A90 & A90	972 South on 2	0 Decembe	r 2016						
No defects recorded Safety Patrol of A90 Swallow									
No defects recorded  Safety Inspection of A90 & As No defects recorded	972 South on 2	7 Decembe	r 2016						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 30 I	December 2	016						
Safety Inspection of A90 & As No defects recorded	972 South on 0	3 January 2	2017						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 06 .	January 201	7						
Safety Inspection of A90 & A90 No defects recorded	972 South on 1	0 January 2	2017						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 13	January 201	7						
Safety Inspection of A90 & As No defects recorded	972 South on 1	7 January 2	2017						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 20	January 201	7						
Safety Inspection of A90 & A90 No defects recorded		_							
Safety Patrol of A90 Swallow No defects recorded	to SCC on 27	January 201	7						
Safety Inspection of A90 & As No defects recorded	972 South on 3	1 January 2	2017						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow	to SCC on 03 Fe	ebruary 201	17						
No defects recorded Safety Inspection of A90 & A9	72 South on 07	February 2	2017						
No defects recorded Safety Patrol of A90 Swallow No defects recorded	to SCC on 10 Fe	ebruary 201	17						
Safety Inspection of A90 & A9 No defects recorded	72 South on 14	February 2	.017						
<b>Safety Patrol of A90 Swallow</b> <i>NE7-244226-235057943</i>	to SCC on 17 Fe 2,680m		<b>17</b> CARRIAGEWAY	Pothole VIAFIX	CAT 1	18/02/2017	Completed	17/02/2017	@ BOGINDOLLO JCT N/B
Outstanding of ACC C AC	270 0 41 0.4	F-1	2017	(POTV)			Defects		
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow No defects recorded	to SCC on 24 Fe	ebruary 201	.7						
Safety Inspection of A90 & AS No defects recorded	72 South on 28	February 2	<b>2017</b>						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 03 M	arch 2017							
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & AS No defects recorded									
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A9 No defects recorded			7						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 24 W	arcn 2017							
Safety Inspection of A90 & A90 No defects recorded Safety Patrol of A90 Swallow									
No defects recorded Safety Inspection of A90 & A9									
No defects recorded Safety Patrol of A90 Swallow	to SCC on 07 A	pril 2017							
No defects recorded Safety Inspection of A90 & A9 No defects recorded	72 South on 11	April 2017							
Safety Patrol of A90 Swallow No defects recorded	to SCC on 14 A	pril 2017							
Safety Inspection of A90 & A90 No defects recorded	72 South on 18	April 2017							
Safety Patrol of A90 Swallow No defects recorded	to SCC on 21 A	pril 2017							
Safety Inspection of A90 & A9									
NE7-263626-235103572	405m		BOLLARDS	Accident damage (ACCD)	CAT 1	23/05/2017	Completed Defects	25/05/2017	BATTLEDYKES JCT N/B
Safety Patrol of A90 Swallow	to SCC on 28 A	pril 2017							
No defects recorded Safety Inspection of A90 & A9 No defects recorded	72 South on 02	May 2017							
Safety Patrol of A90 Swallow NE7-268120-235145634	to SCC on 05 M 366m		CARRIAGEWAY	Pothole VIAFIX	CAT 1	06/05/2017	Completed	05/05/2017	JUST BFORE BATTLEDYKES
				(POTV)			Defects		JCT NB
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow No defects recorded	to SCC on 12 M	ay 2017							
Safety Inspection of A90 & A9	72 South on 16	May 2017							

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE7-271922-235154286	1,349m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	17/05/2017	Completed Defects	16/05/2017	@ BIRKENBUSH CROSSOVER SLIP N/B
NE7-271922-235154287	1,342m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	@ BIRKENBUSH JCT N/B
Safety Patrol of A90 Swallow to S No defects recorded			17	· ,					
Safety Inspection of A90 & A972 S No defects recorded	South on 23	way 201	1						
Safety Patrol of A90 Swallow to S No defects recorded Safety Inspection of A90 & A972 S No defects recorded		_	17						
Safety Patrol of A90 Swallow to S No defects recorded	CC on 02 Ju	ıne 2017							
Safety Inspection of A90 & A972 S No defects recorded									
Safety Patrol of A90 Swallow to S No defects recorded Safety Inspection of A90 & A972 S									
No defects recorded Safety Patrol of A90 Swallow to S									
No defects recorded  Safety Inspection of A90 & A972 S  No defects recorded	South on 20	June 20	17						
Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded Safety Patrol of A90 Swallow to S									
No defects recorded Safety Inspection of A90 & A972 S									
No defects recorded Safety Patrol of A90 Swallow to S No defects recorded	SCC on 07 Ju	ıly 2017							
Safety Inspection of A90 & A972 S No defects recorded		_							
Safety Patrol of A90 Swallow to S NE7-282397-235267759	SCC on 14 Ju 1,745m		MANHOLE	Cracked or broken (IBCK)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	APPROX 250M AFTER BIRKENBUSH NB
Safety Inspection of A90 & A972 S No defects recorded	South on 18	July 201	<b>17</b>						
Safety Patrol of A90 Swallow to S No defects recorded Safety Inspection of A90 & A972 S		_	17						
No defects recorded  Safety Patrol of A90 Swallow to S			,						
No defects recorded Safety Inspection of A90 & A972 S		_	2017						
No defects recorded Safety Patrol of A90 Swallow to S	SCC on 04 Au	ugust 20	17						
No defects recorded Safety Inspection of A90 & A972 S No defects recorded	South on 08	August	2017						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 11 Au	ugust 20	17						
Safety Inspection of A90 & A972 S									
Safety Patrol of A90 Swallow to S No defects recorded Safety Inspection of A90 & A972 S									
No defects recorded Safety Patrol of A90 Swallow to S									
No defects recorded	OC UII 29 AL	uguət 20	11						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A9	72 South on 29	9 August 20	117						
No defects recorded									
Safety Patrol of A90 Swallow t No defects recorded	o SCC on 01 S	September 2	2017						
Safety Inspection of A90 & A9	72 South on 0	5 September	er 2017						
No defects recorded		-							
Safety Patrol of A90 Swallow t No defects recorded	o SCC on 08 S	September 2	2017						
Safety Inspection of A90 & A9	72 South on 1	2 Septembe	er 2017						
No defects recorded	- 000 45 0		2047						
Safety Patrol of A90 Swallow t No defects recorded	0 SCC on 15 S	september 2	2017						
Safety Inspection of A90 & A9	72 South on 19	9 Septembe	er 2017						
No defects recorded Safety Patrol of A90 Swallow t	o SCC on 22 S	Sentember 2	2017						
No defects recorded	0 000 0.11 22 0	optombor 2	-011						
Safety Inspection of A90 & A9 No defects recorded	72 South on 20	6 September	er 2017						
Safety Patrol of A90 Swallow t	o SCC on 29 S	September 2	2017						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 0	3 October 20	017						
Safety Patrol of A90 Swallow t	o SCC on 06 C	October 2017	7						
No defects recorded	72 South on 1	0 Ootobor 20	047						
Safety Inspection of A90 & A9 No defects recorded	72 South on 1	o October 20	.017						
Safety Patrol of A90 Swallow t	o SCC on 13 C	October 2017	7						
No defects recorded  Safety Inspection of A90 & A9	72 South on 1	7 October 20	017						
No defects recorded									
Safety Patrol of A90 Swallow t No defects recorded	o SCC on 20 C	October 2017	7						
Safety Inspection of A90 & A9	72 South on 2	4 October 20	017						
No defects recorded Safety Patrol of A90 Swallow t	o SCC on 27 C	October 2017	7						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 3	1 October 20	017						
Safety Patrol of A90 Swallow t	o SCC on 03 N	November 20	017						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	2 South on 0	/ November	r 201 <i>7</i>						
Safety Patrol of A90 Swallow t	o SCC on 10 N	November 20	017						
No defects recorded  Safety Inspection of A90 & A9	72 South on 1	4 November	r 2017						
No defects recorded	72 30util 011 1	4 NOVEILIBEI	1 2017						
Safety Patrol of A90 Swallow t No defects recorded	o SCC on 17 N	November 20	017						
Safety Inspection of A90 & A9	72 South on 2	1 November	r 2017						
No defects recorded									
Safety Patrol of A90 Swallow t No defects recorded	o SCC on 24 N	November 20	017						
Safety Inspection of A90 & A9	72 South on 2	8 November	r 2017						
No defects recorded Safety Patrol of A90 Swallow t	o SCC on 01 F	December 20	017						
No defects recorded	0 000 011 01 2	Jecember 20	017						
Safety Inspection of A90 & A9 No defects recorded	72 South on 0	5 December	r 2017						
Safety Patrol of A90 Swallow t	o SCC on 08 E	December 20	017						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	r∠ South on 12	∠ December	r <b>∠</b> U1 /						
Safety Patrol of A90 Swallow t	o SCC on 15 E	December 20	017						
No defects recorded  Safety Inspection of A90 & A9	72 South on 10	9 December	r 2017						
No defects recorded									
Safety Patrol of A90 Swallow t	o SCC on 22 E	December 20	017						

Defect Reference	Start m	End m	Item Type	ltem Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded									
Safety Inspection of A90 & A9	72 South on 2	26 Decembe	er 2017						
No defects recorded Safety Patrol of A90 Swallow to	o SCC on 20 I	Docombor '	2017						
No defects recorded	.0 SCC 011 29 1	December 2	2017						
Safety Inspection of A90 & A9	72 South on 0	2 January	2018						
No defects recorded Safety Patrol of A90 Swallow	o SCC on 05 .	Januarv 20	)18						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 0	9 January	2018						
Safety Patrol of A90 Swallow the No defects recorded	o SCC on 12	January 20	18						
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded Safety Inspection of A90 & A9		_							
No defects recorded	72 30utii 0ii 2	.o January	2010						
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 3	30 January	2018						
Safety Patrol of A90 Swallow	o SCC on 02 I	February 20	.018						
No defects recorded  Safety Inspection of A90 & A9	72 South on O	6 Fobruary	v 2018						
No defects recorded	72 30util 011 0	o i ebidai y	7 2010						
Safety Patrol of A90 Swallow to No defects recorded		_							
Safety Inspection of A90 & A9 No defects recorded	72 South on 1	3 February	/ 2018						
Safety Patrol of A90 Swallow the No defects recorded	o SCC on 16 I	February 20	018						
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded		_							
Safety Inspection of A90 & A9 No defects recorded	72 South on 2	7 February	/ 2018						
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 1	3 March 20	)18						
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 2	20 March 20	)18						
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 23 I	March 2018	3						
Safety Inspection of A90 & A9 No defects recorded	72 South on 2	7 March 20	<b>)18</b>						
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 0	3 April 201	18						
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 06	April 2018							
Safety Inspection of A90 & A9	72 South on 1	0 April 201	18						
No defects recorded Safety Patrol of A90 Swallow to No defects recorded	o SCC on 13	April 2018							
Safety Inspection of A90 & A9 No defects recorded	72 South on 1	7 April 201	18						
. 10 dolotto 1000/d0d									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallo No defects recorded	w to SCC on 20 A	pril 2018							
Safety Inspection of A90 & No defects recorded	A972 South on 24	4 April 2018	8						
Safety Patrol of A90 Swallo No defects recorded									
Safety Inspection of A90 & No defects recorded		,							
Safety Patrol of A90 Swallo  No defects recorded  Safety Inspection of A90 &									
No defects recorded Safety Patrol of A90 Swallo									
No defects recorded Safety Inspection of A90 & No defects recorded			i						
Safety Patrol of A90 Swallo No defects recorded	w to SCC on 18 N	lay 2018							
Safety Inspection of A90 & No defects recorded									
Safety Patrol of A90 Swallo No defects recorded		•							
Safety Inspection of A90 & No defects recorded Safety Patrol of A90 Swallo									
No defects recorded  Safety Inspection of A90 & No defects recorded			8						
Safety Patrol of A90 Swallo No defects recorded	w to SCC on 08 J	une 2018							
Safety Inspection of A90 & NE7-360557-235840202	A972 South on 12 1,047m		8 CARRIAGEWAY	Pothole VIAFIX	CAT 1	13/06/2018	Completed	12/06/2018	APPROACHING BIRKENBUSH
	·			(POTV)			Defects		N/B
Safety Patrol of A90 Swallo No defects recorded			_						
Safety Inspection of A90 & No defects recorded Safety Patrol of A90 Swallo			5						
NE7-367267-235863718	152m		CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/06/2018	Completed Defects	22/06/2018	BEFORE BATTLEDYKES N/B
NE7-367267-235863719	199m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	23/06/2018	Completed Defects	22/06/2018	BEFORE BATTLEDYKES N/B
Safety Inspection of A90 & No defects recorded			8						
Safety Patrol of A90 Swallo No defects recorded									
Safety Inspection of A90 & No defects recorded Safety Patrol of A90 Swallo		-							
No defects recorded Safety Inspection of A90 &		-	<b>3</b>						
No defects recorded Safety Patrol of A90 Swallo		-							
No defects recorded Safety Inspection of A90 &	A972 South on 17	7 July 2018	i						
No defects recorded Safety Patrol of A90 Swallo No defects recorded	w to SCC on 20 J	uly 2018							
Safety Inspection of A90 & No defects recorded	A972 South on 24	1 July 2018	i						
Safety Patrol of A90 Swallo No defects recorded	w to SCC on 27 J	uly 2018							
Safety Inspection of A90 & No defects recorded									
Safety Patrol of A90 Swallo	w to SCC on 03 A	ugust 2018	8						

Page 7 of 64

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded									
12240/18: WITH: PARKFOI Safety Inspection of A90 & A97 No defects recorded Safety Patrol of A90 Swallow to No defects recorded	72 South on 09	9 August 20	016						
Safety Inspection of A90 & A97 NE8179548-2121902	7 <b>2 South on 16</b> 657m	•	016 MANHOLE	Cracked or broken (IBCK)	CAT 1	13/09/2016	Completed Defects	26/08/2016	LAYBY JUST AFTER BOGINDOLLO N/B
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 19 A	August 2010	6						
Safety Inspection of A90 & A97 No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded  Safety Inspection of A90 & A97	72 South on 30	August 2	016						
NE8181722-2155703	218m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	31/08/2016	Completed Defects	30/08/2016	BUS STOP AFTER BOGINDOLLO JCT N/B
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 02 S	September :	2016						
Safety Inspection of A90 & A97 NE8-182912-2194503	7 <b>2 South on 06</b> 1,936m		er <b>2016</b> TREE	Obscured sign (OBSG)	CAT 1	04/10/2016	Completed Defects	06/09/2016	approaching bogardo junction n/b
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 09 S	eptember :	2016						
Safety Inspection of A90 & A97 No defects recorded Safety Patrol of A90 Swallow to		-							
No defects recorded Safety Inspection of A90 & A97 NE8-186981-2206284	7 <b>2 South on 20</b> 6m		er <b>2016</b> CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	21/09/2016	Completed Defects	20/09/2016	CROSSOVER JCT BOGINDOLLO N/B
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 23 S	September	2016						
Safety Inspection of A90 & A97 No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded	0 300 011 30 3	eptember	2010						
Safety Inspection of A90 & A97 No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded Safety Inspection of A90 & A97									
No defects recorded Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A97 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 21 C	October 201	16						
Safety Inspection of A90 & A97 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 28 C	October 201	16						
Safety Inspection of A90 & A97 No defects recorded	72 South on 01	1 Novembe	er 2016						
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 04 N	lovember 2	2016						
Safety Inspection of A90 & A97 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	U 300 ON 11 N	ovember 2							

20/09/2018 Page 8 of 64

Delect Reference	Start m	m m	item Type	item Detail	Category	Completion Date	Current Status	Date	Location Description	
Safety Inspection of A90 & A972 S No defects recorded	South on 15	November	2016							
Safety Patrol of A90 Swallow to So No defects recorded	CC on 18 No	ovember 20	)16							
Safety Inspection of A90 & A972 S No defects recorded	South on 22	November	2016							
Safety Patrol of A90 Swallow to So No defects recorded	CC on 25 No	ovember 20	)16							
Safety Inspection of A90 & A972 S No defects recorded	South on 29	November	2016							
Safety Patrol of A90 Swallow to So No defects recorded	CC on 02 De	ecember 20	)16							
Safety Inspection of A90 & A972 S No defects recorded Safety Patrol of A90 Swallow to S0										
No defects recorded Safety Inspection of A90 & A972 S	South on 13	December	· 2016							
No defects recorded Safety Patrol of A90 Swallow to So	CC on 16 De	ecember 20	<b>)16</b>							
No defects recorded Safety Inspection of A90 & A972 S No defects recorded	South on 20	December	2016							
Safety Patrol of A90 Swallow to So No defects recorded	CC on 23 De	ecember 20	)16							
Safety Inspection of A90 & A972 S No defects recorded										
Safety Patrol of A90 Swallow to So No defects recorded										
Safety Inspection of A90 & A972 S No defects recorded Safety Patrol of A90 Swallow to S0										
No defects recorded Safety Inspection of A90 & A972 S										
No defects recorded Safety Patrol of A90 Swallow to So No defects recorded										
Safety Inspection of A90 & A972 S No defects recorded	South on 17	January 20	017							
Safety Patrol of A90 Swallow to Son No defects recorded		-								
Safety Inspection of A90 & A972 S No defects recorded		_								
Safety Patrol of A90 Swallow to So No defects recorded		_								
Safety Inspection of A90 & A972 S No defects recorded Safety Patrol of A90 Swallow to S0										
No defects recorded Safety Inspection of A90 & A972 S	South on 07	February 2	2017							
No defects recorded Safety Patrol of A90 Swallow to So	CC on 10 Fe	bruary 201	17							
No defects recorded Safety Inspection of A90 & A972 S No defects recorded	South on 14	February 2	2017							
Safety Patrol of A90 Swallow to So No defects recorded	CC on 17 Fe	bruary 201	17							
Safety Inspection of A90 & A972 S No defects recorded	South on 21	February 2	2017							
Safety Patrol of A90 Swallow to So No defects recorded	CC on 24 Fe	bruary 201	17							
Safety Inspection of A90 & A972 S No defects recorded		_	<b>2017</b>							
Safety Patrol of A90 Swallow to So No defects recorded			_							
Safety Inspection of A90 & A972 S	outh on 07	March 2017	7							

**Current Status** 

Completion

**Location Description** 

**Defect Reference** 

Start

End

Item Type

Item Detail

Defect

Required

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE7-248966-235063201	385m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	08/03/2017	Completed Defects	25/03/2017	APPROACHING VOSA LAYBY AFTER BOGINDOLLO N/B
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 10 M	larch 201	7						
Safety Inspection of A90 & A972 No defects recorded	South on 14	4 March 20	017						
Safety Patrol of A90 Swallow to S	SCC on 17 M	larch 201	7						
No defects recorded Safety Inspection of A90 & A972 No defects recorded	South on 21	1 March 20	017						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 24 M	larch 201	7						
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 31 M	larch 201	7						
Safety Inspection of A90 & A972 No defects recorded		-							
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 07 A	pril 2017							
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 14 A	pril 2017							
Safety Inspection of A90 & A972 No defects recorded		-							
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 21 A	April 2017							
Safety Inspection of A90 & A972 No defects recorded		-							
Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972 No defects recorded			7						
Safety Patrol of A90 Swallow to S No defects recorded	SCC On US IV	ay 2017							
Safety Inspection of A90 & A972 No defects recorded		-	7						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 12 M	lay 2017							
Safety Inspection of A90 & A972 No defects recorded			7						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 19 M	lay 2017							
Safety Inspection of A90 & A972 No defects recorded			7						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 26 M	lay 2017							
Safety Inspection of A90 & A972 No defects recorded	South on 30	0 May 201	7						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 02 J	une 2017							
Safety Inspection of A90 & A972 No defects recorded	South on 06	6 June 20 <sup>,</sup>	17						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 09 J	une 2017							
Safety Inspection of A90 & A972 No defects recorded	South on 13	3 June 20 <sup>-</sup>	17						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 16 J	une 2017							
Safety Inspection of A90 & A972 No defects recorded	South on 20	) June 20 <sup>-</sup>	17						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 23 J	une 2017							
Safety Inspection of A90 & A972 No defects recorded	South on 27	7 June 20 <sup>-</sup>	17						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow t	o SCC on 30 .	June 2017							
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 0	4 July 2017							
Safety Patrol of A90 Swallow t	o SCC on 07	July 2017							
No defects recorded	<b>-</b> 00 11 1	4 1 1 004=							
Safety Inspection of A90 & A9 No defects recorded	72 South on 1	1 July 2017							
Safety Patrol of A90 Swallow t	o SCC on 14	July 2017							
No defects recorded Safety Inspection of A90 & A9	72 South on 1	8 July 2017							
No defects recorded	, <b>2</b>	o daily 2011							
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 21	July 2017							
Safety Inspection of A90 & A9	72 South on 2	5 July 2017							
No defects recorded	- 000 00	L-1- 0047							
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 28 .	July 2017							
Safety Inspection of A90 & A9	72 South on 0	1 August 20	)17						
No defects recorded Safety Patrol of A90 Swallow t	o SCC on 04	August 2017	7						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 0	8 August 20	017						
Safety Patrol of A90 Swallow t	o SCC on 11	August 2017	•						
No defects recorded	72 South on 1	E August 20	147						
Safety Inspection of A90 & A9 No defects recorded	72 30utii 011 1	5 August 20	) 1 7						
Safety Patrol of A90 Swallow t	o SCC on 18	August 2017	7						
No defects recorded Safety Inspection of A90 & A9	72 South on 2	2 August 20	017						
No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 25	August 2017							
Safety Inspection of A90 & A9	72 South on 2	9 August 20	)17						
No defects recorded Safety Patrol of A90 Swallow t	o SCC on 01 S	Santambar 2	2017						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 0	5 Septembe	er 2017						
Safety Patrol of A90 Swallow t	o SCC on 08	September 2	2017						
No defects recorded	70.0	0.0	0047						
Safety Inspection of A90 & A9 No defects recorded	72 South on 1	2 Septembe	er 201 <i>7</i>						
Safety Patrol of A90 Swallow t	o SCC on 15	September 2	2017						
No defects recorded Safety Inspection of A90 & A9	72 South on 1	9 Septembe	er 2017						
No defects recorded									
Safety Patrol of A90 Swallow t No defects recorded	o SCC on 22	September 2	2017						
Safety Inspection of A90 & A9	72 South on 2	6 Septembe	er 2017						
No defects recorded Safety Patrol of A90 Swallow t	o SCC on 29 9	Santambar 2	2017						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 0	3 October 2	2017						
Safety Patrol of A90 Swallow t	o SCC on 06	October 201	7						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	ı∠ əoutn on 1	o October 2	.U I /						
Safety Patrol of A90 Swallow t	o SCC on 13	October 201	7						
No defects recorded Safety Inspection of A90 & A9	72 South on 1	7 October 2	2017						
No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 20	October 201	7						
Safety Inspection of A90 & A9	72 South on 2	4 October 2	017						

Page 11 of 64

March Patient of ABP de ABP desilien to SC on 27 October 2017  Balty Institution 48 AP & ABY 25 Beach on 31 October 2017  For Salters Institution 48 AP & ABY 25 Beach on 17 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 17 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 17 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 17 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 21 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on 18 Horsenber 2017  For Salters Institution 48 AP & ABY 25 Beach on	Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description	
Sedey 1942 of ASS 2014 ASS 201	No defects recorded										
No Accessed analorus to 50 Can 18 Novembar 2017 Sonder Accessed State y Inspection of AN A A APT 3 South on 17 Novembar 2017 Novembar 2018 State y Inspection of AN A APT 3 South on 18 Novembar 2017 Novembar 2018 State y Inspection of AN A APT 3 South on 18 Novembar 2017 Novembar 2018 State y Inspection of AN A APT 3 South on 18 Novembar 2017 Novembar 2018 State y Inspection of AN A APT 3 South on 18 Novembar 2017 Novembar 2018 State y Inspection of AN A APT 3 South on 18 Novembar 2017 Novembar 2018 State y Inspection of AN A APT 3 South on 18 Novembar 2017 Novembar 2018 State y Inspection of AN A APT 3 South on 18 Novembar 2017 Novembar 2018 State y Inspection of AN A APT 3 South on 18 Novembar 2017 Novembar 2018 State y Inspection of AN A APT 3 South on 18 Novembar 2017 Novembar 2018 State y Inspection of AN A APT 3 South on 18 Novembar 2017 Novembar 2018 State y Inspection of AN A APT 3 South on 18 Novembar 2017 Novembar 2018 Novembar 2018 State y Inspection of AN A APT 3 South on 18 Novembar 2017 Novembar 2018 Novembar	Safety Patrol of A90 Swallow	to SCC on 27	October 201	17							
No arthory in agreeting of ARB Sea ART 2 South on 07 November 2017 Stately Reparation of ARB Sea ART 2 South on 07 November 2017 Sea ART 2 South on 2019 Sea ART 2 South on 20	No defects recorded										
Stately Inspection of ASSA ART2 South on 10 Tenember 2017 To Statistical Recorded Stately Inspection on ASSA ART2 South on 11 Micromotor 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 12 Micromotor 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 12 Micromotor 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 12 Micromotor 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 12 Micromotor 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 12 Micromotor 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 12 Micromotor 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 Micromotor 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 Micromotor 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 December 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 December 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 December 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 December 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 December 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 December 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 December 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 December 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 December 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 December 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 December 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 December 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 December 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 15 December 2017 To Statistical Recorded Stately Inspection of ASSA ART2 South on 25 December 2017 To		to SCC on 03 l	November 2	2017							
No defect second state of the second state of		72 South on 0	7 Novembe	er 2017							
Skelp Inspection of A89 & A872 South on 18 November 2017 No defents recovered Skelp Inspection of A89 & A872 South on 28 November 2017 No defents recovered Skelp Inspection of A89 & A872 South on 28 November 2017 No defents recovered Skelp Inspection of A89 & A872 South on 28 November 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 19 November 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 19 November 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 19 November 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 19 November 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 19 November 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2017 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2018 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2018 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2018 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2018 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2018 No defents recovered Skelp Part of A89 Sembler to 50 Cor and 50 Learniner 2018 No defents recovered S	No defects recorded										
No addiction recorded Stately princed food AND SA AVER South on a 15 November 2017 No addiction recorded Stately princed food AND SA AVER South on a 15 November 2017 No addiction recorded Stately inspection of AND SA AVER South on a 25 November 2017 No addiction recorded Stately inspection of AND SA AVER South on a 25 November 2017 No addiction recorded Stately inspection of AND SA AVER South on 25 December 2017 No addiction recorded Stately inspection of AND SA AVER South on 50 December 2017 No addiction recorded Stately inspection of AND SA AVER South on 15 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25 December 2017 No addiction recorded Stately princed food Southboard to 25	No defects recorded										
No defects recorded Satisfy Inspection of 488 A 4372 South on 21 November 2017 South of Asia Desiration of Asia Desiration of 20 South on 20 Story (Asia Desiration) South of South of Asia Desiration of A	No defects recorded										
No defect recorded Statisty Parties of AND Swallow to SCC on 28 November 2017 Satisty Parties of AND Swallow to SCC on 28 November 2017 No defect recorded Swallow to SCC on 10 December 2017 No defect recorded Swallow to SCC on 10 December 2017 No defect recorded Swallow to SCC on 10 December 2017 No defect recorded Swallow to SCC on 20 December 2017 No defect recorded S	No defects recorded										
Ho artheries recented starty inspection of ARA 6 AR72 South on 28 November 2017 Safety Parri of ARA 9 Swallow to SCC on 10 December 2017 And affecting recent of ARA 6 AR72 South on 10 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 10 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 12 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 12 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 12 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 12 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 12 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 12 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 28 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 28 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 28 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 28 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 28 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 28 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 28 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 28 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 28 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 28 December 2017 Ho defecting recented starty inspection of ARA 6 AR72 South on 30 January 2018 Ho defecting recented starty inspection of ARA 6 AR72 South on 30 January 2018 Ho defecting recented starty inspection of ARA 6 AR72 South on 30 January 2018 Ho defecting recented starty inspection of ARA 6 AR72 South on 30 January 2018 Ho defecting recented starty inspection of ARA 6 AR72 South on 30 January 2018 Ho defecting recented starty inspection of ARA 6 AR72 South on 30 January 2018 Ho defecting r	No defects recorded										
Ho odeficit recorded Sately Partial of ABS Saulilow to SCC on 61 December 2017 Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 Sately Partial of ABS Saulilow to SCC on 62 December 2017 Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 In ordering recorded Sately Partial of ABS Saulilow to SCC on 62 December 2017 Sately Partial of ABS Saulilow to SCC on 62 December 20	No defects recorded										
No defects recorded Sately Impaction of All 98. A 972 South on 15 December 2017 Sately Impaction of All 98. A 972 South on 15 December 2017 No defects recorded Sately Impaction of All 98. A 972 South on 12 December 2017 No defects recorded Sately Impaction of All 98. A 972 South on 12 December 2017 No defects recorded Sately Impaction of All 98. A 972 South on 19 December 2017 No defects recorded Sately Impaction of All 98. A 972 South on 19 December 2017 No defects recorded Sately Impaction of All 98. A 972 South on 19 December 2017 No defects recorded Sately Impaction of All 98. A 972 South on 18 December 2017 No defects recorded Sately Impaction of All 98. A 972 South on 18 December 2017 No defects recorded Sately Impaction of All 98. A 972 South on 18 December 2017 No defects recorded Sately Impaction of All 98. A 972 South on 18 December 2017 No defects recorded Sately Impaction of All 98. A 972 South on 18 December 2017 No defects recorded Sately Impaction of All 98. A 972 South on 18 December 2017 No defects recorded Sately Impaction of All 98. A 972 South on 19 January 2018 No defects recorded Sately Impaction of All 98. A 972 South on 19 January 2018 No defects recorded Sately Impaction of All 98. A 972 South on 18 January 2018 No defects recorded Sately Impaction of All 98. A 972 South on 18 January 2018 No defects recorded Sately Impaction of All 98. A 972 South on 19 January 2018 No defects recorded Sately Impaction of All 98. A 972 South on 19 January 2018 No defects recorded Sately Impaction of All 98. A 972 South on 19 January 2018 No defects recorded Sately Impaction of All 98. A 972 South on 19 January 2018 No defects recorded Sately Impaction of All 98. A 972 South on 19 January 2018 No defects recorded Sately Impaction of All 98. A 972 South on 19 January 2018 No defects recorded Sately Impaction of All 98. A 972 South on 19 January 2018 No defects recorded Sately Impaction of All 98. A 972 South on 19 January 2018 No defects recorded Sately Impaction of All 98. A 972 South on 19 January 2018	No defects recorded										
Safety Inspection of A99 & A972 South on 62 December 2917 No defects recorded Safety Patrol of A90 Savallow to SCC on 19 December 2917 No defects recorded Safety Patrol of A90 Savallow to SCC on 19 December 2917 No defects recorded Safety Patrol of A90 Savallow to SCC on 19 December 2917 No defects recorded Safety Patrol of A90 Savallow to SCC on 19 December 2917 No defects recorded Safety Patrol of A90 Savallow to SCC on 22 December 2917 No defects recorded Safety Patrol of A90 Savallow to SCC on 22 December 2917 No defects recorded Safety Patrol of A90 Savallow to SCC on 22 December 2917 No defects recorded Safety Patrol of A90 Savallow to SCC on 22 December 2917 No defects recorded Safety Patrol of A90 Savallow to SCC on 22 December 2917 No defects recorded Safety Patrol of A90 Savallow to SCC on 29 December 2917 No defects recorded Safety Patrol of A90 Savallow to SCC on 29 December 2917 No defects recorded Safety Patrol of A90 Savallow to SCC on 29 Savansary 2918 No defects recorded Safety Patrol of A90 Savallow to SCC on 29 Savansary 2918 No defects recorded Safety Patrol of A90 Savallow to SCC on 29 Savansary 2918 No defects recorded Safety Patrol of A90 Savallow to SCC on 19 January 2918 No defects recorded Safety Patrol of A90 Savallow to SCC on 19 January 2918 No defects recorded Safety Patrol of A90 Savallow to SCC on 19 January 2918 No defects recorded Safety Patrol of A90 Savallow to SCC on 19 January 2918 No defects recorded Safety Patrol of A90 Savallow to SCC on 19 January 2918 No defects recorded Safety Patrol of A90 Savallow to SCC on 19 January 2918 No defects recorded Safety Patrol of A90 Savallow to SCC on 19 January 2918 No defects recorded Safety Patrol of A90 Savallow to SCC on 19 January 2918 No defects recorded Safety Patrol of A90 Savallow to SCC on 19 January 2918 No defects recorded Safety Patrol of A90 Savallow to SCC on 19 January 2918 No defects recorded Safety Patrol of A90 Savallow to SCC on 19 Savallow to SCC on 19 Savallow to SCC on 19 January 2918 No defects recorded Safety		to SCC on 01 l	December 2	2017							
No defects recorded Safety Impaction of A90 & A972 South on 12 December 2017 No defects recorded Safety Impaction of A90 & A972 South on 12 December 2017 No defects recorded Safety Impaction of A90 & A972 South on 12 December 2017 No defects recorded Safety Impaction of A90 & A972 South on 12 December 2017 No defects recorded Safety Impaction of A90 & A972 South on 25 December 2017 No defects recorded Safety Impaction of A90 & A972 South on 25 December 2017 No defects recorded Safety Impaction of A90 & A972 South on 25 December 2017 No defects recorded Safety Impaction of A90 & A972 South on 20 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 09 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 09 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 19 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 19 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 25 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 25 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 25 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 25 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 25 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 25 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 25 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 25 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 25 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 60 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 60 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 60 January 2018 No defects recorded Safety Impaction of A90 & A972 South on 61 February 2018	Safety Inspection of A90 & A9	72 South on 0	)5 Decembe	er 2017							
No defects recorded Safety Partol of A90 Swallow to SCC on 15 December 2017 Not defects recorded Safety Partol of A90 Swallow to SCC on 22 December 2017 Not defects recorded Safety Inspection of A90 S. A972 South on 19 December 2017 Not defects recorded Safety Inspection of A90 Swallow to SCC on 22 December 2017 Not defects recorded Safety Inspection of A90 Swallow to SCC on 29 December 2017 Safety Partol of A90 Swallow to SCC on 29 December 2017 Safety Partol of A90 Swallow to SCC on 29 December 2017 Safety Partol of A90 Swallow to SCC on 29 December 2017 Safety Partol of A90 Swallow to SCC on 30 Swallow and		to SCC on 08 l	December 2	2017							
No defects recorded Safety Patrol of Ago Savaliow to SCC on 22 December 2017 No defects recorded Safety Patrol of Ago Swaliow to SCC on 22 December 2017 No defects recorded Safety Patrol of Ago Swaliow to SCC on 22 December 2017 No defects recorded Safety Patrol of Ago Swaliow to SCC on 29 December 2017 No defects recorded Safety Patrol of Ago Swaliow to SCC on 29 December 2017 No defects recorded Safety Inspection of Ago Savaliow to SCC on 29 December 2017 No defects recorded Safety Inspection of Ago Swaliow to SCC on 29 December 2018 Safety Patrol of Ago Swaliow to SCC on 29 January 2018 No defects recorded Safety Inspection of Ago Swaliow to SCC on 29 January 2018 No defects recorded Safety Inspection of Ago Swaliow to SCC on 12 January 2018 No defects recorded Safety Inspection of Ago Swaliow to SCC on 19 January 2018 No defects recorded Safety Inspection of Ago Swaliow to SCC on 19 January 2018 No defects recorded Safety Patrol of Ago Swaliow to SCC on 19 January 2018 No defects recorded Safety Inspection of Ago Swaliow to SCC on 19 January 2018 No defects recorded Safety Inspection of Ago Swaliow to SCC on 26 January 2018 No defects recorded Safety Inspection of Ago Swaliow to SCC on 27 January 2018 No defects recorded Safety Inspection of Ago Swaliow to SCC on 27 January 2018 No defects recorded Safety Inspection of Ago Swaliow to SCC on 27 December 2018 Safety Inspection of Ago Swaliow to SCC on 27 December 2018 Safety Inspection of Ago Swaliow to SCC on 27 December 2018 Safety Inspection of Ago Swaliow to SCC on 27 December 2018 Safety Inspection of Ago Swaliow to SCC on 27 December 2018 No defects recorded Safety Inspection of Ago Swaliow to SCC on 27 December 2018 No defects recorded Safety Inspection of Ago Swaliow to SCC on 27 December 2018 Safety Inspection of Ago Swaliow to SCC on 27 December 2018 No defects recorded	No defects recorded										
Safety Inspection of A90 S. A972 South on 19 December 2017 No defects recorded Safety Partol of A90 Swallow to SCC on 22 December 2017 No defects recorded Safety Partol of A90 Swallow to SCC on 22 December 2017 No defects recorded Safety Partol of A90 Swallow to SCC on 29 December 2017 No defects recorded Safety Partol of A90 Swallow to SCC on 29 December 2017 No defects recorded Safety Partol of A90 Swallow to SCC on 85 January 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 85 January 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 12 January 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 12 January 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 12 January 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 12 January 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 19 February 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 16 February 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 16 February 2018 No defects recorded Safety Partol of A90 Swallow to SCC on 16 February 2018 No defects recorded		to SCC on 15 l	December 2	2017							
Safety Parto of A90 Swallow to SCC on 22 December 2017 No defects recorded Safety Inspection of A90 S. A972 South on 22 January 2018 Safety Parto of A90 Swallow to SCC on 29 December 2017 No defects recorded Safety Parto of A90 Swallow to SCC on 95 January 2018 Safety Parto of A90 Swallow to SCC on 95 January 2018 Safety Parto of A90 Swallow to SCC on 95 January 2018 No defects recorded Safety Parto of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Parto of A90 Swallow to SCC on 12 January 2018 No defects recorded Safety Parto of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Parto of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Parto of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Parto of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Parto of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Parto of A90 Swallow to SCC on 26 January 2018 Safety Parto of A90 Swallow to SCC on 26 January 2018 Safety Parto of A90 Swallow to SCC on 85 February 2018 Safety Parto of A90 Swallow to SCC on 85 February 2018 Safety Parto of A90 Swallow to SCC on 95 February 2018 Safety Parto of A90 Swallow to SCC on 95 February 2018 Safety Parto of A90 Swallow to SCC on 95 February 2018 Safety Parto of A90 Swallow to SCC on 95 February 2018 Safety Parto of A90 Swallow to SCC on 95 February 2018 Safety Parto of A90 Swallow to SCC on 95 February 2018 Safety Parto of A90 Swallow to SCC on 95 February 2018 Safety Parto of A90 Swallow to SCC on 95 February 2018 Safety Parto of A90 Swallow to SCC on 95 February 2018 Safety Parto of A90 Swallow to SCC on 95 February 2018 Safety Parto of A90 Swallow to SCC on 95 February 2018	Safety Inspection of A90 & A9	72 South on 1	19 Decembe	er 2017							
No defects recorded Safety Patrol of A90 Swallow to SCC on 29 December 2017 No defects recorded Safety Inspection of A90 & A972 South on 02 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 09 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 09 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 19 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 19 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 19 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 23 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 23 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 30 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 30 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 50 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 6 February 2018 Safety Patrol of A90 Swallow to SCC on 09 February 2018 Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 19 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 19 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 19 February 2018 No defects recorded	Safety Patrol of A90 Swallow	to SCC on 22 l	December 2	2017							
No defects recorded Safety Inspection of A90 & A972 South on 02 January 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 05 January 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 12 January 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 12 January 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 12 January 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 25 January 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 26 January 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 26 January 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 02 February 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 06 February 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 06 February 2018 No defects recorded Safety Patro of A90 Swallow to SCC on 07 February 2018 No defects recorded	No defects recorded										
No defects recorded Safety Patrol of A99 Swallow to SCC on 05 January 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 12 January 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 12 January 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 12 January 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 19 January 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 19 January 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 25 January 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 26 January 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 26 January 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 02 February 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 05 February 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 07 February 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 07 February 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A99 Swallow to SCC on 16 February 2018	No defects recorded										
No defects recorded Safety Inspection of A90 & A972 South on 09 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 16 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 16 January 2018 No defects recorded Safety Patrol of A90 & A972 South on 16 January 2018 No defects recorded Safety Patrol of A90 & A972 South on 2 January 2018 No defects recorded Safety Patrol of A90 & A972 South on 23 January 2018 No defects recorded Safety Patrol of A90 & A972 South on 23 January 2018 No defects recorded Safety Patrol of A90 & A972 South on 30 January 2018 No defects recorded Safety Patrol of A90 & A972 South on 30 January 2018 No defects recorded Safety Patrol of A90 & A972 South on 6 February 2018 No defects recorded Safety Patrol of A90 & A972 South on 6 February 2018 No defects recorded Safety Patrol of A90 & A972 South on 13 February 2018 No defects recorded Safety Patrol of A90 & A972 South on 13 February 2018 No defects recorded Safety Patrol of A90 & A972 South on 15 February 2018 No defects recorded Safety Patrol of A90 & A972 South on 15 February 2018 No defects recorded Safety Patrol of A90 & A972 South on 16 February 2018 No defects recorded Safety Patrol of A90 & A972 South on 16 February 2018 No defects recorded	No defects recorded										
Safety Inspection of A90 & A972 South on 09 January 2018 No defects recorded Satety Patrol of A90 Swallow to SCC on 12 January 2018 No defects recorded Safety Inspection of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 26 January 2018 No defects recorded Safety Inspection of A90 S A972 South on 30 January 2018 No defects recorded Safety Inspection of A90 Swallow to SCC on 26 January 2018 No defects recorded Safety Inspection of A90 Swallow to SCC on 92 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 92 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 99 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 99 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 99 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 99 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 69 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 69 February 2018 No defects recorded		to SCC on 05	January 201	18							
Safety Patrol of A90 Swallow to SCC on 12 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 16 January 2018 No defects recorded Safety Martol of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 23 January 2018 No defects recorded Safety Inspection of A90 Swallow to SCC on 26 January 2018 No defects recorded Safety Inspection of A90 Swallow to SCC on 26 January 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 26 January 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 27 Ebruary 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 95 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 95 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 95 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 97 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 97 February 2018 No defects recorded Safety Natrol of A90 Swallow to SCC on 97 February 2018 No defects recorded Safety Natrol of A90 Swallow to SCC on 98 February 2018 No defects recorded Safety Natrol of A90 Swallow to SCC on 98 February 2018 No defects recorded Safety Natrol of A90 Swallow to SCC on 98 February 2018 No defects recorded Safety Natrol of A90 Swallow to SCC on 98 February 2018 No defects recorded	Safety Inspection of A90 & A9	72 South on 0	9 January 2	2018							
No defects recorded Safety Patrol of A90 Swallow to SCC on 19 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 23 January 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 26 January 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 26 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 30 January 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 02 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 February 2018 No defects recorded	Safety Patrol of A90 Swallow	to SCC on 12	January 201	18							
No defects recorded Safety Inspection of A90 & A972 South on 23 January 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 26 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 30 January 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 02 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 02 February 2018 No defects recorded Safety Inspection of A90 & A972 South on 06 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Inspection of A90 & A972 South on 13 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 February 2018		972 South on 1	16 January 2	2018							
No defects recorded Safety Patrol of A90 Swallow to SCC on 26 January 2018 No defects recorded Safety Inspection of A90 & A972 South on 30 January 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 02 February 2018 No defects recorded Safety Inspection of A90 & A972 South on 06 February 2018 No defects recorded Safety Inspection of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Inspection of A90 & A972 South on 13 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 February 2018	No defects recorded										
No defects recorded Safety Inspection of A90 & A972 South on 30 January 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 02 February 2018 No defects recorded Safety Inspection of A90 & A972 South on 06 February 2018 No defects recorded Safety Inspection of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Inspection of A90 & A972 South on 13 February 2018 No defects recorded Safety Inspection of A90 & A972 South on 13 February 2018 Safety Patrol of A90 Swallow to SCC on 16 February 2018	No defects recorded										
No defects recorded Safety Patrol of A90 Swallow to SCC on 02 February 2018 No defects recorded Safety Inspection of A90 & A972 South on 06 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Inspection of A90 & A972 South on 13 February 2018 No defects recorded Safety Inspection of A90 Swallow to SCC on 16 February 2018 No defects recorded	No defects recorded										
No defects recorded Safety Inspection of A90 & A972 South on 06 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Inspection of A90 & A972 South on 13 February 2018 No defects recorded Safety Inspection of A90 & A972 South on 13 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 February 2018	No defects recorded		_								
No defects recorded Safety Patrol of A90 Swallow to SCC on 09 February 2018 No defects recorded Safety Inspection of A90 & A972 South on 13 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 February 2018		to SCC on 02 l	February 20	)18							
No defects recorded Safety Inspection of A90 & A972 South on 13 February 2018 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 February 2018	No defects recorded										
No defects recorded Safety Patrol of A90 Swallow to SCC on 16 February 2018		to SCC on 09 l	February 20	)18							
	No defects recorded										
		to SCC on 16 l	February 20	)18							

Delect Releience	Start m	Ena m	item Type	item Detail	Category	Required Completion Date	Current Status	Date	Location Description
Safety Inspection of A90 & A972	South on 20	February 2	2018						
No defects recorded Safety Patrol of A90 Swallow to S No defects recorded	SCC on 23 Fe	ebruary 201	18						
Safety Inspection of A90 & A972 No defects recorded	South on 27	February 2	2018						
Safety Patrol of A90 Swallow to S No defects recorded	3CC on 02 M	arch 2018							
Safety Inspection of A90 & A972 No defects recorded	South on 06	March 2018	8						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 09 M	arch 2018							
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to S			8						
No defects recorded Safety Inspection of A90 & A972			R						
No defects recorded Safety Patrol of A90 Swallow to S			·						
No defects recorded Safety Inspection of A90 & A972			8						
No defects recorded Safety Patrol of A90 Swallow to S									
No defects recorded Safety Inspection of A90 & A972	South on 03	April 2018							
No defects recorded Safety Patrol of A90 Swallow to S	SCC on 06 A	pril 2018							
No defects recorded Safety Inspection of A90 & A972 No defects recorded	South on 10	April 2018							
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 13 A	pril 2018							
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to S									
No defects recorded Safety Inspection of A90 & A972 No defects recorded	South on 24	April 2018							
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 27 A	pril 2018							
Safety Inspection of A90 & A972 No defects recorded	South on 01	May 2018							
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 04 M	ay 2018							
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to S									
No defects recorded Safety Inspection of A90 & A972									
No defects recorded Safety Patrol of A90 Swallow to S	3CC on 18 M	ay 2018							
No defects recorded Safety Inspection of A90 & A972	South on 22	: May 2018							
No defects recorded Safety Patrol of A90 Swallow to S No defects recorded	SCC on 25 M	ay 2018							
Safety Inspection of A90 & A972 No defects recorded	South on 29	May 2018							
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 01 Ju	une 2018							
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972	South on 12	June 2018							

**Current Status** 

Completion

**Location Description** 

**Defect Reference** 

Start

End

Item Type

Item Detail

Defect

Required

20/09/2018 Page 13 of 64

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE7-360557-235840203	960m	0m	TRAFFIC_SIGNS	Obscured sign (OBSG)	CAT 1	10/07/2018	Completed Defects	11/07/2018	AFTER VOSA LAYBY N/B
Safety Patrol of A90 Swallow to	SCC on 15 J	June 2018	i						
No defects recorded Safety Inspection of A90 & A97 No defects recorded	2 South on 1	9 June 20	118						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 22 J	lune 2018	i						
Safety Inspection of A90 & A97 No defects recorded	2 South on 2	6 June 20	18						
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A97 No defects recorded		_							
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A97 No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded Safety Inspection of A90 & A97									
No defects recorded Safety Patrol of A90 Swallow to		-							
Safety Inspection of A90 & A97 No defects recorded		_							
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A97 No defects recorded Safety Patrol of A90 Swallow to		-							
No defects recorded	7 000 011 00 7	tuguot 20	.0						
12240/33 : WITH: FINAVON									
Safety Inspection of A90 & A97 No defects recorded Safety Patrol of A90 Swallow to		_							
No defects recorded Safety Inspection of A90 & A97									
No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded Safety Inspection of A90 & A97	2 South on 2	3 August	2016						
No defects recorded Safety Patrol of A90 Swallow to No defects recorded	SCC on 26 A	August 20	16						
Safety Inspection of A90 & A97 No defects recorded		_							
Safety Patrol of A90 Swallow to NE7-182435-2194500	2,333m		er <b>2016</b> CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	03/09/2016	Completed Defects	02/09/2016	LAYBY AFTER FINAVON TRACTORS NB
Safety Inspection of A90 & A97 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	SCC on 09 S	eptember	r 2016						
Safety Inspection of A90 & A97 No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded		-							
Safety Inspection of A90 & A97 NE8-186981-2206276	<b>2 South on 2</b> 024m		ber 2016 CARRIAGEWAY	Patch - difference in level (PDLV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	APPROX 200M AFTER FINAVON CASTLE JCT N/B
Safety Patrol of A90 Swallow to No defects recorded	SCC on 23 S	September	r 2016	·					
<b>(</b>									

Delect Reference	Start m	End m	item Type	Item Detail	Category	Completion Date	Current Status	Date	Location Description
Safety Inspection of A90 & A972 No defects recorded	2 South on 27	7 Septembe	r 2016						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 30 S	September 2	2016						
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded Safety Inspection of A90 & A972									
No defects recorded Safety Patrol of A90 Swallow to No defects recorded	SCC on 21 C	October 2016	6						
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded Safety Inspection of A90 & A972									
No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded Safety Inspection of A90 & A972	2 South on 08	8 November	r 2016						
No defects recorded Safety Patrol of A90 Swallow to No defects recorded	SCC on 11 N	lovember 20	016						
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded Safety Inspection of A90 & A972									
No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded Safety Inspection of A90 & A972	2 South on 29	9 November	r 2016						
No defects recorded Safety Patrol of A90 Swallow to No defects recorded	SCC on 02 D	ecember 20	016						
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded  Safety Inspection of A90 & A972									
No defects recorded Safety Patrol of A90 Swallow to No defects recorded	SCC on 23 D	ecember 20	016						
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to		_							
No defects recorded Safety Inspection of A90 & A972									
No defects recorded Safety Patrol of A90 Swallow to No defects recorded	SCC on 13 J	anuary 2017	7						
Safety Inspection of A90 & A972 No defects recorded	2 South on 17	7 January 20	017						
Safety Patrol of A90 Swallow to	SCC on 20 J	anuary 2017	7						

**Current Status** 

Completion

**Location Description** 

Report Version 1.2

**Defect Reference** 

Start

End

Item Type

Item Detail

Defect

Required

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects as a reduct									
No defects recorded Safety Inspection of A90 & A9	172 South on 24	lanuary	2017						
No defects recorded  Safety Patrol of A90 Swallow									
No defects recorded	to SCC on 27 Ja	anuary 20	J17						
Safety Inspection of A90 & A9 No defects recorded	972 South on 31	January	2017						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 03 F	ebruary 2	2017						
Safety Inspection of A90 & A9	72 South on 07	' Februar	y 2017						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 10 F	ebruary 2	2017						
No defects recorded Safety Inspection of A90 & A9 No defects recorded	972 South on 14	Februar	y 2017						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 17 F	ebruary 2	2017						
Safety Inspection of A90 & A9 No defects recorded	72 South on 21	Februar	y 2017						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 24 F	ebruary 2	2017						
Safety Inspection of A90 & A9 No defects recorded	72 South on 28	Februar	y 2017						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 03 M	larch 201	7						
Safety Inspection of A90 & A9 No defects recorded	972 South on 07	March 2	017						
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A9 No defects recorded Safety Patrol of A90 Swallow									
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow 1 NE7-256321-235075190	to SCC on 31 M 2,853m		7 CARRIAGEWAY	Pothole	CAT 1	28/04/2017	Completed	09/04/2017	@ LAND MANAGEMENT /
NET-200021-200010190	2,000111	Om	OANNAGEWAT	(POTH)	OAT T	20/04/2017	Defects	03/04/2017	STRAW4 BIOMASS ENTRANCE N/B
NE7-256321-235075191	2,857m	0m	CARRIAGEWAY	Patch - loss of	CAT 2	01/01/9999	Completed	20/07/2017	@ LAND MANAGEMENT /
				material (fretting) (PLMT)			Defects		STRAW 4 BIOMASS ENTRANCE N/B
NE7-256321-235075192	3,150m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/04/2017	Completed Defects	31/03/2017	ADJACENT TO LAYBY 2ND LAYBY AFTER NETHERTON TRACTORS N/B
Safety Inspection of A90 & A9 No defects recorded	972 South on 04	April 20	17						TRACTORO IVID
Safety Patrol of A90 Swallow No defects recorded	to SCC on 07 A	pril 2017							
Safety Inspection of A90 & A9 No defects recorded	972 South on 11	April 20	17						
Safety Patrol of A90 Swallow	to SCC on 14 A	pril 2017							
No defects recorded Safety Inspection of A90 & A9	972 South on 18	April 20	17						
No defects recorded Safety Patrol of A90 Swallow No defects recorded	to SCC on 21 A	pril 2017							
Safety Inspection of A90 & A9 No defects recorded	972 South on 25	April 20	17						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 28 A	pril 2017							
Safety Inspection of A90 & A9	72 South on 02	May 201	7						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded Safety Patrol of A90 Swallow No defects recorded	to SCC on 05 M	lay 2017							
Safety Inspection of A90 & A90 No defects recorded	972 South on 09	May 201	17						
Safety Patrol of A90 Swallow	to SCC on 12 M	lay 2017							
No defects recorded  Safety Inspection of A90 & A90	972 South on 16	: May 201	17						
No defects recorded Safety Patrol of A90 Swallow		_							
No defects recorded	10 000 011 13 14	lay 2017							
Safety Inspection of A90 & A90 No defects recorded	972 South on 23	8 May 201	17						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 26 M	lay 2017							
Safety Inspection of A90 & As No defects recorded		_							
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A90 No defects recorded									
Safety Patrol of A90 Swallow No defects recorded	to SCC on 09 J	une 2017							
Safety Inspection of A90 & A	972 South on 13	June 20	17						
NE7-279276-235193438	2,217m		FENCES_AND_BA RRIERS	Damaged / deformed - fence / barrier (DAMM)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	@ LAYBY AFTER NETHERTON TRACTORS NB
Safety Patrol of A90 Swallow No defects recorded	to SCC on 16 J	une 2017		(2,)					
Safety Inspection of A90 & A90 No defects recorded	972 South on 20	June 20	17						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 23 J	une 2017							
Safety Inspection of A90 & A90 No defects recorded	972 South on 27	June 20	17						
Safety Patrol of A90 Swallow	to SCC on 30 J	une 2017							
No defects recorded Safety Inspection of A90 & A90	972 South on 04	L luly 201	17						
NE7-281805-235251503	205m		CARRIAGEWAY	Patch - difference in level (PDLV)	CAT 1	01/08/2017	Completed Defects	11/10/2017	APPROX 205M PAST FINAVON CASTLE NB
NE7-281805-235251504	203m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 2	01/01/9999	Completed Defects	11/10/2017	APPROX 200M AFTER FINAVON CASTLE NB
NE7-281805-235251505	218m	0m	CARRIAGEWAY	Patch -	CAT 2	01/01/9999	Completed	11/10/2017	APPROX 220M AFTER
				difference in level (PDLV)			Defects		FINAVON CASTLE NB
NE7-281805-235251506	238m	238m	CARRIAGEWAY	Patch - difference in level (PDLV)	CAT 2	01/01/9999	Completed Defects	11/10/2017	APPROX 240M AFTER FINAVON CASTLE NB
NE7-281805-235251507	246m	0m	CARRIAGEWAY	Patch - difference in level (PDLV)	CAT 2	01/01/9999	Completed Defects	11/10/2017	APPROX 250M AFTER FINAVON CASTLE NB
Safety Patrol of A90 Swallow No defects recorded	to SCC on 07 J	uly 2017		,					
Safety Inspection of A90 & A90 No defects recorded	972 South on 11	July 201	17						
Safety Patrol of A90 Swallow	to SCC on 14 J	uly 2017							
No defects recorded Safety Inspection of A90 & A9	972 South on 18	3 July 201	17						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 21 J	uly 2017							
No defects recorded Safety Inspection of A90 & A9	972 South on 25	July 201	17						
No defects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow to So	CC on 28 Ju	ılv 2017							
No defects recorded		_							
Safety Inspection of A90 & A972 S No defects recorded	South on 01	August 2	017						
Safety Patrol of A90 Swallow to So	CC on 04 Au	ugust 201	7						
No defects recorded Safety Inspection of A90 & A972 S	South on 09	August 2	017						
No defects recorded	outii oii oo	August 2	317						
Safety Patrol of A90 Swallow to Son No defects recorded	CC on 11 Au	ugust 201	7						
Safety Inspection of A90 & A972 S	South on 15	August 2	017						
No defects recorded Safety Patrol of A90 Swallow to S0	CC am 40 A.		7						
No defects recorded	CC OII 18 AC	ugust 201	1						
Safety Inspection of A90 & A972 S No defects recorded	South on 22	August 2	017						
Safety Patrol of A90 Swallow to So	CC on 25 Au	ugust 201	7						
No defects recorded Safety Inspection of A90 & A972 S	South on 20	August 2	017						
NE7-283881-235346770	2,211m		TRAFFIC_SIGNS	Accident	CAT 1	26/09/2017	Completed	10/09/2017	AFTER NETHERTON
				damage			Defects		TRCTORS N/B
NE7-283881-235346771	2,220m	0m	FENCES_AND_BA	(ACCD) Accident	CAT 1	26/09/2017	Completed	10/09/2017	AFTER NETHERTON
			RRIERS	damage			Defects		TRACTORS N/B
Safety Patrol of A90 Swallow to So	CC on 01 Se	eptember	2017	(ACCD)					
No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded	South on 05	Septemb	er 2017						
Safety Patrol of A90 Swallow to So	CC on 08 Se	eptember	2017						
No defects recorded Safety Inspection of A90 & A972 S	South on 12	Septemb	er 2017						
No defects recorded		-							
Safety Patrol of A90 Swallow to Son No defects recorded	CC on 15 Se	eptember	2017						
Safety Inspection of A90 & A972 S	South on 19	Septemb	er 2017						
No defects recorded Safety Patrol of A90 Swallow to S0	CC on 22 Se	eptember	2017						
No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded	South on 26	Septemb	ar 2017						
Safety Patrol of A90 Swallow to SO				O# " (OTUD)	047.0	04/04/0000	Oat O Assaitia	04/04/0000	FINANCIN LINDEDDAGO
NE7-314961-235397515	1,005m	Um	FOOTWAY	Other (OTHR)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	FINAVON UNDERPASS
Safety Inspection of A90 & A972 S	South on 02	Octobor 1	2017						
No defects recorded									
Safety Patrol of A90 Swallow to Son No defects recorded	CC on 06 O	ctober 20	17						
Safety Inspection of A90 & A972 S	South on 10	October 2	2017						
No defects recorded Safety Patrol of A90 Swallow to S0	CC on 13 O	ctober 20°	17						
No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded	South on 17	October 2	2017						
Safety Patrol of A90 Swallow to So	CC on 20 O	ctober 20	17						
No defects recorded Safety Inspection of A90 & A972 S	South on 24	October 2	2017						
No defects recorded									
Safety Patrol of A90 Swallow to Son No defects recorded	CC on 27 O	ctober 20 <sup>4</sup>	17						
Safety Inspection of A90 & A972 S	South on 31	October 2	2017						
No defects recorded Safety Patrol of A90 Swallow to S0	CC on 03 No	ovember 2	2017						
No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded	South on 07	Novembe	r 2017						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow t	o SCC on 10 N	lovember 20	017						
No defects recorded Safety Inspection of A90 & A9	72 South on 14	4 November	r 2017						
No defects recorded Safety Patrol of A90 Swallow t	o SCC on 17 N	lovember 2	017						
No defects recorded Safety Inspection of A90 & A9	72 South on 21	1 November	r 2017						
No defects recorded Safety Patrol of A90 Swallow t	o SCC on 24 N	lovember 20	017						
No defects recorded Safety Inspection of A90 & A9 No defects recorded	72 South on 28	8 November	r 2017						
Safety Patrol of A90 Swallow t No defects recorded	o SCC on 01 D	December 20	017						
Safety Inspection of A90 & A9 No defects recorded	72 South on 05	5 December	2017						
Safety Patrol of A90 Swallow t No defects recorded									
Safety Inspection of A90 & A9  No defects recorded									
Safety Patrol of A90 Swallow t NE7-316876-235497680	3,398m	0m (	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/01/2018	Completed Defects	11/01/2018	APPROX 150M BEFORE MIL OF MARCUS FARM ENTRANCE NB
Safety Inspection of A90 & A9 NE7-316959-235497677	<b>72 South on 19</b> 2,354m		r <b>2017</b> CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/12/2017	Completed Defects	19/12/2017	@ LAYBY AFTER NETHERTON TRACTORS N/B
NE7-316959-235497678	2,339m	0m (	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	20/12/2017	Completed Defects	19/12/2017	@ LAYBY AFTER NETHERTON TRACTORS N/B
Safety Patrol of A90 Swallow t	o SCC on 22 D	December 20	017						
No defects recorded Safety Inspection of A90 & A9 No defects recorded Safety Patrol of A90 Swallow t									
No defects recorded  Safety Inspection of A90 & A9  No defects recorded	72 South on 02	2 January 2	018						
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 05 J	lanuary 201	8						
Safety Inspection of A90 & A9 No defects recorded	72 South on 09	9 January 2	018						
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 12 J	anuary 201	8						
Safety Inspection of A90 & A9 No defects recorded Safety Patrol of A90 Swallow t		_							
No defects recorded Safety Inspection of A90 & A9	72 South on 23	3 January 2	018						
No defects recorded Safety Patrol of A90 Swallow t No defects recorded	o SCC on 26 J	anuary 201	8						
Safety Inspection of A90 & A9 No defects recorded	72 South on 30	0 January 2	018						
Safety Patrol of A90 Swallow t No defects recorded	o SCC on 02 F	ebruary 20	18						
Safety Inspection of A90 & A9 No defects recorded Safety Patrol of A90 Swallow t									
No defects recorded Safety Inspection of A90 & A9 No defects recorded	72 South on 13	3 February 2	2018						
Safety Patrol of A90 Swallow t No defects recorded	o SCC on 16 F	ebruary 20 <sup>-</sup>	18						
Safety Inspection of A90 & A9 No defects recorded	72 South on 20	0 February 2	2018						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow to No defects recorded	SCC on 23 Fe	ebruary 2	018						
Safety Inspection of A90 & A97. NE7-322563-235549043	2 South on 27 3,612m		y <b>2018</b> CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	28/02/2018	Awaiting CCMS Permanent Date	27/02/2018	BEFORE MILL OF MARCUS N/B
Safety Patrol of A90 Swallow to	SCC on 02 M	arch 201	В						
Safety Inspection of A90 & A97 NE7-324685-235552236	2 South on 06 4,198m		018 CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	03/04/2018	Completed Defects	07/06/2018	APPROX 300M BEFORE WATERSTON RD NB
Safety Patrol of A90 Swallow to No defects recorded	SCC on 09 M	arch 2018	8	,					
Safety Inspection of A90 & A97 NE7-326686-235554439	2 South on 13 4,174m		018 CARRIAGEWAY	Pothole (POTH)	CAT 1	10/04/2018	Completed Defects	12/04/2018	BEFORE NORAN WATER N/B
NE7-326686-235554440	4,244m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	10/04/2018	Completed Defects	12/04/2018	APPROACHING NORAN WATER N/B
Safety Patrol of A90 Swallow to No defects recorded Safety Inspection of A90 & A97									
No defects recorded Safety Patrol of A90 Swallow to No defects recorded	SCC on 23 M	arch 2018	В						
Safety Inspection of A90 & A97 No defects recorded	2 South on 27	March 20	018						
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A97 NE7-332669-235614505	2 South on 03 3,011m		18 CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	01/05/2018	Completed Defects	14/05/2018	AT FIRST LAYBY AFTER PEGGY SCOTTS NB
Safety Patrol of A90 Swallow to No defects recorded Safety Inspection of A90 & A97 No defects recorded									
Safety Patrol of A90 Swallow to NE7-336898-235640964	SCC on 13 A <sub>1</sub> 2,925m		CARRIAGEWAY	Pothole (POTH)	CAT 1	11/05/2018	Awaiting CCMS Permanent Date	24/04/2018	BEFORE LAYBY AFTER NETHERTON FARM N/B
Safety Inspection of A90 & A97 NE7-337482-235640964	2 South on 17 2,330m		18 CARRIAGEWAY	Pothole VIAFIX	CAT 1	18/04/2018	Completed	17/04/2018	@ LAYBY AFTER NETHERTON
, (L) 301702-2000-030 <del>-</del>	2,000111	OIII	JAMAJOLIVAI	(POTV)	OAT T	10/04/2010	Defects	1770-772010	TRACTORS N/B
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A97 No defects recorded		-							
Safety Patrol of A90 Swallow to No defects recorded Safety Inspection of A90 & A97									
No defects recorded  Safety Patrol of A90 Swallow to No defects recorded	SCC on 04 M	ay 2018							
Safety Inspection of A90 & A97 NE7-344813-235705408	2 South on 08 202m		8 CARRIAGEWAY	Pothole (POTH)	CAT 1	05/06/2018	Completed Defects	01/06/2018	APPROX 200M AFTER FINAVON CASTLE NB
NE7-344813-235705409	197m	0m	CARRIAGEWAY	Patch - material cracking (PMCK)	CAT 2	01/01/9999	Completed Defects	31/05/2018	APPROX 200M AFTER FINAVON CASTLE NB

20/09/2018

Page 20 of 64

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swall	low to SCC on 11 I	May 2018							
No defects recorded Safety Inspection of A90 8		_							
No defects recorded									
Safety Patrol of A90 Swall No defects recorded									
Safety Inspection of A90 8 No defects recorded	≩ A972 South on 2	2 May 2018							
Safety Patrol of A90 Swall No defects recorded	low to SCC on 25 l	May 2018							
Safety Inspection of A90 8	<b>&amp; A972 South on 2</b>	.9 May 2018							
No defects recorded Safety Patrol of A90 Swall	low to SCC on 01 .	June 2018							
No defects recorded Safety Inspection of A90 8	& A972 South on 0	)5 June 2018	3						
No defects recorded Safety Patrol of A90 Swall									
No defects recorded			_						
Safety Inspection of A90 8 No defects recorded									
Safety Patrol of A90 Swall No defects recorded	ow to SCC on 15 J	June 2018							
Safety Inspection of A90 & No defects recorded	<b>ል A972 South on 1</b>	.9 June 2018	j						
Safety Patrol of A90 Swalle No defects recorded	low to SCC on 22 .	June 2018							
Safety Inspection of A90 8	& A972 South on 2	26 June 2018	}						
No defects recorded Safety Patrol of A90 Swall No defects recorded	low to SCC on 29 .	June 2018							
Safety Inspection of A90 8 No defects recorded	<b>Ֆ A972 South on 0</b>	3 July 2018							
Safety Patrol of A90 Swall	low to SCC on 06 .	July 2018							
No defects recorded Safety Inspection of A90 8	& A972 South on 1	0 July 2018							
No defects recorded Safety Patrol of A90 Swall	low to SCC on 13 .	July 2018							
No defects recorded Safety Inspection of A90 8	& A972 South on 1	7 July 2018							
No defects recorded Safety Patrol of A90 Swall	low to SCC on 20 .	July 2018							
No defects recorded Safety Inspection of A90 8	& A972 South on 2	24 July 2018	,						
No defects recorded Safety Patrol of A90 Swall		-							
No defects recorded		_							
Safety Inspection of A90 8 No defects recorded		-							
Safety Patrol of A90 Swall No defects recorded	ow to SCC on 03 A	August 2018							
12240/53 : WITH: NORA	AN WATER BRI	DGE TO J	CT (R) TO NETI	HERTON					
Safety Inspection of A90 8 No defects recorded				-					
Safety Patrol of A90 Swall No defects recorded	ow to SCC on 12 /	August 2016	j						
Safety Inspection of A90 8 No defects recorded	& A972 South on 1	6 August 20	)16						
Safety Patrol of A90 Swall No defects recorded	low to SCC on 19 /	August 2016	š						
Safety Inspection of A90 8 No defects recorded	≩ A972 South on 2	≀3 August 20	116						
Safety Patrol of A90 Swall No defects recorded	low to SCC on 26 /	August 2016	j						
Safety Inspection of A90 8 No defects recorded	§ A972 South on 3	i0 August 20	116						
Safety Patrol of A90 Swall	ow to SCC on 02 S	September 2	<u> 2016</u>						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded									
Safety Inspection of A90 & A No defects recorded	972 South on 0	6 Septemb	er 2016						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 09	September	2016						
Safety Inspection of A90 & A	972 South on 1	3 Septemb	er 2016						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 16	September	2016						
No defects recorded Safety Inspection of A90 & A No defects recorded	972 South on 2	0 Septemb	er 2016						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 23	September	2016						
Safety Inspection of A90 & A No defects recorded	972 South on 2	7 Septembe	er 2016						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 30 S	September	2016						
Safety Inspection of A90 & A No defects recorded	972 South on 0	4 October 2	2016						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 07 (	October 201	16						
Safety Inspection of A90 & A No defects recorded	972 South on 1	1 October 2	2016						
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A No defects recorded Safety Patrol of A90 Swallow									
No defects recorded  Safety Inspection of A90 & A	972 South on 2	5 October 2	2016						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 28 (	October 201	16						
No defects recorded Safety Inspection of A90 & A No defects recorded	972 South on 0	1 Novembe	er 2016						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 04 I	November 2	2016						
Safety Inspection of A90 & A No defects recorded Safety Patrol of A90 Swallow									
No defects recorded Safety Inspection of A90 & A	972 South on 1	5 Novembe	er 2016						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 18 I	November 2	2016						
No defects recorded Safety Inspection of A90 & A No defects recorded									
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A No defects recorded									
Safety Patrol of A90 Swallow No defects recorded Safety Inspection of A90 & A									
No defects recorded  Safety Patrol of A90 Swallow									
No defects recorded Safety Inspection of A90 & A									
No defects recorded  Safety Patrol of A90 Swallow									
No defects recorded									
Safety Inspection of A90 & A No defects recorded Safety Patrol of A90 Swallow									
Safety Patrol of A90 Swallow No defects recorded Safety Inspection of A90 & A									
Safety Inspection of A90 & A No defects recorded	ar∠ South on 2	, necembe	#1 <b>ZU</b> 10						

20/09/2018 Page 22 of 64

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow	to SCC on 30 D	ecember	2016						
No defects recorded Safety Inspection of A90 & A	.972 South on 03	3 January	2017						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 06 J	anuary 20	17						
No defects recorded  Safety Inspection of A90 & A	.972 South on 10	) January	2017						
No defects recorded Safety Patrol of A90 Swallow									
No defects recorded Safety Inspection of A90 & A									
No defects recorded Safety Patrol of A90 Swallow									
No defects recorded									
Safety Inspection of A90 & A No defects recorded									
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A No defects recorded									
Safety Patrol of A90 Swallow No defects recorded	to SCC on 03 F	ebruary 2	017						
Safety Inspection of A90 & A No defects recorded	.972 South on 07	7 February	/ 2017						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 10 F	ebruary 2	017						
Safety Inspection of A90 & A No defects recorded	.972 South on 14	4 February	/ 2017						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 17 F	ebruary 2	017						
Safety Inspection of A90 & A No defects recorded	.972 South on 21	1 February	/ 2017						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 24 F	ebruary 2	017						
Safety Inspection of A90 & A	.972 South on 28	B February	<i>,</i> 2017						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 03 N	larch 2017	7						
No defects recorded Safety Inspection of A90 & A	.972 South on 07	7 March 20	017						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 10 N	larch 2017	7						
No defects recorded  Safety Inspection of A90 & A	.972 South on 14	4 March 20	017						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 17 N	larch 2017	7						
No defects recorded  Safety Inspection of A90 & A	.972 South on 21	1 March 20	017						
No defects recorded Safety Patrol of A90 Swallow									
No defects recorded Safety Inspection of A90 & A									
No defects recorded Safety Patrol of A90 Swallow									
NE7-256321-235075194	408m		CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/04/2017	Completed Defects	31/03/2017	@ LAYBY AFTER WATERSTON RD JCT NB
NE7-256321-235075195	408m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/04/2017	Completed Defects	31/03/2017	@ LAYBY AFTER WATERSTON RD JCT NB
NE7-256321-235075196	408m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/04/2017	Completed Defects	31/03/2017	@ LAYBY AFTER WATERSTON RD JCT NB
NE7-256321-235075197	408m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/04/2017	Completed Defects	31/03/2017	@ LAYBY AFTER WATERSTON RD JCT NB
Safety Inspection of A90 & A No defects recorded	972 South on 04	4 April 201	17						
Safety Patrol of A90 Swallow	to SCC on 07 A	pril 2017							

20/09/2018

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
N 16 1									
No defects recorded Safety Inspection of A90 & A972 S No defects recorded	outh on 11	April 2017	•						
Safety Patrol of A90 Swallow to SO No defects recorded	CC on 14 A <sub>l</sub>	pril 2017							
Safety Inspection of A90 & A972 S	outh on 18	April 2017	7						
NE7-261634-235087469	871m	0m	TRAFFIC_SIGNS	Accident damage (ACCD)	CAT 1	16/05/2017	Completed Defects	07/05/2017	@ CARESTON HOUSE N/B ( ACROSS FROM LAYBY)
Safety Patrol of A90 Swallow to SO No defects recorded	CC on 21 Ap	pril 2017		,					
Safety Inspection of A90 & A972 S No defects recorded			7						
Safety Patrol of A90 Swallow to SO No defects recorded Safety Inspection of A90 & A972 S									
No defects recorded									
Safety Patrol of A90 Swallow to S0 No defects recorded		-							
Safety Inspection of A90 & A972 S No defects recorded Safety Patrol of A90 Swallow to S6									
Safety Patrol of A90 Swallow to SO No defects recorded Safety Inspection of A90 & A972 S									
No defects recorded	outil on 10	May 2017							
Safety Patrol of A90 Swallow to SO No defects recorded Safety Inspection of A90 & A972 S									
No defects recorded									
Safety Patrol of A90 Swallow to SC No defects recorded		-							
Safety Inspection of A90 & A972 S  No defects recorded  Safety Patrol of A90 Swallow to S0									
No defects recorded  Safety Inspection of A90 & A972 S			7						
No defects recorded	outil on oo	ounc 2011							
Safety Patrol of A90 Swallow to S0 NE7-279104-235193439	669m		CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	10/06/2017	Completed Defects	13/06/2017	APPROX 150M AFTER LAYBY - AFTER WATERSTON RD NB
Safety Inspection of A90 & A972 S No defects recorded	outh on 13	June 2017	7						
Safety Patrol of A90 Swallow to SO No defects recorded	CC on 16 Ju	ıne 2017							
Safety Inspection of A90 & A972 S No defects recorded			7						
Safety Patrol of A90 Swallow to SO No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded			7						
Safety Patrol of A90 Swallow to SO No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded									
Safety Patrol of A90 Swallow to SO No defects recorded									
Safety Inspection of A90 & A972 S  No defects recorded  Safety Patrol of A90 Swallow to S0									
No defects recorded  Safety Inspection of A90 & A972 S									
No defects recorded Safety Patrol of A90 Swallow to S0									
No defects recorded  Safety Inspection of A90 & A972 S									
No defects recorded		•							

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow to S	SCC on 28 J	July 2017							
No defects recorded		-							
Safety Inspection of A90 & A972 S No defects recorded	South on 0'	1 August 20	017						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 04 A	August 2017	7						
Safety Inspection of A90 & A972 S No defects recorded	South on 08	8 August 20	017						
Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded		_							
Safety Patrol of A90 Swallow to S NE7-283690-235323661	953m	0m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	15/09/2017	Completed Defects	18/09/2017	AFTER NETHERTON FARM N/B
Safety Inspection of A90 & A972 S No defects recorded									
Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded									
Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded									
Safety Patrol of A90 Swallow to S No defects recorded Safety Inspection of A90 & A972 S No defects recorded		-							
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 15 S	3eptember ∶	2017						
Safety Inspection of A90 & A972	South on 19	9 Septembe	er 2017						
No defects recorded Safety Patrol of A90 Swallow to S No defects recorded	SCC on 22 S	September :	2017						
Safety Inspection of A90 & A972 S	South on 26	6 Septembe	er 2017						
Safety Patrol of A90 Swallow to S No defects recorded		-							
Safety Inspection of A90 & A972 S NE7-315008-235397516	South on 03 774m		2017 SAFETY_FENCE	Accident	CAT 1	31/10/2017	Completed	26/10/2017	BEFORE MAINS OF
7127 010000 200007070		0	5/11	damage (ACCD)	<i>G71.7</i> 1	01/10/2011	Defects	20/10/2011	CARESTON FARM N/B
NE7-315008-235397517	875m	0m	CARRIAGEWAY	Other (OTHR)	CAT 1	31/10/2017	Completed Defects	10/10/2017	MAINS OF CARESTON FARM N/B
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 06 C	October 201	17						
Safety Inspection of A90 & A972 S No defects recorded									
Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972 S NE7-315448-235430568	South on 17 406m		<b>2017</b> CARRIAGEWAY	Pothole VIAFIX	CAT 1	18/10/2017	Completed	17/10/2017	APPROX 400M AFTER NORAN
NE7-313440-233430300	400111	Om	CANNIAGEWAT	(POTV)	CALL	10/10/2017	Defects	17710/2017	WATER BRIDGE NB
NE7-315448-235430569	414m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/10/2017	Completed Defects	17/10/2017	APPROX 415M AFTER NORAN WATER BRIDGE NB
NE7-315448-235430570	418m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	18/10/2017	Completed Defects	17/10/2017	APPROX 420M AFTER NORAN WATER BRIDGE NB
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 20 C	October 201	17						
Safety Inspection of A90 & A972 S No defects recorded	South on 24	4 October 2	2017						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow to S	SCC on 27 C	october 201	7						
Safety Inspection of A90 & A972 NE7-315737-235445744	<b>South on 3</b> 1 <i>500m</i>		<b>017</b> CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	01/11/2017	Completed Defects	31/10/2017	PAST LAYBY AFTER WATERSTON RD N/B
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 03 N	lovember 2	017						
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972 No defects recorded	South on 14	4 November	r 2017						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 17 N	lovember 2	017						
Safety Inspection of A90 & A972 No defects recorded	South on 21	l Novembei	r 2017						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 24 N	lovember 2	017						
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to S									
No defects recorded Safety Inspection of A90 & A972	South on 05	5 December	2017						
No defects recorded Safety Patrol of A90 Swallow to S No defects recorded	SCC on 08 D	ecember 20	017						
Safety Inspection of A90 & A972 No defects recorded	South on 12	2 December	r 2017						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 15 D	ecember 20	017						
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to S									
No defects recorded Safety Inspection of A90 & A972 No defects recorded	South on 26	6 December	2017						
Safety Patrol of A90 Swallow to S	SCC on 29 D	ecember 20	017						
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to 9									
No defects recorded Safety Inspection of A90 & A972	South on 09	January 2	018						
NE7-317402-235513829	418m		CARRIAGEWAY	Patch - difference in level (PDLV)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	@ LAYBY AFTER NORAN WATER BRIDGE NB
Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to S		_							
No defects recorded Safety Inspection of A90 & A972 No defects recorded	South on 23	3 January 2	018						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 26 J	anuary 201	8						
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to S									
No defects recorded Safety Inspection of A90 & A972		_							
No defects recorded Safety Patrol of A90 Swallow to 9									
No defects recorded Safety Inspection of A90 & A972									
			<del>-</del>						

Page 26 of 64

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded									
Safety Patrol of A90 Swallow to S0	CC on 16 Fe	bruary 2	018						
NE7-319990-235544804	411m		CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	16/03/2018	Completed Defects	18/04/2018	APPROX 410M AFTER NORAN WATER BRIDGE @ LAYBY NB
Safety Inspection of A90 & A972 S No defects recorded		_							
Safety Patrol of A90 Swallow to So No defects recorded	CC on 23 Fe	bruary 2	018						
Safety Inspection of A90 & A972 S No defects recorded Safety Patrol of A90 Swallow to S0		_							
No defects recorded		Manada 00	N40						
Safety Inspection of A90 & A972 S NE7-324685-235552237	57m		CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/03/2018	Completed Defects	07/03/2018	APPROX 60M AFTER NORAN WATER BRIDGE JCT NB
NE7-324685-235552238	75m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	28/03/2018	APPROX 75M AFTER NORANWATER BRIDGE JCT NB
NE7-324685-235552239	153m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	07/03/2018	Completed Defects	07/03/2018	JUST BEFORE LAYBY AFTER NORAN WATER BRIDGE NB
NE7-324685-235552240	417m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	03/04/2018	Completed Defects	28/03/2018	ADJACENT TO LAYBY APPROX 420M AFTER NORAN WATER BRIDGE NB
Safety Patrol of A90 Swallow to SO No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded	South on 13	March 20	)18						
Safety Patrol of A90 Swallow to So	CC on 16 Ma	arch 2018	3						
NE7-328091-235587611	791m		CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	13/04/2018	Completed Defects	31/05/2018	APPROX 800M AFTER NORAN WATER BRIDGE NB @ CARESTON HOUSE ENTRANCE
Safety Inspection of A90 & A972 S No defects recorded	outh on 20	March 20	)18						
Safety Patrol of A90 Swallow to So	CC on 23 Ma	arch 2018	3						
No defects recorded  Safety Inspection of A90 & A972 S  No defects recorded	outh on 27	March 20	018						
Safety Patrol of A90 Swallow to So No defects recorded	CC on 30 Ma	arch 2018	3						
Safety Inspection of A90 & A972 S	outh on 03	April 201	8						
No defects recorded  Safety Patrol of A90 Swallow to S0 No defects recorded	CC on 06 Ap	oril 2018							
Safety Inspection of A90 & A972 S No defects recorded	outh on 10	April 201	8						
Safety Patrol of A90 Swallow to So No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded			8						
Safety Patrol of A90 Swallow to So No defects recorded			0						
Safety Inspection of A90 & A972 S No defects recorded	outh on 24	April 201	8						
Safety Patrol of A90 Swallow to So No defects recorded	CC on 27 Ap	oril 2018							
Safety Inspection of A90 & A972 S No defects recorded	outh on 01	May 2018	3						
Safety Patrol of A90 Swallow to So No defects recorded		_							
Safety Inspection of A90 & A972 S No defects recorded		_	3						
Safety Patrol of A90 Swallow to So	CC on 11 Ma	ay 2018							

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects vessibled									
No defects recorded Safety Inspection of A90 & A No defects recorded	.972 South on 1	5 May 201	8						
Safety Patrol of A90 Swallow No defects recorded		-							
Safety Inspection of A90 & A No defects recorded			3						
Safety Patrol of A90 Swallow No defects recorded Safety Inspection of A90 & A		-	8						
No defects recorded Safety Patrol of A90 Swallow		_							
No defects recorded  Safety Inspection of A90 & A	.972 South on 0	5 June 20 <sup>,</sup>	18						
NE7-357250-235819922	456m		FENCES_AND_BA RRIERS	Accident damage (ACCD)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	LAYBY AFTER WATERSTON RD N/B
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A No defects recorded									
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A No defects recorded Safety Patrol of A90 Swallow									
No defects recorded  Safety Inspection of A90 & A									
No defects recorded Safety Patrol of A90 Swallow									
No defects recorded  Safety Inspection of A90 & A	.972 South on 0	3 July 201	8						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 06 J	luly 2018							
No defects recorded Safety Inspection of A90 & A No defects recorded	1972 South on 10	0 July 201	8						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 13 J	uly 2018							
Safety Inspection of A90 & A No defects recorded			8						
Safety Patrol of A90 Swallow No defects recorded		-							
Safety Inspection of A90 & A No defects recorded		-	8						
Safety Patrol of A90 Swallow No defects recorded		-	0						
Safety Inspection of A90 & A No defects recorded Safety Patrol of A90 Swallow									
No defects recorded	7 to SCC on 03 P	tugust 201	10						
12240/70 : WITH: JUNCTI				NCRETE					
Safety Inspection of A90 & A No defects recorded									
Safety Patrol of A90 Swallow No defects recorded Safety Inspection of A90 & A									
No defects recorded Safety Patrol of A90 Swallow									
No defects recorded  Safety Inspection of A90 & A		_							
No defects recorded Safety Patrol of A90 Swallow	to SCC on 26 A	August 201	16						
No defects recorded Safety Inspection of A90 & A	.972 South on 30	0 August 2	2016						

Salety Particul of All 8 Swallow to SCC on 16 September 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 23 September 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 23 September 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 30 September 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 30 September 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 30 September 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 30 September 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 30 September 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 30 September 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 Cotober 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 Cotober 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 Cotober 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 Cotober 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 Cotober 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 Cotober 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 Cotober 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 Cotober 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 November 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 November 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 November 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 November 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 November 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 November 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 November 2016 No School: Incompose Salety Particul of All 8 Swallow to SCC on 10 November 2016 No School: Incompose Salety Particul of A	Defect Reference	Start m	End m	Item Type	ltem Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Statisty Patrol of ABO Seation to SEC OF IN SECRETARY 2015  **Control Seation Seation Secretary 2015  **Control Secret	No defeate recorded									
Safety Inspection of ABIS A AATZ South on 193 Englamentar 2016 No octoors recented Safety Partie of ABIS Safety Safety Committed (Committed Committed Commit	Safety Patrol of A90 Swallov	w to SCC on 02 S	Septembe	er 2016						
No sinders in secretors of AND 8 APT 2 South on 13 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 15 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 13 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 13 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 13 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 13 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 13 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 10 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 10 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 10 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 10 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 10 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 10 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 10 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 10 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 11 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 11 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 12 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 12 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 12 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 12 Experimentor 2016 Sabely Partic of AND 8 AND 8 Southine to SCC on 12 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 12 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 12 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 12 Experimentor 2016 Sabely Partic of AND 8 AND 8 Southine to SCC on 10 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 10 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 10 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 10 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 10 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 10 Experimentor 2016 Sabely Partic of AND 8 Southine to SCC on 10 Experimentor 2016 Sabely Parti	Safety Inspection of A90 & A	A972 South on 0	6 Septem	ber 2016						
Sakely Inspectation of ARIS & ARTS 2 counts on 3 5 september 2016  19 defects recorded  19 de	Safety Patrol of A90 Swallov	w to SCC on 09 S	Septembe	er 2016						
No effects restricted Starting Places (All Comments and Section 2015) Starting		A972 South on 1	3 Septem	ber 2016						
No addict recorded  Askety Parties of AND Swallow to SCC on 23 September 2916  Sately Inspection of AND ANT 25 South on 17 September 2916  No addicts recorded  AND ANT 25 South on 14 September 2916  No addicts recorded  AND ANT 25 South on 14 September 2916  No addicts recorded  AND ANT 25 South on 14 September 2916  No addicts recorded  AND ANT 25 South on 14 Declare 2916  No addicts recorded  AND ANT 25 South on 14 Declare 2916  No addicts recorded  AND ANT 25 South on 15 Declare 2916  No addicts recorded  AND ANT 25 South on 15 Declare 2916  No addicts recorded  AND ANT 25 South on 15 Declare 2916  No addicts recorded  AND ANT 25 South on 15 Declare 2916  No addicts recorded  AND ANT 25 South on 15 Declare 2916  No addicts recorded  AND ANT 25 South on 15 Declare 2916  No addicts recorded  AND ANT 25 South on 15 November 2916  No addicts recorded  AND ANT 25 South on 15 November 2916  No addicts recorded  AND ANT 25 South on 15 November 2916  No addicts recorded  AND ANT 25 South on 15 November 2916  No addicts recorded  AND ANT 25 South on 15 November 2916  No addicts recorded  AND ANT 25 South on 15 November 2916  No addicts recorded  AND ANT 25 South on 15 November 2916  No addicts recorded  AND ANT 25 South on 15 November 2916  No addicts recorded  AND ANT 25 South on 15 November 2916  No addicts recorded  AND ANT 25 South on 15 November 2916  No addicts recorded  AND ANT 25 South on 15 November 2916  NO addicts recorded  AND ANT 25 South on 15 November 2916  NO addicts recorded  AND ANT 25 South on 15 November 2916  NO addicts recorded  AND ANT 25 South on 15 November 2916  NO addicts recorded  AND ANT 25 South on 15 November 2916  NO addicts recorded  AND ANT 25 South on 15 November 2916  NO addicts recorded  AND ANT 25 South on 15 November 2916  NO addicts recorded  AND ANT 25 South on 15 November 2916  NO addicts recorded  AND ANT 25 South on 15 November 2916  NO addicts recorded  AND ANT 25 South on 15 November 2916  NO addicts recorded  AND ANT 25 South on 15 November 2916  NO addicts recorded  AND	Safety Patrol of A90 Swallov	w to SCC on 16	Septembe	er 2016						
No defects described shade a ARYZ South on 72 September 2016 Statily Particul of ARIS Southware No ECC on 30 September 2016 Statily Particul of ARIS Southware No ECC on 30 September 2016 Statily Particul of ARIS Southware No ECC on 30 September 2016 Statily Particul of ARIS Southware No ECC on 30 September 2016 No defects received No Ecc on 20 September 2016 No Septembe	Safety Inspection of A90 & A No defects recorded	A972 South on 2	0 Septem	ber 2016						
Manipulation for controls Salitary Patriol of All 30 Swellow to 50 Con 30 September 2016 Salitary Patriol of All 30 Swellow to 50 Con 30 September 2016 Salitary Patriol of All 30 Swellow to 50 Con 30 Con 50 Con 5		w to SCC on 23	Septembe	er 2016						
Moderfuer recorded Stately Interpretation of ARIB & ARIZ South on 64 Octobar 2016 Satisty Partial of ARIB Seatlow to 5.CC on 67 Octobar 2016 Satisty Partial Oct		A972 South on 2	7 Septem	ber 2016						
His defective recorded Sately Patrol of ABB Swallow to SCC on B7 October 2016 Sately Patrol of ABB Swallow to SCC on 14 October 2016 (Sately Patrol of ABB Swallow to SCC on 14 October 2016 (Sately Patrol of ABB Swallow to SCC on 14 October 2016 (Sately Patrol of ABB Swallow to SCC on 14 October 2016 (Sately Patrol of ABB Swallow to SCC on 27 October 2016 (Sately Patrol of ABB Swallow to SCC on 27 October 2016 (Sately Patrol of ABB Swallow to SCC on 27 October 2016 (Sately Patrol of ABB Swallow to SCC on 27 October 2016 (Sately Patrol of ABB Swallow to SCC on 27 October 2016 (Sately Patrol of ABB Swallow to SCC on 27 October 2016 (Sately Patrol of ABB Swallow to SCC on 27 October 2016 (Sately Patrol of ABB Swallow to SCC on 27 October 2016 (Sately Patrol of ABB Swallow to SCC on 27 October 2016 (Sately Patrol of ABB Swallow to SCC on 28 October 2016 (Sately Patrol of ABB Swallow to SCC on 38 October 2016 (Sately P		w to SCC on 30 S	Septembe	er 2016						
No director recorded Sately Inspection of ABD & AB72 South on 11 October 2018 Sately Part of ABD Swallow to SCC on 14 October 2016 Sately Part of ABD Swallow to SCC on 12 October 2016 Sately Inspection of ABD & AB72 South on 18 October 2016 No director recorded Sately Inspection of ABD & AB72 South on 18 October 2016 No director recorded Sately Inspection of ABD & AB72 South on 28 October 2016 No director recorded Sately Inspection of ABD & AB72 South on 28 October 2016 No director recorded Sately Inspection of ABD & AB72 South on 28 October 2016 No director recorded Sately Inspection of ABD & AB72 South on 28 October 2016 No director recorded Sately Inspection of ABD & AB72 South on 28 October 2016 No director recorded Sately Inspection of ABD & AB72 South on 38 November 2016 No director recorded Sately Inspection of ABD & AB72 South on 38 November 2016 No director recorded Sately Inspection of ABD & AB72 South on 38 November 2016 No director recorded Sately Inspection of ABD & AB72 South on 38 November 2016 No director recorded Sately Inspection of ABD & AB72 South on 38 November 2016 No director recorded Sately Part of ABD & AB72 South on 38 November 2016 No director recorded Sately Part of ABD & AB72 South on 38 November 2016 No director recorded Sately Part of ABD & AB72 South on 28 November 2016 No director recorded Sately Part of ABD & AB72 South on 29 November 2016 No director recorded Sately Part of ABD & AB72 South on 29 November 2016 No director recorded Sately Part of ABD & AB72 South on 29 November 2016 No director recorded Sately Part of ABD & AB72 South on 30 December 2016 No director recorded Sately Part of ABD & AB72 South on 30 December 2016 No director recorded Sately Part of ABD & AB72 South on 30 December 2016 No director recorded Sately Part of ABD & AB72 South on 30 December 2016 No director recorded Sately Part of ABD & AB72 South on 30 December 2016 No director recorded Sately Part of ABD & AB72 South on 30 December 2016 No director recorded Sately Part of ABD & Swallow to SCC on 12 Dec	Safety Inspection of A90 & A No defects recorded	A972 South on 0	4 Octobei	r 2016						
No defects recommed Satisty Partial of A98 Swallow to SCC on 14 October 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 12 October 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 12 October 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 12 October 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 28 October 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 28 October 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 28 October 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 28 October 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 18 November 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 18 November 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 18 November 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 18 November 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 18 November 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 18 November 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 18 November 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 18 November 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 18 November 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 02 November 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 03 December 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 03 December 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 03 December 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 03 December 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 03 December 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 03 December 2016 No defects recommed Satisty Partial of A98 Swallow to SCC on 03 December 2016 No defects recommed		w to SCC on 07 (	October 2	016						
No effects recorded Sately Inspection of A98 & A972 South on 18 October 2016 No reference in recorded No reference in rec	Safety Inspection of A90 & A No defects recorded	A972 South on 1	1 October	r 2016						
No defects recorded Safety Part of ABD Swallow to SCC on 21 October 2016 No defects recorded Safety Part of ABD Swallow to SCC on 28 October 2016 Safety Part of ABD Swallow to SCC on 28 October 2016 Safety Part of ABD Swallow to SCC on 28 October 2016 Safety Part of ABD Swallow to SCC on 28 October 2016 Safety Part of ABD Swallow to SCC on 28 October 2016 Safety Part of ABD Swallow to SCC on 28 October 2016 Safety Part of ABD Swallow to SCC on 28 October 2016 Safety Part of ABD Swallow to SCC on 28 October 2018 Safety Part of ABD Swallow to SCC on 18 November 2018 Safety Part of ABD Swallow to SCC on 18 November 2018 Safety Part of ABD Swallow to SCC on 18 November 2016 Safety Part of ABD Swallow to SCC on 18 November 2016 Safety Part of ABD Swallow to SCC on 18 November 2016 Safety Part of ABD Swallow to SCC on 18 November 2016 Safety Part of ABD Swallow to SCC on 18 November 2016 Safety Part of ABD Swallow to SCC on 18 November 2016 Safety Part of ABD Swallow to SCC on 18 November 2016 Safety Part of ABD Swallow to SCC on 18 November 2016 Safety Part of ABD Swallow to SCC on 18 November 2016 Safety Part of ABD Swallow to SCC on 18 November 2016 Safety Part of ABD Swallow to SCC on 18 November 2016 Safety Part of ABD Swallow to SCC on 18 November 2016 Safety Part of ABD Swallow to SCC on 18 November 2016 Safety Part of ABD Swallow to SCC on 18 November 2016 Safety Part of ABD Swallow to SCC on 18 December 2016 Safety Part of ABD Swallow to SCC on 18 December 2016 Safety Part of ABD Swallow to SCC on 18 December 2016 Safety Part of ABD Swallow to SCC on 18 December 2016 Safety Part of ABD Swallow to SCC on 18 December 2016 Safety Part of ABD Swallow to SCC on 28 December 2016 Safety Part of ABD Swallow to SCC on 28 December 2016 Safety Part of ABD Swallow to SCC on 28 December 2016 Safety Part of ABD Swallow to SCC on 28 December 2016 Safety Part of ABD Swallow to SCC on 28 December 2016 Safety Part of ABD Swallow to SCC on 28 December 2016 Safety Part of ABD Swallow to SCC on 28 December 2016 Safety Part of AB		w to SCC on 14 (	October 2	016						
No advices recorded Safety Inspection of A90 & A972 South on 25 October 2016 No advices recorded Safety Patric of A90 Swallow to SCC on 28 October 2016 No advices recorded Safety Inspection of A90 & A972 South on 08 November 2016 No advices recorded Safety Inspection of A90 & A972 South on 08 November 2016 No advices recorded Safety Inspection of A90 & A972 South on 08 November 2016 No advices recorded Safety Inspection of A90 & A972 South on 08 November 2016 No advices recorded Safety Inspection of A90 & A972 South on 08 November 2016 No advices recorded Safety Inspection of A90 & A972 South on 18 November 2016 No advices recorded Safety Inspection of A90 & A972 South on 18 November 2016 No advices recorded Safety Inspection of A90 & A972 South on 18 November 2016 No advices recorded Safety Inspection of A90 & A972 South on 28 November 2016 No advices recorded No advices recorded Safety Inspection of A90 & A972 South on 28 November 2016 No advices recorded Safety Inspection of A90 & A972 South on 28 November 2016 No advices recorded Safety Inspection of A90 & A972 South on 28 November 2016 No advices recorded Safety Inspection of A90 & A972 South on 28 November 2016 No advices recorded Safety Inspection of A90 & A972 South on 08 December 2016 No advices recorded Safety Inspection of A90 & A972 South on 08 December 2016 No advices recorded Safety Inspection of A90 & A972 South on 18 December 2016 No advices recorded Safety Inspection of A90 & A972 South on 18 December 2016 No advices recorded Safety Inspection of A90 & A972 South on 18 December 2016 No advices recorded Safety Inspection of A90 & A972 South on 18 December 2016 No advices recorded Safety Inspection of A90 & A972 South on 18 December 2016 No advices recorded Safety Inspection of A90 & A972 South on 20 December 2016 No advices recorded	Safety Inspection of A90 & A No defects recorded	A972 South on 1	8 Octobei	r 2016						
No defects recorded Safety Parties of A99 Swallow to SCC on 28 October 2016 No defects recorded Safety Inspection of 490 & A972 South on 01 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 05 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 05 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 05 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 05 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 05 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 05 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 22 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 22 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 22 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 22 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 28 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 29 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 29 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 29 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 30 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 30 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 30 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 30 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 30 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 30 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 30 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 30 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 30 December 2016 No defects recorded		w to SCC on 21 (	October 2	016						
No adelects recorded Safety Inspection of A90 & A972 South on 02 November 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 09 November 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 09 December 2016 No adelects recorded Safety Inspection of A90 & A972 South on 08 November 2016 No adelects recorded Safety Inspection of A90 Swallow to SCC on 18 November 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 18 November 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 18 November 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 18 November 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 28 November 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 28 November 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 28 November 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 28 November 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 19 December 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 19 December 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 19 December 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 19 December 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 19 December 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 19 December 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 19 December 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 19 December 2016 No adelects recorded Safety Partol of A90 Swallow to SCC on 29 December 2016 No adelects recorded	Safety Inspection of A90 & A No defects recorded	A972 South on 2	25 Octobei	r 2016						
No defects recorded Safety Patrol of A90 Savaliow to SCC on 04 November 2016 No defects recorded Safety Patrol of A90 Savaliow to SCC on 18 November 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 18 November 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 18 November 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 18 November 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 18 November 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 28 November 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 29 November 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 29 November 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 29 November 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 29 November 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 09 December 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 09 December 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 09 December 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 18 December 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 18 December 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 18 December 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 18 December 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 18 December 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 18 December 2016 No defects recorded Safety Nation of A90 Savaliow to SCC on 20 December 2016 No defects recorded		w to SCC on 28 (	October 2	016						
No defects recorded Safety Party off A99 Swallow to SCC on 11 November 2016 No defects recorded Safety Party off A99 Swallow to SCC on 11 November 2016 No defects recorded Safety Party off A99 Swallow to SCC on 18 November 2016 No defects recorded Safety Party off A99 Swallow to SCC on 18 November 2016 No defects recorded Safety Party off A99 Swallow to SCC on 18 November 2016 No defects recorded Safety Party off A99 Swallow to SCC on 18 November 2016 No defects recorded Safety Party off A99 Swallow to SCC on 25 November 2016 No defects recorded Safety Party off A99 Swallow to SCC on 25 November 2016 No defects recorded Safety Party off A99 Swallow to SCC on 25 November 2016 No defects recorded Safety Party off A99 Swallow to SCC on 20 December 2016 No defects recorded Safety Party off A99 Swallow to SCC on 20 December 2016 No defects recorded Safety Party off A99 Swallow to SCC on 20 December 2016 No defects recorded Safety Party off A99 Swallow to SCC on 00 December 2016 No defects recorded Safety Party off A99 Swallow to SCC on 00 December 2016 No defects recorded Safety Party off A99 Swallow to SCC on 10 December 2016 No defects recorded Safety Party off A99 Swallow to SCC on 10 December 2016 No defects recorded Safety Party off A99 Swallow to SCC on 10 December 2016 No defects recorded Safety Party off A99 Swallow to SCC on 10 December 2016 No defects recorded Safety Party off A99 Swallow to SCC on 10 December 2016 No defects recorded Safety Party off A99 Swallow to SCC on 23 December 2016 No defects recorded Safety Party off A99 Swallow to SCC on 23 December 2016		A972 South on 0	1 Novemb	ber 2016						
No defects recorded Safety Patrol of A90 Swallow to SCC on 11 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 18 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 18 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 18 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 28 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 25 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 25 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 02 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 02 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 03 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 03 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 03 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 03 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 03 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 18 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 18 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 18 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 18 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 18 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 28 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 29 December 2016		w to SCC on 04 I	November	r 2016						
No defects recorded Safety Inspection of A90 & A972 South on 15 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 22 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 18 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 25 November 2016 No defects recorded Safety Patrol of A90 & A972 South on 29 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 25 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 02 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 18 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 23 December 2016	No defects recorded									
No defects recorded Safety Patrol of A90 Swallow to SCC on 18 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 25 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 25 November 2016 No defects recorded Safety Inspection of A90 Swallow to SCC on 25 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 25 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 02 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 15 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 20 December 2016 No defects recorded	No defects recorded									
No defects recorded Safety Inspection of A90 & A972 South on 22 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 25 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 29 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 02 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 02 December 2016 No defects recorded Safety Safety Inspection of A90 & A972 South on 06 December 2016 No defects recorded Safety Inspection of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Inspection of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 19 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 10 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 10 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 10 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 10 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 12 December 2016 No defects recorded Safety Of A90 Swallow to SCC on 23 December 2016 No defects recorded	Safety Inspection of A90 & A No defects recorded	A972 South on 1	5 Novemb	ber 2016						
No defects recorded Safety Patrol of A90 Swallow to SCC on 25 November 2016 No defects recorded Safety Inspection of A90 & A972 South on 29 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 02 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 06 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 06 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 23 December 2016 No defects recorded	No defects recorded									
No defects recorded Safety Patrol of A90 & A972 South on 29 November 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 02 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 06 December 2016 No defects recorded Safety Inspection of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Inspection of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 23 December 2016	No defects recorded									
No defects recorded Safety Patrol of A90 Swallow to SCC on 02 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 06 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 13 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 20 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 20 December 2016 No defects recorded	No defects recorded									
No defects recorded Safety Inspection of A90 & A972 South on 06 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 13 December 2016 No defects recorded Safety Inspection of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 20 December 2016 No defects recorded Safety Inspection of A90 Swallow to SCC on 23 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 23 December 2016	No defects recorded									
No defects recorded Safety Patrol of A90 Swallow to SCC on 09 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 13 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 20 December 2016 No defects recorded Safety Inspection of A90 Swallow to SCC on 23 December 2016 Safety Patrol of A90 Swallow to SCC on 23 December 2016	No defects recorded									
No defects recorded Safety Inspection of A90 & A972 South on 13 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 20 December 2016 No defects recorded Safety Inspection of A90 & A978 South on 20 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 23 December 2016	No defects recorded									
No defects recorded Safety Patrol of A90 Swallow to SCC on 16 December 2016 No defects recorded Safety Inspection of A90 & A972 South on 20 December 2016 No defects recorded Safety Patrol of A90 Swallow to SCC on 23 December 2016	No defects recorded									
No defects recorded  Safety Inspection of A90 & A972 South on 20 December 2016  No defects recorded  Safety Patrol of A90 Swallow to SCC on 23 December 2016	No defects recorded									
No defects recorded Safety Patrol of A90 Swallow to SCC on 23 December 2016	No defects recorded									
	No defects recorded									
		w to SCC on 23 I	December	r 2016						

20/09/2018 Page 29 of 64

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A97	'2 South on 27	7 December	2016						
No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded									
Safety Inspection of A90 & A97 No defects recorded	2 South on 03	3 January 2	017						
Safety Patrol of A90 Swallow to	SCC on 06 J	anuary 201	7						
No defects recorded  Safety Inspection of A90 & A97	2 South on 10	0 January 2	017						
No defects recorded  Safety Patrol of A90 Swallow to	SCC on 13.I	anuary 201	7						
No defects recorded									
Safety Inspection of A90 & A97 No defects recorded	2 South on 17	7 January 2	017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 20 J	anuary 201	7						
Safety Inspection of A90 & A97	2 South on 24	4 January 2	017						
No defects recorded  Safety Patrol of A90 Swallow to	SCC on 27 J	anuary 201	7						
No defects recorded  Safety Inspection of A90 & A97	'2 South on 31	1 January 2	017						
No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	SCC on 03 F	ebruary 20	17						
Safety Inspection of A90 & A97 No defects recorded	2 South on 07	7 February 2	2017						
Safety Patrol of A90 Swallow to	SCC on 10 F	ebruary 20	17						
No defects recorded  Safety Inspection of A90 & A97	'2 South on 14	4 February 2	2017						
NE7-243228-235056798	1,993m		SAFETY_FENCE	Accident damage (ACCD)	CAT 1	14/03/2017	Completed Defects	08/03/2017	APPROX 500M BEFORE START OF CONCRETE SECTION NB
Safety Patrol of A90 Swallow to No defects recorded	SCC on 17 F	ebruary 20	17						
Safety Inspection of A90 & A97 No defects recorded	2 South on 21	1 February 2	2017						
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A97 No defects recorded	2 South on 28	8 February 2	2017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 03 N	larch 2017							
Safety Inspection of A90 & A97	2 South on 07	7 March 201	7						
No defects recorded  Safety Patrol of A90 Swallow to	SCC on 10 N	March 2017							
No defects recorded  Safety Inspection of A90 & A97	'2 South on 14	4 March 201	7						
No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A97 No defects recorded	'2 South on 21	1 March 201	7						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 24 N	larch 2017							
Safety Inspection of A90 & A97	2 South on 28	8 March 201	7						
No defects recorded Safety Patrol of A90 Swallow to No defects recorded	SCC on 31 N	larch 2017							
Safety Inspection of A90 & A97	2 South on 04	4 April 2017							
No defects recorded  Safety Patrol of A90 Swallow to	SCC on 07 A	April 2017							
No defects recorded Safety Inspection of A90 & A97									
No defects recorded Safety Patrol of A90 Swallow to	SCC on 14 A	April 2017							
No defects recorded									
Safety Inspection of A90 & A97	2 South on 18	s April 2017							

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded									
Safety Patrol of A90 Swallov No defects recorded	v to SCC on 21 A	April 2017							
Safety Inspection of A90 & A No defects recorded	1972 South on 2	5 April 2017	,						
Safety Patrol of A90 Swallov No defects recorded	v to SCC on 28 A	April 2017							
Safety Inspection of A90 & A No defects recorded	\972 South on 0	2 May 2017							
Safety Patrol of A90 Swallov No defects recorded	v to SCC on 05 N	May 2017							
Safety Inspection of A90 & A No defects recorded	1972 South on 0	9 May 2017							
Safety Patrol of A90 Swallov No defects recorded	v to SCC on 12 M	May 2017							
Safety Inspection of A90 & A No defects recorded	1972 South on 1	6 May 2017							
Safety Patrol of A90 Swallow No defects recorded	v to SCC on 19 N	May 2017							
Safety Inspection of A90 & A No defects recorded	\972 South on 2	3 May 2017							
Safety Patrol of A90 Swallov No defects recorded	v to SCC on 26 M	May 2017							
Safety Inspection of A90 & A No defects recorded									
Safety Patrol of A90 Swallov No defects recorded			_						
Safety Inspection of A90 & A No defects recorded	N972 South on 0	6 June 2017							
Safety Patrol of A90 Swallov No defects recorded									
Safety Inspection of A90 & A NE7-279276-235193439	A972 South on 1 2,306m		r SAFETY_FENCE	Accident damage (ACCD)	CAT 1	11/07/2017	Completed Defects	19/07/2017	JUST BEFORE OF THE START OF CONCRETE SECTION NB
Safety Patrol of A90 Swallov No defects recorded	v to SCC on 16 J	June 2017		(/:002)					
Safety Inspection of A90 & A No defects recorded	1972 South on 2	0 June 2017	7						
Safety Patrol of A90 Swallov	v to SCC on 23 J	June 2017							
No defects recorded Safety Inspection of A90 & A	1972 South on 2	7 June 2017	7						
No defects recorded Safety Patrol of A90 Swallov	v to SCC on 30 J	June 2017							
No defects recorded Safety Inspection of A90 & A	1972 South on 0	4 July 2017							
No defects recorded Safety Patrol of A90 Swallov No defects recorded	v to SCC on 07 J	July 2017							
Safety Inspection of A90 & A No defects recorded	N972 South on 1	1 July 2017							
Safety Patrol of A90 Swallov No defects recorded	v to SCC on 14 J	July 2017							
Safety Inspection of A90 & A No defects recorded	\972 South on 1	8 July 2017							
Safety Patrol of A90 Swallov No defects recorded	v to SCC on 21 J	July 2017							
Safety Inspection of A90 & A No defects recorded	1972 South on 2	5 July 2017							
Safety Patrol of A90 Swallov No defects recorded	v to SCC on 28 J	July 2017							
Safety Inspection of A90 & A No defects recorded	N972 South on 0	1 August 20	017						
Safety Patrol of A90 Swallov No defects recorded	v to SCC on 04 A	August 2017	7						
Safety Inspection of A90 & A No defects recorded	A972 South on 0	8 August 20	017						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow to	SCC on 11 A	August 2017							
No defects recorded		_							
Safety Inspection of A90 & A972 No defects recorded	South on 1	5 August 201	17						
Safety Patrol of A90 Swallow to	SCC on 18 A	August 2017							
No defects recorded Safety Inspection of A90 & A972	South on 2	2 August 201	17						
No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded		_							
Safety Inspection of A90 & A972 No defects recorded	South on 2	9 August 201	17						
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A972 No defects recorded	South on 0	5 September	r 2017						
Safety Patrol of A90 Swallow to	SCC on 08 S	September 20	017						
No defects recorded Safety Inspection of A90 & A972	South on 1	2 September	r 2017						
No defects recorded		-							
Safety Patrol of A90 Swallow to No defects recorded	300 ON 15 S	september 20	U1/						
Safety Inspection of A90 & A972 No defects recorded	South on 1	9 September	r 2017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 22 S	September 20	017						
Safety Inspection of A90 & A972 No defects recorded	South on 2	6 September	r 2017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 29 S	September 20	017						
Safety Inspection of A90 & A972 No defects recorded	South on 0	3 October 20	017						
Safety Patrol of A90 Swallow to	SCC on 06 (	October 2017	7						
No defects recorded Safety Inspection of A90 & A972 No defects recorded	South on 1	0 October 20	017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 13 (	October 2017	7						
Safety Inspection of A90 & A972 No defects recorded	South on 1	7 October 20	017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 20 (	October 2017	7						
Safety Inspection of A90 & A972 No defects recorded	South on 2	4 October 20	017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 27 (	October 2017	7						
Safety Inspection of A90 & A972 No defects recorded	South on 3	1 October 20	017						
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A972 No defects recorded	South on 0	7 November	2017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 10 N	November 20	017						
Safety Inspection of A90 & A972 No defects recorded	South on 1	4 November	2017						
Safety Patrol of A90 Swallow to	SCC on 17 l	November 20	017						
No defects recorded Safety Inspection of A90 & A972 No defects recorded	South on 2	1 November	2017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 24 N	November 20	)17						
Safety Inspection of A90 & A972 No defects recorded	South on 2	8 November	2017						
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A972	South on 0	5 December	2017						

Page 32 of 64

Report Version 1.2 20/09/2018

Defect Reference	Start m	End m		em Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded										
Safety Patrol of A90 Swallo No defects recorded	ow to SCC on 08	Decemi	ber 2017							
Safety Inspection of A90 & No defects recorded	A972 South on	12 Dece	ember 2017	7						
Safety Patrol of A90 Swallo	ow to SCC on 15	Deceml	ber 2017							
No defects recorded Safety Inspection of A90 &	A972 South on	19 Dece	ember 2017	7						
No defects recorded  Safety Patrol of A90 Swalld  No defects recorded	ow to SCC on 22	Decemi	ber 2017							
Safety Inspection of A90 & No defects recorded	A972 South on	26 Dece	ember 2017	7						
Safety Patrol of A90 Swallo No defects recorded	ow to SCC on 29	Decemi	ber 2017							
Safety Inspection of A90 & No defects recorded	A972 South on	02 Janu	ıary 2018							
Safety Patrol of A90 Swalld No defects recorded	ow to SCC on 05	January	y 2018							
Safety Inspection of A90 & No defects recorded	A972 South on	09 Janu	ary 2018							
Safety Patrol of A90 Swalld No defects recorded										
Safety Inspection of A90 & No defects recorded										
No defects recorded										
Safety Inspection of A90 & No defects recorded										
No defects recorded										
No defects recorded Safety Patrol of A90 Swalld										
No defects recorded  Safety Inspection of A90 &										
No defects recorded Safety Patrol of A90 Swallo			•							
No defects recorded Safety Inspection of A90 &										
No defects recorded Safety Patrol of A90 Swallo No defects recorded	ow to SCC on 16	Februa	ry 2018							
Safety Inspection of A90 & No defects recorded	A972 South on	20 Febr	uary 2018							
Safety Patrol of A90 Swalld No defects recorded										
Safety Inspection of A90 & No defects recorded										
No defects recorded										
Safety Inspection of A90 & No defects recorded Safety Patrol of A90 Swallo										
No defects recorded  Safety Inspection of A90 &										
No defects recorded Safety Patrol of A90 Swalld										
No defects recorded Safety Inspection of A90 &										
No defects recorded Safety Patrol of A90 Swallo										
No defects recorded Safety Inspection of A90 &										
No defects recorded Safety Patrol of A90 Swalld										
No defects recorded										

Page 33 of 64

Report Version 1.2 20/09/2018

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972 S	South on 03	Δnril 2018							
No defects recorded  Safety Patrol of A90 Swallow to SO  No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded	outh on 10	April 2018							
Safety Patrol of A90 Swallow to SC	CC on 13 A <sub>l</sub>	pril 2018							
No defects recorded Safety Inspection of A90 & A972 S No defects recorded	outh on 17	April 2018							
Safety Patrol of A90 Swallow to SO No defects recorded	CC on 20 A	pril 2018							
Safety Inspection of A90 & A972 S No defects recorded									
Safety Patrol of A90 Swallow to SC NE7-341083-235672793	CC on 27 A <sub>l</sub> 1,943m		SAFETY_FENCE	Accident damage (ACCD)	CAT 1	25/05/2018	Completed Defects	30/04/2018	JUST BEFORE CONCRETE SECTION N/B
Safety Inspection of A90 & A972 S	outh on 01	May 2018							
No defects recorded  Safety Patrol of A90 Swallow to SO  No defects recorded	CC on 04 M	ay 2018							
Safety Inspection of A90 & A972 S No defects recorded	outh on 08	May 2018							
Safety Patrol of A90 Swallow to SO No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded									
Safety Patrol of A90 Swallow to SO No defects recorded Safety Inspection of A90 & A972 S		-							
No defects recorded Safety Patrol of A90 Swallow to S0									
No defects recorded		-							
Safety Inspection of A90 & A972 S No defects recorded									
Safety Patrol of A90 Swallow to SO No defects recorded Safety Inspection of A90 & A972 S									
No defects recorded Safety Patrol of A90 Swallow to SO No defects recorded	CC on 08 Ju	une 2018							
Safety Inspection of A90 & A972 S No defects recorded									
Safety Patrol of A90 Swallow to SO No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded									
Safety Patrol of A90 Swallow to SO No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded									
Safety Patrol of A90 Swallow to SC No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded									
Safety Patrol of A90 Swallow to SO No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded									
Safety Patrol of A90 Swallow to SC No defects recorded									
Safety Inspection of A90 & A972 S  No defects recorded									
Safety Patrol of A90 Swallow to SC No defects recorded		_							
Safety Inspection of A90 & A972 S	outh on 24	July 2018							

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defect									
No defects recorded Safety Patrol of A90 Swallow to No defects recorded	to SCC on 27	July 2018							
Safety Inspection of A90 & A9 No defects recorded	72 South on 3	1 July 2018							
Safety Patrol of A90 Swallow	to SCC on 03 A	August 2018							
No defects recorded	NE CONCRE	TE TO AG	DE IUNCTION						
12240/95 : WITH: START C Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 12	August 2016							
Safety Inspection of A90 & A9	72 South on 1	6 August 20	16						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 19 A	August 2016							
No defects recorded Safety Inspection of A90 & A9 No defects recorded	72 South on 2	3 August 20	16						
Safety Patrol of A90 Swallow	to SCC on 26 A	August 2016							
No defects recorded Safety Inspection of A90 & A9	72 South on 3	0 August 20	16						
No defects recorded Safety Patrol of A90 Swallow to No defects recorded	to SCC on 02 S	September 2	016						
Safety Inspection of A90 & A9 No defects recorded	72 South on 0	6 Septembe	r 2016						
Safety Patrol of A90 Swallow the No defects recorded	to SCC on 09 S	September 2	016						
Safety Inspection of A90 & A9 No defects recorded	72 South on 1	3 Septembe	r 2016						
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 16 S	September 2	016						
Safety Inspection of A90 & A9 No defects recorded	72 South on 2	0 Septembe	r 2016						
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded		-							
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 1	5 November	2016						

20/09/2018 Page 35 of 64

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow	to SCC on 18 N	lovember 2	2016						
No defects recorded  Safety Inspection of A90 & A  No defects recorded									
Safety Patrol of A90 Swallow No defects recorded	to SCC on 25 N	lovember 2	016						
Safety Inspection of A90 & A No defects recorded	972 South on 29	9 Novembei	r 2016						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 02 D	December 20	016						
Safety Inspection of A90 & A No defects recorded	972 South on 00	6 December	r <b>2016</b>						
Safety Patrol of A90 Swallow No defects recorded Safety Inspection of A90 & A No defects recorded									
Safety Patrol of A90 Swallow No defects recorded	to SCC on 16 E	December 20	016						
Safety Inspection of A90 & A No defects recorded									
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A No defects recorded	972 South on 27	7 December	r <b>2016</b>						
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A NE8-228636-235030442	972 South on 03 447m		2017 CARRIAGEWAY	Failed repair	CAT 1	31/01/2017	Completed	24/01/2017	approximately 450 after the start
==================================	, , , , , ,	•		(RFAL)	<b></b> .	• • · . · . · . · . · . · . · .	Defects	0 0	of the concrete section NB
Safety Patrol of A90 Swallow No defects recorded	to SCC on 06 J	lanuary 201	7						
Safety Inspection of A90 & A No defects recorded	972 South on 10	0 January 2	:017						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 13 J	lanuary 201	7						
Safety Inspection of A90 & A	972 South on 17	7 January 2	:017						
No defects recorded Safety Patrol of A90 Swallow No defects recorded	to SCC on 20 J	lanuary 201	7						
Safety Inspection of A90 & A						24/22/224			
NE8-237501-235040631	636m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2017	Completed Defects	13/02/2017	APPROX 600M BEFORE ST ANNES JCT N/B
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A No defects recorded	9/2 South on 3'	1 January 2	.017						
Safety Patrol of A90 Swallow No defects recorded		-							
Safety Inspection of A90 & A No defects recorded									
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A No defects recorded									
Safety Patrol of A90 Swallow No defects recorded		-							
Safety Inspection of A90 & A No defects recorded	9/2 South on 2	1 February 2	2017						
Safety Patrol of A90 Swallow No defects recorded		-							
Safety Inspection of A90 & A No defects recorded	972 South on 28	8 February 2	2017						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 03 N	March 2017							
Safety Inspection of A90 & A	972 South on 0	7 March 201	l7						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded Safety Patrol of A90 Swallow to SC No defects recorded	C on 10 Ma	arch 2017	,						
Safety Inspection of A90 & A972 So No defects recorded	outh on 14	March 20	)17						
Safety Patrol of A90 Swallow to SC	C on 17 Ma	arch 2017	1						
No defects recorded									
Safety Inspection of A90 & A972 So No defects recorded	outh on 21	March 20	117						
Safety Patrol of A90 Swallow to SC No defects recorded	C on 24 Ma	arch 2017	,						
Safety Inspection of A90 & A972 So No defects recorded	outh on 28	March 20	)17						
Safety Patrol of A90 Swallow to SC No defects recorded	C on 31 Ma	arch 2017	,						
Safety Inspection of A90 & A972 So	outh on 04								
NE7-256929-235075188	718m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/05/2017	Completed Defects	17/04/2017	APPROX 600M BEFORE ST ANNS JCT N/B
Safety Patrol of A90 Swallow to SC No defects recorded									
Safety Inspection of A90 & A972 So No defects recorded	outh on 11	April 201	7						
Safety Patrol of A90 Swallow to SC No defects recorded	C on 14 Ap	oril 2017							
Safety Inspection of A90 & A972 So No defects recorded	outh on 18	April 201	7						
Safety Patrol of A90 Swallow to SC No defects recorded	C on 21 Ap	oril 2017							
Safety Inspection of A90 & A972 So No defects recorded	outh on 25	April 201	7						
Safety Patrol of A90 Swallow to SC No defects recorded	C on 28 Ap	oril 2017							
Safety Inspection of A90 & A972 So No defects recorded	outh on 02	May 2017	1						
Safety Patrol of A90 Swallow to SC No defects recorded	C on 05 Ma	ay 2017							
Safety Inspection of A90 & A972 So	outh on 09	May 2017	7						
No defects recorded	C on 42 Ma	2047							
Safety Patrol of A90 Swallow to SC No defects recorded		_	_						
Safety Inspection of A90 & A972 So No defects recorded		_	<u>'</u>						
Safety Patrol of A90 Swallow to SC No defects recorded		_							
Safety Inspection of A90 & A972 So No defects recorded	outh on 23	May 2017	7						
No defects recorded Safety Patrol of A90 Swallow to SC	C on 26 Ma	av 2017							
NE7-277071-235173856	458m		CARRIAGEWAY	Pothole (POTH)	CAT 1	23/06/2017	Completed Defects	13/06/2017	500M AFTER START OF CONCRETE SECTION N/B
NE7-277071-235173857	479m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/06/2017	Completed Defects	13/06/2017	500M AFTER START OF CONCRETE SECTION N/B
NE7-277071-235173858	624m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/06/2017	Completed Defects	13/06/2017	600M BEFORE ST ANNES JCT NB
NE7-277071-235173859	632m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/06/2017	Completed Defects	13/06/2017	600M BEFORE ST ANNES JCT N/B
NE7-277071-235173860	641m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/06/2017	Completed Defects	13/06/2017	600M BEFORE ST ANNES JCT N/B
NE7-277071-235173861	717m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	23/06/2017	Completed Defects	13/06/2017	500M BEFORE ST ANNES JCT N/B
Safety Inspection of A90 & A972 So	outh on 30	May 2017	7						

Safety Inspection of A90 & A972 South on 30 May 2017 No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow to SC	C on 02 J	une 2017							
No defects recorded	00 011 02 0	une zon							
Safety Inspection of A90 & A972 Son No defects recorded	outh on 06	3 June 2017	7						
Safety Patrol of A90 Swallow to SC	CC on 09 J	une 2017							
No defects recorded									
Safety Inspection of A90 & A972 Service NE7-279276-235193440	outh on 13 <i>454m</i>		7 CARRIAGEWAY	Pothole	CAT 1	11/07/2017	Completed	06/07/2017	APPROX 450M AFTER START
				(POTH)			Defects		OF CONCRETE SECTION NB
NE7-279276-235193441	621m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	11/07/2017	Completed Defects	13/06/2017	APPROX 600M BEFORE ST ANNS NB
Safety Patrol of A90 Swallow to SC No defects recorded	CC on 16 J	une 2017							
Safety Inspection of A90 & A972 S	outh on 20	) June 2017	7						
No defects recorded Safety Patrol of A90 Swallow to SC No defects recorded	CC on 23 J	une 2017							
Safety Inspection of A90 & A972 S	outh on 27	7 June 2017	7						
No defects recorded Safety Patrol of A90 Swallow to S0	C on 30 I	une 2017							
No defects recorded									
Safety Inspection of A90 & A972 Service NE7-281805-235251509	956m		CARRIAGEWAY	Pothole	CAT 1	01/08/2017	Completed	17/07/2017	@ 200 C/MARKER POST
				(POTH)			Defects		BEFORE ST ANNS NB
Safety Patrol of A90 Swallow to SC No defects recorded	CC on 07 J	uly 2017							
Safety Inspection of A90 & A972 S	outh on 11	July 2017							
No defects recorded Safety Patrol of A90 Swallow to S0	CC on 14 J	uly 2017							
No defects recorded		_							
Safety Inspection of A90 & A972 Son No defects recorded	outh on 18	3 July 2017							
Safety Patrol of A90 Swallow to SC No defects recorded	CC on 21 J	uly 2017							
Safety Inspection of A90 & A972 Son No defects recorded	outh on 25	5 July 2017							
Safety Patrol of A90 Swallow to SC	CC on 28 J	uly 2017							
No defects recorded Safety Inspection of A90 & A972 Se	outh on 01	l August 20	017						
No defects recorded Safety Patrol of A90 Swallow to SC									
No defects recorded									
Safety Inspection of A90 & A972 Son No defects recorded	outh on 08	3 August 20	)17						
Safety Patrol of A90 Swallow to SC No defects recorded	CC on 11 A	ugust 2017	•						
Safety Inspection of A90 & A972 S									
NE7-283445-235313547	714m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	12/09/2017	Completed Defects	22/08/2017	APPROX 600M BEFORE A935 JCT ST ANNS NB LWT
Safety Patrol of A90 Swallow to SC NE7-283690-235323662	CC on 18 A 485m		7 CARRIAGEWAY	Pothole	CAT 1	15/09/2017	Completed	14/09/2017	APPROX 700M BEFORE ST
NET 200030-200020002	703111	OIII	SAN MAGENTAL	(POTH)	OAT T	10/00/2017	Defects	17/03/2017	ANNES JCT N/B
Safety Inspection of A90 & A972 So	outh on 22	2 August 20	017						
Safety Patrol of A90 Swallow to SC No defects recorded	CC on 25 A	ugust 2017	7						
Safety Inspection of A90 & A972 Some No defects recorded	outh on 29	August 20	)17						
Safety Patrol of A90 Swallow to SC No defects recorded	CC on 01 S	eptember 2	2017						
Safety Inspection of A90 & A972 S	outh on 05	5 Septembe	er 2017						
No defects recorded Safety Patrol of A90 Swallow to S0	CC on 08 S	eptember 1	2017						
Salety Fattor of A30 Swallow to 30		SPROMING! A							

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE7-292189-235370646	462m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	06/10/2017	Completed Defects	21/09/2017	APPROX 700M BEFORE ST ANNES JCT N/B
Safety Inspection of A90 & A972	South on 12	2 Septem	ber 2017						
No defects recorded Safety Patrol of A90 Swallow to S No defects recorded	SCC on 15 S	Septembe	er 2017						
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to S NE7-312833-235385828	SCC on <b>22</b> S 243m		e <b>r 2017</b> CARRIAGEWAY	Pothole (POTH)	CAT 1	20/10/2017	Completed Defects	26/07/2018	250M AFTER START OF CONCRETE SECTION N/B
Safety Inspection of A90 & A972 No defects recorded	South on 20	6 Septem	ber 2017						
Safety Patrol of A90 Swallow to S	SCC on 29 S	Septembe	er 2017						
No defects recorded Safety Inspection of A90 & A972 No defects recorded	South on 0	3 Octobe	r 2017						
Safety Patrol of A90 Swallow to S NE7-315221-235426305	6 <b>CC on 06 C</b> 463m		CO17 CARRIAGEWAY	Pothole (POTH)	CAT 1	03/11/2017	Completed Defects	26/10/2017	800M BEFORE ST ANNES JCT N/B
Safety Inspection of A90 & A972	South on 10	0 Octobe	r 2017						
No defects recorded Safety Patrol of A90 Swallow to S No defects recorded	SCC on 13 C	October 2	2017						
Safety Inspection of A90 & A972 No defects recorded	South on 17	7 Octobe	r 2017						
Safety Patrol of A90 Swallow to S	SCC on 20 C	October 2	2017						
No defects recorded Safety Inspection of A90 & A972 No defects recorded	South on 24	4 Octobe	r 2017						
Safety Patrol of A90 Swallow to S No defects recorded Safety Inspection of A90 & A972									
No defects recorded  Safety Patrol of A90 Swallow to S No defects recorded	SCC on 03 N	lovembe	r 2017						
Safety Inspection of A90 & A972 No defects recorded	South on 0	7 Novem	ber 2017						
Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972 No defects recorded	South on 14	4 Novem	ber 2017						
Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to S No defects recorded									
No defects recorded									
Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972 No defects recorded	South on 0	5 Decemi	ber 2017						
Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972 No defects recorded	South on 12	2 Decemi	per 2017						
Safety Patrol of A90 Swallow to S No defects recorded									
<b>Safety Inspection of A90 &amp; A972</b> <i>NE7-316959-235497679</i>	South on 19 651m		ber 2017 CARRIAGEWAY	Pothole (POTH)	CAT 1	16/01/2018	Completed Defects	23/01/2018	APPROX 600M BEFORE ST ANNES JCT N/B
Safety Patrol of A90 Swallow to S	SCC on 22 D	ecembe	r 2017	, ,					

Report Version 1.2 20/09/2018 Page 39 of 64

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE7-317029-235510752	842m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/01/2018	Completed Defects	23/01/2018	APPROX 300M BEFORE ST ANNS NB
Safety Inspection of A90 & A972	South on 26	Decemb	per 2017						
No defects recorded  Safety Patrol of A90 Swallow to S	SCC on 29 D	ecember	2017						
NE7-317148-235513444	718m		CARRIAGEWAY	Failed repair (RFAL)	CAT 1	26/01/2018	Completed Defects	23/01/2018	500M BEFORE ST ANNES JCT N/B
Safety Inspection of A90 & A972 No defects recorded	South on 02	2 January	2018						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 05 Ja	anuary 20	018						
Safety Inspection of A90 & A972 No defects recorded	South on 09	January	2018						
Safety Patrol of A90 Swallow to S	SCC on 12 J	anuary 20	018						
Safety Inspection of A90 & A972 No defects recorded	South on 16	January	2018						
Safety Patrol of A90 Swallow to S	SCC on 19 Ja	anuary 20	018						
No defects recorded Safety Inspection of A90 & A972	South on 23	3 January	2018						
No defects recorded Safety Patrol of A90 Swallow to S No defects recorded	SCC on 26 Ja	anuary 20	018						
Safety Inspection of A90 & A972 No defects recorded	South on 30	) January	2018						
Safety Patrol of A90 Swallow to S	SCC on 02 F	ebruary 2	2018						
Safety Inspection of A90 & A972 No defects recorded	South on 06	6 Februar	y 2018						
Safety Patrol of A90 Swallow to S				5 " '	0.47	00/00/2012		45/00/00 10	WAT DEFADE OF ANNIES
NE7-319041-235539918	1,114m	Оm	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/03/2018	Completed Defects	15/03/2018	JUST BEFORE ST ANNES OFFSLIP N/B
Safety Inspection of A90 & A972 No defects recorded	South on 13	S Februar	y 2018						
Safety Patrol of A90 Swallow to S	SCC on 16 F								
NE7-319990-235544805	455m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	16/03/2018	Completed Defects	21/03/2018	APPROX 455M AFTER START OF CONCRETE SECTION NB
NE7-319990-235544806	468m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	16/03/2018	Completed Defects	21/03/2018	APPROX 455M AFTER START OF CONCRETE SECTION NB
NE7-319990-235544807	633m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	16/03/2018	Completed Defects	21/03/2018	APPROX 630M AFTER THE START OF CONCRETE
Safety Inspection of A90 & A972	South on 20	) Februar	y 2018						SECTION NB
No defects recorded Safety Patrol of A90 Swallow to S No defects recorded	SCC on 23 F	ebruary 2	2018						
Safety Inspection of A90 & A972 No defects recorded	South on 27	' Februar	y 2018						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 02 M	larch 201	8						
Safety Inspection of A90 & A972 No defects recorded	South on 06	March 2	2018						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 09 M	larch 201	8						
Safety Inspection of A90 & A972									
NE7-326686-235554441	827m		CARRIAGEWAY	Pothole (POTH)	CAT 1	10/04/2018	Completed Defects	09/04/2018	350M BEFORE ST ANNES JCT N/B
NE7-326686-235554442	1,102m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	10/04/2018	Completed Defects	09/04/2018	JUST BEFORE ST ANNES OFFSLIP N/B
Safety Patrol of A90 Swallow to S	SCC on 16 M	larch 201	8						

Report Version 1.2 20/09/2018

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded Safety Inspection of A90 & A972 So No defects recorded	outh on 20 l	March 20	18						
Safety Patrol of A90 Swallow to SC No defects recorded	C on 23 Ma	rch 2018							
Safety Inspection of A90 & A972 So	outh on 27 l	March 20	18						
No defects recorded Safety Patrol of A90 Swallow to SC No defects recorded									
Safety Inspection of A90 & A972 So									
NE7-332669-235614506	616m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	01/05/2018	Completed Defects	28/04/2018	APPROX 615M AFTER THE START OF CONCRETE SECTION NB
Safety Patrol of A90 Swallow to SC			DOLLADDO	Mii (MICO)	047.4	04/05/0040	0	04/00/0040	
	1,288m		BOLLARDS	Missing (MISS)	CAT 1	04/05/2018	Completed Defects	01/08/2018	@ ST ANNS OF SLIP NB
Safety Inspection of A90 & A972 So No defects recorded			8						
Safety Patrol of A90 Swallow to SC No defects recorded	C On 13 Ap	rii 2016							
Safety Inspection of A90 & A972 So No defects recorded			8						
Safety Patrol of A90 Swallow to SC No defects recorded	C on 20 Ap	ril 2018							
Safety Inspection of A90 & A972 So	outh on 24 A	April 201	8						
No defects recorded Safety Patrol of A90 Swallow to SC No defects recorded									
Safety Inspection of A90 & A972 So	outh on 01 l	Mav 2018	<b>š</b>						
No defects recorded Safety Patrol of A90 Swallow to SC	C on 04 Ma	y 2018							
NE7-343879-235705403	247m		CARRIAGEWAY	Pothole (POTH)	CAT 1	01/06/2018	Completed Defects	29/05/2018	APPROX 250M AFTER THE START OF CONCRETE SECTION NB
Safety Inspection of A90 & A972 So No defects recorded Safety Patrol of A90 Swallow to SC		Ū	•						
NE7-346847-235785133	633m		CARRIAGEWAY	Failed repair (RFAL)	CAT 1	08/06/2018	Completed Defects	28/05/2018	APPROX 600M BEFORE ST ANNES N/B
NE7-346847-235785134	633m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	08/06/2018	Completed Defects	28/05/2018	APPROX 600M BEFORE ST ANNES N/B
Safety Inspection of A90 & A972 So	outh on 15 l	May 2018	<b>;</b>						
			CARRIAGEWAY	Failed repair (RFAL)	CAT 1	12/06/2018	Completed Defects	29/05/2018	JUST PRIOR TO ST ANNS (A935)OFF SLIP NB
Safety Patrol of A90 Swallow to SC									
NE7-349695-235803431	966m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	15/06/2018	Completed Defects	29/05/2018	BEFORE ST ANNES JCT N/B
Safety Inspection of A90 & A972 So				A4:- ' (4:22)	047	40/00/0045	0	40/00/0045	
NE7-350753-235803427	1,287m	1,287m	BOLLARDS	Missing (MISS)	CAT 1	19/06/2018	Completed Defects	19/06/2018	@ ST ANNES JCT N/B OFFSLIP
Safety Patrol of A90 Swallow to SC No defects recorded									
Safety Inspection of A90 & A972 So No defects recorded	outh on 29 l	May 2018							
Safety Patrol of A90 Swallow to SC	C on 01 Jui	ne 2018							
No defects recorded Safety Inspection of A90 & A972 So	outh on 05	June 201	8						
No defects recorded Safety Patrol of A90 Swallow to SC No defects recorded	C on 08 Jui	ne 2018							
Safety Inspection of A90 & A972 So	outh on 12	June 201	8						
No defects recorded									

Page 41 of 64

Defect Reference	Start m	End m	Item Type	ltem Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
	000 := :	***							
Safety Patrol of A90 Swallow to NE7-363572-235858112	SCC on 15 Ji 1,238m		SAFETY_FENCE	Accident damage (ACCD)	CAT 1	13/07/2018	Completed Defects	05/07/2018	JUST BEFORE ST ANNS JCT NB
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded Safety Inspection of A90 & A972									
No defects recorded Safety Patrol of A90 Swallow to			5						
No defects recorded Safety Inspection of A90 & A972			8						
No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded Safety Inspection of A90 & A972	South on 17	7 July 2018	8						
No defects recorded  Safety Patrol of A90 Swallow to No defects recorded		_							
Safety Inspection of A90 & A972 No defects recorded			8						
Safety Patrol of A90 Swallow to No defects recorded			•						
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded  12245/05: WITH: A935 JUNG									
Safety Inspection of A90 & A972	South on 09	August 2	2016						
No defects recorded Safety Patrol of A90 Swallow to	SCC on 12 A	ugust 201	16						
No defects recorded Safety Inspection of A90 & A972 No defects recorded	South on 16	6 August 2	2016						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 19 A	ugust 201	16						
Safety Inspection of A90 & A972 No defects recorded	South on 23	3 August 2	2016						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 26 A	ugust 201	16						
Safety Inspection of A90 & A972 No defects recorded		_							
Safety Patrol of A90 Swallow to No defects recorded		-							
Safety Inspection of A90 & A972  No defects recorded  Safety Patrol of A90 Swallow to									
No defects recorded Safety Inspection of A90 & A972									
No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded  Safety Inspection of A90 & A972									
No defects recorded Safety Patrol of A90 Swallow to	SCC on 23 S	eptember	2016						
No defects recorded Safety Inspection of A90 & A972	South on 27	7 Septemb	per 2016						
No defects recorded Safety Patrol of A90 Swallow to No defects recorded	SCC on 30 S	eptember	· 2016						
140 0616618 16601060									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972	South on M	Octobor	2016						
No defects recorded	30utii 0ii 04	October	2016						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 07 O	ctober 20	116						
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972	South on 18	October	2016						
No defects recorded Safety Patrol of A90 Swallow to S	SCC on 21 O	ctober 20	116						
NE8-199340-2268465	4,361m	0m	CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	22/10/2016	Awaiting CCMS Permanent Date	21/10/2016	APPROX 350M PRIOR TO B966 JCT N/B
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to S NE8-202133-2287335	SCC on 28 O 4,361m		016 CARRIAGEWAY	Pothole	CAT 1	25/11/2016	Completed	20/11/2016	annravimataly 400m hafara
NE0-202133-2207333	4,301111	OIII	CARRIAGEWAT	(POTH)	CATT	23/11/2010	Completed Defects	20/11/2010	approximately 400m before B966 keithock off slip n/b
Safety Inspection of A90 & A972 No defects recorded	South on 01	Novemb	er 2016						
Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 18 N	ovember	2016						
Safety Inspection of A90 & A972 No defects recorded	South on 22	Novemb	er 2016						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 25 N	ovember	2016						
Safety Inspection of A90 & A972 No defects recorded	South on 29	Novemb	er 2016						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 02 D	ecember	2016						
Safety Inspection of A90 & A972 No defects recorded	South on 06	Decembe	er 2016						
Safety Patrol of A90 Swallow to S No defects recorded Safety Inspection of A90 & A972									
NE8-220020-2384089	4,646m		CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/12/2016	Completed Defects	13/12/2016	APPROACHING KEITHOCK JCT N/B
Safety Patrol of A90 Swallow to S	SCC on 16 D	ecember	2016						
No defects recorded Safety Inspection of A90 & A972 No defects recorded	South on 20	Decemb	er 2016						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 23 D	ecember	2016						
Safety Inspection of A90 & A972 No defects recorded	South on 27	Decembe	er 2016						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 30 D	ecember	2016						
Safety Inspection of A90 & A972 No defects recorded	South on 03	January	2017						
Safety Patrol of A90 Swallow to S NE8-230731-235031093	6 <b>CC on 06 J</b> a 4,673m		017 CARRIAGEWAY	Failed repair (RFAL)	CAT 1	03/02/2017	Completed Defects	24/01/2017	approximately 150m before keithock junction n /b
Safety Inspection of A90 & A972 No defects recorded	South on 10	January	2017						
Safety Patrol of A90 Swallow to S No defects recorded	SCC on 13 Ja	anuary 20	17						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972 S	outh on 17	January	2017						
No defects recorded Safety Patrol of A90 Swallow to S0	C on 20 Ja	ınuary 20	)17						
No defects recorded Safety Inspection of A90 & A972 Se		-							
NE8-237501-235040633	4,111m		CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2017	Completed Defects	13/02/2017	APPROX 700M BEFORE KEITHOCK JCT N/B
NE8-237501-235040634	4,351m	0m	TREE	Unstable (UNST)	CAT 2	01/01/9999	Cat 2 Awaiting Action	01/01/9999	APPROACHING KEITHOCK JCT N/B
NE8-237501-235040632	1,724m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/02/2017	Completed Defects	13/02/2017	APPROACHING COOKSTON UNDERPASS N/B
Safety Patrol of A90 Swallow to SC No defects recorded Safety Inspection of A90 & A972 So No defects recorded		_							
Safety Patrol of A90 Swallow to SC				5 4 4	0.47.4	00/00/00/47		07/00/00/17	
NE7-242535-235051572	4,320m		CARRIAGEWAY	Pothole (POTH)	CAT 1	03/03/2017	Completed Defects	27/02/2017	APPROX 350M BEFORE KEITHOCK JCT NB
Safety Inspection of A90 & A972 Son No defects recorded	outh on 07	February	<i>j</i> 2017						
Safety Patrol of A90 Swallow to SC No defects recorded		_							
Safety Inspection of A90 & A972 Son No defects recorded	outh on 14	February	/ 2017						
Safety Patrol of A90 Swallow to SC NE7-244226-235057944	C on 17 Fe 891m		2017 CARRIAGEWAY	Pothole	CAT 1	17/03/2017	Completed	06/03/2017	LAYBY AFTER ST ANNE N/B
NL7-244220-233037344				(POTH)	CALL		Defects		
NE7-244226-235057945	4,643m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/03/2017	Completed Defects	06/03/2017	APPROACHING KEITHOCK JCT N/B
NE7-244226-235057946	4,677m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/03/2017	Completed Defects	06/03/2017	APPROACHING KEITHOCK JCT N/B
Safety Inspection of A90 & A972 Service NE7-244817-235058704	outh on 21 2,089m		y 2017 CARRIAGEWAY	Pothole	CAT 1	21/03/2017	Completed	06/03/2017	APPROACHING COOKSTON
NE7-244017-233030704	2,009111	OIII	CARRIAGEWAT	(POTH)	CATT	21/03/2017	Defects	00/03/2017	OVERBRIDGE N/B
NE7-244817-235058705	4,232m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/03/2017	Completed Defects	06/03/2017	APPROX 500M BEFORE KEITHOCK JCT N/B
NE7-244817-235058703	1,409m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	21/03/2017	Completed Defects	06/03/2017	@ BRIDGEDECK AFTER ST ANNES JCT N/B
Safety Patrol of A90 Swallow to SC No defects recorded	C on 24 Fe	bruary 20	.017						
Safety Inspection of A90 & A972 Son No defects recorded	outh on 28	February	y 2017						
Safety Patrol of A90 Swallow to SC	CC on 03 Ma	arch 2017	7						
No defects recorded Safety Inspection of A90 & A972 Se No defects recorded	outh on 07	March 20	017						
Safety Patrol of A90 Swallow to SC No defects recorded	C on 10 Ma	arch 2017	7						
Safety Inspection of A90 & A972 S	outh on 14	March 20	017						
No defects recorded Safety Patrol of A90 Swallow to SC	C on 17 Ma	arch 2017	7						
No defects recorded Safety Inspection of A90 & A972 Se	outh on 21	March 20	017						
NE7-252954-235071789	2,782m		CARRIAGEWAY	Pothole (POTH)	CAT 1	18/04/2017	Completed Defects	02/04/2017	APPROACHING TRINITY  O/BRIDGE N/B
Safety Patrol of A90 Swallow to SC	C on 24 Ma	arch 2017	7						

Safety Patrol of A90 Swallow to SCC on 24 March 2017

Defeat Deference								•	
Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE7-254350-235073992	4,289m	0m	CARRIAGEWAY	Pothole	CAT 1	21/04/2017	Completed	17/04/2017	APPROX 400M PRIOR TO THE
0.64.1				(POTH)			Defects		KEITHOCK 0FF SLIP N/B
Safety Inspection of A90 & A97 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A97 NE7-256929-235075194	72 South on 04 4,239m		117 CARRIAGEWAY	Failed repair	CAT 1	02/05/2017	Completed	17/04/2017	APPROX 500M BEFORE
N27 200020 200070707	1,200111	o	G/ II (I II) (G_27)/ (7	(RFAL)	<i>G</i> 7 1	02/06/2011	Defects	1170172011	KEITHOCK JCT N/B
NE7-256929-235075195	4,365m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/05/2017	Completed Defects	17/04/2017	APPROX 300M BEFORE KEITHOCK JCT NB
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 07 A	pril 2017							
Safety Inspection of A90 & A97 No defects recorded	72 South on 11	April 20	17						
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 14 A	pril 2017							
Safety Inspection of A90 & A97 No defects recorded	72 South on 18	3 April 20	17						
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 21 A	pril 2017							
Safety Inspection of A90 & A97 No defects recorded	72 South on 25	5 April 20	17						
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 28 A	pril 2017							
Safety Inspection of A90 & A97 No defects recorded	72 South on 02	2 May 201	17						
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 05 M	lay 2017							
Safety Inspection of A90 & A97 No defects recorded	72 South on 09	) May 201	17						
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 12 M	lay 2017							
Safety Inspection of A90 & A97 No defects recorded	72 South on 16	մ May 201	17						
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 19 M	lay 2017							
Safety Inspection of A90 & A97 No defects recorded	72 South on 23	3 May 201	17						
Safety Patrol of A90 Swallow to NE7-277071-235173863	o SCC on 26 M 3,012m		CARRIAGEWAY	Pothole	CAT 1	23/06/2017	Completed	13/06/2017	350M BEFORE TRINITY
NET 211011 200110000	5,012111	OIII	CARTIAGEWAT	(POTH)	OAT 1	20/00/2011	Defects	10/00/2017	OVERBRIDGE N/B
NE7-277071-235173864	3,654m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/06/2017	Completed Defects	13/06/2017	@LAYBY AFTER TRINITY N/B
NE7-277071-235173866	4,362m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	23/06/2017	Completed Defects	13/06/2017	400M BEFORE KEITHOCK N/B
NE7-277071-235173862	2,987m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	23/06/2017	Completed Defects	13/06/2017	400M BEFORE TRINITY OVERBRIDGE N/B
NE7-277071-235173865	4,273m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	23/06/2017	Completed Defects	13/06/2017	500M BEFORE KEITHOCK JCT N/B
Safety Inspection of A90 & A97 No defects recorded	72 South on 30	) May 201	17						
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 02 J	une 2017							
Safety Inspection of A90 & A97 No defects recorded	72 South on 06	3 June 20	17						
Safety Patrol of A90 Swallow to	o SCC on 09 J	une 2017							
No defects recorded Safety Inspection of A90 & A97	72 South on 15	3 June 20	117						

Safety Inspection of A90 & A972 South on 13 June 2017
No defects recorded

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow	to SCC on 16 J	une 2017							
No defects recorded  Safety Inspection of A90 & A9	972 South on 20	) June 20'	17						
No defects recorded Safety Patrol of A90 Swallow									
No defects recorded Safety Inspection of A90 & A9 No defects recorded	)72 South on 27	′ June 201	17						
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 30 J	une 2017							
Safety Inspection of A90 & A9 No defects recorded	)72 South on 04	July 201	7						
Safety Patrol of A90 Swallow ( NE7-282190-235262467	to SCC on 07 July 869m		CARRIAGEWAY	Pothole (POTH)	CAT 1	04/08/2017	Completed Defects	17/07/2017	@ LAYBY AFTER ST ANNES JCT N/B
Safety Inspection of A90 & A9	972 South on 11	July 201	7						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 14 J	uly 2017							
No defects recorded Safety Inspection of A90 & A9	972 South on 18	3 July 201	7						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 21 J	uly 2017							
NE7-282573-235276454	566m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/08/2017	Completed Defects	16/08/2017	APPROX 560M AFTER ST ANNS NB
NE7-282573-235276455	4,346m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	18/08/2017	Completed Defects	16/08/2017	APPROX 500M BEFORE KEITHOCK JCT NB
Safety Inspection of A90 & A9 No defects recorded	72 South on 25	July 201	7						
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 01	August 2	2017						
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 04 A	ugust 201	17						
Safety Inspection of A90 & A9  No defects recorded	)72 South on 08	August 2	2017						
Safety Patrol of A90 Swallow No defects recorded		_							
Safety Inspection of A90 & A9 NE7-283445-235313548	372 South on 15 364m		2017 CARRIAGEWAY	Pothole	CAT 1	12/09/2017	Completed	22/08/2017	APPROX 365M AFTER A935
				(POTH)			Defects		JCT ST ANNS NB LWT
Safety Patrol of A90 Swallow to No defects recorded Safety Inspection of A90 & A9		_							
NE7-283732-235323661	4,656m		CARRIAGEWAY	Pothole (POTH)	CAT 1	19/09/2017	Completed Defects	23/08/2017	APPROACHING KEITHOCK JCT N/B
NE7-283732-235323662	4,670m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	19/09/2017	Completed Defects	23/08/2017	APPROACHING KEITHOCK JCT N/B
Safety Patrol of A90 Swallow ( NE7-283833-235335439	to SCC on 25 A 3,019m		17 CARRIAGEWAY	Pothole (POTH)	CAT 1	22/09/2017	Completed Defects	18/09/2017	APPROACHING TRINITY O/B (GOLFERS) NB
Safety Inspection of A90 & A9 No defects recorded	372 South on 29	) August 2	2017						
Safety Patrol of A90 Swallow ( NE7-283947-235361589	to SCC on 01 S		r <b>2017</b> CARRIAGEWAY	Pothole	CAT 1	29/09/2017	Completed	15/09/2017	@ BRIGE DECK AFTER ST
	ŕ			(POTH)	CALL	Z31U31ZU11	Defects	13/08/2017	ANNS NB APPROX 1390M
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 08 S	eptember	r <b>2017</b>						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972 NE7-295215-235370646	2 South on 12 1,091m		ber 2017 CARRIAGEWAY	Pothole (POTH)	CAT 1	10/10/2017	Completed Defects	25/09/2017	PAST LAYBY AFTER ST ANNES JCT N/B
Safety Patrol of A90 Swallow to NE7-302508-235377765	SCC on 15 S 1,700m		r 2017 CARRIAGEWAY	Pothole (POTH)	CAT 1	13/10/2017	Completed Defects	03/10/2017	APPROACHING COOKSTON U/PASS APPROX 1700M AFTER ST ANNS NB
Safety Inspection of A90 & A972 NE7-305456-235377769	2,816m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/10/2017	Completed Defects	03/10/2017	APPROX 500M BEFORE TRINITY O/BRIDGE NB
Safety Patrol of A90 Swallow to No defects recorded	SCC on 22 S	eptembe	r <b>2017</b>						
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to No defects recorded		-							
Safety Inspection of A90 & A972 NE7-315008-235397518	2 South on 03 1,384m		· <b>2017</b> CARRIAGEWAY	Pothole (POTH)	CAT 1	31/10/2017	Completed Defects	12/10/2017	UNDERPASS AFTER ST ANNES JCT N/B
<b>Safety Patrol of A90 Swallow to</b> <i>NE7-315221-235426306</i>	SCC on 06 C 2,105m		017 CARRIAGEWAY	Pothole (POTH)	CAT 1	03/11/2017	Completed Defects	26/10/2017	BEFORE COOKSTON UNDERPASS N/B
Safety Inspection of A90 & A972 NE7-315313-235426308	2 South on 10 1,309m		· <b>2017</b> CARRIAGEWAY	Pothole (POTH)	CAT 1	07/11/2017	Completed Defects	08/11/2017	APPROX 200M PAST THE LAYBY AFTER ST ANNS NB
Safety Patrol of A90 Swallow to	SCC on 13 C	ctober 20	)17						
No defects recorded Safety Inspection of A90 & A972	South on 17	7 October	· 2017						
NE7-315448-235430571	1,862m		CARRIAGEWAY	Pothole (POTH)	CAT 1	14/11/2017	Completed Defects	09/11/2017	APPROX 800M PAST LAYBY AFTER ST ANNS NB
NE7-315448-235430572	1,901m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	14/11/2017	Completed Defects	09/11/2017	APROX 840M PAST LAYBY AFTER ST ANNS NB
NE7-315448-235430573	2,209m		CARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	14/11/2017	Completed Defects	09/11/2017	APPROX 300M BEFORE COOKSTON U/PASS NB
Safety Patrol of A90 Swallow to NE7-315510-235434441	SCC on 20 C 2,357m		017 CARRIAGEWAY	Pothole	CAT 1	17/11/2017	Completed	08/12/2017	JSUT BEFORE COOKSTON
				(POTH)			Defects		U/PASS NB
NE7-315510-235434442	2,810m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/11/2017	Completed Defects	08/12/2017	APPROACHING TRINITY OVER BRIDGE NB
NE7-315510-235434443	3,147m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/11/2017	Completed Defects	08/12/2017	APPROX 150M BEORE TRINITY OVER BRIDGE NB
Safety Inspection of A90 & A972									
NE7-315594-235434441	2,092m		CARRIAGEWAY	Pothole (POTH)	CAT 1	21/11/2017	Completed Defects	10/11/2017	@ THE START OF LONG BARRIER BEFORE COOKSTON U/PASS NB
Safety Patrol of A90 Swallow to No defects recorded	SCC on 27 C	ctober 20	)17						
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded									
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded Safety Inspection of A90 & A972	South on 14	1 Novemb	er 2017						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
NE7-316172-235470040	377m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	12/12/2017	Completed Defects	01/12/2017	APPROX 380M AFTER STANNS JCT NB
Safety Patrol of A90 Swallow to S	CC on 17 N	ovember	2017						
No defects recorded Safety Inspection of A90 & A972 S	South on 21	Novemb	per 2017						
No defects recorded Safety Patrol of A90 Swallow to S	CC on 24 N	ovember	2017						
NE7-316393-235479075	364m		CARRIAGEWAY	Pothole (POTH)	CAT 1	22/12/2017	Completed Defects	01/12/2017	APPROX 365M AFTER ST ANNS JCT NB
NE7-316393-235479076	383m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	22/12/2017	Completed Defects	01/12/2017	APPROX 385M AFTER ST ANNS NB
Safety Inspection of A90 & A972 S No defects recorded	South on 28	Novemb	per 2017						
Safety Patrol of A90 Swallow to S	CC on 01 D	ecember	2017						
NE7-316494-235485433	2,119m		CARRIAGEWAY	Pothole (POTH)	CAT 1	29/12/2017	Completed Defects	22/12/2017	COOKSTON BRIDGEDECK N/B
Safety Inspection of A90 & A972 S				Dathala	CAT 1	02/04/2049	Completed	22/12/2017	ADDDOACHING COOKSTON
NE7-316633-235485410	2,056m		CARRIAGEWAY	Pothole (POTH)	CAT 1	02/01/2018	Completed Defects	22/12/2017	APPROACHING COOKSTON BRIDGEDECK N/B
Safety Patrol of A90 Swallow to S No defects recorded Safety Inspection of A90 & A972 S									
NE7-316790-235495351	0m		CARRIAGEWAY	Pothole (POTH)	CAT 1	09/01/2018	Completed Defects	22/12/2017	APPROACHING COOKSTON OVER BRIDGE NB
Safety Patrol of A90 Swallow to S No defects recorded Safety Inspection of A90 & A972 S									
NE7-316959-235497680	1,388m		CARRIAGEWAY	Pothole (POTH)	CAT 1	16/01/2018	Completed Defects	23/01/2018	@ BRIDGEDECK AFTER ST ANNES N/B
Safety Patrol of A90 Swallow to S NE7-317029-235510753	CC on 22 Do 2,812m		<b>2017</b> CARRIAGEWAY	Pothole (POTH)	CAT 1	19/01/2018	Completed Defects	25/01/2018	APPROACHING TRINITY O/BRIDGE NB
Safety Inspection of A90 & A972 S	South on 26	Decemb	er 2017						
No defects recorded Safety Patrol of A90 Swallow to S No defects recorded									
Safety Inspection of A90 & A972 S NE7-317225-235513447	South on 02 387m		2018 CARRIAGEWAY	Failed repair	CAT 1	30/01/2018	Completed	25/01/2018	450 YDS BEFORE LAYBY N/B
				(RFAL)	CALL	30/01/2010	Defects	25/01/2010	@ BRECHIN CASTLE CENTER
Safety Patrol of A90 Swallow to S NE7-317340-235513832	4,281m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	02/02/2018	Completed Defects	25/01/2018	APPROX 600M BEFORE B966 JCT NB
Safety Inspection of A90 & A972 S NE7-317402-235513830	South on 09 2,054m		2018 CARRIAGEWAY	Failed repair (RFAL)	CAT 1	06/02/2018	Completed Defects	25/01/2018	APPROX 500M BEFORE COOKSTON OVER BRIDGE
NE7-317402-235513831	3,420m	0m	SAFETY_FENCE	Accident damage (ACCD)	CAT 1	06/02/2018	Completed Defects	01/02/2018	NB @ TRINITY OVER BRIDGE NB
Safety Patrol of A90 Swallow to S	CC on 12 Ja								
NE7-317479-235518753	1,341m		CARRIAGEWAY	Pothole (POTH)	CAT 1	09/02/2018	Completed Defects	25/01/2018	APPROACHING BRIDGEDECK AFTER ST ANNES N/B
NE7-317479-235518754	1,384m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/02/2018	Completed Defects	25/01/2018	@ BRIDGEDECK AFTER ST ANNES N/B
NE7-317479-235518755	3,146m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	09/02/2018	Completed Defects	25/01/2018	APPROACHING TRINITY  O/BRIDGE N/B

Report Version 1.2 Page 48 of 64 20/09/2018

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972 S	South on 16	.lanuarı	2018						
No defects recorded	South on 10	January	2010						
Safety Patrol of A90 Swallow to S	CC on 19 Ja	nuary 20	)18						
No defects recorded  Safety Inspection of A90 & A972 S	South on 23	January	2018						
No defects recorded	CC on 26 la		14.0						
Safety Patrol of A90 Swallow to Son No defects recorded	CC on 26 Ja	inuary 20	J18						
Safety Inspection of A90 & A972 S No defects recorded	South on 30	January	2018						
Safety Patrol of A90 Swallow to S	CC on 02 Fe	bruary 2	2018						
No defects recorded Safety Inspection of A90 & A972 S	South on 06	February	v 2018						
NE7-318679-235533732	373m		CARRIAGEWAY	Failed repair (RFAL)	CAT 1	06/03/2018	Completed Defects	21/03/2018	APPROX 370M AFTER ST ANNS JCT NB
Safety Patrol of A90 Swallow to S	CC on 09 Fe	bruary 2	018						
No defects recorded Safety Inspection of A90 & A972 S	South on 13	February	v 2018						
No defects recorded Safety Patrol of A90 Swallow to S		-							
NE7-319990-235544808	1,865m		CARRIAGEWAY	Failed repair	CAT 1	16/03/2018	Completed	21/03/2018	APPROX 150M BEFORE
				(RFAL)			Defects		COOKSTON O/BRIDGE NB
Safety Inspection of A90 & A972 S									
NE7-320574-235544998	1,385m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	20/03/2018	Completed Defects	20/03/2018	@ FIRST BIDGE DECK AFTER ST ANNS NB
NE7-320574-235544999	1,388m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	20/03/2018	Completed Defects	20/03/2018	@ FIRST B/DECK AFTER ST ANNS NB
NE7-320574-235545000	4,257m	0m	CARRIAGEWAY	Pothole	CAT 1	20/03/2018	Completed Defects	20/03/2018	APPROX 400M BEFORE KIETHOCK JCT
				(POTH)					
NE7-320574-235544997	1,338m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	20/03/2018	Completed Defects	20/03/2018	JUST BEFORE FIRSTOVER BRIDGE AFTER ST ANNS NB
Safety Patrol of A90 Swallow to S	CC on 23 Fe	bruary 2	018						
No defects recorded									
Safety Inspection of A90 & A972 S NE7-322563-235549045	30uth on 27 1,062m		y 2018 CARRIAGEWAY	Failed repair	CAT 1	27/03/2018	Awaiting CCMS	01/01/9999	PAST LAYBY AFTER ST
NE7 022000 2000 100 10	7,002	0	<i>0,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1</i>	(RFAL)	<b>6</b> 71. 7	2770072010	Temp Date	0 1/10 1/10 000	ANNES N/B
Safety Patrol of A90 Swallow to S	CC on 02 Ma	arch 201	8						
No defects recorded Safety Inspection of A90 & A972 S	South on ne	March 2	018						
NE7-324685-235552241	937m		EMERGENCY_TEL	Damaged	3RD PTY	07/03/2018	Awaiting CCMS	01/01/9999	LAYBY AFTER ST ANNS JCT
			EPHONE_BOX	(DAMG)			Permanent Date		NB
Safety Patrol of A90 Swallow to S	CC on 09 Ma	arch 201	8						
No defects recorded Safety Inspection of A90 & A972 S	South on 13	March 2	018						
No defects recorded	South on 13	IVIAI CII Z	010						
Safety Patrol of A90 Swallow to Son No defects recorded	CC on 16 Ma	arch 2018	8						
Safety Inspection of A90 & A972 S	South on 20								
NE7-328680-235594213	33m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	17/04/2018	Completed Defects	09/04/2018	JUST AFTER ST ANNS JCT NB
NE7-328680-235594214	355m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	17/04/2018	Completed Defects	09/04/2018	APPROX 350M AFTER ST ANNS JCT NB
NET 228680 225504245	2 1111	0	CARRIAGEWAY		CAT 1	17/04/2018		00/04/2049	APPROX 200M BEFORE
NE7-328680-235594215	3,144m	UITI	CARRIAGEWAY	Pothole (POTH)	CALL	17/04/2010	Completed Defects	09/04/2018	TRINITY O/BRIDGE NB
Safety Patrol of A90 Swallow to S									
NE7-330089-235606489	334m		CARRIAGEWAY	Patch - difference in level (PDLV)	CAT 1	20/04/2018	Completed Defects	09/04/2018	JUST AFTER THE A935 JCT NB
				, ,					

20/09/2018

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972	2 South on 27	' March 2	.018						
No defects recorded  Safety Patrol of A90 Swallow to	SCC on 30 M	larch 201	8						
NE7-332089-235614503	1,390m		CARRIAGEWAY	Failed repair (RFAL)	CAT 1	27/04/2018	Completed Defects	25/04/2018	@ FIRST BRIDGE DECK AFTER ST ANNS JCT NB
NE7-332089-235614504	1,809m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	27/04/2018	Completed Defects	25/04/2018	APPROACHING COOKSTON U BRIDGE NB
Safety Inspection of A90 & A972 NE7-332669-235614507	2 <b>South on 03</b> 537m		18 CARRIAGEWAY	Pothole (POTH)	CAT 1	01/05/2018	Completed Defects	27/04/2018	APPROX 540M AFTER ST ANNS JCT NB
NE7-332669-235614508	1,914m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	01/05/2018	Completed Defects	27/04/2018	APPROACHING COOKSTON U/PASS NB
NE7-332669-235614509	2,805m	0m	CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	01/05/2018	Completed Defects	27/04/2018	APPROACHING TRINITY O/BRIDGE NB
Safety Patrol of A90 Swallow to	SCC on 06 A	pril 2018							
No defects recorded Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to		-							
No defects recorded									
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to		-							
No defects recorded									
Safety Inspection of A90 & A972 NE7-339472-235658979	2 <b>South on 24</b> 3,004m		18 CARRIAGEWAY	Patch - loss of material (fretting) (PLMT)	CAT 1	22/05/2018	Completed Defects	16/05/2018	APPROX 200M BEFORE TRINITY OVER BRIDGE NB
Safety Patrol of A90 Swallow to NE7-341083-235672792			CARRIAGEWAY	Patch - difference in	CAT 1	25/05/2018	Completed Defects	16/05/2018	APPROX 500M BEFORE KEITHOCK JCT N/B
Safety Inspection of A90 & A972 No defects recorded	2 South on 01	May 201	8	level (PDLV)					
Safety Patrol of A90 Swallow to	SCC on 04 M	ay 2018							
No defects recorded	Couth on 00	Mov 201	10						
Safety Inspection of A90 & A972 NE7-344813-235705404	4,311m		CARRIAGEWAY	Failed repair (RFAL)	CAT 1	05/06/2018	Completed Defects	30/05/2018	APPROX 500M BEFORE B966 KEITHOCK JCT NB
Safety Patrol of A90 Swallow to	SCC on 11 M	ay 2018							
No defects recorded Safety Inspection of A90 & A972	South on 15	May 201	18						
NE7-347699-235789461	2,108m		CARRIAGEWAY	Pothole (POTH)	CAT 1	12/06/2018	Completed Defects	30/05/2018	JUST PRIOR TO COOKSTIN UNDERPASS NB
Safety Patrol of A90 Swallow to	SCC on 18 M	ay 2018							
No defects recorded Safety Inspection of A90 & A972	South on 22	May 201	18						
NE7-350753-235803428	373m	0m	CARRIAGEWAY	Failed repair (RFAL)	CAT 1	19/06/2018	Completed Defects	29/05/2018	@ PARKING 450 YDS SIGN N/B AFTER ST ANNES JCT
Safety Patrol of A90 Swallow to No defects recorded	SCC on 25 M	ay 2018							
Safety Inspection of A90 & A972	2 South on 29	May 201	.8						
No defects recorded Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A972 No defects recorded	2 South on 05	June 20	18						
Safety Patrol of A90 Swallow to	SCC on 08 Ju	une 2018							

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded									
Safety Inspection of A90 &	A972 South on 1	12 June 2018	3						
No defects recorded		l 2040							
Safety Patrol of A90 Swallo No defects recorded	w to SCC on 15	June 2018							
Safety Inspection of A90 & No defects recorded	A972 South on 1	19 June 2018	3						
Safety Patrol of A90 Swallo No defects recorded									
Safety Inspection of A90 & No defects recorded			3						
Safety Patrol of A90 Swallo No defects recorded	w to SCC on 29	June 2018							
Safety Inspection of A90 & No defects recorded	A972 South on (	03 July 2018							
Safety Patrol of A90 Swallo No defects recorded	w to SCC on 06	July 2018							
Safety Inspection of A90 & No defects recorded	A972 South on 1	10 July 2018							
Safety Patrol of A90 Swallo No defects recorded	w to SCC on 13	July 2018							
Safety Inspection of A90 & No defects recorded	A972 South on 1	17 July 2018							
Safety Patrol of A90 Swallo No defects recorded	w to SCC on 20	July 2018							
Safety Inspection of A90 & No defects recorded	A972 South on 2	24 July 2018							
Safety Patrol of A90 Swallo No defects recorded	w to SCC on 27	July 2018							
Safety Inspection of A90 & No defects recorded	A972 South on 3	31 July 2018							
Safety Patrol of A90 Swallo No defects recorded	w to SCC on 03	August 2018	3						
12250/10 : WITH: END C	F CONCRETE	E TO STRA	ACATHRO HOSP	ITAL JCT					
Safety Inspection of A90 & No defects recorded									
Safety Patrol of A90 Swallo	w to SCC on 12	August 2016	3						
No defects recorded Safety Inspection of A90 &	A972 South on 1	16 August 20	016						
No defects recorded Safety Patrol of A90 Swallo	w to SCC on 19	August 2016	3						
No defects recorded Safety Inspection of A90 &	A972 South on 2	23 August 20	016						
No defects recorded Safety Patrol of A90 Swallo	w to SCC on 26	August 2016	3						
No defects recorded Safety Inspection of A90 &	A972 South on 3	30 August 20	016						
No defects recorded Safety Patrol of A90 Swallo	w to SCC on 02	September 2	2016						
No defects recorded Safety Inspection of A90 &	A972 South on (	06 Septembe	er 2016						
No defects recorded Safety Patrol of A90 Swallo	w to SCC on 09	September 2	2016						
No defects recorded Safety Inspection of A90 &	A972 South on 1	13 Septembe	er 2016						
No defects recorded Safety Patrol of A90 Swallo	w to SCC on 16	September 2	2016						
No defects recorded Safety Inspection of A90 &	A972 South on 2	20 Septembe	er 2016						
No defects recorded Safety Patrol of A90 Swallo	w to SCC on 23	September 2	2016						
No defects recorded Safety Inspection of A90 &	A972 South on 2	27 Septembe	er 2016						
No defects recorded Safety Patrol of A90 Swallo No defects recorded	w to SCC on 30	September 2	2016						
ino derects recorded									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A972 S	outh on 04	October 20	16						
No defects recorded									
Safety Patrol of A90 Swallow to SC NE8-194065-2253683	CC on <b>07 O</b> 1,176m		AFETY_FENCE	Accident	CAT 1	04/11/2016	Completed	11/10/2016	APPROACHING INCHBARE
1420 10 1000 220000	1,770111	0111 0.	W 277_7 21102	damage (ACCD)	<i>5717 7</i>	0 11 11/2010	Defects	11/10/2010	JCT N/B
Safety Inspection of A90 & A972 S	outh on 11	October 20	16						
No defects recorded Safety Patrol of A90 Swallow to S0	CC on 14 O	ctober 2016							
No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded Safety Patrol of A90 Swallow to SO									
No defects recorded									
Safety Inspection of A90 & A972 S No defects recorded	outh on 25	October 20	16						
Safety Patrol of A90 Swallow to SC No defects recorded	CC on 28 O	ctober 2016							
Safety Inspection of A90 & A972 S NE8-202999-2287335	outh on 01 1,648m		<b>2016</b> ARRIAGEWAY	Pothole VIAFIX (POTV)	CAT 1	02/11/2016	Completed Defects	01/11/2016	crossover slip inchbare NB
Safety Patrol of A90 Swallow to SC	CC on 04 No	ovember 20	16						
No defects recorded Safety Inspection of A90 & A972 S No defects recorded	outh on 08	November 2	2016						
Safety Patrol of A90 Swallow to SC No defects recorded	CC on 11 No	ovember 20°	16						
Safety Inspection of A90 & A972 S No defects recorded	outh on 15	November	2016						
Safety Patrol of A90 Swallow to SC No defects recorded	CC on 18 No	ovember 20	16						
Safety Inspection of A90 & A972 S No defects recorded	outh on 22	November 2	2016						
Safety Patrol of A90 Swallow to SC No defects recorded	CC on 25 No	ovember 20	16						
Safety Inspection of A90 & A972 S No defects recorded	outh on 29	November 2	2016						
Safety Patrol of A90 Swallow to SC No defects recorded	CC on 02 De	ecember 20°	16						
Safety Inspection of A90 & A972 S No defects recorded	outh on 06	December 2	2016						
Safety Patrol of A90 Swallow to SC	CC on 09 De	ecember 20°	16						
No defects recorded Safety Inspection of A90 & A972 S	outh on 13	December 2	2016						
No defects recorded Safety Patrol of A90 Swallow to SO	CC on 16 De	ecember 20°	16						
No defects recorded Safety Inspection of A90 & A972 S	outh on 20	December 2	2016						
No defects recorded Safety Patrol of A90 Swallow to SC No defects recorded	CC on 23 De	ecember 20	16						
Safety Inspection of A90 & A972 S No defects recorded	outh on 27	December 2	2016						
Safety Patrol of A90 Swallow to SC No defects recorded	CC on 30 De	ecember 20°	16						
Safety Inspection of A90 & A972 S No defects recorded	outh on 03	January 20	17						
Safety Patrol of A90 Swallow to SC No defects recorded	CC on 06 Ja	nuary 2017							
Safety Inspection of A90 & A972 S No defects recorded	outh on 10	January 20	17						
Safety Patrol of A90 Swallow to SC	CC on 13 Ja	nuary 2017							
No defects recorded Safety Inspection of A90 & A972 S	outh on 17	January 20	17						
No defects recorded Safety Patrol of A90 Swallow to SO		_							

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded									
Safety Inspection of A90 & A97 NE8-237501-235040635	<b>72 South on 24</b> 2,089m		<b>2017</b> SAFETY_FENCE	Accident damage (ACCD)	CAT 1	21/02/2017	Completed Defects	13/02/2017	300M BEFORE STRACATHRO OFFSLIP N/B
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 27 Ja	anuary 20	17	,					
Safety Inspection of A90 & A97 No defects recorded		_							
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A97 No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded Safety Inspection of A90 & A97									
No defects recorded Safety Patrol of A90 Swallow to No defects recorded	SCC on 17 Fe	ebruary 20	017						
Safety Inspection of A90 & A97 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A97 No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded  Safety Inspection of A90 & A97  No defects recorded	72 South on 07	March 20	017						
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 10 M	arch 2017	•						
Safety Inspection of A90 & A97 No defects recorded Safety Patrol of A90 Swallow to									
NE7-252356-235071781	1,184m		SAFETY_FENCE	Accident damage (ACCD)	CAT 1	14/04/2017	Completed Defects	02/04/2017	BEFORE INCHBARE CENTRE RES JCT N/B
Safety Inspection of A90 & A97 No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded  Safety Inspection of A90 & A97	72 South on 29	March 20	117						
No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded  Safety Inspection of A90 & A97 No defects recorded	72 South on 04	April 201	7						
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 07 A	pril 2017							
Safety Inspection of A90 & A97 No defects recorded Safety Patrol of A90 Swallow to			7						
No defects recorded			7						
Safety Inspection of A90 & A97 No defects recorded Safety Patrol of A90 Swallow to		-	1						
No defects recorded  Safety Inspection of A90 & A97  No defects recorded			7						
Safety Patrol of A90 Swallow to	o SCC on 28 A	pril 2017							
No defects recorded Safety Inspection of A90 & A97 No defects recorded			7						
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A97 No defects recorded	72 South on 09	May 2017	7						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow	to SCC on 12 l	May 2017							
No defects recorded		_							
Safety Inspection of A90 & A	972 South on 1	16 May 2017							
No defects recorded Safety Patrol of A90 Swallow	to SCC on 19 l	May 2017							
No defects recorded	10 000 011 10 1	may 2011							
Safety Inspection of A90 & A	972 South on 2	23 May 2017							
No defects recorded Safety Patrol of A90 Swallow	to SCC on 26 l	May 2017							
No defects recorded	10 000 011 20 1	may 2011							
Safety Inspection of A90 & A	972 South on 3	30 May 2017							
No defects recorded Safety Patrol of A90 Swallow	to SCC on 02.	June 2017							
No defects recorded	10 000 011 02 1	Outil 2017							
Safety Inspection of A90 & A No defects recorded			7						
Safety Patrol of A90 Swallow No defects recorded	to SCC on U9	June 2017							
Safety Inspection of A90 & A	972 South on 1	13 June 2017	7						
No defects recorded	to 800 a= 40	lune 2047							
Safety Patrol of A90 Swallow No defects recorded	10 SCC on 16	June 2017							
Safety Inspection of A90 & A	972 South on 2	20 June 2017	7						
No defects recorded	. 4- 000 00	l 2047							
Safety Patrol of A90 Swallow No defects recorded	to SCC on 23	June 2017							
Safety Inspection of A90 & A	972 South on 2	27 June 2017	7						
No defects recorded	40 SCC on 20	luna 2017							
Safety Patrol of A90 Swallow No defects recorded	to SCC on 30 .	June 2017							
Safety Inspection of A90 & A	972 South on 0	04 July 2017							
No defects recorded Safety Patrol of A90 Swallow	to SCC on 07	luly 2017							
No defects recorded	10 300 011 07 .	July 2017							
Safety Inspection of A90 & A	972 South on 1	l1 July 2017							
No defects recorded Safety Patrol of A90 Swallow	to SCC on 14	July 2017							
No defects recorded	10 000 011 14 1	July 2017							
Safety Inspection of A90 & A	972 South on 1	18 July 2017							
No defects recorded Safety Patrol of A90 Swallow	to SCC on 21 .	July 2017							
No defects recorded									
Safety Inspection of A90 & A No defects recorded	972 South on 2	25 July 2017							
Safety Patrol of A90 Swallow	to SCC on 28 .	July 2017							
No defects recorded									
Safety Inspection of A90 & A No defects recorded	972 South on 0	)1 August 20	)17						
Safety Patrol of A90 Swallow	to SCC on 04	August 2017	7						
No defects recorded									
Safety Inspection of A90 & A No defects recorded		_							
Safety Patrol of A90 Swallow No defects recorded	to SCC on 11 /	August 2017							
Safety Inspection of A90 & A	972 South on 1	I5 August 20	017						
No defects recorded	to 800 a= 40	August 2047	,						
Safety Patrol of A90 Swallow No defects recorded	10 300 01 18 /	August 2017							
Safety Inspection of A90 & A	972 South on 2	22 August 20	)17						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 25	August 2017	7						
No defects recorded									
Safety Inspection of A90 & A No defects recorded		_							
Safety Patrol of A90 Swallow No defects recorded	to SCC on 01	September 2	2017						
Safety Inspection of A90 & A	972 South on 0	)5 Septembe	er 2017						
		•							

Defect Reference	Start m	End m	Item Type	ltem Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	SCC on 08 S	September 2	2017						
Safety Inspection of A90 & A972 No defects recorded	South on 12	2 Septembe	er 2017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 15 S	September 2	2017						
Safety Inspection of A90 & A972 No defects recorded	South on 19	9 Septembe	er 2017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 22 S	September 2	2017						
Safety Inspection of A90 & A972 No defects recorded	South on 20	6 Septembe	er 2017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 29 S	September 2	2017						
Safety Inspection of A90 & A972 No defects recorded	South on 0	3 October 2	2017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 06 C	October 201	7						
Safety Inspection of A90 & A972 No defects recorded	South on 10	0 October 2	2017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 13 C	October 201	7						
Safety Inspection of A90 & A972 No defects recorded	South on 1	7 October 2	2017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 20 C	October 201	7						
Safety Inspection of A90 & A972 No defects recorded	South on 24	4 October 2	2017						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 27 C	October 201	7						
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A972 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A972 No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded  Safety Inspection of A90 & A972									
No defects recorded  Safety Patrol of A90 Swallow to									
No defects recorded Safety Inspection of A90 & A972									
No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded Safety Inspection of A90 & A972									
No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded Safety Inspection of A90 & A972									
No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded Safety Inspection of A90 & A972									
No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded Safety Inspection of A90 & A972									
No defects recorded Safety Patrol of A90 Swallow to									
No defects recorded									

20/09/2018 Page 55 of 64

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A97	2 South on 02	2 January 20	018						
No defects recorded Safety Patrol of A90 Swallow to	SCC on 05 J	lanuary 2018	8						
No defects recorded									
Safety Inspection of A90 & A97 No defects recorded	2 South on 09	9 January 20	J18						
Safety Patrol of A90 Swallow to	SCC on 12 J	anuary 2018	В						
No defects recorded  Safety Inspection of A90 & A97	2 South on 10	6 January 20	018						
No defects recorded		_							
Safety Patrol of A90 Swallow to No defects recorded	SCC on 19 J	anuary 2018	3						
Safety Inspection of A90 & A97 No defects recorded	2 South on 2	3 January 20	018						
Safety Patrol of A90 Swallow to	SCC on 26 J	anuary 2018	8						
No defects recorded  Safety Inspection of A90 & A97	2 South on 3	Ո.lanuary 20	018						
No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	SCC on 02 F	ebruary 201	18						
Safety Inspection of A90 & A97	2 South on 0	6 February 2	2018						
No defects recorded Safety Patrol of A90 Swallow to	SCC on 09 F	ebruary 201	18						
No defects recorded									
Safety Inspection of A90 & A97 No defects recorded		_							
Safety Patrol of A90 Swallow to No defects recorded	SCC on 16 F	ebruary 201	18						
Safety Inspection of A90 & A97	2 South on 20	0 February 2	2018						
No defects recorded Safety Patrol of A90 Swallow to	SCC on 23 F	ebruary 201	18						
No defects recorded									
Safety Inspection of A90 & A97 No defects recorded	2 South on 2	/ February 2	2018						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 02 N	March 2018							
Safety Inspection of A90 & A97	2 South on 0	6 March 201	.8						
No defects recorded  Safety Patrol of A90 Swallow to	SCC on 09 N	March 2018							
No defects recorded									
Safety Inspection of A90 & A97 No defects recorded	2 South on 1	3 March 201	8						
Safety Patrol of A90 Swallow to No defects recorded	SCC on 16 N	March 2018							
Safety Inspection of A90 & A97	2 South on 20	0 March 201	8						
No defects recorded  Safety Patrol of A90 Swallow to	SCC on 23 N	March 2018							
No defects recorded									
Safety Inspection of A90 & A97 No defects recorded	2 South on 2	7 March 201	8						
Safety Patrol of A90 Swallow to	SCC on 30 N	March 2018							
No defects recorded Safety Inspection of A90 & A97 No defects recorded	2 South on 0	3 April 2018							
Safety Patrol of A90 Swallow to	SCC on 06 A	April 2018							
No defects recorded  Safety Inspection of A90 & A97	2 South on 10	0 April 2018	,						
No defects recorded		-							
Safety Patrol of A90 Swallow to No defects recorded	SCC on 13 P	Aprii 2018							
Safety Inspection of A90 & A97 NE7-337482-235640975	2 South on 17 1,788m		SAFETY_FENCE	Accident damage (ACCD)	CAT 1	15/05/2018	Completed Defects	24/04/2018	AFTER INCHBARE N/B
Safety Patrol of A90 Swallow to No defects recorded	SCC on 20 A	April 2018							
Safety Inspection of A90 & A97	2 South on 2	4 April 2018							
<u></u>									

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded Safety Patrol of A90 Swallow t No defects recorded	to SCC on 27 A	April 2018							
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow t No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow t No defects recorded									
Safety Inspection of A90 & A9 No defects recorded Safety Patrol of A90 Swallow t No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow t No defects recorded Safety Inspection of A90 & A9			8						
No defects recorded Safety Patrol of A90 Swallow t			,						
No defects recorded Safety Inspection of A90 & A9			8						
No defects recorded Safety Patrol of A90 Swallow t	to SCC on 15 J	lune 2018							
No defects recorded Safety Inspection of A90 & A9 No defects recorded	72 South on 19	9 June 2018	В						
Safety Patrol of A90 Swallow t No defects recorded	to SCC on 22 J	lune 2018							
Safety Inspection of A90 & A9 No defects recorded	72 South on 26	6 June 2018	3						
Safety Patrol of A90 Swallow t No defects recorded									
Safety Inspection of A90 & A9 No defects recorded Safety Patrol of A90 Swallow t		-							
No defects recorded Safety Inspection of A90 & A9		_							
NE7-375083-235902882	1,520m		SAFETY_FENCE	Accident damage (ACCD)	CAT 1	07/08/2018	Completed Defects	14/08/2018	JUST BEFORE INCHBARE JCT N/B
Safety Patrol of A90 Swallow t No defects recorded		_							
Safety Inspection of A90 & A9 No defects recorded Safety Patrol of A90 Swallow t		-							
No defects recorded Safety Inspection of A90 & A9	72 South on 24	4 July 2018							
No defects recorded Safety Patrol of A90 Swallow t	to SCC on 27 J	luly 2018							
No defects recorded Safety Inspection of A90 & A9 No defects recorded	72 South on 31	1 July 2018							
Safety Patrol of A90 Swallow t No defects recorded	to SCC on 03 A	August 2018	3						
12250/06: WITH: B966 JUI Safety Inspection of A90 & A9 No defects recorded	72 South on 09	9 August 20	016						

Safety Patrol of A90 Swallow to SCC on 12 August 2016

20/09/2018 Page 57 of 64

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded									
Safety Inspection of A90 & AS No defects recorded	72 South on 1	6 August 20	016						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 19	August 201	6						
Safety Inspection of A90 & A9	72 South on 2	3 August 2	016						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 26	August 201	6						
No defects recorded  Safety Inspection of A90 & A9  No defects recorded	72 South on 3	0 August 2	016						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 02 S	September :	2016						
Safety Inspection of A90 & A90 No defects recorded	72 South on 0	6 Septembe	er 2016						
Safety Patrol of A90 Swallow No defects recorded		·							
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow No defects recorded	to SCC on 16 8	September .	2016						
Safety Inspection of A90 & A9 No defects recorded	72 South on 2	0 Septembe	er 2016						
No defects recorded									
Safety Inspection of A90 & A90 No defects recorded Safety Patrol of A90 Swallow									
No defects recorded  Safety Inspection of A90 & A9	172 South on 0	4 October 2	2016						
No defects recorded Safety Patrol of A90 Swallow									
No defects recorded Safety Inspection of A90 & A9									
No defects recorded Safety Patrol of A90 Swallow	to SCC on 14 (	October 201	16						
No defects recorded Safety Inspection of A90 & A9 No defects recorded	72 South on 1	8 October 2	2016						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 21 (	October 201	16						
Safety Inspection of A90 & A9 No defects recorded	72 South on 2	5 October 2	2016						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 28 (	October 201	16						
Safety Inspection of A90 & A90 No defects recorded	72 South on 0	1 Novembe	er 2016						
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow No defects recorded	to SCC on 18 I	November 2	2016						
Safety Inspection of A90 & A90 No defects recorded	72 South on 2	2 Novembe	er 2016						
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A9									
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 0	6 Decembe	er 2016						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow t	o SCC on 09 I	December 2	016						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 1	3 December	r 2016						
Safety Patrol of A90 Swallow t	o SCC on 16 I	December 2	016						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 2	0 December	r 2016						
Safety Patrol of A90 Swallow t	o SCC on 23 I	December 2	016						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 2	7 December	r 2016						
Safety Patrol of A90 Swallow t	o SCC on 30 I	December 2	016						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 06 .	January 201	1						
Safety Inspection of A90 & A9	72 South on 1	0 January 2	017						
No defects recorded	o ecc 40	lanuam: 004	7						
Safety Patrol of A90 Swallow t No defects recorded	o 500 on 13 .	January 201	1						
Safety Inspection of A90 & A9	72 South on 1	7 January 2	017						
No defects recorded	- 000 00	I 004	7						
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 20 .	January 201	1						
Safety Inspection of A90 & A9	72 South on 2	4 January 2	017						
No defects recorded Safety Patrol of A90 Swallow t	o SCC on 27	January 201	7						
No defects recorded	0 300 011 27	January 201	1						
Safety Inspection of A90 & A9	72 South on 3	1 January 2	017						
No defects recorded Safety Patrol of A90 Swallow t	o SCC on 03 F	February 20	17						
No defects recorded	00000	obludiy 20	.,						
Safety Inspection of A90 & A9	72 South on 0	7 February	2017						
No defects recorded Safety Patrol of A90 Swallow t	o SCC on 10 i	February 20	17						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 1	4 February	2017						
Safety Patrol of A90 Swallow t	o SCC on 17 i	February 20	17						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 2	1 February	2017						
Safety Patrol of A90 Swallow t	o SCC on 24 I	February 20	17						
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 2	8 February	2017						
Safety Patrol of A90 Swallow t	o SCC on 03 I	March 2017							
No defects recorded	70.0	7 14	.~						
Safety Inspection of A90 & A9 No defects recorded	72 South on 0	7 March 201	17						
Safety Patrol of A90 Swallow t	o SCC on 10 I	March 2017							
No defects recorded  Safety Inspection of A90 & A9	72 South on 1	4 March 204	17						
No defects recorded	12 30utii 011 1	4 Warch 20	17						
Safety Patrol of A90 Swallow t	o SCC on 17 I	March 2017							
No defects recorded  Safety Inspection of A90 & A9	72 South on 2	1 March 201	17						
No defects recorded	004 0								
Safety Patrol of A90 Swallow t No defects recorded	o SCC on 24 I	March 2017							
Safety Inspection of A90 & A9	72 South on 2	8 March 201	17						
No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	o SCC on 31 I	March 2017							
Safety Inspection of A90 & A9	72 South on 0	4 April 2017	,						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defeate recorded									
No defects recorded Safety Patrol of A90 Swallow No defects recorded	to SCC on 07 Ap	pril 2017							
Safety Inspection of A90 & A90 No defects recorded	972 South on 11	April 20	17						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 14 Ap	pril 2017							
Safety Inspection of A90 & A90 No defects recorded		-							
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A90 No defects recorded		-							
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A90 No defects recorded Safety Patrol of A90 Swallow			7						
No defects recorded  Safety Inspection of A90 & A90	972 South on 09	May 201	7						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 12 Ma	ay 2017							
No defects recorded  Safety Inspection of A90 & A9  No defects recorded	972 South on 16	May 201	7						
Safety Patrol of A90 Swallow	to SCC on 19 Ma	ay 2017							
NE7-273896-235161635	133m		CARRIAGEWAY	Pothole (POTH)	CAT 1	16/06/2017	Completed Defects	06/06/2017	@ END OF CONCRETE SECTION NB
NE7-273896-235161636	124m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/06/2017	Completed Defects	06/06/2017	@ END OF CONCRTE SECTION NB
NE7-273896-235161637	119m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/06/2017	Completed Defects	06/06/2017	@ END OF CONCRETE SECTION NB
NE7-273896-235161638	118m	0m	CARRIAGEWAY	Pothole (POTH)	CAT 1	16/06/2017	Completed Defects	06/06/2017	@END OF COCRETE SECTION NB
Safety Inspection of A90 & A90 No defects recorded	972 South on 23	May 201	7						
Safety Patrol of A90 Swallow No defects recorded		_	_						
Safety Inspection of A90 & A9 No defects recorded	972 South on 30	May 201	7						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 02 Ju	ıne 2017							
Safety Inspection of A90 & A90 No defects recorded	972 South on 06	June 20	17						
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A90 No defects recorded									
Safety Patrol of A90 Swallow No defects recorded									
Safety Inspection of A90 & A90 No defects recorded Safety Patrol of A90 Swallow									
No defects recorded  Safety Inspection of A90 & A90									
No defects recorded  Safety Patrol of A90 Swallow									
No defects recorded  Safety Inspection of A90 & A90									
No defects recorded  Safety Patrol of A90 Swallow		-							
No defects recorded  Safety Inspection of A90 & A90		_	7						
No defects recorded		•							

Report Version 1.2 20/09/2018

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Patrol of A90 Swallow t	to SCC on 14 J	luly 2017							
No defects recorded Safety Inspection of A90 & A9		_	7						
No defects recorded Safety Patrol of A90 Swallow t		-							
No defects recorded									
Safety Inspection of A90 & A9 No defects recorded	72 South on 2	5 July 201	7						
Safety Patrol of A90 Swallow to No defects recorded		_							
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded									
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow t NE7-283399-235305331	to SCC on 11 A 121m		17 CARRIAGEWAY	Pothole (POTH)	CAT 1	08/09/2017	Completed Defects	03/08/2018	@ END OF CONCRETE SECTION N/B
NE7-283399-235305332	114m	0m	CARRIAGEWAY	Surfacing joints (SRJT)	CAT 2	01/01/9999	Completed Defects	03/08/2018	@ END OF CONCRETE SECTION N/B
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 18 A	August 201	17						
Safety Inspection of A90 & A9 No defects recorded	72 South on 22	2 August 2	2017						
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 25 A	August 201	17						
Safety Inspection of A90 & A9 No defects recorded	72 South on 29	9 August 2	2017						
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 01 S	September	<sup>,</sup> 2017						
Safety Inspection of A90 & A9 No defects recorded	72 South on 0	5 Septemb	per 2017						
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 08 S	September	2017						
Safety Inspection of A90 & A9 No defects recorded	72 South on 12	2 Septemb	per 2017						
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 15 S	September	· 2017						
Safety Inspection of A90 & A9 No defects recorded	72 South on 19	9 Septemb	per 2017						
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 22 S	September	2017						
Safety Inspection of A90 & A9 No defects recorded	72 South on 20	6 Septemb	per 2017						
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 29 S	September	2017						
Safety Inspection of A90 & A9 No defects recorded	72 South on 03	3 October	2017						
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 06 C	October 20	17						
Safety Inspection of A90 & A9 No defects recorded	72 South on 10	0 October	2017						
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 13 C	October 20	117						
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 20 C	October 20	ı <b>17</b>						
Safety Inspection of A90 & A9 No defects recorded	72 South on 24	4 October	2017						
Safety Patrol of A90 Swallow the No defects recorded	to SCC on 27 C	October 20	17						

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
Safety Inspection of A90 & A9	72 South on 2	4 Ootobor 3	2047						
No defects recorded	72 South on 3	of October 2	2017						
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 03 I	November 2	2017						
Safety Inspection of A90 & A9	72 South on 0	7 Novembe	er 2017						
No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 10 I	November 2	2017						
Safety Inspection of A90 & A9	72 South on 1	4 Novembe	r 2017						
No defects recorded Safety Patrol of A90 Swallow	to SCC on 17 I	November 2	2017						
No defects recorded Safety Inspection of A90 & A9 No defects recorded	72 South on 2	1 Novembe	er 2017						
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 24 I	November 2	2017						
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 01 I	December 2	:017						
Safety Inspection of A90 & A9 No defects recorded	72 South on 0	5 Decembe	r 2017						
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 08 I	December 2	2017						
Safety Inspection of A90 & A9 No defects recorded	72 South on 1	2 Decembe	r 2017						
Safety Patrol of A90 Swallow to defects recorded	to SCC on 15 I	December 2	<u>2</u> 017						
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 22 I	December 2	2017						
Safety Inspection of A90 & A9 No defects recorded Safety Patrol of A90 Swallow									
No defects recorded  Safety Inspection of A90 & A9  No defects recorded									
Safety Patrol of A90 Swallow to defects recorded	to SCC on 05	January 201	18						
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow No defects recorded	to SCC on 12 .	January 201	18						
Safety Inspection of A90 & A9 No defects recorded		_							
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 19 、	January 201	18						
Safety Inspection of A90 & A9 No defects recorded	72 South on 2	3 January 2	2018						
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 26	January 201	18						
Safety Inspection of A90 & A9 No defects recorded									
Safety Patrol of A90 Swallow to No defects recorded	to SCC on 02 I	February 20	)18						
Safety Inspection of A90 & A9 No defects recorded	72 South on 0	6 February	2018						
Safety Patrol of A90 Swallow	to SCC on 09 I	February 20	118						
No defects recorded Safety Inspection of A90 & A9 No defects recorded	72 South on 1	3 February	2018						
Safety Patrol of A90 Swallow	to SCC on 16 I	February 20	)18						
No defects recorded Safety Inspection of A90 & A9 No defects recorded	72 South on 2	0 February	2018						
Safety Patrol of A90 Swallow	to SCC on 23 I	February 20	)18						

20/09/2018 Page 62 of 64

Defect Reference	Start m	End m	Item Type	Item Detail	Defect Category	Required Completion Date	Current Status	Completion Date	Location Description
No defects recorded									
Safety Inspection of A90 & A	\972 South on 2	7 February 2	2018						
No defects recorded Safety Patrol of A90 Swallov	to SCC on 02 l	March 2018							
No defects recorded  Safety Inspection of A90 & A									
No defects recorded									
Safety Patrol of A90 Swallov No defects recorded	to SCC on 09 l	March 2018							
Safety Inspection of A90 & A No defects recorded	\972 South on 1	3 March 201	8						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 16 l	March 2018							
Safety Inspection of A90 & A No defects recorded	1972 South on 2	0 March 201	18						
Safety Patrol of A90 Swallov No defects recorded	to SCC on 23 l	March 2018							
Safety Inspection of A90 & A No defects recorded	1972 South on 2	7 March 201	8						
Safety Patrol of A90 Swallow No defects recorded	to SCC on 30 l	March 2018							
Safety Inspection of A90 & A No defects recorded	1972 South on 0	3 April 2018							
Safety Patrol of A90 Swallov No defects recorded	to SCC on 06 A	April 2018							
Safety Inspection of A90 & A No defects recorded	1972 South on 1	0 April 2018							
Safety Patrol of A90 Swallow No defects recorded	to SCC on 13 A	April 2018							
Safety Inspection of A90 & A No defects recorded	1972 South on 1	7 April 2018							
Safety Patrol of A90 Swallow No defects recorded	to SCC on 20 A	April 2018							
Safety Inspection of A90 & A No defects recorded	1972 South on 2	4 April 2018							
Safety Patrol of A90 Swallow No defects recorded	to SCC on 27	April 2018							
Safety Inspection of A90 & A No defects recorded	1972 South on 0	1 May 2018							
Safety Patrol of A90 Swallov No defects recorded	to SCC on 04 l	May 2018							
Safety Inspection of A90 & A No defects recorded	1972 South on 0	8 May 2018							
Safety Patrol of A90 Swallow No defects recorded	to SCC on 11 M	May 2018							
Safety Inspection of A90 & A No defects recorded	.972 South on 1	5 May 2018							
Safety Patrol of A90 Swallov No defects recorded	to SCC on 18 l	May 2018							
Safety Inspection of A90 & A No defects recorded	.972 South on 2	2 May 2018							
Safety Patrol of A90 Swallow No defects recorded	to SCC on 25 l	May 2018							
Safety Inspection of A90 & A No defects recorded	\972 South on 2	9 May 2018							
Safety Patrol of A90 Swallow No defects recorded	to SCC on 01	June 2018							
Safety Inspection of A90 & A No defects recorded	.972 South on 0	5 June 2018							
Safety Patrol of A90 Swallov	to SCC on 08	June 2018							
No defects recorded Safety Inspection of A90 & A	\972 South on 1	2 June 2018	•						
No defects recorded Safety Patrol of A90 Swallov	to SCC on 15	June 2018							
No defects recorded  Safety Inspection of A90 & A	.972 South on 1	9 June 2018	<b>.</b>						
No defects recorded									

Defect Reference	Start	End	Item Type	Item Detail	Defect	Required	Current Status	Completion	Location Description
Delect Reference	m Start	m	пеш туре	item Detail	Category	Completion Date	Current Status	Date	Location Description
Safety Patrol of A90 Swallo	w to SCC on 22 J	une 2018							
No defects recorded									
Safety Inspection of A90 & Annual No defects recorded	A972 South on 2	6 June 2018	}						
Safety Patrol of A90 Swallo	w to SCC on 29 J	une 2018							
No defects recorded									
Safety Inspection of A90 & Annual No defects recorded	A972 South on 0	3 July 2018							
Safety Patrol of A90 Swallow	w to SCC on 06 J	uly 2018							
No defects recorded									
Safety Inspection of A90 &	A972 South on 1	July 2018							
No defects recorded									
Safety Patrol of A90 Swallo	w to SCC on 13 J	uly 2018							
No defects recorded									
Safety Inspection of A90 &	A972 South on 1	7 July 2018							
No defects recorded									
Safety Patrol of A90 Swallo	w to SCC on 20 J	uly 2018							
No defects recorded									
Safety Inspection of A90 & Annual No defects recorded									
Safety Patrol of A90 Swallo	w to SCC on 27 J	uly 2018							
No defects recorded									
Safety Inspection of A90 & Annual No defects recorded	A972 South on 3	1 July 2018							
Safety Patrol of A90 Swallo	w to SCC on 03 A	ugust 2018	3						
No defects recorded									

Report Version 1.2 20/09/2018 Page 64 of 64